Technology Department
UCC - Metals Division
P. O. Box 579
Niagara Falls, NY 14302
December 16, 1975

PLAINTIFF'S EXHIBIT
tabbies
UC-1583

MEMORANDUM

TO: Mr. C. C. Masterman

COPIES: Technology File
Messrs. W. A. Beccue, C. M. Brown, R. A. Buchanan, R. E. Byrne, Jr., W. Chynoweth, J. H. Downing, D. J. Hansen, G. A. Headley, R. H. Kaiser, R. J. Kennedy, Jr., E. J. Klesta, R. J. Klotzbach, J. T. Langley, C. F. Lincoln, Jr., L. R. Matricardi, T. K. McCluhan, W. L. Murphy, J. L. Myers, C. M. Offenhauer, J. G. Oxaal, H. B. Rhodes, A. H. Soeder, J. R. Williams, R. G. Woolery, W. J. Wymer

FROM: Messrs. B. L. Ingalls
R. J. Kennedy, Sr.
J. S. Olearczyk

SUBJECT: November Safety Inspection (Actual Date Performed 12/9/75) By Messrs. B. L. Ingalls, R. J. Kennedy, Sr., and J. S. Olearczyk

General Safety was the main topic of this month's inspection with emphasis on safety rules and practice compliance. Several potential hazards were reported. The most common deficiency observed was in the area of housekeeping. Items stored in working areas blocking aisles and limiting mobility, and cluttered benches posed hazards in several of the laboratories. Lack of storage facilities seemed to be a common complaint.

Building 94

Location	Hazard
1. Room 205	Bench grinder running unattended.
2. Room 202	Inadequate guard around drive gears of hand press.
3. Room 222	Cluttered - materials in aisle.
4. Center stairwell	Damaged door on electrical junction box. Would not close.
5. Center stairwell	Overhead light out.
6. Maintenance shop	Needs goggle sign at south entrance.
7. Maintenance shop	Several pieces of equipment do not have exhaust ventilation including the band saw, planer, and table saw.
8. Maintenance shop	Fire extinguishers not hung on walls.
9. Room 02	General housekeeping.
10. Room 02	Shelf located near top of fire extinguisher needs to be removed. Head hazard.

A20777

Published by AsbestosClaims.Law
asbestosclaims.law/library/16681/1

Building 99

1. Chem Lab	Inadequate ventilation. No exhaust hoods.
2. Chem Lab	Poor housekeeping; chemical reagents not stored properly.
3. Bay area	Employee working without hard hat.
4. Grinding Lab	Inadequate ventilation.
5. North entrance	Air pack masks not adequately identified as to location. They were sitting on the floor and subject to damage. Also, they have not been serviced for several months.
6. Main bay area	Cluttered and improper high-voltage wiring overhanging equipment and work area.
7. Building in general	Poor housekeeping. Very dirty and cluttered.

Building 166

1. Room 104	Guard needed around gears on hand press.
2. 1st floor, south end Open bay area	Instrument wiring tripping hazard.
3. 2nd floor, north end Open bay area	Debris near vacuum furnace needs to be removed.
4. 2nd floor, north end Open bay area	Fire extinguisher should be relocated to a more visible location.
5. Room 381	Materials stored on top of cabinets.
6. Room 379A	Materials stored on top of cabinets.
7. Room 379A	Glass annealing oven requires safety sign and lock when in operation.
8. Room 357	General housekeeping.
9. Room 365	General housekeeping.
10. Room 118	General housekeeping.
11. Room 114	General housekeeping.

Building 95

1. Operating furnace area	Some personnel in area without proper protective equipment, face shields and protective clothing.

Building 170

1. Second floor	Some tools laying on top of drum near rail. Hazard to people working below.

B. L. Ingalls

BLI:cjb

A20778

Union Carbide trial exhibit UC-1583: B. L. Ingalls, R. J. Kennedy, Sr., and J. S. Olearczyk to C. C. Masterman on th... Published by AsbestosClaims.Law
ACL Doc 16681 · Page 2 of 2 asbestosclaims.law/library/16681/2