WV-0191 # 145

UNION CARBIDE

UNION CARBIDE CORPORATION
P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303
Silicones and Urethane Intermediates
South Charleston Plant

PLAINTIFF'S EXHIBIT
UC-2290

ASBESTOS ESTIMATE

DEPARTMENT: The Fire Tower South Side Of Upperbridge

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS: 388

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.

Priority 1 is insulation in very bad condition with a high degree of exposure.

Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.

Blue - Cover and/or patch existing insulation.

Green - Strip and reinsulate.

Red - Strip only.

All of the insulation pictured has been spray painted with the appropriate color.

Union Carbide trial exhibit UC-2290: Union Carbide South Charleston Plant Asbestos Estimate Forms for Sealing, S... Published by AsbestosClaims.Law
ACL Doc 17282 · Page 1 of 12 asbestosclaims.law/library/17282/1

UNION CARBIDE

UNION CARBIDE CORPORATION
P. O BOX 8004, SOUTH CHARLESTON, W. VA. 25303
Silicones and Urethane Intermediates
South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: Loading Rack North Of 209 Shed

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS:

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.
Priority 1 is insulation in very bad condition with a high degree of exposure.
Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.
Blue - Cover and/or patch existing insulation.
Green - Strip and reinsulate.
Red - Strip only.
All of the insulation pictured has been spray painted with the appropriate color.

UCC 002248

UNION CARBIDE

UNION CARBIDE CORPORATION
P. O BOX 8004, SOUTH CHARLESTON, W. VA. 25303
Silicones and Urethane Intermediates
South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: Bldg. 412

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS: 716

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.
Priority 1 is insulation in very bad condition with a high degree of exposure.
Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.
Blue - Cover and/or patch existing insulation.
Green - Strip and reinsulate.
Red - Strip only.
All of the insulation pictured has been spray painted with the appropriate color.

UCC 002249

UNION CARBIDE

UNION CARBIDE CORPORATION
P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303
Silicones and Urethane Intermediates
South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: Bldg. #75

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS: 200

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.
Priority 1 is insulation in very bad condition with a high degree of exposure.
Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.
Blue - Cover and/or patch existing insulation.
Green - Strip and reinsulate.
Red - Strip only.
All of the insulation pictured has been spray painted with the appropriate color.

UCC 002250

UNION CARBIDE

UNION CARBIDE CORPORATION

P. O BOX 8004, SOUTH CHARLESTON, W. VA. 25303

Silicones and Urethane Intermediates

South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: Cafeteria, Bldg. #314 & Garage, Bldg. #428

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS:

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.

Priority 1 is insulation in very bad condition with a high degree of exposure.

Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.

Blue - Cover and/or patch existing insulation.

Green - Strip and reinsulate.

Red - Strip only.

All of the insulation pictured has been spray painted with the appropriate color.

UCC 002251

UNION CARBIDE

UNION CARBIDE CORPORATION
P. O BOX 8004, SOUTH CHARLESTON, W. VA. 25303
Silicones and Urethane Intermediates
South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: Paint Shop

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS: 80 MH.

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.
Priority 1 is insulation in very bad condition with a high degree of exposure.
Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.
Blue - Cover and/or patch existing insulation.
Green - Strip and reinsulate.
Red - Strip only.
All of the insulation pictured has been spray painted with the appropriate color.

Union Carbide trial exhibit UC-2290: Union Carbide South Charleston Plant Asbestos Estimate Forms for Sealing, S... Published by AsbestosClaims.Law
ACL Doc 17282 · Page 6 of 12 asbestosclaims.law/library/17282/6

UNION CARBIDE CORPORATION
P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303
Silicones and Urethane Intermediates
South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT: 426

INSULATOR MANHOURS ESTIMATE: 280

ACTUAL MANHOURS:

ESTIMATED COST:

The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.


With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.
Priority 1 is insulation in very bad condition with a high degree of exposure.
Priority 2 is insulation needing attention but with less immediate risk of exposure.


COLOR CODE - This signifies the work necessary.
Blue - Cover and/or patch existing insulation.
Green - Strip and reinsulate.
Red - Strip only.
All of the insulation pictured has been spray painted with the appropriate color.

Union Carbide trial exhibit UC-2290: Union Carbide South Charleston Plant Asbestos Estimate Forms for Sealing, S... Published by AsbestosClaims.Law
ACL Doc 17282 · Page 7 of 12 asbestosclaims.law/library/17282/7

WV-0191 #146



BLDG-5
103-216



UCC 002254

UNION CARBIDE CORPORATION
P. O. BOX 8004, SOUTH CHARLESTON, W. VA. 25303
Silicones and Urethane Intermediates
South Charleston Plant

ASBESTOS ESTIMATE

DEPARTMENT:

INSULATOR MANHOURS ESTIMATE:

ACTUAL MANHOURS:

ESTIMATED COST:


The above estimate is to seal, cover, strip, or strip and reinsulate the asbestos insulation in the above mentioned department. The work is described in the following pictures.

With the description of the pictures are the following information:

PRIORITY - This is the condition of the insulation.
Priority 1 is insulation in very bad condition with a high degree of exposure.
Priority 2 is insulation needing attention but with less immediate risk of exposure.

COLOR CODE - This signifies the work necessary.
Blue - Cover and/or patch existing insulation.
Green - Strip and reinsulate.
Red - Strip only.
All of the insulation pictured has been spray painted with the appropriate color.

Union Carbide trial exhibit UC-2290: Union Carbide South Charleston Plant Asbestos Estimate Forms for Sealing, S... Published by AsbestosClaims.Law
ACL Doc 17282 · Page 9 of 12 asbestosclaims.law/library/17282/9



PICTURE: Left

DISCRIPTION: Unused line at stairway on the N/W corner of bldg. 195.

COLOR CODED: Red
MANHOURS REQUIRED: 24
PRIORITY: 1


PICTURE: Below

DISCRIPTION: Two lines at stairway on the N/W corner of bldg. 195.

1?

195


PRIORITY: 1
COLOR CODED: Red
MANHOURS REQUIRED: 32




1

UCC 002256


BLDG
152,



UCC 002257



BLDG.
152



UCC 002258