4-1-87
K.E. Coyne

YES

RECEIVED
APR 20 1987
M. A. PATEL

PLAINTIFF'S EXHIBIT
UC-3110

Dowtherm Line in Rack

Dowtherm line with asbestos material on it in Rack that runs East + West on the South side of Bl. 9 was not feasible to A Enclosure because it was in Pipe Rack with Pipe in way, can not get good seal around Pipe to make Enclosure feasible, Talk to Plant 512 Industrial Hygeienest About Job.

Procedure used on Job.

barricade Area, Put up warning signs wet Asbestos with amended water Be moved Asbestos very carefully. Put in Black Asbestos Bags

All workers on Job worn Protective clothing in Regulated Area with Full Face Supplied Air Respiration

UCC 019220