
MEMO AVOID ORAL INSTRUCTIONS DATE 6-26 197

TO Don Pugh

#2. Bill Blythe of 511 Industrial Hygiene has been contacted to evaluate the dust problem specified on item #2. We requested that he give us some recommendations to eliminate the problem as soon as possible.

#3. I contacted Jerry Tawney to request that he take care of this problem. He told us that H. Parsons had already been assigned to replace the pale.

514-686-D ✠ DO IT THE SAFE WAY ✠ SIGNED



WV-0143 #5(A)

PLAINTIFF'S EXHIBIT

UC-3252


UCC 016788

MEMO AVOID ORAL INSTRUCTIONS DATE _____ 197_____

TO _____

FYI. The employees exposure is not to exceed 15 milligrams per cubic meter (mg/m^3) based on an 8 hour time weighted average. Because this is a nuisance dust it is difficult to tell if the employee is over exposed and if respiratory equipment is required. Bechtel 511 I-H is going to monitor this job and recommend to us if respiratory equipment is required. In the mean time we recommend it be worn while emptying the bins.

514-686-D ✠ DO IT THE SAFE WAY ✠ SIGNED Randy Noble



UCC 016789

UW 0143 #5(b)

UNION CARBIDE CORPORATION
CHEMICALS AND PLASTICS
ENGINEERING
SOUTH CHARLESTON, WEST VIRGINIA

RECEIVED
JUN 25 1979
D. R. PAUGH

MEMORANDUM

June 21, 1979

TO: D. R. Paugh
P. P. Price
D. E. Raines

COPY TO: C. W. Carman, Jr.
J. H. Hall

SUBJECT: SAFETY INSPECTION - INSULATION FABRICATION SHOP - BUILDING 2018

On June 15, 1979, a Safety Inspection was conducted at the Insulation Fabrication Shop. The inspection was conducted by D. E. Raines, J. A. Byrd, and myself.

Attached is a copy of the inspection teams findings and observations.

L. R. Noble

Ready when I am ? a night page.
DGPaugh

LRN:lkw
Attachment

UCC 016790

Union Carbide trial exhibit UC-3252: L. R. Noble Memo to D. E. Raines on Safety Inspection of the Insulation Fabric... Published by AsbestosClaims.Law
ACL Doc 18054 · Page 3 of 4 asbestosclaims.law/library/18054/3

1. The protective screen on the tar pot was not placed back over the pot. This cover may prevent an employee from inadvertently placing his hand in the pot. It should be placed over the pot at all times when the pot is not in use.

Who will do this?

2. There is a considerable amount of dust around the work benches on the east side of the shop. There is not any dust collection apparatus on this side of the shop which may be the cause of the dust problem. The Industrial Hygiene Department shall be contacted to evaluate our needs in this area.

Who will do this?

3. There is a protective pole that was removed from the south side of the fire hydrant on the south west corner of the shop. This pole should be replaced. The pole was removed when the fire water line was being replaced this fall. J. Tawney should be contacted to have the pole replaced.

Randy - Is this mandatory or not?

4. Two labor craft employees were observed cleaning out the dust collection bins on the West side of the shop.. This job created an excessive amount of dust, therefore, any employee assigned to this job will be requested to wear a particulate removing respirator, such as, the Norton 7170 Disposal Respirator.

GENERAL OBSERVATIONS

Mr. Raines and all of the employees in the Insulation Shop should be commended for the outstanding job they all are doing in maintaining a clean and safe work place. It is obvious that all of the employees in this shop have worked hard to make their shop a respectable place in which to work.

LRN:lkw

Union Carbide trial exhibit UC-3252: L. R. Noble Memo to D. E. Raines on Safety Inspection of the Insulation Fabric... Published by AsbestosClaims.Law
ACL Doc 18054 · Page 4 of 4 asbestosclaims.law/library/18054/4