PLAINTIFF'S EXHIBIT

UC-3621

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

May 6, 1987

TO: L. C. Stewart

CC: G. F. Painter*
M. J. Shoger*

Re: SHARE Inspection Results

Dear Larry:

You will find attached a copy of the findings from the SHARE inspection held May 6, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

Steve Kovach

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (June 6, 1987)	60 Days (July 6, 1987)	90 Days (Aug. 6, 1987)
% Complete	39%	42%	
Signature	L.C. Stewart	L.C. Stewart	

Send copy of update to: S. B. Kovach - Bldg. 109-2
G. F. Painter - Bldg. 82-3

SBH/yc
1658A

Attachment

*Copy of letter only

UCC 008444

Union Carbide trial exhibit UC-3621: S. B. Kovach to L. C. Stewart Transmitting SHARE Inspection Results, South...
ACL Doc 18347 · Page 2 of 4

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title MICC / UICC | Dept. No. 121 | Location TANK FARM - MICC | Date of Inspection 5-6-87

Inspector Submitting Report H. H. PRICE / SBK | Phone No. 2953 / 2411 | Inspection Responsibility INSULATION | Date of Report 5-6-87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN 1	EAST OF 174 WALKWAY - NEXT TO		NEED TO TEST FOR ASBESTOS		
	SOUTH STAINS - 3" LINE W/ FLYAWAY	✓			
	INSULATION				
IN 2	WEATHER STRIPPING MISSING		REPLACE PROTECTIVE COVERING		
	2" LINE RUNNING FROM 174 - 205'	✓			
	JUST ABOVE SB-45				
	EXPOSED INSULATION				
* IN 3	(4) FOUR PIPES OVERHEAD GROUNDS RUNNING		TEST		
	BETEEN TANKS 6250, 6240, 6213, ETC.	✓			
	MUCH EXPOSED, FLYAWAY INSULATION				
	MOUSEWOOL OVER ANOTHER LINE				
	INCLUDES LINES ON GROUND WHERE				
	THEY HAVE BEEN WALKED ON				
	LINES CONTINUE THROUGH ALL 6200 SERIES TANKS				
IN 4	AROUND 6100 SERIES TANKS		TEST		
	EXPOSED INSULATION				
	NEAR 174.				

* - DENOTES AREA NEEDING PROMPT ATTENTION.
CONTACT HH PRICE @ 2953 TO COORDINATE ACTIVITIES

UCC 008445
Published by AsbestosClaims.Law
asbestosclaims.law/library/183472

Union Carbide trial exhibit UC-3621: S. B. Kovach to L. C. Stewart Transmitting SHARE Inspection Results, South...
ACL Doc 18347 · Page 3 of 4

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title MICC/UICC | Dept. No. 121 | Location TANK FARM | Date of Inspection 5-6-87

Inspector Submitting Report HH PRICE SBK | Phone No. 2953 2411 | Inspection Responsibility INSULATION | Date of Report 5-6-87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Date Correct	Shop Ord. Number
IN 5	FIRE EXIT ONLY STAIRWELLS NEED SIGN AT FOOT OF STAIRS TO PREVENT USAGE FROM STREET LEVEL TO 6100 SERIES TANK FARM				195213
IN 6	NEW INS. NOT WEATHER SEALED NEAR 6227 TANK - TOP LEVEL ? 6236	✓			
IN 7 *	INSULATION EXPOSED, WEATHERED, LAYING ON GRATING - NEAR 17Y EAST SIDE TOP LEVEL. CLOSE TO 6236 TANK	✓			
IN 8	TANK 6240 -- TOP OF TANK NEEDS WEATHER BARRIER BEFORE INSULATION IS TOTALLY LOST. FIXABLE NOW. SOME EXPOSED INSULATION	✓	TEST + FIX/REMOVE		
IN 9 *	B.208 STRUCTURE ON TOP - EVAPORATOR EXPOSED INSULATION OLD & NEW. ↓ WEATHERED - FALLING TO GROUND ENTIRE AREA	✓	TEST + FIX/REMOVE		

* SEE 1 OF 3

UCC 008446
Published by AsbestosClaims.Law
asbestosclaims.law/library/183473

Union Carbide trial exhibit UC-3621: S. B. Kovach to L. C. Stewart Transmitting SHARE Inspection Results, South...
ACL Doc 18347 · Page 4 of 4

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title: MILL / UICC | Dept. No.: 121 | Location: TANK FARM | Date of Inspection: 5-6-87

Inspector Submitting Report: H H PRICE SBK | Phone No.: 2953 2411 | Inspection Responsibility: INSULATION | Date of Report: 5-6-87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN 10	EXPOSED INSULATION OVERHEAD - NEAR 6747 - 7035 TANKS	✓			
	8-10' ON LINE				
	MOUSEWOOL ON LINES NT CANTLE - AND SHAFT				
IN 11	086-30 LINE - ENTIRE LENGTH THRU TANK FARM - EXPOSED INSULATION	✓	TEST + FIX		
	INSULATION EXPOSED / FEYAWAY IN NUMEROUS SPOTS				
	INSULATION ON PIPERACK POST NEXT TO 1660				
IN 12	EXPOSED INSULATION OVERHEAD IN ROCK BY 1635 T/S TANK	✓			
IN 13	EXPOSED INSULATION OVERHEAD SB # WEST OF 1516 ETC. TANK TKS 5915, 599 ETC.	✓	TEST + FIX.	6/11/87	

* UCC 008447

* SEE 1 OF 3

Published by AsbestosClaims.Law
asbestosclaims.law/library/183474