

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

August 12, 1987

TO: D. H. Ott

CC: B. N. Gliatta*
M. J. Shoger*

Re: SHARE Inspection Results

Dear Dave:

You will find attached a copy of the findings from the SHARE inspection held August 12, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

Steve K.

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Sep. 12, 1987)	60 Days (Oct. 12, 1987)	90 Days (Nov. 12, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: B. N. Gliatta - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment

*Copy of letter only

UCC 008474

Union Carbide trial exhibit UC-3629: S. B. Kovach to D. H. Ott Transmitting SHARE Inspection Results, with Audit T...
ACL Doc 18355 · Page 2 of 2

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title Phase 4 Polyols | Dept. No. 10600 | Location 196 | Date of Inspection 8/12/82

Inspector Submitting Report H. H. Price | Phone No. 3953 | Inspection Responsibility Insulation | Date of Report 8/12/82

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Date Correct	Shop Ord. Number
IN1	Exposed ins. at 127 overhead North. 1st Floor		Patch & Seal		
IN2	Exposed ins. N. No 7 Cat Bed Mix. & N 9 Cat Bed Mix. 1st Floor		Patch & Seal		
IN3	Metal Weather Barrier on N. side & sill Collum Needs Repaired 3rd Land Condensate Blowing on it		Repair		
INA	Evaporator Top Stairs East End Needs Repairs		Repair		
IN5	Exposed Unibestos West Elect Switch Rack West 22'	✓	Remove & Replace		

UCC 008475
Published by AsbestosClaims.Law
asbestosclaims.law/library/18355/2