PLAINTIFF'S EXHIBIT

UC-3630

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

August 19, 1987

TO: J. C. Ketcham

CC: S. W. Drake*
M. J. Shoger*

Re: SHARE Inspection Results

Dear Jan:

You will find attached a copy of the findings from the SHARE inspection held August 19, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Sep. 19, 1987)	60 Days (Oct. 19, 1987)	90 Days (Nov. 19, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: S. W. Drake - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment

*Copy of letter only

UCC 008476

Union Carbide trial exhibit UC-3630: S. B. Kovach to J. C. Ketcham Transmitting SHARE Safety Inspection Results...
ACL Doc 18356 · Page 2 of 3

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title Oxide Adducts | Dept. No. 109 | Location 36 N. Structure | Date of Inspection 8-19-87

Inspector Submitting Report H H Price | Phone No. 2953 | Inspection Responsibility Insulation | Date of Report 8-19-87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Date Correct	Shop Ord. Number
IN 1	Exposed Ins West end structure ground Floor Up in Rack	✓	Patch & Seal		
IN 2	Exposed Ins in Rack 1st Floor inbetween 96/5 & 96A & Entire Length Structure	✓	Patch & Seal		
* IN 3	Exposed Asbestos N. 9775	✓	Strip & Replace		
* IN 4	No 5 Still Col and Lines	✓	Strip & ~~Redo~~ Insulate at Sch.		
* IN 5	Exposed ins West of No 4 & 5 Reactors along Walkway N. & S.	✓	Patch & Seal		

UCC 00847

Published by AsbestosClaims.Law
asbestosclaims.law/library/18356/2

Union Carbide trial exhibit UC-3630: S. B. Kovach to J. C. Ketcham Transmitting SHARE Safety Inspection Results...
ACL Doc 18356 · Page 3 of 3

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title Chloride Addducts | Dept. No. 169 | Location 36 N. Structure | Date of Inspection 5/18/87

Inspector Submitting Report H H Price | Phone No. 7953 | Inspection Responsibility Insulation | Date of Report 5/19/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Date Correct	Shop Ord. Number
IN6	Exposed Ins So. Side Structure 2nd Land. ~~Rack~~	✓	Strip Parted Metal & Patch		
* IN7	Rack N. S. End of Bridge Unbestos (Ins Laying in Rack)	✓	Strip & Reinstate		
* IN8	Exposed Ins in Rack East of West Between River & Structure in Bad Shape	✓	Patch & Seal		
IN9	Exposing on Landing at N. S Rack East End Structure	✓	Patch & Seal		
* IN10	Exposed Asbestos Walkway Rt side going Pipe Rack East of structure 2nd Land	✓	Seal & Patch		

* Asbestos.

UCC 008478

Published by AsbestosClaims.Law
asbestosclaims.law/library/18356/3