April 25, 1932.

MILL FOREMEN:-

USE OF RESPIRATORS

All of the workmen in the Baghouse and at No.11 and No. 2-3 System Bates Packers must wear respirators.

The shift foremen will be held responsible for having their workmen wear respirators at all times during the following operations:

1. Shaking stockings in all Baghouses.
2. Packing at No.11 and No.2-3 System Bates Packers.
3. Refeeding at No.11 while the Bates Packers are in operation.
4. All other locations where there is excessive dust for workmen (Subject to judgment of foreman.)

The Foremen and workmen who do not follow these instructions will be subject to immediate discharge.

O.B. WESTMONT
Supt. of Mills.

OBW:AB

Published by AsbestosClaims.Law
asbestosclaims.law/library/11776/1