8/12/76 ✓

DON'T USE
DISCONTINUED

U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved
OMB No. 44-R1387

# MATERIAL SAFETY DATA SHEET

## SECTION I

| MANUFACTURER'S NAME | EMERGENCY TELEPHONE NO. |
|---|---|
| Johns-Manville Corp. and Subsidiaries | 303/770-1000 Ext. 2252 |

ADDRESS (Number, Street, City, State, and ZIP Code)
Greenwood Plaza, Denver, Colorado 80217

| CHEMICAL NAME AND SYNONYMS | TRADE NAME AND SYNONYMS |
|---|---|
| Asphalt saturated & Coated asbestos felt | 7700 Weatherproofing Jacket |
| CHEMICAL FAMILY | FORMULA |
| | |

## SECTION II - HAZARDOUS INGREDIENTS

| PAINTS, PRESERVATIVES, & SOLVENTS | % | TLV (Units) | ALLOYS AND METALLIC COATINGS | % | TLV (Units) |
|---|---|---|---|---|---|
| PIGMENTS | | | BASE METAL | | |
| CATALYST | | | ALLOYS | | |
| VEHICLE | | | METALLIC COATINGS | | |
| SOLVENTS | | | FILLER METAL PLUS COATING OR CORE FLUX | | |
| ADDITIVES | | | OTHERS | | |
| OTHERS | | | | | |

| HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES | % | TLV (Units) |
|---|---|---|
| Chrysotile Asbestos Fiber | 60 | |
| (Fiber is firmly bound in product by asphalt saturant) | | |
| | | |
| | | |

## SECTION III - PHYSICAL DATA

| | | | |
|---|---|---|---|
| BOILING POINT (°F.) | | SPECIFIC GRAVITY ($H_2O$=1) | |
| VAPOR PRESSURE (mm Hg.) | | PERCENT, VOLATILE BY VOLUME (%) | |
| VAPOR DENSITY (AIR=1) | | EVAPORATION RATE (_____ =1) | |
| SOLUBILITY IN WATER | | | |

APPEARANCE AND ODOR Asphalt coated asbestos felt

## SECTION IV - FIRE AND EXPLOSION HAZARD DATA

| FLASH POINT (Method used) | FLAMMABLE LIMITS | Lel | Uel |
|---|---|---|---|
| N/A | | | |

EXTINGUISHING MEDIA

SPECIAL FIRE FIGHTING PROCEDURES

UNUSUAL FIRE AND EXPLOSION HAZARDS



(Continued on reverse side)



*Johns-Manville Material Safety Data Sheet for 7700 Weatherproofing Jacket (1976)*
ACL Doc 24031 · Page 1 of 2
Published by AsbestosClaims.Law
asbestosclaims.law/library/24031/1

## SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE
See attached Federal Register of 6/7/72

EFFECTS OF OVEREXPOSURE
N/A - Field tests have demonstrated that asbestos fiber is firmly bound in the product and fibers over TLV are not released during any reasonably foreseeable use.

EMERGENCY AND FIRST AID PROCEDURES

## SECTION VI - REACTIVITY DATA

| | | | |
|---|---|---|---|
| STABILITY | UNSTABLE | | CONDITIONS TO AVOID |
| | STABLE | X | |

INCOMPATABILITY *(Materials to avoid)*

HAZARDOUS DECOMPOSITION PRODUCTS

| | | | |
|---|---|---|---|
| HAZARDOUS POLYMERIZATION | MAY OCCUR | | CONDITIONS TO AVOID |
| | WILL NOT OCCUR | X | |

## SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED
N/A

WASTE DISPOSAL METHOD
Normal good practice.

## SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION *(Specify type)*

| | | |
|---|---|---|
| VENTILATION | LOCAL EXHAUST | SPECIAL |
| | MECHANICAL *(General)* | OTHER |

| | |
|---|---|
| PROTECTIVE GLOVES | EYE PROTECTION |

OTHER PROTECTIVE EQUIPMENT

## SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

OTHER PRECAUTIONS

While the information and recommendations set forth herein are believed to be accurate as of the date hereof, JOHNS-MANVILLE CORPORATION MAKES NO WARRANTY WITH RESPECT THERETO AND DISCLAIMS ALL LIABILITY FROM RELIANCE THEREON.



*Johns-Manville Material Safety Data Sheet for 7700 Weatherproofing Jacket (1976)*
ACL Doc 24031 · Page 2 of 2
Published by AsbestosClaims.Law
asbestosclaims.law/library/24031/2