2/23/78 DISCONTINUED

U. S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved
OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

SECTION I

MANUFACTURER'S NAME	EMERGENCY TELEPHONE NO.
Johns-Manville Corp.	303/978-3118
ADDRESS (Number, Street, City, State, and ZIP Code)	
Ken-Caryl Ranch, Denver, Colorado 80217	
CHEMICAL NAME AND SYNONYMS	TRADE NAME AND SYNONYMS
Asbestos-Calcium Silicate Board	MARINITE #65
CHEMICAL FAMILY	FORMULA

SECTION II HAZARDOUS INGREDIENTS

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					

HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES	%	TLV (Units)
Chrysotile Asbestos Fiber Approx.	55	*
* See attached (29 CFR 1910.1001)		

SECTION III PHYSICAL DATA

BOILING POINT (°F.)		SPECIFIC GRAVITY (H_2O=1)	0.96
VAPOR PRESSURE (mm Hg.)		PERCENT VOLATILE BY VOLUME (%)	
VAPOR DENSITY (AIR=1)		EVAPORATION RATE (_____=1)	
SOLUBILITY IN WATER			

APPEARANCE AND ODOR Grey Solid Sheet - No Odor

SECTION IV FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used)	FLAMMABLE LIMITS	Lel	Uel

EXTINGUISHING MEDIA Non-Flammable

SPECIAL FIRE FIGHTING PROCEDURES

UNUSUAL FIRE AND EXPLOSION HAZARDS

(Continued on reverse side)

Johns-Manville Material Safety Data Sheet for MARINITE #65 (1978)
ACL Doc 24070 · Page 1 of 2
Published by AsbestosClaims.Law
asbestosclaims.law/library/24070/1

SECTION V HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE: See Section II

EFFECTS OF OVEREXPOSURE: Overexposure to excessive concentrations of asbestos fiber may cause pulmonary disease.

EMERGENCY AND FIRST AID PROCEDURES: Avoid breathing excessive dust when cutting, drilling & sanding.

SECTION VI REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	

INCOMPATABILITY *(Materials to avoid)*: None

HAZARDOUS DECOMPOSITION PRODUCTS: None

HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	

SECTION VII SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED: Vacuum clean loose dust and chips. If sweeping is necessary, wet loose material.

WASTE DISPOSAL METHOD: Comply with 40 CFR Chapter 1, Part 61

SECTION VIII SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION *(Specify type)*: NIOSH approved for protection against pneumoconiosis-producing dusts.

VENTILATION: LOCAL EXHAUST: Install ventilation equipment to maintain airborne fiber levels at fabrication operations below TLV.

MECHANICAL *(General)*

OTHER

PROTECTIVE GLOVES

EYE PROTECTION: Recommended during fabricating operations.

OTHER PROTECTIVE EQUIPMENT

SECTION IX SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING: Maintain good housekeeping practices. Vacuum clean or wet down waste when cleaning.

OTHER PRECAUTIONS

While the information and recommendations set forth herein are believed to be accurate as of the date hereof, JOHNS-MANVILLE CORPORATION MAKES NO WARRANTY WITH RESPECT THERETO AND DISCLAIMS ALL LIABILITY FROM RELIANCE THEREON

Johns-Manville Material Safety Data Sheet for MARINITE #65 (1978)
ACL Doc 24070 · Page 2 of 2
Published by AsbestosClaims.Law
asbestosclaims.law/library/24070/2