1972 VOID - PRODUCT DISCONTINUED

U.S. DEPARTMENT OF LABOR
Occupational Safety and Health Administration

Form Approved
OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

SECTION I

MANUFACTURER'S NAME	EMERGENCY TELEPHONE NO.
Johns-Manville Corp.	303/978-3118
ADDRESS (Number, Street, City, State, and ZIP Code) Ken-Caryl Ranch, Denver, Colorado 80217 (P. O. Box 5108)	
CHEMICAL NAME AND SYNONYMS Thermal Insulation	TRADE NAME AND SYNONYMS SUPEREX 2000
CHEMICAL FAMILY	FORMULA

SECTION II - HAZARDOUS INGREDIENTS

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Units)
PIGMENTS			BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					

HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES	%	TLV (Units)
Asbestos Fiber	10	*
Diatomaceous Earth	70	**
*See attached sheet		
**Calculated TLV 8 mppcf or .4 mg/M^3 respirable dust		

SECTION III - PHYSICAL DATA

BOILING POINT (°F.)	NA	SPECIFIC GRAVITY (H_2O=1)	0.4
VAPOR PRESSURE (mm Hg.)	NA	PERCENT, VOLATILE BY VOLUME (%)	NA
VAPOR DENSITY (AIR=1)	NA	EVAPORATION RATE (_____ _____ =1)	NA
SOLUBILITY IN WATER	Slight		
APPEARANCE AND ODOR	Solid block or pipe covering section - off white. No odor.		

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method used)	FLAMMABLE LIMITS	Lel	Uel

EXTINGUISHING MEDIA
Non-flammable

SPECIAL FIRE FIGHTING PROCEDURES

UNUSUAL FIRE AND EXPLOSION HAZARDS

(Continued on reverse side)

Form OSHA-20
Rev. May 72

Johns-Manville Material Safety Data Sheet for SUPEREX 2000
ACL Doc 24080 · Page 1 of 2
Published by AsbestosClaims.Law
asbestosclaims.law/library/24080/1

SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE
See Section II.

EFFECTS OF OVEREXPOSURE
Overexposure to excessive concentrations of airborne dust may cause pulmonary disease.

EMERGENCY AND FIRST AID PROCEDURES

SECTION VI - REACTIVITY DATA

STABILITY	UNSTABLE		CONDITIONS TO AVOID
	STABLE	X	

INCOMPATABILITY *(Materials to avoid)*

HAZARDOUS DECOMPOSITION PRODUCTS

HAZARDOUS POLYMERIZATION	MAY OCCUR		CONDITIONS TO AVOID
	WILL NOT OCCUR	X	

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED
Vacuum clean or damp sweep dust and chips created by fabricating operations.

WASTE DISPOSAL METHOD
Comply with all applicable local, state and federal regulations.

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION *(Specify type)*
NIOSH approved for protection against pneumoconiosis producing dusts.

VENTILATION	LOCAL EXHAUST Recommended at fabricating operations.	SPECIAL
	MECHANICAL *(General)*	OTHER

PROTECTIVE GLOVES	EYE PROTECTION

OTHER PROTECTIVE EQUIPMENT

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING
Maintain good housekeeping practices.

OTHER PRECAUTIONS

While the information and recommendations set forth herein are believed to be accurate as of the date hereof, JOHNS-MANVILLE CORPORATION MAKES NO WARRANTY WITH RESPECT THERETO AND DISCLAIMS ALL LIABILITY FROM RELIANCE THEREON.

Johns-Manville Material Safety Data Sheet for SUPEREX 2000
ACL Doc 24080 · Page 2 of 2
Published by AsbestosClaims.Law
asbestosclaims.law/library/24080/2