0191 2677

R. E. SPRAGUE
PRESIDENT-TREASURER
P. F. ORELUP
VICE PRESIDENT
JAMES E. GALE
SECRETARY

B. D. PIERCE, JR. INC.
THE BRIDGEPORT-CITY TRUST COMPANY BUILDING
955 MAIN STREET
BRIDGEPORT, CONNECTICUT
TELEPHONE 3-3197

INSURANCE
OF ALL KINDS
—
BONDS

May 5, 1936

Mr. Morton F. Judd
Raybestos-Manhattan, Inc.
1427 Railroad Avenue
Bridgeport, Conn.

Dear Mr. Judd:

In regard to the making of a dust count in the weaving room and other places at the Bridgeport and Stratford plant by the engineers of the American Surety Company, they would like very much to have permission to do this next week.

They own a dust counting camera which has been developed by Messrs. Ficklund and Ott. Mr. Ott will be with the engineer of the American Surety Company when the pictures are taken.

We would like very much to have this permission and we would appreciate your advising me upon receipt of this letter.

Very truly yours,

James E. Gale

Secretary

JEG/MM

0487

F128649

Published by AsbestosClaims.Law
asbestosclaims.law/library/13342/1

0191 2690

May 8 1936

LOCATION OF DUST CHECKS

BRIDGEPORT PLANT March 24 1936

Third Floor:

1. Between Looms #319 & #321
2. Between Looms #309 & #313

Second Floor:

3. Between Looms #225 & #227
4. " " " " #224 & #220
5. Next to Loom #9
6. Next to Inspection Bench
7. In Front of Loom #45
8. Between Loom #234 & #236
9. " " " " #238 & #240

First Floor:

10. In front of Loom #83
11. Besides Large Press (Farral & Birmingham)
12. Beside Sander
    Warp Room
13. Between Cob Winders
14. Beside Warping Machine #295
15. " " " " " " #296

STRATFORD PLANT March 24-25 1936

Building #6

1. Mixer #19 & Lead Litharge in Compound Room
2. Beside Mixer #9
3. Between Mixers #11 & #12
4. Next to Opener in Asbestos Room

Building #1

5. Next to Beater #2

Cutting Dept.

6. Beside Press #15
7. " " " " #17
8. Between the Calanders

00485

F 128647

Published by AsbestosClaims.Law
asbestosclaims.law/library/13342/2

0191 2891

STRATFORD PLANT - CONT'D

Sanding Dept.

9. Beside Blanchard #1
10. " " Drill #58
11. " " Cincinnati (Cutting O D)
12. Between Blanchards #4 & #5
13. Beside Boring #4(Cutting I D)
14. Brinell Hardness 100% #150

Molded Brake Dept.

15. Beside Internal Grinder #124
16. " " Belt Sander #123
17. " " Sanding Ends #130
18. " " External Grinding #105
19. " " Multiple Drill #233
20. " " Burring #92
21. " " " " #117

Inspection Dept.

22. Beside 4th Inspector on Bench Facing Shipping Room
23. 8 feet behind #22
24. Tapping Rings

-Lorge D'Olier

F128648

00486

Published by AsbestosClaims.Law
asbestosclaims.law/library/13342/3