PLAINTIFF'S EXHIBIT UC-651

Bob - [illegible]

(1) Meet Wyatt/Clayborn @ Hou... in Delta terminal 7:45 - 8:... Sunday

(2) Take camera, slides, lite... (Pix of sampling equip, sites, personnel, etc.)

(3) Get room and place reserva... tions for Oke City Flight and Baker-Taylor well when you know schedule Wednesday near Houston. (See Note #10)

motel

Cancel Tue. Nite and return to Oke City after Arco at OBI.

(4) Leon Miles is staying at Same Holiday Inn Sunday night. Connect with him for directions to OBI plant Monday morning.

(5) On all applications - watch closely. Make sure material is dumped normally (like in the field.) Simulate close as possible

(6) Make sure flow rates are sufficient to make hopper work right. (Don't want any "blow-back".)

(7) ~~Cancel~~ May run air tests on bag disposal (Talk to Uear

(8) For Baker Taylor - Stay at Canadian Motel in Canadian, Tex. (Call ahead for rooms)

(8)

(9) Bob Newman – General Notes
Keep diary on what goes on. Problems, mechanics etc.

(10) Amoco well in South Texas is scratched. – Harry trying to set one up in Okla. area for Wednesday, 9/27. Call us Monday for an update on this.

(11)

9/21/72

Arco

(1) On site test 9/25 and 9/26 at OEI - 401 Mayo Shell Rd. in Galena Park, Texas. (713+666-0106)

(2) Those present:
Arco - Leon Miles
Arco - Kerr Godfrey
OEI - Bill Taylor
Ucar - John Myers
Ucar - Ed ~~Kleber~~ Kleber
Montello - Bob Newman

(3) Rooms at Holiday Inn I-10 East for 9/24 - 9/25 - 9/26

Myers has car (4) Myers, Clayburn arr. Delta #943 @ 7:52, Newman arr Hous. - Braniff #137 @ 7:45p.

(5) Two days of tests -
A. Start Arco w.s in diesel Fast dump, enclosed & w. th "door" open.
B. Fin. - New granular - in water Fast dump, enclosed & "door" open

(6) OEI burn. all plant, etc. -
Arco pay in full on all diesel trial, matl., disposal, etc.
Mont. pay - land water in and disposal (Can use Arco w111 & Vac truck @ 18.00 - 25.00/hr, no mileage, est. tot. cost @ 150.00 - 200.00)

(7) 60 Arco w.s and 60 N. Gran. S.W.s. in via Nova Air - A/C #1710204 Lv. 9/21/72 @ 1800 - (h.d CME for #)
Blue Bonnet dely car. to Galena Pa

Amoco -

(1) On site test [redacted] 9/27
East of Houston. (Hastings area)

(2) People involved (not necessarily on well)

Tulsa-581-3011 Amoco - Owen Rowley - Safety - Tulsa
Amoco - Bill Franey - "Upstairs" - Tulsa
Amoco - Dan Bee
713+482-7581 Amoco - Maxwell/Blocker (boss) - Hastings area
Amoco - Lynn Camp - Houston, safety (may be on well)

(3) One day test projected 15-20
Air samples during [redacted] bag dumps of New Gram. S.V.'s and S.V.'s (as in making "pills".)

(4) Montello furnish materials only (out of Lk. Chas. stock)

Scratch No well available - 9/22 (Dan Bee

1. Finish Arco & [redacted] to Oke City Tues. Night - 9/26. (Trying for Amoco well in Okla. Area. If can't work it out - go on to Baker & Taylor a day early). -

2. Call us Monday sure for update on this. May have to push Baker & Taylor back to Wednesday and skip Amoco entirely.

Baker & Taylor (thru Harry)

(1) On site Thursday - 9/28 if possible. - Well 7 mi. from Canadian on Perryton Hyway #83.

(2) Those involved (not necessarily on well)
Montello - Wyatt arranged
Baker Taylor - Gayle Goode

(3) One day test simulates building system. Pumping 20-40 sax of Silis and New granular @ nominal rate. (2 hours or so, each batch)

(4) Montello furnish material (40 sax each) out of Okla. City stock. -
Material shipped to:
Baker & Taylor c/o OBI
Canadian, Texas
OBI Store Mgr. is Milford Thompson

A - 9:15 AM
V - 9:20 V

1-714-278-3375

9/28/82

Rhodes - On Site

Ed Kleber

(Repts. to Arco/OLI/Amico/Dr Tay/Mo

Amico - (Simulate No. slope)

I. - Start D.I) (disposal)

shipped 60 ea. (air) A. Arcovis - 30 sx @ 1/min - door open

work like B. - Arcovis - 30 sx @ 1/2min door shut.

req. Hopper (venturi)

II - start water (disposal)

A. - N. Gran. - 30 sx @ 1/min door open.

B. - ~~N. Gran~~ similar 30 sx @ 1/2 min door closed.

1. Low shear to accomodate hi concentration (200-250 bbl. dies. @ 2000# = 15#/bbl)

empty bag (optional std.) Mulle sack dump is done as usual.

2. Same on water.

set sampler before bags. 3. CK build up and decay 20 in - rate for 2-4 hours.

Amoco - (Simulate slugs)

ship 30 ea. Bot - Make sure it's like on rig

1. Looks like 15-20 sx p.i/s @ prox 3-5 min/bag. (Open air)

2. Try for min. # ea. - Sv's and N. Gran. (may be Flosal)

3. Ck Max conc. & decay

Dr Tay - (Simulate building system

ship 40 ea.

1. Build syst. - 20-40 sx ea Sv's & N. Gran. ea (Spread is 2-4 hrs.) Open air.

Lariat on - IMCO test - ~~Lariat~~ trucks

Dry