

III. Complaint Documents

A04153

HAZARDOUS CONDITION REPORT

Rec 6/20/85

Prepare in Triplicate
White & Yellow Copies to Supervisor - Job Hazard Analysis
Pink Copy Retained by Originator — Plant 512
Yellow Copy with Answer to be Returned to Employee through his Supervisor

17.85
Number

To be used in reporting unsafe conditions, requirements for safe job performance, or suggesting safe job procedures. Your interest in submitting this suggestion is appreciated.

To M Collins — Date 6/17/1985
Immediate Supervisor

Hazardous Condition or Suggestion Asbestos dust on floor not stored in plastic bags or containers

Reason Unsafe Health hazards

Received by C M Collins Jr. — Date 6/18/85 — Name [illegible]
Immediate Supervisor — Originator

To W K Meadows — Date 6/18/85
Department Head or Complex Supervisor

I have investigated the above hazardous condition or suggestion and have taken ☐ or recommend ☒ the following action: Have the safety dept. check the area for asbestos dust

Note: Please answer within APPROXIMATELY 7 DAYS.

C. M. Collins Jr.
Immediate Supervisor

To W. D. Boggess — Date 6/18/85
Originator

☒ The following action is being taken The area is [illegible] and will be vacuumed regularly via water filter vacuum. No E.P. equipment has been found any air borne dust from asbestos - We will have them check again.

☐ Your suggestion was reviewed with the Safety Department and we believe that no corrective action is necessary.

W. K. Meadows
Department Head or Complex Supervisor

Form 512-2804E
Revised: 2-24-76

AU4154

I. H. - Has this been covered

in triplicate
White & yellow copies to supervisor
Pink copy retained by originator
Yellow copy with answer to be returned to employee through his supervisor

Department No. 157 HCR/SA No. 157-421

HAZARDOUS CONDITION/SAFETY AWARENESS REPORT

☐ Safety Suggestion	☐ Safety Program	Date: 11-4-86
☐ Potential Injury	☒ Potential Health Hazard	☐ Potential Fire or explosion
☐ Personnel Related	☐ Equipment Related	☐ Potential Equipment Failure
☐ Other Related	☐ Training Required	☒ Potential Environmental Problem

Description Contract insulators stripping asbestos all around Sevin area. No monitoring is being done to insure the employees are not being exposed to higher concentrations of asbestos fibers than what the OSHA standard specifies

L.F. Wilkins
Originator

Analysis/Action (Within 7 Days)
(or reasons why no action is planned) Procedure is being evaluated for revision - however a outside firm will monitor the area November 13-14 1986.

11/8/86
(Date)

C.E. Mooney
(First Line Supervisor)

C.H. Hayden
(Second Line Supervisor)

(Department Head)

If no action is planned:

A04151

(Safety Department)

(Asst. Plant Manager)

Form 512-2804F
Revised 8/5/86