PLAINTIFF'S EXHIBIT
UC-860

120th day - 245 days follow

DAY OFF

Last Day for employers to file quarterly Social Security Tax Return and Wage Report, covering three previous calendar months

Feb X-12
10-7-81 MC

(1) TALKED TO TOM RUCKLE ABOUT TANK 1087 & AGREED TO RUN CHECK FOR DENSITY & ETC
(2) RAN CHECK @ TANK 1087 - THEN WENT TO FIBER T WHERE RAN RAD. SURVEY ON 4 SOME SOURCES
(3) CHECKED MAIL
(4) TALKED TO DOUGLAS ABOUT ABOUT LETTER
(5) WENT TO MAINT. INSTRUMENT SHOP WHERE RAN RAD CHECK ON ANOTHER SEALED SOURCE & TALKED TO TOM WILKERSON ABOUT WORK PROCEDURES IN SHOP
(6) CALLED RUCKLE ABOUT TANK 1087 RESULTS WAND IT REQUIRED TOMORROW
(7) WENT TO LAB TO SEE FOX BUT NOT IN CELLOSIZE TO CHECK TWO RAD SOURCES BUT NEED TO STOP DUE TO PAIN
(8) SAW DR. SEXTON & MET BOB LEVEP OF OWENS CORNING — TALKED TO LATER ABOUT DUST ANALYSIS & SAMPLING TECHNIQUES AGREED TO PROVIDE COPIES OF CURRENT & TO TALK TO RESPONSIBLE ABOUT METHOD
(9) TALKED TO CHARLIE CRAWFORD ABOUT TAICH LETTER AND DESIRE TO CLOSE OUT CONDITION
(10) TALKED TO BOARD ABOUT COMMITTEE ROSTER & TRIP TO AIHA.
(11) STRAIGHTEN OUT A.P. FILE
(12) WORKED TO DO [illegible] CHART V.P. WILKERSON

AU2000

worked on Maint Instrument Shop Lighting Problem.

Wednesday, May 1, 1963

121st day – 244 days follow

[illegible] 7:30 TRY [illegible]

[illegible] to Bob Ruckle about check of Tank 1087.

[illegible] Two Rad Sources @ Cellasite

[illegible] to Slover who could not meet until 11:00

[illegible] Leo for a rearranged meeting for 12:00

Guy Arbaugh about Supinger Simple In his office

[illegible] to Bob Estep of Current Cooling & set up Meeting

[illegible] & W.A. Lotz for May 16th @ 10:00

[illegible] Ketchum & Discussed Sealed Sources, A.I.N.A. Meeting

called Tom Wilkinson for Info. On Type of Work In Instrument Shop Areas.

Talked to Bill Mollahan About Continuous Samples for [illegible]

called Dick Rozier for Info. on Hen House

talked to John Perkins About Down Time on Geo. Expo. Suggested I contact Paul Laine - Laine not In

Talked to Dr Sexton About Checking Simplified Dart Forms.

Met with Geo Fox & Discussed Hal Sandling, has Request for Meeting with T.C. Whitson

talked to Earl Bates About Summ. Requests for Extra Help & Arranged for Him To Meet T.C. Whitson When He Arrives

called Ind To Relate About Whitson But He Is In Conf with Ed Slover & Set up To Check on Personnel Matters

Folder X-14

Thursday, May 16, 1963 K-7-81 M

136th day – 229 days follow

ARR 7:30 TRC

(1) Called Maurice Eisminger for DC Lt Alleg Benzene Unit & Coal Pit Research

(2) Contacted Ed Slover About Residues @ New Alky Recycle Unit

(3) Talked To Jerri About Running Copies of Tox Data

(4) " " Doug Ross About Recent Visit Friday

(5) " " Patricia About Hel Check @ Looking At I.R. Alkyl Benzene Check

(6) Called Fleet Woods For Info. On New Alkyl Benzene Unit Startup

(7) Talked to Fred Williams About Lunch & Lounge

(8) L" " " Walsh About General Living H

(9) Met With William Tate & Bob Ritter & Dennis Corning Co & Discussed Dust Tech For Air Analysis

(10) Talked to Kenneth About Lunch & Conference

(11) Checked With Hazel About Residue Test & Gave Her My Report & Rad Reports Plus Tox Data to Copy

(12) Checked With Doug Ross & Pete Wilson About State Gov. Visit Tomorrow

(13) Called to IND about

APPENDIX II

TEST DATA

ATMOSPHERIC DUST CONCENTRATION DATA

	Experimental Pan Coat (Calp. Blocks)			Std. 4-in. Tectum Board	Std. 4-in.
	1-AT	2-AT	3-AT*	4-AT	5-AT
Concentration in ppcf of Air					
Dried at 250F	110.0	19.9	16.4	34.2	52.0
Conditioned at 70% RH, 70F	39.3	14.0	47.1	15.8	36.4
Conditioned at 95-100% RH, 95F	59.6	20.6	31.4	104.0	97.6
Avg. of three conditions	83.2	15.1	31.6	51.3	62.0
Moisture Absorbed During Conditioning - %					
Dry to 70% RH, 70F	2.7	2.0	2.5	3.8	3.9
Dry to 95-100% RH, 95F	13.6	12.3	17.2	15.8	12.8

*This formulation was used for samples submitted to Union Carbide for evaluation. Refer to formula No. 58, samples 21, 22, 23, Research Report No. [illegible], P 1.

Bob Peale

Published by AsbestosClaims.Law
asbestosclaims.law/library/16071/4