Union Carbide trial exhibit UC-1154: OSHA Violations Report on Asbestos Insulation and Filter Aid Findings, Gener...
ACL Doc 16329 · Page 1 of 2


OSHA VIOLATIONS

Department GENERAL

ASBESTOS

Bldg. No.	Item	Violation No.	Description and Reference	O.T.C. Priority	Department Action Plan
79 North	IMPORTANT	75-5-31	Asbestos insulation from instrument tube bundle piping was noted on the grating. To reduce air borne asbestos fibers, asbestos insulation should be wet down and stored in sealed containers such as plastic bags. 1910.93 (a) (c) Page 23543.	A	
79 Struct 80-A	IMPORTANT	75-5-33	Asbestos insulation was noted on the floor at No. 4 steam drum where level alarm maintenance work was in progress. To reduce airburne asbestos fibers, asbestos insulation should be wet down and stored in sealed containers, such as plastic bags. 1910.93 (a) (c) (2) Page 23543.	A	
17 2nd Level	IMPORTANT	75-5-87	Asbestos insulation was noted on the grating near Organic Recovery Column. To prevent airborne asbestos fibers, asbestos insulation should be wet and stored in sealed containers such as plastic bags. 1910.93 (a) (c) (2) Page 23543.	A	
152 South Side	IMPORTANT	75-5-360	Asbestos insulation removed from piping at HTM pumps, west side, was noted to be dry, to be placed in plastic bags which were over-filled and open. Asbestos insulation should be handled wet to reduce airborne asbestos fiber exposure and should be sealed in containers such as the provided plastic bags. 1910.93 (a) (c) (2) Page 23543.	A	

UCTC 19839



Published by AsbestosClaims.Law
asbestosclaims.law/library/16329/1

OSHA VIOLATIONS

Department GENERAL

ASBESTOS

Bldg. No.	Item	Violation No.	Description and Reference	O.T.C. Priority	Department Action Plan
122	IMPORTANT	75-5-416	John Mansfield Hyglo Super-Cell filter aid was noted on approximately 16 bags on a pallet in the area. Asbestos dust hazard signs are posted at the filter aid mixing tank. The filter aid should be cleaned to reduce possibility of airborne asbestos fibers. (1910.93 (a) (c) (2) Page 23543.)	A	

UCTC 19837

Union Carbide trial exhibit UC-1154: OSHA Violations Report on Asbestos Insulation and Filter Aid Findings, Gener...
ACL Doc 16329 - Page 2 of 2
Published by AsbestosClaims.Law
asbestosclaims.law/library/16329/2