PLAINTIFF'S EXHIBIT

UC-1672

Texas Water Quality Board
P.O. Box 13246 Capitol Station
Austin, Texas 78711

Ticket No. 064616

INDUSTRIAL WASTE SHIPPING–CONTROL TICKET

(Please Type or Print Clearly)

PART I: To be completed by Shipper/Generator (see reverse side for instructions)

Company Name: Union Carbide Corp., Materials + Coatings Div.

Business Address: P.O. Box 3370, Brownsville, Tx. 78520

TWQB Registration No.: 3108

Address From Which Shipment Originates:
State Hwy. 48, Port of Brownsville

Emergency Phone: 512-831-4501

DESTINATION:

Receiver's Name: City of Brownsville, Sanitary Land Fill

Business Address: Market Square

Destination (Site) Address: Port of Brownsville, Brownsville Navig. Dist.

TWQB Permit No. (if applicable):

1. WASTE CODE	2. QUANTITY	UNITS*	3. HAZARDOUS PROPERTIES	4. DESCRIPTION
179390	2.5	1 2 **(3)** 4	Asbestos dust	Asbestos-containing insulation
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		

* Circle one: (1) tons; (2) gallons; (3) cubic yards; (4) drums (55 gal.)

SPECIAL INSTRUCTIONS: handle so as not to make dust.

12/19/79
Date of Shipment

The materials described above were consigned to the Carrier named below. I certify (or declare) that the foregoing is true and correct to the best of my knowledge.

Heddy Butler
Signature of Authorized Agent

PART II: To be completed by Carrier/Driver (see reverse side for instructions)

Carrier Name: Brownsville Navigation District

Business Address:

Phone Number: 831-4592

12/19/79
Date Received

I certify (or declare) that the materials in the quantity described above are received by me for shipment to the above destination.

Ramon Arestiaga
Signature of Authorized Agent

PART III: To be completed by Receiver (see reverse side for instructions)

Receiver's Name: City of Brownsville, Sanitary Land fill

Phone Number: 831-3641

Site Address: Port of Brownsville, Brownsville Navig. Dist.

TWQB Permit No. (if applicable):

Receiver's Comments:

12-19-1979
Date Received

I certify (or declare) that the materials in the quantities described in Part I are received by me.

Alvil L. von Ohlen
Signature of Authorized Agent

White - Original Yellow - Carrier Pink - Receiver Green - Shipper's First Copy

BRA 0008

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazardou... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 1 of 785 asbestosclaims.law/library/16757/1

PART I: INSTRUCTIONS TO SHIPPER/GENERATOR (Please Type or Print Clearly)

1. On the first line enter the shipping firm's name and the Texas Water Quality Board assigned solid waste registration number in the spaces provided.
2. Enter the correct business address.
3. Enter the address from which the Waste Shipment originates; if it is the same as the above note "SAME" in this space.
4. Enter a phone number where a company agent may be reached in the event of an emergency.

DESTINATION

5. Enter the receiving company's name and the assigned Texas Water Quality Board Permit number in the spaces provided. For waste disposal well permit numbers, such as "WDW XXX", enter only the last five digits, i.e. "DW XXX".
6. Enter the receiving company's correct business address, (if it is out of Texas be sure to note the State).
7. Enter the point of destination if different from the business address.
   NOTE: If shipping to a County or Municipal Disposal Site, note the name of the county or municipality in the space for company name and the location of the disposal site under point of destination.
8. Complete the waste description table as follows:
   a. In Column (1), enter the assigned Texas Water Quality Board Waste Code which corresponds to each waste that you are shipping. If you need additional spaces to list all of the wastes you are shipping, complete an additional shipping ticket.
   b. In Column (2), Quantity, enter the amount in the first part and circle one number which corresponds to the units of measure: (1) tons; (2) gallons: (3) cubic yards; (4) drums (55 gal.).
   c. In Column (3), Hazardous Properties, enter any known hazardous properties (Toxic, Flammable, Explosive, Corrosive). If none, enter "NONE".
   d. In Column (4), Description, enter the waste description which corresponds to the assigned Texas Water Quality Board Waste Code.
9. Part I must be signed by an authorized representative of the shipper/generator. IMPORTANT: PART II MUST BE SIGNED BY THE CARRIER/DRIVER IN THE PRESENCE OF A SHIPPER'S REPRESENTATIVE PRIOR TO SHIPMENT.
10. Retain the green copy and send the other three copies with the driver.

PART II: INSTRUCTIONS FOR THE CARRIER/DRIVER (Please Type or Print Clearly)

1. Enter the carrier or trucking firm's name and correct business address. If the waste shipper or waste receiver identified in Part I is the owner of the transport vehicle then enter "SAME AS SHIPPER" or "SAME AS RECEIVER", as is applicable.
2. As driver of the transport vehicle you have the responsibility of ensuring that all waste accepted by you arrives at the specified destination.
3. Sign for the shipment in the space provided. Be certain you sign for the shipment in the presence of a shipper's representative. IMPORTANT: IF FOR ANY REASON YOU ARE UNABLE TO CARRY OUT DELIVERY OF THE SHIPMENT, THEN DIAL THE EMERGENCY PHONE NUMBER FOR THE SHIPPER IN PART I.
4. Upon delivery the receiver is to sign in your presence. You are to give him the pink copy, send the white copy back to the shipper, and retain the yellow copy for your records.

PART III: INSTRUCTIONS FOR THE RECEIVER (Please Type or Print Clearly)

1. If for any reason the receiving company is different than that identified in Part I enter the company name, your Texas Water Quality Board Permit number, phone number, and address.
2. Verify that the quantities received are those listed in Part I.
3. Date and sign for receipt of the shipment in the presence of the driver.
4. Retain the pink copy for your records.
5. If the receiver is a County or Municipal Disposal Site, signature for receipt of the waste is the only action required for the purposes of this record.

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazardou... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 2 of 785 asbestosclaims.law/library/16757/2

Texas Water Quality Board
P.O. Box 13246 Capitol Station
Austin, Texas 78711

Ticket No. 064617

INDUSTRIAL WASTE SHIPPING–CONTROL TICKET

(Please Type or Print Clearly)

PART I: To be completed by Shipper/Generator (see reverse side for instructions)

Company Name: Union Carbide Corp., Materials & Coatings Div.

Business Address: P. O. Box 3370, Brownsville, TX 78520

TWQB Registration No.: 3 1 1 0 8

Address From Which Shipment Originates:
State Hwy. 48, Port of Brownsville

Emergency Phone: 512-831-4501

DESTINATION:

Receiver's Name: City of Brownsville, Sanitary Landfill

Business Address: Market Square

Destination (Site) Address: Port of Brownsville, Brownsville Navig. Dist.

TWQB Permit No. (if applicable): 0 1 2 7 3

1. WASTE CODE	2. QUANTITY	UNITS*	3. HAZARDOUS PROPERTIES	4. DESCRIPTION
179390	2.5	1 2 (3) 4	Asbestos Dust	Asbestos - containing insulation
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		

* Circle one: (1) tons; (2) gallons; (3) cubic yards; (4) drums (55 gal.)

SPECIAL INSTRUCTIONS: Handle so as not to make dust

12-19-79
Date of Shipment

The materials described above were consigned to the Carrier named below. I certify (or declare) that the foregoing is true and correct to the best of my knowledge.

L. T. Windel
Signature of Authorized Agent

PART II: To be completed by Carrier/Driver (see reverse side for instructions)

Carrier Name: Brownsville Navigation District

Business Address:

Phone Number: 831-4592

12-19-79
Date Received

I certify (or declare) that the materials in the quantity described above are received by me for shipment to the above destination.

Ramon Martinez
Signature of Authorized Agent

PART III: To be completed by Receiver (see reverse side for instructions)

Receiver's Name: City of Brownsville, Sanitary Landfill

Phone Number: 831-3641

TWQB Permit No. (if applicable):

Site Address: Port of Brownsville, Brownsville Navig. Dist.

Receiver's Comments:

12-19-1979
Date Received

I certify (or declare) that the materials in the quantities described in Part I are received by me.

Adrian von Ahlen
Signature of Authorized Agent

White - Original Yellow - Carrier Pink - Receiver Green - Shipper's First Copy

BRA 0010

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/3

PART I: INSTRUCTIONS TO SHIPPER/GENERATOR (Please Type or Print Clearly)

1. On the first line enter the shipping firm's name and the Texas Water Quality Board assigned solid waste registration number in the spaces provided.
2. Enter the correct business address.
3. Enter the address from which the Waste Shipment originates; if it is the same as the above note "SAME" in this space.
4. Enter a phone number where a company agent may be reached in the event of an emergency.

DESTINATION

5. Enter the receiving company's name and the assigned Texas Water Quality Board Permit number in the spaces provided. For waste disposal well permit numbers, such as "WDW XXX", enter only the last five digits, i.e. "DW XXX".
6. Enter the receiving company's correct business address, (if it is out of Texas be sure to note the State).
7. Enter the point of destination if different from the business address.
   NOTE: If shipping to a County or Municipal Disposal Site, note the name of the county or municipality in the space for company name and the location of the disposal site under point of destination.
8. Complete the waste description table as follows:
   a. In Column (1), enter the assigned Texas Water Quality Board Waste Code which corresponds to each waste that you are shipping. If you need additional spaces to list all of the wastes you are shipping, complete an additional shipping ticket.
   b. In Column (2), Quantity, enter the amount in the first part and circle one number which corresponds to the units of measure: (1) tons; (2) gallons: (3) cubic yards; (4) drums (55 gal.).
   c. In Column (3), Hazardous Properties, enter any known hazardous properties (Toxic, Flammable, Explosive, Corrosive). If none, enter "NONE".
   d. In Column (4), Description, enter the waste description which corresponds to the assigned Texas Water Quality Board Waste Code.
9. Part I must be signed by an authorized representative of the shipper/generator. IMPORTANT: PART II MUST BE SIGNED BY THE CARRIER/DRIVER IN THE PRESENCE OF A SHIPPER'S REPRESENTATIVE PRIOR TO SHIPMENT.
10. Retain the green copy and send the other three copies with the driver.

PART II: INSTRUCTIONS FOR THE CARRIER/DRIVER (Please Type or Print Clearly)

1. Enter the carrier or trucking firm's name and correct business address. If the waste shipper or waste receiver identified in Part I is the owner of the transport vehicle then enter "SAME AS SHIPPER" or "SAME AS RECEIVER", as is applicable.
2. As driver of the transport vehicle you have the responsibility of ensuring that all waste accepted by you arrives at the specified destination.
3. Sign for the shipment in the space provided. Be certain you sign for the shipment in the presence of a shipper's representative. IMPORTANT: IF FOR ANY REASON YOU ARE UNABLE TO CARRY OUT DELIVERY OF THE SHIPMENT, THEN DIAL THE EMERGENCY PHONE NUMBER FOR THE SHIPPER IN PART I.
4. Upon delivery the receiver is to sign in your presence. You are to give him the pink copy, send the white copy back to the shipper, and retain the yellow copy for your records.

PART III: INSTRUCTIONS FOR THE RECEIVER (Please Type or Print Clearly)

1. If for any reason the receiving company is different than that identified in Part I enter the company name, your Texas Water Quality Board Permit number, phone number, and address.
2. Verify that the quantities received are those listed in Part I.
3. Date and sign for receipt of the shipment in the presence of the driver.
4. Retain the pink copy for your records.
5. If the receiver is a County or Municipal Disposal Site, signature for receipt of the waste is the only action required for the purposes of this record.

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazardou... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 4 of 785 asbestosclaims.law/library/16757/4

Texas Water Quality Board
P.O. Box 13246 Capitol Station
Austin, Texas 78711

Ticket No. 064618

INDUSTRIAL WASTE SHIPPING–CONTROL TICKET

(Please Type or Print Clearly)

PART I: To be completed by Shipper/Generator (see reverse side for instructions)

Company Name: Union Carbide Corp., Materials & Coatings Div.

Business Address: P. O. Box 3370, Brownsville, TX 78520

TWQB Registration No.: 3 1 1 0 8

Address From Which Shipment Originates:
State Hwy. 48, Port of Brownsville

Emergency Phone: 512-831-4501

DESTINATION:

Receiver's Name: City of Brownsville, Sanitary Landfill

Business Address: Market Square

Destination (Site) Address: Port of Brownsville, Brownsville Navig. Dist.

TWQB Permit No. (if applicable): 0 1 2 7 3

1. WASTE CODE	2. QUANTITY	UNITS*	3. HAZARDOUS PROPERTIES	4. DESCRIPTION
179390	2.5	1 2 (3) 4	Asbestos Dust	Asbestos - containing insulation
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		

* Circle one: (1) tons; (2) gallons; (3) cubic yards; (4) drums (55 gal.)

SPECIAL INSTRUCTIONS: Handle so as not to make dust

12-15-79
Date of Shipment

The materials described above were consigned to the Carrier named below. I certify (or declare) that the foregoing is true and correct to the best of my knowledge.

L. T. Windel
Signature of Authorized Agent

PART II: To be completed by Carrier/Driver (see reverse side for instructions)

Carrier Name: Brownsville Navigation District

Business Address:

Phone Number: 831-4592

Date Received

I certify (or declare) that the materials in the quantity described above are received by me for shipment to the above destination.

Ramon Martinez
Signature of Authorized Agent

PART III: To be completed by Receiver (see reverse side for instructions)

Receiver's Name: City of Brownsville, Sanitary Landfill

Phone Number: 831-3641

Site Address: Port of Brownsville, Brownsville Navig. Dist.

TWQB Permit No. (if applicable):

Receiver's Comments:

Date Received

I certify (or declare) that the materials in the quantities described in Part I are received by me.

[redacted] Samuel Salinas
Signature of Authorized Agent

White - Original Yellow - Carrier Pink - Receiver Green - Shipper's First Copy

BRA 0012

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/5

PART I: INSTRUCTIONS TO SHIPPER/GENERATOR (Please Type or Print Clearly)

1. On the first line enter the shipping firm's name and the Texas Water Quality Board assigned solid waste registration number in the spaces provided.
2. Enter the correct business address.
3. Enter the address from which the Waste Shipment originates; if it is the same as the above note "SAME" in this space.
4. Enter a phone number where a company agent may be reached in the event of an emergency.

DESTINATION

5. Enter the receiving company's name and the assigned Texas Water Quality Board Permit number in the spaces provided. For waste disposal well permit numbers, such as "WDW XXX", enter only the last five digits, i.e. "DW XXX".
6. Enter the receiving company's correct business address, (if it is out of Texas be sure to note the State).
7. Enter the point of destination if different from the business address.
   NOTE: If shipping to a County or Municipal Disposal Site, note the name of the county or municipality in the space for company name and the location of the disposal site under point of destination.
8. Complete the waste description table as follows:
   a. In Column (1), enter the assigned Texas Water Quality Board Waste Code which corresponds to each waste that you are shipping. If you need additional spaces to list all of the wastes you are shipping, complete an additional shipping ticket.
   b. In Column (2), Quantity, enter the amount in the first part and circle one number which corresponds to the units of measure: (1) tons; (2) gallons: (3) cubic yards; (4) drums (55 gal.).
   c. In Column (3), Hazardous Properties, enter any known hazardous properties (Toxic, Flammable, Explosive, Corrosive). If none, enter "NONE".
   d. In Column (4), Description, enter the waste description which corresponds to the assigned Texas Water Quality Board Waste Code.
9. Part I must be signed by an authorized representative of the shipper/generator. IMPORTANT: PART II MUST BE SIGNED BY THE CARRIER/DRIVER IN THE PRESENCE OF A SHIPPER'S REPRESENTATIVE PRIOR TO SHIPMENT.
10. Retain the green copy and send the other three copies with the driver.

PART II: INSTRUCTIONS FOR THE CARRIER/DRIVER (Please Type or Print Clearly)

1. Enter the carrier or trucking firm's name and correct business address. If the waste shipper or waste receiver identified in Part I is the owner of the transport vehicle then enter "SAME AS SHIPPER" or "SAME AS RECEIVER", as is applicable.
2. As driver of the transport vehicle you have the responsibility of ensuring that all waste accepted by you arrives at the specified destination.
3. Sign for the shipment in the space provided. Be certain you sign for the shipment in the presence of a shipper's representative. IMPORTANT: IF FOR ANY REASON YOU ARE UNABLE TO CARRY OUT DELIVERY OF THE SHIPMENT, THEN DIAL THE EMERGENCY PHONE NUMBER FOR THE SHIPPER IN PART I.
4. Upon delivery the receiver is to sign in your presence. You are to give him the pink copy, send the white copy back to the shipper, and retain the yellow copy for your records.

PART III: INSTRUCTIONS FOR THE RECEIVER (Please Type or Print Clearly)

1. If for any reason the receiving company is different than that identified in Part I enter the company name, your Texas Water Quality Board Permit number, phone number, and address.
2. Verify that the quantities received are those listed in Part I.
3. Date and sign for receipt of the shipment in the presence of the driver.
4. Retain the pink copy for your records.
5. If the receiver is a County or Municipal Disposal Site, signature for receipt of the waste is the only action required for the purposes of this record.

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazardou... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 6 of 785 asbestosclaims.law/library/16757/6

Texas Water Quality Board
P.O. Box 13246 Capitol Station
Austin, Texas 78711

Ticket No. 064619

INDUSTRIAL WASTE SHIPPING–CONTROL TICKET

(Please Type or Print Clearly)

PART I: To be completed by Shipper/Generator (see reverse side for instructions)

Company Name: Union Carbide Corp., Materials & Coatings Div.

Business Address: P. O. Box 3370, Brownsville, TX 78520

TWQB Registration No.: 3 1 1 0 8

Address From Which Shipment Originates:
State Hwy. 48, Port of Brownsville

Emergency Phone: 512-831-4501

DESTINATION:

Receiver's Name: City of Brownsville, Sanitary Landfill

Business Address: Market Square

Destination (Site) Address: Port of Brownsville, Brownsville Navig. Dist.

TWQB Permit No. (if applicable): 0 1 2 7 3

1. WASTE CODE	2. QUANTITY	UNITS*	3. HAZARDOUS PROPERTIES	4. DESCRIPTION
179390	2.5	1 2 (3) 4	Asbestos Dust	Asbestos-containing insulation
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		

* Circle one: (1) tons; (2) gallons; (3) cubic yards; (4) drums (55 gal.)

SPECIAL INSTRUCTIONS: Handle so as not to make dust

12-19-79
Date of Shipment

The materials described above were consigned to the Carrier named below. I certify (or declare) that the foregoing is true and correct to the best of my knowledge.

L. T. Vidal
Signature of Authorized Agent

PART II: To be completed by Carrier/Driver (see reverse side for instructions)

Carrier Name: Brownsville Navigation District

Business Address:

Phone Number: 831-4592

Date Received

I certify (or declare) that the materials in the quantity described above are received by me for shipment to the above destination.

Ramon Martinez
Signature of Authorized Agent

PART III: To be completed by Receiver (see reverse side for instructions)

Receiver's Name: City of Brownsville, Sanitary Landfill

Phone Number: 831-3641

TWQB Permit No. (if applicable):

Site Address: Port of Brownsville, Brownsville Navig. Dist.

Receiver's Comments:

Date Received

I certify (or declare) that the materials in the quantities described in Part I are received by me.

Signature of Authorized Agent

White - Original Yellow - Carrier Pink - Receiver Green - Shipper's First Copy

BRA 0014

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazardou... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 7 of 785 asbestosclaims.law/library/16757/7

PART I: INSTRUCTIONS TO SHIPPER/GENERATOR (Please Type or Print Clearly)

1. On the first line enter the shipping firm's name and the Texas Water Quality Board assigned solid waste registration number in the spaces provided.
2. Enter the correct business address.
3. Enter the address from which the Waste Shipment originates; if it is the same as the above note "SAME" in this space.
4. Enter a phone number where a company agent may be reached in the event of an emergency.

DESTINATION

5. Enter the receiving company's name and the assigned Texas Water Quality Board Permit number in the spaces provided. For waste disposal well permit numbers, such as "WDW XXX", enter only the last five digits, i.e. "DW XXX".
6. Enter the receiving company's correct business address, (if it is out of Texas be sure to note the State).
7. Enter the point of destination if different from the business address.
   NOTE: If shipping to a County or Municipal Disposal Site, note the name of the county or municipality in the space for company name and the location of the disposal site under point of destination.
8. Complete the waste description table as follows:
   a. In Column (1), enter the assigned Texas Water Quality Board Waste Code which corresponds to each waste that you are shipping. If you need additional spaces to list all of the wastes you are shipping, complete an additional shipping ticket.
   b. In Column (2), Quantity, enter the amount in the first part and circle one number which corresponds to the units of measure: (1) tons; (2) gallons: (3) cubic yards; (4) drums (55 gal.).
   c. In Column (3), Hazardous Properties, enter any known hazardous properties (Toxic, Flammable, Explosive, Corrosive). If none, enter "NONE".
   d. In Column (4), Description, enter the waste description which corresponds to the assigned Texas Water Quality Board Waste Code.
9. Part I must be signed by an authorized representative of the shipper/generator. IMPORTANT: PART II MUST BE SIGNED BY THE CARRIER/DRIVER IN THE PRESENCE OF A SHIPPER'S REPRESENTATIVE PRIOR TO SHIPMENT.
10. Retain the green copy and send the other three copies with the driver.

PART II: INSTRUCTIONS FOR THE CARRIER/DRIVER (Please Type or Print Clearly)

1. Enter the carrier or trucking firm's name and correct business address. If the waste shipper or waste receiver identified in Part I is the owner of the transport vehicle then enter "SAME AS SHIPPER" or "SAME AS RECEIVER", as is applicable.
2. As driver of the transport vehicle you have the responsibility of ensuring that all waste accepted by you arrives at the specified destination.
3. Sign for the shipment in the space provided. Be certain you sign for the shipment in the presence of a shipper's representative. IMPORTANT: IF FOR ANY REASON YOU ARE UNABLE TO CARRY OUT DELIVERY OF THE SHIPMENT, THEN DIAL THE EMERGENCY PHONE NUMBER FOR THE SHIPPER IN PART I.
4. Upon delivery the receiver is to sign in your presence. You are to give him the pink copy, send the white copy back to the shipper, and retain the yellow copy for your records.

PART III: INSTRUCTIONS FOR THE RECEIVER (Please Type or Print Clearly)

1. If for any reason the receiving company is different than that identified in Part I enter the company name, your Texas Water Quality Board Permit number, phone number, and address.
2. Verify that the quantities received are those listed in Part I.
3. Date and sign for receipt of the shipment in the presence of the driver.
4. Retain the pink copy for your records.
5. If the receiver is a County or Municipal Disposal Site, signature for receipt of the waste is the only action required for the purposes of this record.

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazardou... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 8 of 785 asbestosclaims.law/library/16757/8

Texas Water Quality Board
P.O. Box 13246 Capitol Station
Austin, Texas 78711

Ticket No. 064620

INDUSTRIAL WASTE SHIPPING–CONTROL TICKET

(Please Type or Print Clearly)

PART I: To be completed by Shipper/Generator (see reverse side for instructions)

Company Name: Union Carbide Corp., Materials & Coatings Div.

Business Address: P. O. Box 3370, Brownsville, TX 78520

TWQB Registration No.: 3 1 1 0 8

Address From Which Shipment Originates:
State Hwy. 48, Port of Brownsville

Emergency Phone: 512-831-4501

DESTINATION:

Receiver's Name: City of Brownsville, Sanitary Landfill

Business Address: Market Square

Destination (Site) Address: Port of Brownsville, Brownsville Navig. Dist.

TWQB Permit No. (if applicable): 0 1 2 7 3

1. WASTE CODE	2. QUANTITY	UNITS*	3. HAZARDOUS PROPERTIES	4. DESCRIPTION
179390	25	1 2 3 4	Asbestos Dust	Asbestos-containing insulation
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		

* Circle one: (1) tons; (2) gallons; (3) cubic yards; (4) drums (55 gal.)

SPECIAL INSTRUCTIONS: Handle so as not to make dust

12-15-79
Date of Shipment

The materials described above were consigned to the Carrier named below. I certify (or declare) that the foregoing is true and correct to the best of my knowledge.

L. T. Windel
Signature of Authorized Agent

PART II: To be completed by Carrier/Driver (see reverse side for instructions)

Carrier Name: Brownsville Navigation District

Business Address:

Phone Number: 831-4592

Date Received

I certify (or declare) that the materials in the quantity described above are received by me for shipment to the above destination.

Ramon Martinez
Signature of Authorized Agent

PART III: To be completed by Receiver (see reverse side for instructions)

Receiver's Name: City of Brownsville, Sanitary Landfill

Phone Number: 831-3641

TWQB Permit No. (if applicable):

Site Address: Port of Brownsville, Brownsville Navig. Dist.

Receiver's Comments:

Date Received

I certify (or declare) that the materials in the quantities described in Part I are received by me.

Samuel Salinas
Signature of Authorized Agent

White - Original Yellow - Carrier Pink - Receiver Green - Shipper's First Copy

BRA 0016

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/9

PART I: INSTRUCTIONS TO SHIPPER/GENERATOR (Please Type or Print Clearly)

1. On the first line enter the shipping firm's name and the Texas Water Quality Board assigned solid waste registration number in the spaces provided.
2. Enter the correct business address.
3. Enter the address from which the Waste Shipment originates; if it is the same as the above note "SAME" in this space.
4. Enter a phone number where a company agent may be reached in the event of an emergency.

DESTINATION

5. Enter the receiving company's name and the assigned Texas Water Quality Board Permit number in the spaces provided. For waste disposal well permit numbers, such as "WDW XXX", enter only the last five digits, i.e. "DW XXX".
6. Enter the receiving company's correct business address, (if it is out of Texas be sure to note the State).
7. Enter the point of destination if different from the business address.
   NOTE: If shipping to a County or Municipal Disposal Site, note the name of the county or municipality in the space for company name and the location of the disposal site under point of destination.
8. Complete the waste description table as follows:
   a. In Column (1), enter the assigned Texas Water Quality Board Waste Code which corresponds to each waste that you are shipping. If you need additional spaces to list all of the wastes you are shipping, complete an additional shipping ticket.
   b. In Column (2), Quantity, enter the amount in the first part and circle one number which corresponds to the units of measure: (1) tons; (2) gallons: (3) cubic yards; (4) drums (55 gal.).
   c. In Column (3), Hazardous Properties, enter any known hazardous properties (Toxic, Flammable, Explosive, Corrosive). If none, enter "NONE".
   d. In Column (4), Description, enter the waste description which corresponds to the assigned Texas Water Quality Board Waste Code.
9. Part I must be signed by an authorized representative of the shipper/generator. IMPORTANT: PART II MUST BE SIGNED BY THE CARRIER/DRIVER IN THE PRESENCE OF A SHIPPER'S REPRESENTATIVE PRIOR TO SHIPMENT.
10. Retain the green copy and send the other three copies with the driver.

PART II: INSTRUCTIONS FOR THE CARRIER/DRIVER (Please Type or Print Clearly)

1. Enter the carrier or trucking firm's name and correct business address. If the waste shipper or waste receiver identified in Part I is the owner of the transport vehicle then enter "SAME AS SHIPPER" or "SAME AS RECEIVER", as is applicable.
2. As driver of the transport vehicle you have the responsibility of ensuring that all waste accepted by you arrives at the specified destination.
3. Sign for the shipment in the space provided. Be certain you sign for the shipment in the presence of a shipper's representative. IMPORTANT: IF FOR ANY REASON YOU ARE UNABLE TO CARRY OUT DELIVERY OF THE SHIPMENT, THEN DIAL THE EMERGENCY PHONE NUMBER FOR THE SHIPPER IN PART I.
4. Upon delivery the receiver is to sign in your presence. You are to give him the pink copy, send the white copy back to the shipper, and retain the yellow copy for your records.

PART III: INSTRUCTIONS FOR THE RECEIVER (Please Type or Print Clearly)

1. If for any reason the receiving company is different than that identified in Part I enter the company name, your Texas Water Quality Board Permit number, phone number, and address.
2. Verify that the quantities received are those listed in Part I.
3. Date and sign for receipt of the shipment in the presence of the driver.
4. Retain the pink copy for your records.
5. If the receiver is a County or Municipal Disposal Site, signature for receipt of the waste is the only action required for the purposes of this record.

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazardo... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 10 of 785 asbestosclaims.law/library/16757/10

TEXAS DEPARTMENT OF WATER RESOURCES
SELF REPORTING SECTION
FIELD OPERATIONS DIVISION
P.O. BOX 13087, CAPITOL STATION
AUSTIN, TEXAS 78711

SHIPPER'S TDWR REGISTRATION NO. 31108

REPORT FOR 08 (Month) 19 79 (Year)

INDUSTRIAL WASTE SHIPMENT SUMMARY

To be completed MONTHLY by shippers of industrial waste and submitted to the TDWR by the 25th of each month for the prior month. Attach additional sheets if necessary. Please type or print in ink. Read instructions before completing this report.

NAME OF SHIPPER: Union Carbide Corp. PHONE: 512-831-4501

BUSINESS ADDRESS: P.O. Box 3378 Brownsville

ZIP: 78520

PAGE 1 OF 1

GROUP ENTRIES BY RECEIVER OR USE SEPARATE SHEET

1 RECEIVER'S PERMIT NO.	2 SHIPPING TICKET NUMBER	3 TDWR WASTE CODE	4 QUANTITY	5 *	6 DATE SHIPPED	7 COMMENTS
12 13 14 15 16	17 18 19 20 21 22	23 24 25 26 27 28	29 30 31 32 33 34	35	36 37 38 39	40 41 42 43 44 45 46 47 48
X	064614	179390	2.5	3	0823	BROWNSVILLE
X	064615	179390	4.5	3	0823	BROWNSVILLE

* Enter one number: (1) tons, (2) gallons, (3) cubic yards, (4) drums (55 gal.)

The foregoing represents all Class I industrial wastes shipped for the above specified report period.

R. L. Windel — 9-14-79

Signature of Authorized Agent — Date

TDWR 0040

BRA 0018

Texas Water Quality Board
P.O. Box 13246 Capitol Station
Austin, Texas 78711

Ticket No. 064615

INDUSTRIAL WASTE SHIPPING–CONTROL TICKET

(Please Type or Print Clearly)

PART I: To be completed by Shipper/Generator (see reverse side for instructions)

Company Name: Union Carbide Corp., Chem + Plastics Div.
Business Address: P.O. Box 3320, Brownsville, Tx. 78520
TWQB Registration No.: 3 1 1 0 8
Address From Which Shipment Originates: State Hwy. 48, Port of Brownsville
Emergency Phone: 512-831-4501

DESTINATION:
Receiver's Name: City of Brownsville, Sanitary Land fill
Business Address: Market Square
Destination (Site) Address: Port of Brownsville, Brownsville Navig. Dist.
TWQB Permit No. (if applicable):

1. WASTE CODE	2. QUANTITY	UNITS*	3. HAZARDOUS PROPERTIES	4. DESCRIPTION
179390	4.5	1 2 ③ 4	Asbestos dust	Asbestos-containing insulation
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		

* Circle one: (1) tons; (2) gallons; (3) cubic yards; (4) drums (55 gal.)

SPECIAL INSTRUCTIONS: Handle so as not to make dust.

8/23/79
Date of Shipment

The materials described above were consigned to the Carrier named below. I certify (or declare) that the foregoing is true and correct to the best of my knowledge.

K. G. Townsend
Signature of Authorized Agent

PART II: To be completed by Carrier/Driver (see reverse side for instructions)

Carrier Name: Brownsville Navigation District
Business Address:
Phone Number: 831-4592

8/23/79
Date Received

I certify (or declare) that the materials in the quantity described above are received by me for shipment to the above destination.

K. G. Townsend Ramon Martinez
Signature of Authorized Agent

PART III: To be completed by Receiver (see reverse side for instructions)

Receiver's Name: City of Brownsville, Sanitary Land fill
Phone Number: 831-3641
Site Address: Port of Brownsville, Brownsville Navig. Dist
Receiver's Comments:
TWQB Permit No. (if applicable):

8/23/79
Date Received

I certify (or declare) that the materials in the quantities described in Part I are received by me.

Signature of Authorized Agent

White - Original Yellow - Carrier Pink - Receiver Green - Shipper's First Copy

BRA 0019

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/12

PART I: INSTRUCTIONS TO SHIPPER/GENERATOR (Please Type or Print Clearly)

1. On the first line enter the shipping firm's name and the Texas Water Quality Board assigned solid waste registration number in the spaces provided.
2. Enter the correct business address.
3. Enter the address from which the Waste Shipment originates; if it is the same as the above note "SAME" in this space.
4. Enter a phone number where a company agent may be reached in the event of an emergency.

DESTINATION

5. Enter the receiving company's name and the assigned Texas Water Quality Board Permit number in the spaces provided. For waste disposal well permit numbers, such as "WDW XXX", enter only the last five digits, i.e. "DW XXX".
6. Enter the receiving company's correct business address, (if it is out of Texas be sure to note the State).
7. Enter the point of destination if different from the business address.
   NOTE: If shipping to a County or Municipal Disposal Site, note the name of the county or municipality in the space for company name and the location of the disposal site under point of destination.
8. Complete the waste description table as follows:
   a. In Column (1), enter the assigned Texas Water Quality Board Waste Code which corresponds to each waste that you are shipping. If you need additional spaces to list all of the wastes you are shipping, complete an additional shipping ticket.
   b. In Column (2), Quantity, enter the amount in the first part and circle one number which corresponds to the units of measure: (1) tons; (2) gallons: (3) cubic yards; (4) drums (55 gal.).
   c. In Column (3), Hazardous Properties, enter any known hazardous properties (Toxic, Flammable, Explosive, Corrosive). If none, enter "NONE".
   d. In Column (4), Description, enter the waste description which corresponds to the assigned Texas Water Quality Board Waste Code.
9. Part I must be signed by an authorized representative of the shipper/generator. IMPORTANT: PART II MUST BE SIGNED BY THE CARRIER/DRIVER IN THE PRESENCE OF A SHIPPER'S REPRESENTATIVE PRIOR TO SHIPMENT.
10. Retain the green copy and send the other three copies with the driver.

PART II: INSTRUCTIONS FOR THE CARRIER/DRIVER (Please Type or Print Clearly)

1. Enter the carrier or trucking firm's name and correct business address. If the waste shipper or waste receiver identified in Part I is the owner of the transport vehicle then enter "SAME AS SHIPPER" or "SAME AS RECEIVER", as is applicable.
2. As driver of the transport vehicle you have the responsibility of ensuring that all waste accepted by you arrives at the specified destination.
3. Sign for the shipment in the space provided. Be certain you sign for the shipment in the presence of a shipper's representative. IMPORTANT: IF FOR ANY REASON YOU ARE UNABLE TO CARRY OUT DELIVERY OF THE SHIPMENT, THEN DIAL THE EMERGENCY PHONE NUMBER FOR THE SHIPPER IN PART I.
4. Upon delivery the receiver is to sign in your presence. You are to give him the pink copy, send the white copy back to the shipper, and retain the yellow copy for your records.

PART III: INSTRUCTIONS FOR THE RECEIVER (Please Type or Print Clearly)

1. If for any reason the receiving company is different than that identified in Part I enter the company name, your Texas Water Quality Board Permit number, phone number, and address.
2. Verify that the quantities received are those listed in Part I.
3. Date and sign for receipt of the shipment in the presence of the driver.
4. Retain the pink copy for your records.
5. If the receiver is a County or Municipal Disposal Site, signature for receipt of the waste is the only action required for the purposes of this record.

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazardo... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 13 of 785 asbestosclaims.law/library/16757/13

Texas Water Quality Board
P.O. Box 13246 Capitol Station
Austin, Texas 78711

Ticket No. 064614

INDUSTRIAL WASTE SHIPPING–CONTROL TICKET
(Please Type or Print Clearly)

PART I: To be completed by Shipper/Generator (see reverse side for instructions)

Company Name: Union Carbide Corp., Chems+Plastics Div.
Business Address: P.O. Box 3370, Brownsville, Tx. 78520
TWQB Registration No.: 31108
Address From Which Shipment Originates: State Hwy. 48, Port of Brownsville
Emergency Phone: 512-831-4501

DESTINATION:
Receiver's Name: City of Brownsville, Sanitary Land Fill
Business Address: Market Square
Destination (Site) Address: Port of Brownsville, Brownsville Navig. Dist.
TWQB Permit No. (if applicable):

1. WASTE CODE	2. QUANTITY	UNITS*	3. HAZARDOUS PROPERTIES	4. DESCRIPTION
179390	2.5	1 2 (3) 4	Asbestos dust	Asbestos-containing insulation
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		
		1 2 3 4		

* Circle one: (1) tons; (2) gallons; (3) cubic yards; (4) drums (55 gal.)

SPECIAL INSTRUCTIONS: handle so as not to make dust.

8/23/79
Date of Shipment

The materials described above were consigned to the Carrier named below. I certify (or declare) that the foregoing is true and correct to the best of my knowledge.

K. L. Townsend
Signature of Authorized Agent

PART II: To be completed by Carrier/Driver (see reverse side for instructions)

Carrier Name: Brownsville Navigation District
Business Address:
Phone Number: 831-4592

Ramon Martinez
Date Received
8/23/79

I certify (or declare) that the materials in the quantity described above are received by me for shipment to the above destination.

Signature of Authorized Agent

PART III: To be completed by Receiver. (see reverse side for instructions)

Receiver's Name: City of Brownsville, Sanitary land fill
Phone Number: 831-3641
Site Address: Port of Brownsville, Brownsville Navig. Dist.
TWQB Permit No. (if applicable):
Receiver's Comments:

8/23/79
Date Received

I certify (or declare) that the materials in the quantities described in Part I are received by me.

Pedro Guevara
Signature of Authorized Agent

White - Original | Yellow - Carrier | Pink - Receiver | Green - Shipper's First Copy

BRA 0021

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/14

PART I: INSTRUCTIONS TO SHIPPER/GENERATOR (Please Type or Print Clearly)

1. On the first line enter the shipping firm's name and the Texas Water Quality Board assigned solid waste registration number in the spaces provided.
2. Enter the correct business address.
3. Enter the address from which the Waste Shipment originates; if it is the same as the above note "SAME" in this space.
4. Enter a phone number where a company agent may be reached in the event of an emergency.

DESTINATION

5. Enter the receiving company's name and the assigned Texas Water Quality Board Permit number in the spaces provided. For waste disposal well permit numbers, such as "WDW XXX", enter only the last five digits, i.e. "DW XXX".
6. Enter the receiving company's correct business address, (if it is out of Texas be sure to note the State).
7. Enter the point of destination if different from the business address.
   NOTE: If shipping to a County or Municipal Disposal Site, note the name of the county or municipality in the space for company name and the location of the disposal site under point of destination.
8. Complete the waste description table as follows:
   a. In Column (1), enter the assigned Texas Water Quality Board Waste Code which corresponds to each waste that you are shipping. If you need additional spaces to list all of the wastes you are shipping, complete an additional shipping ticket.
   b. In Column (2), Quantity, enter the amount in the first part and circle one number which corresponds to the units of measure: (1) tons; (2) gallons: (3) cubic yards; (4) drums (55 gal.).
   c. In Column (3), Hazardous Properties, enter any known hazardous properties (Toxic, Flammable, Explosive, Corrosive). If none, enter "NONE".
   d. In Column (4), Description, enter the waste description which corresponds to the assigned Texas Water Quality Board Waste Code.
9. Part I must be signed by an authorized representative of the shipper/generator. IMPORTANT: PART II MUST BE SIGNED BY THE CARRIER/DRIVER IN THE PRESENCE OF A SHIPPER'S REPRESENTATIVE PRIOR TO SHIPMENT.
10. Retain the green copy and send the other three copies with the driver.

PART II: INSTRUCTIONS FOR THE CARRIER/DRIVER (Please Type or Print Clearly)


1. Enter the carrier or trucking firm's name and correct business address. If the waste shipper or waste receiver identified in Part I is the owner of the transport vehicle then enter "SAME AS SHIPPER" or "SAME AS RECEIVER", as is applicable.
2. As driver of the transport vehicle you have the responsibility of ensuring that all waste accepted by you arrives at the specified destination.
3. Sign for the shipment in the space provided. Be certain you sign for the shipment in the presence of a shipper's representative. IMPORTANT: IF FOR ANY REASON YOU ARE UNABLE TO CARRY OUT DELIVERY OF THE SHIPMENT, THEN DIAL THE EMERGENCY PHONE NUMBER FOR THE SHIPPER IN PART I.
4. Upon delivery the receiver is to sign in your presence. You are to give him the pink copy, send the white copy back to the shipper, and retain the yellow copy for your records.

PART III: INSTRUCTIONS FOR THE RECEIVER (Please Type or Print Clearly)

1. If for any reason the receiving company is different than that identified in Part I enter the company name, your Texas Water Quality Board Permit number, phone number, and address.
2. Verify that the quantities received are those listed in Part I.
3. Date and sign for receipt of the shipment in the presence of the driver.
4. Retain the pink copy for your records.
5. If the receiver is a County or Municipal Disposal Site, signature for receipt of the waste is the only action required for the purposes of this record.

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazardo... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 15 of 785 asbestosclaims.law/library/16757/15

TRASH TO LANDFILL 1979-80



BRA 0023

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/16

LOAD #99

#00180264

35405.

DATE 11/17/89

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

10:05	12/11/89	27020 LB G	GROSS
14:37	11/17/89	9120 LB G	TARE
		17,900	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0032

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
TX D 0 0 8 1 1 4 0 9 2	8 0 2 6 4		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: Nº 00180264

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number:

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number:

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	440	BA	179.00	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible]

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	1	24	87

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
Jose R. Jimenez	J R Jimenez	1	24	87

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year
Miguel S Vargas	Miguel Vargas			

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0033

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0034

LOAD # 99

#0180264

35105

DATE 11/17/89

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

10:05	12/11/89	27020 LB G	GROSS
14:37	11/17/89	9120 LB G	TARE
		17700	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0035

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #99 # 35468

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: TX D 0 0 8 1 1 4 0 9 2
Manifest Document No.: 8 0 2 6 4
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: No 00180264
B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	440	BA	17900	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR # 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	1 2 1 1 8 9

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year
Jose R. Jimenez		1 2 1 1 8 9

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month Day Year
Hermelinda Vargas	Hermelinda Vargas	

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0036

LOAD #100
#3
D01802611
~~25~~ lb.
32 4 lb

DATE 11-17-89

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

10:00	12/11/89	25080 LB G	GROSS
14:34	11/17/89	10860 LB G	TARE
		14,220	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY KYE.

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0037

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
T X D 0 0 8 1 1 4 0 9 2	8 0 2 6 1		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: Nº 00180261
B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	410	BA	14220	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[illegible]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 12/1/87

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: 12/1/87

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date:

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date:

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0038

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0039

4004100
F3
DU 0201
[illegible] lbs
32,460 lbs

DATE 11-17-89

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

10:00	12/11/89	25080 LB G	GROSS
14:34	11/17/89	10860 LB G	TARE
		14220	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY K H

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0040

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	8 0 2 6 1		

3. Generator's Name and Mailing Address Union Carbide Corporation Star Route Box 90 Brownsville, Texas 78521 4. Generator's Phone ( )	A. State Manifest Document Number No 00180261 B. State Generator's ID 31108
5. Transporter 1 Company Name Intersales Equip., Inc.	6. US EPA ID Number C. State Transporter's ID 41317 D. Transporter's Phone 512-831-7288
7. Transporter 2 Company Name	8. US EPA ID Number E. State Transporter's ID F. Transporter's Phone
9. Designated Facility Name and Site Address Harlingen City Landfill South FM 106 Harlingen, Texas	10. US EPA ID Number G. State Facility's ID 1162 H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12 Containers No.	Type	13. Total Quantity	14 Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	410	BA	14220	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above	K. Handling Codes for Wastes Listed Above
PIPE INSULATION & VESSEL INSULATION	"D-81"

15. Special Handling Instructions and Additional Information

DISPOSAL IN ACCORDANCE WITH TDH MSWR-25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[redacted]

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	12	11	79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year	Date
Jose R. Jimenez		12	11	79	

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year	Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year	Date
[illegible] 12-15-79	[illegible]				

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0041

#001[redacted]260 #L000101

#2 35 yds

DATE 11/17/89

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

10:04	12/11/89	27180 LB G	GROSS
14:36	11/17/89	9140 LB G	TARE
		18,040	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo

Form 510

BRA 0042

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Load #101 35 yds.

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law
	T X D 0 0 8 1 1 4 0 9 2	8 0 2 6 0		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: No 00180260

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number:

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number:

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	4.00	BA	1.8040	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

~~If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select~~

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	12	11	89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez		12	11	89

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year
Miguel A Vargas	Miguel A Vargas			

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0043

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0044

DATE 11/17/89

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

10:04	12/11/89	27190 LB G	GROSS
14:36	11/17/89	9140 LB G	TARE
			NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0045

Load #102
#3
#00180267
324 lbs.

DATE 12/13/89

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

14:30	12/11/89	10860 LB G	GROSS
15:08	12/12/89		TARE
			NET
		18120 LB N	
		7260 NET	

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0047

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

Loose #101 35 lbs.

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 6 0

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number No 00180260

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	400	BA	17040	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] generated to the degree I have determined to be [illegible] best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	12 11 79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month Day Year
Jose R. Jimenez	[signature]	12 11 79

18 Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month Day Year
[illegible]	[signature]	

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0046

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #102 32yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 6 7

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 00180267

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13 Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	410	BA	7.260	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 12 18 81

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 12 19 81

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name
Signature
Date: 12 19 81

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0048

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0049

Load # 102
#3
#0170267
32 yds.

DATE 12/12/89

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

14:30	12/11/89	10860 LB G	GROSS
15:08	12/12/89		TARE
			NET

18120 LB N
7260 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0050

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #102 -324B

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 6 7

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: No 00180267

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	4.10	BA	7.260	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	12	17	81

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
Jose R. Jimenez		12	17	81

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0051

Load #103

#1

#5070069

35 yds

DATE 12/13/89

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

15:10	12/12/89		GROSS
14:29	~~12/11/89~~	9180 LB G	TARE
12/12/89		20520 LB N	NET

11340 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0052

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD # 103 354 ds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 80268

2. Page 1 of | Information in the shaded areas is not required by Federal law.

A. State Manifest Document Number № 00180268

3. Generator's Name and Mailing Address
Union CarBide Corporation
Star Route Box 90 Brownsville, Texas 78521

B. State Generator's ID 31108

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	400	BA	11340	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH 25 325.136 (b)(6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

GENERATOR

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 1 21 89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: Month Day Year: 1 21 89

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name
Signature: Kenneth Longacre
Date: Month Day Year: 1 21 89

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0053

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0054

Lane 103

DATE 12/12/89

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

15:10	12/12/89		GROSS
14:29	~~12/11/89~~	9180 LB G	TARE
12/12/89		20520 LB N	NET

11340 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0055

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

LXD# 103 3540's

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 Manifest Document No. 802688

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union CarBide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 00180268

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	100	BA	1.1.34.0	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH 25 325.136 (b)(6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
~~If I am a large quantity generator I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.~~

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez				

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez				

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0056

Load #104
#2
#00180266

35 yds

DATE 12/13/89

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

15:09	12/12/89		GROSS
14:31	~~12/11/89~~	9380 LB G	TARE
	12/12/89	23100 LB N	NET

13720 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 5'0

BRA 0057

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 8.0.2.6.6

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number
Nº 00180266

B. State Generator's ID
31108

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID
1162

H. Facility's Phone
(512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12 Containers No.	Type	13. Total Quantity	14 Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	46D	BA	13720	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH 25 325.136 (b)(6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] XXX [illegible]

GENERATOR

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 12 17 85

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature: [signature]
Date: Month Day Year: 12 17 85

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name:
Signature: [signature]
Date: Month Day Year: 12 18 85

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0058

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0059

DATE 12/12/89

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

15:09	12/12/89		GROSS
14:31	~~12/11/89~~	9380 LB G	TARE
	12/12/89	23100 LB N	NET

13720 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0060

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
T.X.D.0.0.8.1.1.4.0.9.2	8.0.2.6.6		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: No 00180266

B. State Generator's ID: 31108

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

E. State Transporter's ID:

F. Transporter's Phone:

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number:

7. Transporter 2 Company Name:

8. US EPA ID Number:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	4	BA	1372	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH 25 325.136 (b)(6)

16 GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[redacted]

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	12	1	81

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
Jose R. Jimenez		12	1	81

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0061

...MISSION
...Capitol Station
...Texas 78711-3087

Sample Load #1

...se print or type (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	7 9 4 8 6		NP 00579486

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number
7. Transporter 2 Company Name
8. US EPA ID Number
9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

State Transporter's ID 4317
Transporter's Phone 512-831-7288
State Transporter's ID
Transporter's Phone
State Facility's ID 1162
Facility's Phone (512) 425-7902

11A HM	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	330	BA	19.760	P	179390
	b.					
	c.					
	d.					

12. Additional Descriptions for Materials Listed Above
ASBESTOS INSULATION WASTE

13. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

GENERATOR

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	06 02 89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month Day Year
Jose R. Jimenez		06 02 89

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Date

BRA 0062

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. | Manifest Document No.

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address

4. Generator's Phone ( )

A. State Manifest Document Number: № 0057 9486

B. State Generator's ID

5. Transporter 1 Company Name: INTERSTATES EQ. INC | 6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-731-7248

7. Transporter 2 Company Name | 8. US EPA ID Number

E. State Transporter's ID: 41317

F. Transporter's Phone: 512-731-7248

9. Designated Facility Name and Site Address: HARLINGEN CITY LANDFILL South FM 106 Harlingen | 10. US EPA ID Number

G. State Facility's ID: 1462 X

H. Facility's Phone: 423-4830 X

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS), ORM-E, NA 9188, RQ=1 lb		BA		P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: D-81

15. Special Handling Instructions and Additional Information: DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 TAC 325.136(b)(6)

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date

Printed/Typed Name | Signature | Month Day Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0063

TRUCK #2
ASBESTOS
0080270

LOAD #106
35 yds

DATE 1/5/90

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

07:34	01/05/90	23440 LB G	GROSS
08:11	12/19/89	9300 LB G	TARE
		14,140	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 5'3

BRA 0064

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Loop #106 35 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD 000811140927 Manifest Document No. 801827 0

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

A. State Manifest Document Number
No. 801827 0

B. State Generator's ID
1108

C. State Transporter's ID
1317

D. Transporter's Phone 512-831-7288

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID
1162

H. Facility's Phone
(512) 423-4302

11A. HM	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	400	BA	14.14.0	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

GENERATOR

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 10/10/79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 10/12/79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel S Vargas
Date

TWC 0311 (Rev. 01/01/80)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0065

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0066

TRUCK #2
ASBESTOS
00180270

Load #106
35 yds

DATE 1/5/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:34	01/05/90	23440 LB G	GROSS
08:11	12/19/89	9300 LB G	TARE
		14,140	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

[redacted]

BRA 0067

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Loop #106 3545

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD 008114092 | Manifest Document No. 80270

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc. | 6. US EPA ID Number

7. Transporter 2 Company Name | 8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas | 10. US EPA ID Number

A. State Manifest Document Number: NE 0018027
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	400	BA	14 14	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and [redacted]

GENERATOR

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	01 02 79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date
Jose R. Jimenez	[signature]	01 02 79

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0068

TRUCK #2
ASBESTOS
00180270

LOAD #106
35 yds

DATE 1/5/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:34	01/05/90	23440 LB G	GROSS
08:11	12/19/89	9300 LB G	TARE
		14,140	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 5[illegible]

BRA 0069

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Loop # 106 35 yds.

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD 008114092	Manifest Document No. 80-2-7-0	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

A. State Manifest Document Number: No 0018027O
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	400	BA	14.140	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 10/10/17.0

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: 10/12/17.0

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date:

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguez S Vargas
Signature: Miguez S Vargas
Date:

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0070

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0071

TRUCK #2
ASBESTOS
00 80270

Load #106
35 yds

DATE 1/5/90

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

07:34	01/05/90	23440 LB G	GROSS
08:11	12/19/89	9300 LB G	TARE
		14,140	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0072

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Losp# 106 354yds.

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 80270	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: NO 00180270
B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	400	BA	14 14	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and [illegible]

GENERATOR

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	01/05/90

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month Day Year
Jose R. Jimenez		01/05/90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month Day Year

TRANSPORTER

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date Month Day Year

FACILITY

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0073

CA

C

16,420.00+
17,880.00+
12,700.00+
16,240.00+
6,740.00+
7,420.00+
8,580.00+
7,160.00+
8,660.00+
9,140.00+
7,440.00+
8,460.00+
9,260.00+

Total 126,150.50 C

32.00+
35.00+
35.00+
35.00+
32.00+
35.00+
32.00+
35.00+
35.00+
35.00+
32.00+
32.00+
35.00+

C

32.00 x
440. =
14,080.00*

C

C

C

C

BRA 0074



900

0.*

336. *
22.30 =
6,823.8*

BRA 0075

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/60

K#1
00180269
LOAD# 105

DATE 1/5/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

35 yds

07:30	01/05/90	23740 LB G	GROSS
		9300	TARE
		14,440	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0076

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Load # 105 35 yds.

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	8 0 2 6 9		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: No. 00180269
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill, South FM 106 Harlingen, Texas
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	39	BA	1440	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION
K. Handling Codes for Wastes Listed Above: D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

GENERATOR
Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 01 05 90

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: 01 05 90
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date:

FACILITY
19. Discrepancy Indication Space
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date:

TWC-0311 (Rev. 2/01/89) White - original Pink - TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0077

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0078

TRUCK #1
00180269
LOAD # 105

35 yds

DATE 1/5/90

SELLER ☐
BUYER ☐

ADDRESS

CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

07:30	01/05/90	23740 LB 6	GROSS
		9300	TARE
		14,440	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0079

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Load # 105 35 yds.

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 6 9

2. Page 1 of ___ | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

A. State Manifest Document Number: NO 0018269
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	39.0	BA	1440	P	179390
	b.					
	c.					
	d.					

Belia Cortez

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	01	05	90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
Jose R. Jimenez		01	05	90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0080

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazardo... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 65 of 785 asbestosclaims.law/library/16757/65

CA

C

16,420.00+
17,880.00+
12,700.00+
16,240.00+
6,740.00+
7,420.00+
8,580.00+
7,160.00+
8,660.00+
9,140.00+
7,440.00+
8,460.00+
9,260.00+
Total 126,190.00 C

32.00+
35.00+
35.00+
35.00+
32.00+
35.00+
32.00+
35.00+
35.00+
35.00+
32.00+
32.00+
35.00+
C

32.00 x
440. =
14,080.00*

C

C

C

C

BRA 0081



.00

0.*

306. *
22.30 =
6,823.8*

BRA 0082

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/67

1 K #1
Tr
0018026G
LOAD# 105

DATE 1/5/90

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

35 yds

07:30	01/05/90	23740 LB 6	GROSS
		9300	TARE
		14,440	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0083

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load # 105 35 Yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 6 9

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 001802691

B. State Generator's ID 31108

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

	11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
GENERATOR		a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	39	BA	1440	P	179390
		b.					
		c.					
		d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 01 05 79 | Date

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez | Signature | Month Day Year: 01 05 79 | Date

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Month Day Year | Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.
Printed/Typed Name: Miguel Vargas | Signature: Miguel Vargas | Month Day Year | Date

TWC-0311 (Rev. 2/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0084

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line:

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0085

TRUCK #1
00180269
LOAD # 105

DATE 1/5/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

35 yds

07:30	01/05/90	23740 LB G	GROSS
		9300	TARE
		14,440	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

[redacted]

BRA 0086

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load # 105 35 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 8 0 2 6 9

2. Page 1 of _ _ | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number [redacted] 80269
B. State Generator's ID [redacted] 31103
C. State Transporter's ID 4137
D. Transporter's Phone 512-831-7288
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID [redacted] 1162
H. Facility's Phone (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc. | 6. US EPA ID Number
7. Transporter 2 Company Name | 8. US EPA ID Number
9. Designated Facility Name and Site Address: Harlingen City Landfill, South FM 106 Harlingen, Texas | 10. US EPA ID Number

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	39.0	BA	14440	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION
K. Handling Codes for Wastes Listed Above [redacted]

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that the method of treatment, storage or disposal currently available to me which minimizes the present and future threat to human health and the environment is [redacted] a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	01 05 79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials		Date
Printed/Typed Name: Jose R. Jimenez	Signature	Month Day Year: 01 05 79
18. Transporter 2 Acknowledgement of Receipt of Materials		Date
Printed/Typed Name	Signature	Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name	Signature	Date (Month Day Year)

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0087

120x80 274

#1.

Cond #109

35 yds

DATE 1-16-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:13	02/01/90	30720 LB 6	GROSS
13:38	01/15/90	9560 LB 6	TARE
		21,160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0088

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #105 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 7 4 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number No 00180274

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13 Total Quantity	14 Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	445	BA	21.60	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

GENERATOR

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 10 20 79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez | Signature | Date: 10 20 79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas | Signature: Miguel Vargas | Date

TWC 0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0089

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0090

00 80274
#1
Load #109
35 yds

DATE 1-15-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:13	02/01/90	30720 LB G	GROSS
13:38	01/15/90	9560 LB G	TARE
		21,160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY L Fisher

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0091

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #105 35 Yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 80274

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 00180274

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc. | 6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name | 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas | 10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	4.45	BA	24.60	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month Day Year
Belia Cortez		10 20 19.0

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year
Jose R. Jimenez		10 20 19.0

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0092

#3 TRUCK
00180275
LOAD# 110
32yds

DATE 1-15-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:53	02/01/90	16440 LB G	GROSS
13:37	01/15/90	11180 LB G	TARE
		5,260	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY L Fisher

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0093

TEXAS WATER COMMISSION
P.O. Box 13087, Capital Station
Austin, Texas 78711-3087

Load #110 32yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T·X·D·0·0·8·1·1·4·0·9·2 | Manifest Document No. 8·0·2·7·5

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: NO 00180275

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	370	BA	5260	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] to be [illegible] waste [illegible].

GENERATOR

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 02 01 80

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 02 01 80

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.
Printed/Typed Name: Miguel Vargas
Signature
Date

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0094

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0095

#3 TRUCK
0018027S
LOAD# 110
32yds

DATE 1-15-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:53	02/01/90	16440 LB G	GROSS
13:37	01/15/90	11180 LB G	TARE
		5,260	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY L Fisher

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0096

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #110 32yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 8027[illegible]

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc. | 6. US EPA ID Number

7. Transporter 2 Company Name | 8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas | 10. US EPA ID Number

A. State Manifest Document Number [illegible]027
B. State Generator's ID [illegible]1108
C. State Transporter's ID [illegible]1317
D. Transporter's Phone 512-831-7288
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID [illegible]1162
H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	370	BA	5261	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
[illegible] PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
[illegible]

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

2 Loads

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	[signature]	02	01	79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez	[signature]	02	01	79

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0097

#3 Load #107

00180 271

32yds

DATE 1/15/90

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

09:46 01/15/90 26420 LB 6

GROSS

11000 TARE

15,420 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form S10

BRA 0098

TEXAS WATER COMMISSION
P.O. Box 13087, Capital Station
Austin, Texas 78711-3087

LOAD # 107 32 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 7 1 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NO 0018071

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	390	BA	15.420	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[illegible] economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator and have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 01 25 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: Month Day Year 01 25 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD/Facility Yellow-Transporter Green-Generator's first copy

BRA 0099

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0100

#3 Load #107

00180271

32yds

DATE 1/15/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

09:46 01/15/90 26420 LB 6

GROSS	11000
TARE	15,420
NET	

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0101

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD # 107 32 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T.X.D.0.0.8.1.1.4.0.9.2	8 0 2 7 1		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc. — 6. US EPA ID Number

7. Transporter 2 Company Name — 8. US EPA ID Number

9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas — 10. US EPA ID Number

A. State Manifest Document Number: NM 80271
B. State Generator's ID
C. State Transporter's ID
D. Transporter's Phone: 512-831-7285
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	390	BA	15420	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & TRANSITE INSULATION
K. Handling Codes for Wastes Listed Above: 81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	01 15 80

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year
Jose R. Jimenez		01 15 80

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0102

#2: 00180272
Load # 108.
35 yds

DATE 1-15-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:52	02/01/90	18700 LB G	GROSS
13:38	01/15/90	9420 LB G	TARE
		9,280	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY L. Fisher

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0103

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load # 108 354

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 7 2

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number No. 0018027.2

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	4.10	BA	9280	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 02 10 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 02 12 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature
Date

TWC 0311 (Rev. 01/01/90) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0104

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0105

#2 DD180272
Loss #108
35 yds

DATE 1-15-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:52 02/01/90 18700 LB G GROSS

13:38 01/15/90 9420 LB G TARE

9280 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY L. Fisher

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0106

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load # 108 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	8 0 2 7 7		

GENERATOR

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: NE 40102 22
B. State Generator's ID: 160...
C. State Transporter's ID: 1317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	4.10	BA	925.0	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION
K. Handling Codes for Wastes Listed Above: "D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	07 01 19

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year
Jose R. Jimenez		07 01 19

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month Day Year

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0107

#3 Load #107

00180 271

32 yds

DATE 1/15/90

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

09:46 01/15/90 26420 LB G

GROSS

11,000

TARE

15,420

NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0108

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD # 107 32 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T·X·D·0·0·8·1·1·4·0·9·2 | Manifest Document No. 8·0·2·7·1

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

A. State Manifest Document Number No 0018027 1
B. State Generator's ID 31108
C. State Transporter's ID 41317
D. Transporter's Phone 512-831-7288
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID 1162
H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	3.90	BA	15.420	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] to be economically practicable and that the method of treatment, storage or disposal currently available to me minimizes the present and future threat to human health and the environment OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 01 15 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: Month 01 Day 15 Year 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Margaret Vargas
Signature: Miguel Vargas
Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0109

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0110

#3 LOAD #107

001802.71

32yds

DATE 1/15/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

09:46 01/15/90 26420 LB G

GROSS 11000

TARE 15,420

NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0111

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

LOAD # 107 32 yds.

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 8.0.2.7.1

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: № 0018027[illegible]
B. State Generator's ID: [illegible]1108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	390	BA	15420	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: "D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 01 15 90

GENERATOR

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: Month Day Year: 01 15 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

TRANSPORTER

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name:
Signature:
Date: Month Day Year:

FACILITY

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0112

#3 TRUCK
00180275
Load# 110
32 yds

DATE 1-15-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:53	02/01/90	16440 LB G	GROSS
13:37	01/15/90	11180 LB G	TARE
		5,260	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY L Fisher

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0113

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #110 32 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T·X·D·0·0·8·1·1·4·0·9·2	8·0·2·7·5		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: Nº 00180275
B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	3.70	BA	5.260	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I have determined to be the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	02	01	80

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez	J R Jimenez	02	01	80

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
Miguel Vargas	Miguel Vargas			

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0114

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/99

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0115

#3 Truck
00180275
Load# 110
32yds

DATE 1-15-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:53	02/01/90	16440 LB G	GROSS
13:37	01/15/90	11180 LB G	TARE
		5,260	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY L Fisher

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0116

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

LOAD #110 32yds

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 8.0.2.7.5

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: NE 0018027 5

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	370	BA	5261	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR. 25 325.136 (b) (6)

2 Cu yds.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez		0.2	01	7.0

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez		0.2	01	7.0

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0117

20480274

#1.

Coop #109

35 yds

DATE 1-15-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:13	02/01/90	30720 LB 6	GROSS
13:38	01/15/90	9560 LB 6	TARE
		21,160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0118

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #105 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD.0.0.8.1.1.4.0.9.2 | Manifest Document No. 8.0.2.7.4

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 0018024

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14 Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	4.4.5	BA	24.160	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[redacted]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 02 01 80

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Month Day Year: 02 01 80

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature
Date: Month Day Year

TWC 0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0119

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/104

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0120

00-80274
#1
Load #109
35 yds

DATE 1-15-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:13	02/01/90	30720 LB G	GROSS
13:38	01/15/90	9560 LB G	TARE
		21,160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY L. Fisher

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0121

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #109 35 4/8

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 Manifest Document No. 80274
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

A. State Manifest Document Number: NP 00180274
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14 Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	4.4.5	BA	21.60	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez		02	01	90

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez		02	01	90

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0122

#2: 00180272
Load #108.
35 yds

DATE 1-15-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:52 02/01/90 18700 LB G GROSS

13:38 01/15/90 9420 LB G TARE

9,280 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY L. Fisher

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0123

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load # 108 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 7 2

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 0018027 2

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
C. State Transporter's ID 41317
D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:
G. State Facility's ID 1162
H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	4.10	BA	9.280	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible]

GENERATOR

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	10/19/80

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year
Jose R. Jimenez	J R Jimenez	10/19/80

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month Day Year
Miguel Vargas	Miguel Vargas	

TWC 8711 (Rev. 01/84/100) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0124

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/109

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0125

#2 DD180272
Load #108
35 yds

DATE 1-15-90

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

08:52 02/01/90 18700 LB G GROSS

13:38 01/15/90 9420 LB G TARE

9,280 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY L. Fisher

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0126

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load # 108 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 8 0 2 7 2

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

A. State Manifest Document Number: NO. 00180272
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	4.10	BA	9250	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I have determined to be the most practicable method available to me which will minimize the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select [illegible] practicable method currently available to me which minimizes the present and future threat to human health and the environment.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	02	01	79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez		02	01	79

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0127

#00-80298
#3
Insulation
1000 #/13 32yds

DATE 3/5/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:44 03/04/90 23300 LB G

11,100	GROSS
	TARE
12,200	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0128

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

#18 32426.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 80278

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NO 00180278

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	270	BA	22.00	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 03 01 90

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez | Signature | Date: 03 05 90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: Miguel S. Ramos | Signature | Date

GENERATOR / TRANSPORTER / FACILITY

White: TCC Facility - Yellow: Transporter - Green: Generator's first copy

BRA 0129

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/114

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0130

#0017027 8.

DATE 3/5/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

cs # 13

WEIGHED ON CARDINAL SCALES

07:44 03/04/90 23300 LB G

11100	GROSS
12,200	TARE
	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

For— 510

BRA 0131

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type (Form designed for use on elite (12-pitch) typewriter)

Form approved. OMB No. 2050-0039 expires 09-30-81

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 80278 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

A. State Manifest Document Number NO 00180278

4. Generator's Phone ( )

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number
C. State Transporter's ID 41317
D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number
G. State Facility's ID 1162
H. Facility's Phone (512) 423-4302

11A HM	11 US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12 Containers No.	Type	13 Total Quantity	14 Unit Wt/Vol	I Waste No.
	a HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.		DA	[illegible]	P	179390
	b					
	c					
	d					

J Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K Handling Codes for Wastes Listed Above
"D-81"

15 Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.13[illegible] (b) (6)

16 GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez				

TRANSPORTER

17 Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
Jose R. Jimenez				

18 Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

FACILITY

19 Discrepancy Indication Space

20 Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year

TWC-0311 (Rev. 11/01/80) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0132

LOAD # 112
#2
35 yds
00180276

DATE 3/5/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:55	03/04/90	25120 LB G	GROSS
		9280	TARE
		15,840	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0133

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #112 35yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 — Manifest Document No. 18027 76

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: Nº 0018027 6

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc. — 6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name — 8. US EPA ID Number

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	400	BA	15840	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and [illegible] I have made a good faith effort to minimize my waste generation and select [illegible] available to me and that I can afford.

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 03/01/90

GENERATOR

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez — Signature — Date: 03/05/90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date

TRANSPORTER

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: Miguel Vargas — Signature — Date

FACILITY

BRA 0134

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/119

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms.	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0135

LOAD # 112

#2

35 yds

#00150276

DATE 3/5/90

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:55 03/04/90 25120 LB 6

GROSS

9230

TARE

15840

NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0136

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/121

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

LOAD #112 35yds

Form approved. OMB No. 2050-0039; expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	8 0 2 7 6		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales, Equip., Inc.
6. US EPA ID Number:

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

A. State Manifest Document Number: NO 00180276
B. State Generator's ID: 11108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	400	BA	15840	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	02	11	90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez		02	10	90

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0137

#00580278

#3 Insulation

4000 #/13 32 yds

DATE 3/5/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:44 03/04/90 23300 LB 6

11,100	GROSS
12,200	TARE
	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0138

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

#18 32485.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 80278

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: No. 00180278

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	270	BA	22.00	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 03 01 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name: Jose R. Jimenez | Signature | Month Day Year: 03 05 90

18. Transporter 2 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date

Printed/Typed Name: Miguel S. Ramos | Signature | Month Day Year

White - TSD Facility; Yellow - Transporter; Green - Generator's first copy

BRA 0139

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or matorial in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0140

#0017027[illegible]

DATE 3/5/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:44 03/04/90 23300 LB 6

GROSS	11100
TARE	
NET	12,200

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0141

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039 expires 09-30-81

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 80278 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NO 00180278
B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number
C. State Transporter's ID 41317
D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number
G. State Facility's ID 1162
H. Facility's Phone (512) 423-4302

11A HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.		BA	[illegible]	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH NSWR 25 325.13[illegible] (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month Day Year
Belia Cortez		

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date Month Day Year
Jose R. Jimenez		

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name	Signature	Date Month Day Year

TWC-0311 (Rev. 01/01/83) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0142

1000 #111
00180277
#1

3548

DATE 3/5/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

09:35	03/04/90	24380 LB G	GROSS
		9220	TARE
		15,160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0143

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #111 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD 0 0 8 1 1 4 0 9 2 — Manifest Document No. 8 0 2 7 7

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NS 0018027 7 FI

B. State Generator's ID 31108

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	385	BA	15060	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

GENERATOR

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 03 01 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez — Signature — Date: 03 05 90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name — Signature — Date

White - original Pink - TSD Facility Yellow - Transporter Green - Generator's first copy

BRA 0144

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0145

DATE 3/5/90

6000 #111
00180277
#1

SELLER
BUYER
ADDRESS
CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

35yds

09:35 03/04/90 24380 LB G GROSS
9220 TARE
15,160 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0146

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Load #111 35 yds

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	TXD0081140927	802777		

GENERATOR

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: No. 0018027
B. State Generator's ID: 31108

5. Transporter 1 Company Name: Interaales Equip., Inc.
6. US EPA ID Number:
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	335	BA	15.000	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez		12	20	79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez		12	25	79

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0147

LOAD # 112

#2

35 yds

00180276

DATE 3/5/90

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:55	03/04/90	25120 LB G	GROSS
		9220	TARE
		15,840	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0148

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Load #112 35yds

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 Manifest Document No. 18027 6	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: No. 3018027

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID: 4131

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	400	BA	15840	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-84

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] to the best of my knowledge and belief, the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) is true.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 03 01 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: Month Day Year: 03 05 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature
Date: Month Day Year

BRA 0149

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0150

Load # 112

#2

35 yds

#00150276

DATE 3/5/90

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:55 03/04/90 25120 LB 6 GROSS

9220 TARE

15540 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0151

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Load #112 35yds

Form approved. OMB No. 2050-0039; expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 8 0 2 7 6

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number [redacted]

B. State Generator's ID [redacted]

5. Transporter 1 Company Name: Intersales, Equip., Inc. — 6. US EPA ID Number

C. State Transporter's ID 4517

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name — 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas — 10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	400	BA	15840	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above [redacted]

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	03 01 90

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year
Jose R. Jimenez	[signature]	03 03 90

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month Day Year

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0152

DATE 3/5/90

SELLER ☐
BUYER ☐

ADDRESS

CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

09:35 03/04/90 24380 LB G GROSS
9220 TARE
15,160 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0153

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #111 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TX.D.0.0.8.1.1.4.0.9.2	Manifest Document No. 8027.7	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: Nº 0018027 (S)
B. State Generator's ID: 31108 (S)

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	385	BA	15060	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] minimize the quantity [illegible] to human health and the environment; [illegible] a good faith effort to minimize my waste generation and select [illegible]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 03 01 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: Month Day Year: 03 05 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name:
Signature:
Date: Month Day Year:

White-original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0154

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/139

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0155

DATE 3/5/90

600 #111
00180277
#1

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

354 lbs

09:35 03/04/90

24380 LB 6	GROSS
9220	TARE
15,160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0156

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/141

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Load #111 35 yds.

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 80277	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: № 00180277
B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	375	BA	15000	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez		03	05	79

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez		03	05	79

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0157

DATE 3/24/90

SELLER ☐
BUYER ☐

ADDRESS

CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

12:49	03/18/90	27020 LB G	GROSS
14:04	03/04/90	9140 LB G	TARE
		17880	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0158

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/143

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

cond# 115 3548

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 8.0.2.8.0

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 00180280

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	80	BA	17880	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[illegible]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 03 20 90

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 03 20 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date: 03 20 90

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0159

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0160

Asbestos #
Truck 1
Load # 15
35 yds
0018028b

DATE 3/20/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:49	03/18/90	27020 LB G	GROSS
14:04	03/04/90	9140 LB G	TARE
		17,880	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0161

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

load = 115 3545

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	8 0 2 8 0		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

A. State Manifest Document Number: NO 00180280
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	3 5	BA	17880	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 03 20 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: Month Day Year: 03 20 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name:
Signature:
Date: Month Day Year:

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0162

DATE 3/[illegible]/90

SELLER ☐
BUYER ☐

ADDRESS

CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

12:49	03/18/90	27020 LB G	GROSS
14:04	03/04/90	9140 LB G	TARE
		17,880	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0163

TEXAS WATER COMMISSION
P.O. Box 13087, Capital Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

load # 115 3548

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 Manifest Document No. 8.0.2.8.0

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number No 00180280

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	3.80	BA	17.880	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[redacted]

GENERATOR

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 03 20 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 03 20 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date: 03 20 90

TWC-C311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0164

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0165

Asbesto #
Truck 1
Load # 15
35 Yds
0018086

DATE 3/20/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:49	03/18/90	27020 LB G	GROSS
14:04	03/04/90	9140 LB G	TARE
		17,880	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0166

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 80280 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: NO 80280
B. State Generator's ID: 51008
C. State Transporter's ID: TDA1117
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	3	BA	1780	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION
K. Handling Codes for Wastes Listed Above:

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	03	20	79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez		03	20	79

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0167

Asbesto #3
Truck
Load #114
32yds.
00180279

DATE 3/20/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:47	03/18/90	27040 LB G	GROSS
14:03	03/04/90	10620 LB G	TARE
		16,420	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0168

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

LDD 114 38 yds

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	8 0 2 7 9		

GENERATOR

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: Nº 00180279

B. State Generator's ID

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID

D. Transporter's Phone

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID

H. Facility's Phone

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.		BA	18420	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 03 20 79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: Month Day Year: 03 20 79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature
Date: Month Day Year: 03 20 79

BRA 0169

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0170

Sheet 2 of 3
Load #114
32 1/2 T.
UU1672.1

DATE 3/20/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:47	03/18/90	27040 LB G	GROSS
14:03	03/04/90	10620 LB G	TARE
		16420	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0171

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
T X D 0 0 8 1 1 4 0 9 2	8 0 2 7 9		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name — 6. US EPA ID Number
Intersales Equip., Inc.

7. Transporter 2 Company Name — 8. US EPA ID Number

9. Designated Facility Name and Site Address — 10. US EPA ID Number
Harlingen City Landfill
South FM 106 Harlingen, Texas

A. State Manifest Document Number: NO 00180279
B. State Generator's ID:
C. State Transporter's ID:
D. Transporter's Phone:
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID:
H. Facility's Phone:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.		BA	4 1/8	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] I have a large quantity generator certification that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be [redacted] economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, that I have made a good faith effort to minimize my waste generation and select [redacted] practicable method of treatment, storage, or disposal currently available to me and that I can afford.

Printed/Typed Name: Belia Cortez — Signature: [signature] — Month Day Year: 03 07 79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez — Signature: [signature] — Date: Month Day Year: 03 07 79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0172

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/157

Asbesto #3
Truck
Load #114
32 yds.
00180279

DATE 3/20/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:47	03/18/90	27040 LB G	GROSS
14:03	03/04/90	10620 LB G	TARE
		16420	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0173

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/158

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

LOAD 114 38 yds

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 7 9 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number No 00180279

B. State Generator's ID

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID

D. Transporter's Phone

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID

H. Facility's Phone

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.		BA	4RQ 18420	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible]

GENERATOR

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 03 20 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 03 20 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date: 03 20 90

BRA 0174

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/159

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0175

Sheet 3
LXD #114
324 lbs.

DATE 3/20/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:47	03/18/90	27040 LB 6	GROSS
14:03	03/04/90	10620 LB 6	TARE
		16420	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co.. Webb City, Mo.

Form 510

BRA 0176

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 7 9 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

7. Transporter 2 Company Name
8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

A. State Manifest Document Number: NE 00180279
B. State Generator's ID:
C. State Transporter's ID:
D. Transporter's Phone:
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID:
H. Facility's Phone:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.		BA	1 6 4 2 0	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez
Signature:
Month Day Year: 03 15

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: Month Day Year: 03 15 79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name
Signature
Date: Month Day Year

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0177

LOAD #118
#3 32yds
0054/224

DATE 4/10/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:31	04/09/90	17560 LB G	GROSS
15:32	03/19/90	10820 LB G	TARE
		6,740	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0178

LOAD #18 32yds

...ION
...trol Station
...6711-3087

...or type. (Form designed for use on elite (12-pitch) ty... writer.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 4 1 2 2 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

A. State Manifest Document Number NO 00541224

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

B. State Generator's ID

4. Generator's Phone ( )

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	32yds	BA	6.740	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 04/10/8[illegible] — Date

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez — Signature — Month Day: 04/10 — Date

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day — Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name — Signature: Marcos Marquez — Month Day: 04/10 — Date

GENERATOR — Green-Generator's first copy

BRA 0179

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

BRA 0180

DATE 4/10/90

LOAD #113
#3
00541224

32yds

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:31	04/09/90	17560 LB G	GROSS
15:32	03/19/90	10820 LB G	TARE
		6,740	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0181

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

LOAD #118 32yds.

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 41224 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: NO. 001224

B. State Generator's ID: [redacted] 0408

5. Transporter 1 Company Name: Intersales Equip., Inc. | 6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name | 8. US EPA ID Number

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas | 10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	32yds	BA	6.740	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: [illegible]-81"

15. Special Handling Instructions and Additional Information

DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[illegible] large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	04	10	90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez	[signature]	04	10	90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0182

#2 LOAD #117
354 yds.
00541225

DATE 4/10/90

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

08:35 04/09/90 25580 LB G

GROSS
9340 TARE
16,240 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0183

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

1117 354

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 4 1 2 2 5

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

A. State Manifest Document Number NE 0054225

4. Generator's Phone ( )

B. State Generator's ID 31108

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 131

D. Transporter's Phone (512) 881-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	354	BA	10240	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[illegible]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 04 10 90

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature: J R Jimenez
Date: Month Day Year: 04 09 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date: Month Day Year: 04 10 90

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0184

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

BRA 0185

#2 LOAD #117
354 yds.
00541225

DATE 4/10/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:35 04/09/90 25580 LB G — GROSS
9340 — TARE
16,240 — NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0186

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

LOAD #117 354 lb

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. / Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2 / 4 1 2 2 5		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: [illegible] 0041225
B. State Generator's ID: [illegible] 1108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: [illegible] 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	354	BA	1.0240	P	179390
	b.					
	c.					
	d.					

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION
K. Handling Codes for Wastes Listed Above: D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree determined to be economically practicable and that I have selected the practicable method of treatment, storage or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
Celia Cortez	Celia Cortez	04	10	79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
Jose R. Jimenez	[signature]	04	10	79

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0187

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/172

Load #16
#1 35yds.
0054/227

DATE 4/10/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:29	04/09/90	22040 LB G	GROSS
15:31	03/19/90	9340 LB G	TARE
		12,700	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY J. [illegible]

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0188

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #116 — 35 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) — Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No.: 4 1 2 2 7
2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: NP 0054122
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill, South FM 106 Harlingen, Texas
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	35 yds	BA	1.2700	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

GENERATOR

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 2 9 / 0 9 8 0

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date
Printed/Typed Name: Jose R. Jimenez — Signature: J R Jimenez — Month Day Year: 0 9 / 0 9 8 0
18. Transporter 2 Acknowledgement of Receipt of Materials — Date
Printed/Typed Name: — Signature: — Month Day Year: / /

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date
Printed/Typed Name: Miqueas Vargas — Signature: Miqueas Vargas — Month Day Year: 0 9 / 0 9 8 0

TWC-0311 (Rev 11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0189

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

BRA 0190

DATE 4/10/90

SELLER ☐
BUYER ☐

ADDRESS

CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

08:29	04/09/90	22040 LB G	GROSS
15:31	03/19/90	9340 LB G	TARE
		12700	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0191

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #116

35 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 4 1 2 2 7

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 00541227

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen, City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	35 yds	BA	12700	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
~~If a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.~~

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	10	10	79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez		10	10	79

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev.11-06-86)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0192

#1 LOAD #119

35 yds

#00541229

DATE 4/12/90

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

13:05	04/11/90	16340 LB G	GROSS
13:04	04/09/90	8920 LB G	TARE
		7420	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0193

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD # 119 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2	Manifest Document No. 4 1 2 2 9	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: No. 0054122 9

B. State Generator's ID

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	19	BA	7420	P	179390
	b.					
	c.					
	d.					

GENERATOR

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: Month 04 Day 17 Year 79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date: Month Day Year

TWC-0311 (Rev. 11-06-86)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0194

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

BRA 0195

#1 LOAD #119

35 yds

#0054/229

DATE 4/12/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

13:05	04/11/90	16340 LB G	GROSS
13:04	04/09/90	8920 LB G	TARE
		7420	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0196

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/181

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD # 119 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 4 1 2 2 9

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: No 00541229

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	18	BA	7.42	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: "D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible]

GENERATOR

Printed/Typed Name: Belia Cortez | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name: Jose R. Jimenez | Signature | Month Day Year 2 4 [illegible]

18. Transporter 2 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date

Printed/Typed Name | Signature | Month Day Year

TWC-0311 (Rev.11-06-86)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0197

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 80276

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NO 0054122

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) South ORM-E NA 9188 RQ = 1 Lb.		BA		P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name: Jose R. Jimenez | Signature | Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date

Printed/Typed Name | Signature | Month Day Year

BRA 0198

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

BRA 0199

TEXAS WATER COMMISSION
P.O. Box 13087 Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 7 6

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: NO 00541222

B. State Generator's ID: 1108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID: LL62

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) South, ORM-E NA 9188 RQ = 1 Lb.		BA		P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCQRDANCE WITH TDH, MSWR, 25 .325.136 (b) (6)

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Bella Carter | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez | Signature | Date: Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Date: Month Day Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0200

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 7 6 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: № 00541222

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) South ORM-E NA 9188 RQ = 1 Lb.		BA		P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Delia Cortez | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez | Signature | Date: Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Date: Month Day Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0201

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/186

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 6 1 1 4 0 9 2 | Manifest Document No. 00[illegible]6 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NO 00541222

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, ROOF[illegible], SOLID N.O.S. (ASBESTOS) South [illegible] RQ = 1 Lb.					179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
[illegible]

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Delia Cortez | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date
Printed/Typed Name: Jose L. Jim[illegible] | Signature | Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials | Date
Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date
Printed/Typed Name | Signature | Month Day Year

TWC-0311 (Rev.11-06-86)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0202

Load #1 35 yds.
0054227

DATE 4/10/90

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

08:29	04/09/90	22040 LB G	GROSS
15:31	03/19/90	9340 LB G	TARE
		12,700	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0203

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/188

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #116 — 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 4 1 2 2 7

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

A. State Manifest Document Number NE 0054227

B. State Generator's ID 31108

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 5162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	35 yds	BA	1.27.00	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

GENERATOR

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 09/01/79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez — Signature — Date: 09/01/79

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: Miguel Vargas — Signature — Date: 09/01/79

TWC-0311 (Rev'd 1-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0204

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

BRA 0205

DATE 4/10/90

Load #16
#1 35 yds
DDC 11227

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:29	04/09/90	22040 LB G	GROSS
15:31	03/19/90	9340 LB G	TARE
		12700	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0206

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #116

35 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. / Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2 / 4 1 2 2 7		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number [redacted]
B. State Generator's ID [redacted]

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number
C. State Transporter's ID [redacted]
D. Transporter's Phone 512-811-7288

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen, City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number
G. State Facility's ID [redacted]
H. Facility's Phone (512) 421-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	354	BA	12,700	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 10 / 01 / 79

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: Month 10 Day 01 Year 79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name
Signature
Date: Month Day Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0207

#2 LOAD #117
354 yds.
00541225

DATE 4/10/90

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

08:35 04/09/90 25580 LB G

GROSS
9340 TARE
16,240 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City Mo.

Form 510

BRA 0208

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/193

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

1 Load 117 3548

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 Manifest Document No. 41225
2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

7. Transporter 2 Company Name
8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

(512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	354	BA	16240	P	079390
	b.					
	c.					
	d.					

13. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 04/19/79

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez — Signature — Date: 04/09/79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas — Signature: Miguel Vargas — Date: 04/10/79

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0209

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

BRA 0210

#2 LOAD #117

35 Yds.

0054 1225

DATE 4/10/90

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:35 04/09/90 25580 LB G GROSS

9340 TARE

16,240 NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0211

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087
Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

#LOAD 117 354 lb

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	4 1 2 2 5		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Interseales Equip., Inc.
6. US EPA ID Number:

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

A. State Manifest Document Number:
B. State Generator's ID: 5108
C. State Transporter's ID: 5117
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 5162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	354	BA	1.624	P	179390
	b.					
	c.					
	d.					

I. Additional Descriptions for Materials Listed Above
PIPE INSULATION

J. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	12	14	91

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
Jose R. Jimenez		12	14	91

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0212

LOAD #118
#3 32yds
0054/224

DATE 4/10/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

08:31	04/09/90	17560 LB G	GROSS
15:32	03/19/90	10820 LB G	TARE
		6,740	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0213

LOAD #18 32yds

...ION
...trol Station
...0711-3087
...or type. (Form designed for use on elite (12-pitch) ty... writer.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2
Manifest Document No. 4 1 2 2 4
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name
Intersales Equip., Inc.
6. US EPA ID Number

7. Transporter 2 Company Name
8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	32yds	BA	6.740	P	979390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day: 04/10
Date

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Month Day: 04/10
Date

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Month Day
Date

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name
Signature
Month Day: 04/10
Date

GENERATOR | TRANSPORTER | FACILITY

Green-Generator's first co...

BRA 0214

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

BRA 0215

DATE 4/10/90

LOAD #118
#3
0054122 4

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

08:31	04/09/90	17560 LB G	GROSS
15:32	03/19/90	10820 LB G	TARE
		6,740	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0216

TEXAS WATER COMMISSION
P.O. Box T3087, Capitol Station
Austin, Texas 78711-3087

LOAD #18 32yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	4 1 2 2 4		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc. — 6. US EPA ID Number

7. Transporter 2 Company Name — 8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

[redacted] (512) 425-3502

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	32yds	BA	6.740	P	9390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	04 10 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year
Jose R. Jimenez	J R J	04 10 90

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month Day Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0217

#1 LOAD #119

35 yds

#00541225

DATE 4/12/90

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

13:05	04/11/90	16340 LB G	GROSS
13:04	04/09/90	8920 LB G	TARE
		7420	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0218

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD # 119 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) — Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 4 1 2 2 9

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

A. State Manifest Document Number: NO 0054122 9

B. State Generator's ID

C.

D. Transporter's Phone 512 831-7288

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	19	BA	7420	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

GENERATOR

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name: Jose R. Jimenez — Signature — Month Day Year: 3 4 79

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name: Miguel Vargas — Signature — Month Day Year

TWC-0311 (Rev 11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0219

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "X" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

BRA 0220

#1 LOAD #119

35 yds

#00541229

DATE 4/12/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

13:05	04/11/90	16340 LB G	GROSS
13:04	04/09/90	8920 LB G	TARE
		7,420	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0221

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/206

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD # 119 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D .0.0.8.1.1.4.0.9.2	4 1 2 2 9		

GENERATOR

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: No. 0154
B. State Generator's ID: 3110
C. State Transporter's ID: 61317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	18	BA	7.42	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION
K. Handling Codes for Wastes Listed Above: D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name: Belia Cortez | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date
Printed/Typed Name: Jose R. Jimenez | Signature | Month Day Year: 2 4 7 1

18. Transporter 2 Acknowledgement of Receipt of Materials | Date
Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Date: Month Day Year

TWC-0311 (Rev.11-06-86)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0222

LOAD #121
#1 #00263438
35yds

DATE 4/17/90

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

07:26	04/17/90	16180 LB G	GROSS
13:02	04/09/90	9020 LB G	TARE
		7,160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0223

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

LOAD #121 35 yds.

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No.: 6 3 4 3 8

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc. | 6. US EPA ID Number

7. Transporter 2 Company Name | 8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

A. State Manifest Document Number: № 00263438
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	17	BA	7100	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] a small quantity generator, I certify that [redacted]

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez | Signature | Date: Month Day Year 04 07 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0224

LOAD #121
#2 #0026438
35 yds

DATE 4/17/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:26	04/17/90	16180 LB G	GROSS
13:02	04/09/90	9020 LB G	TARE
		7,160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0225

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #121 35 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 3 4 3 8

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number Nº 00263438

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	17	BA	7.1.CO	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 10 17 79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date

TRANSPORTER

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date

FACILITY

BRA 0226

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the **HM** box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0227

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #121 35 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 3 4 3 8

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number Nº 00263438

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	17	BA	7.1.60	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 04 17 80

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date

BRA 0228

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/213

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0229

LOAD #121
#1 #0026438
35yds

DATE 4/17/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:26	04/17/90	16180 LB G	GROSS
13:02	04/09/90	9020 LB G	TARE
		7,160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0230

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Load #121 354 yds.

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 3 4 3 8

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 00263438

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc. — 6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name — 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas — 10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	17	BA	7120	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez — Signature — Date: Month Day Year 01 17 80

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0231

#3 #170
0026349?
32 yds.

DATE 4/18/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:12	04/17/90	19060 LB G	GROSS
13:05	04/09/90	10480 LB G	TARE
		8580	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0232

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #20 32 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T·X·D·0·0·8·1·1·4·0·9·2	6·3·4·3·7		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: Nº 00263437

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number:

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number:

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	16	BA	8580	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: "D-81"

15. Special Handling Instructions and Additional Information

DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[redacted]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year:

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: Month Day Year: 04 17 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature:
Date: Month Day Year:

BRA 0233

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0234

DATE 11/3 F/

SELLER ☐
BUYER ☐

ADDRESS

CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

07:12	04/17/90	19060 LB G	GROSS
13:05	04/09/90	10480 LB G	TARE
			NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0235

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

LOAD #120 3248

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	TXD008114092	63437		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc. | 6. US EPA ID Number

7. Transporter 2 Company Name | 8. US EPA ID Number

9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas | 10. US EPA ID Number

A. State Manifest Document Number: № 00263437
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	16	BA	3530	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: "D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez | Signature | Date: 04/17/80

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Date

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0236

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/221

LOAD #122

DATE 4/18/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

0026440

35 yds

WEIGHED ON CARDINAL SCALES

12:34	04/19/90	17560 LB G	GROSS
14:43	04/17/90	8900 LB G	TARE
		8660	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0237

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD # 122 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved: OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2	Manifest Document No. 6 3 4 4 0	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: NO 00263440
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill, South FM 106 Harlingen, Texas
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. 15. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	18	BA	860	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[illegible]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 04 20 80

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature: J R J
Date: Month Day Year: 04 23 80

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date: Month Day Year:

BRA 0238

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/223

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0239

#1 LOAD #124

DATE 4/19/90

SELLER ☐
BUYER ☐

ADDRESS

CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

12:34	04/19/90	17560 LB G	GROSS
14:43	04/17/90	8900 LB G	TARE
		8660	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0240

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD # 122 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 Manifest Document No. 63440
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

A. State Manifest Document Number: № 00263440
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	18	BA	360	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment. OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 04 23 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: Month Day Year: 04 23 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name:
Signature:
Date: Month Day Year:

TWC-0311 (Rev. 01/01/90) White ... Pink ...

BRA 0241

#3 Load #724
0026344
32yds

DATE 4/18/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:27	04/19/90	18040 LB G	GROSS
14:44	04/17/90	10600 LB G	TARE
		7440	NET

DRIVER ON ☐ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0242

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

COAD #124 32yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 6.3.4.4.4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

GENERATOR

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: No. 0026344

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	16	BA	7440	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 04 12 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: Month Day Year: 04 12 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel S Vargas
Signature
Date: Month Day Year

BRA 0243

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0244

#3 LOAD #124
0026444
32 yds

DATE 4/19/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:27	04/19/90	18040 LB G	GROSS
14:44	04/17/90	10600 LB G	TARE
		7440	NET

DRIVER ON ☐ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0245

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #124 32yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 3 4 4 4

2. Page 1 of — Information in the shaded areas is not required by Federal law.

A. State Manifest Document Number: № 00263444

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

B. State Generator's ID: 31108

4. Generator's Phone ( )

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	16	BA	3440	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select [redacted]

GENERATOR

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 6 12 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 6 12 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name
Signature
Date

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0246

#3 #120
0026343?
32 yds.

DATE 4/18/91

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

07:12	04/17/90	19060 LB G	GROSS
13:05	04/09/90	10480 LB G	TARE
		8580	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0247

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #20 32 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T·X·D·0·0·8·1·1·4·0·9·2 | Manifest Document No. 6343·7

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

A. State Manifest Document Number № 00263437

4. Generator's Phone ( )

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	16	BA	8580	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez | Signature | Date: Month Day Year 04 11 90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: Miguel Vargas | Signature | Date: Month Day Year

BRA 0248

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0249

DATE 4/17/90

SELLER ☐
BUYER ☐

ADDRESS

CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

07:12	04/17/90	19060 LB G	GROSS
13:05	04/09/90	10480 LB G	TARE
			NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0250

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #20 3248

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	TXD008114092	63437		

GENERATOR

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: NO 0026843
B. State Generator's ID: 31108
C. State Transporter's ID: 1317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	16	BA	3550	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION
K. Handling Codes for Wastes Listed Above: "D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year:

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: Month Day Year: 04 17 79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name:
Signature:
Date: Month Day Year:

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0251

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #121 35 Yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	6 3 4 3 8		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number NO 00263438
B. State Generator's ID 31108
C. State Transporter's ID 41317
D. Transporter's Phone 512-831-7288
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID 1162
H. Facility's Phone (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number
7. Transporter 2 Company Name
8. US EPA ID Number
9. Designated Facility Name and Site Address: Harlingen City Landfill, South FM 106 Harlingen, Texas
10. US EPA ID Number

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	17	BA	7160	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION
K. Handling Codes for Wastes Listed Above: D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: Month Day Year 04 17 80

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature
Date: Month Day Year

BRA 0252

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0253

LOAD #121
#1 #00263438
35 yds

DATE 4/17/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:26	04/17/90	16180 LB G	GROSS
13:02	04/09/90	9020 LB G	TARE
		7160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0254

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

LOAD #121 35 yds.

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	6 9 4 3 8		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number NR 00263438
B. State Generator's ID 31108
C. State Transporter's ID 41917
D. Transporter's Phone 512-831-7288
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID 1162
H. Facility's Phone (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number
7. Transporter 2 Company Name
8. US EPA ID Number
9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	17	BA	7140	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: Month Day Year 04 VP 70

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name
Signature
Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0255

#3 Load #724
0026344
32yds

DATE 4/18/90

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

12:27	04/19/90	18040 LB G	GROSS
14:44	04/17/90	10600 LB G	TARE
		7440	NET

DRIVER ON ☐ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0256

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #124 32yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 6.3.4.4.4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number No. 0026344

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	16	BA	7440	P	M179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] the best waste management method that is [illegible] and that I have selected the method which is available to me which minimizes the present and future threat to human health and the environment.

GENERATOR

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 6 12 90

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 6 12 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date

TRANSPORTER

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.
Printed/Typed Name: Miqueas Vargas
Signature: Miqueas Vargas
Date

FACILITY

BRA 0257

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0258

#3 LOAD #124
0026344
32 yds

DATE 4/19/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:27	04/19/90	18040 LB G	GROSS
14:44	04/17/90	10600 LB G	TARE
		7440	NET

DRIVER ON ☐ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0259

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #124 32yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 5 3 4 4 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

A. State Manifest Document Number [redacted]444

B. State Generator's ID [redacted]31108

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S, (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	16	BA	7440	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 12 12 80

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez — Signature — Date: 12 17 80

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name — Signature — Date

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0260

LOAD #121

#1 #0026438

35yds

DATE 4/17/90

SELLER ☐

BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

07:26	04/17/90	16180 LB G	GROSS
13:02	04/09/90	9020 LB G	TARE
		7160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0261

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Load #121 35 yds.

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	6 3 4 3 8		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: NR 00263438
B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	17	BA	7 1 0	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year
Jose R. Jimenez	J R J	04 VP 7 0

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0262

LOAD #121

#2 #0026348

35yds

DATE 4/17/90

SELLER

BUYER

ADDRESS

CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

07:26	04/17/90	16180 LB G	GROSS
13:02	04/09/90	9020 LB G	TARE
		7160	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0263

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #121 35 Yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 3 4 3 8

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NO. 00263438

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	18	BA	7.1 CY	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I have selected the method of treatment, storage or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if no such treatment, storage or disposal is available to me, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: Month 04 Day 17 Year 79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name
Signature
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature
Date: Month Day Year

BRA 0264

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0265

~~#2~~ LOAD# 123
00263441
35yds

DATE 4/19/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:28	04/19/90	18260 LB G	GROSS
07:24	04/18/90	9120 LB G	TARE
		9140	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co Webb City, Mo.

Form 510

BRA 0266

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #123 35 Yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 6 3 4 4 1

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number: No. 00263441

B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number:

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number:

G. State Facility's ID: 1162

H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	18	BA	9140	P	179390
	b.					
	c.					
	d.					

GENERATOR

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 04 23 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez | Signature | Date: 04 23 90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: Miguel Vargas | Signature: Miguel Vargas | Date

BRA 0267

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/252

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0268

EZ LOAD# 123
0026341
35 yds.

DATE 4/19/

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:28	04/19/90	18260 LB G	GROSS
07:24	04/18/90	9120 LB G	TARE
		9140	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0269

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #123 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 3 4 4 1

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 00263441

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	18	BA	9140	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[redacted]

Printed/Typed Name: Belia Cortez | Signature | Month Day Year: 11 23 90

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez | Signature | Date: 11 23 90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Date

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0270

Load #122

DATE 4/18/90

SELLER
BUYER
ADDRESS
CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

12:34	04/19/90	17560 LB G	GROSS
14:43	04/17/90	8900 LB G	TARE
		8660	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0271

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD # 122 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 3 4 4 0

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

A. State Manifest Document Number
№ 00263440

B. State Generator's ID
31108

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

E. State Transporter's ID

F. Transporter's Phone

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	18	BA	8640	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[redacted]

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 06 25 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez | Signature: J R J | Date: Month Day Year: 6 4 23 90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: Mariano Vargas | Signature: Mariano Vargas | Date: Month Day Year

BRA 0272

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the TSD Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0273

#1 LOAD #124

DATE 4/17/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:34	04/19/90	17560 LB G	GROSS
14:43	04/17/90	8900 LB G	TARE
		3660	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0274

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD # 122 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 3 4 4 0 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: № 0026340
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	18	BA	360	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION
K. Handling Codes for Wastes Listed Above: "D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted] waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 12 13 79

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: Month Day Year: 12 13 79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name:
Signature:
Date: Month Day Year:

TWC-0311 (Rev. 01/01/90) White [illegible]

BRA 0275

...MISSION
...Capitol Station
...Texas 78711-3087

Sample

...e print or type (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2	Manifest Document No. 79486	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc. — 6. US EPA ID Number

7. Transporter 2 Company Name — 8. US EPA ID Number

9. Designated Facility Name and Site Address: Harlingen City Landfill
South FM 106 Harlingen, Texas — 10. US EPA ID Number

11A HM	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	330	BA	19.760	P	179390
	b.					
	c.					
	d.					

12. Additional Descriptions for Materials Listed Above — Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 06 02 89

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez — Signature — Month Day Year: 06 02 89 — Date

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year — Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

BRA 0276

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. | Manifest Document No.

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address

4. Generator's Phone ( )

A. State Manifest Document Number: No. 005 79486

B. State Generator's ID

5. Transporter 1 Company Name: INTERSALES EQ. INC

6. US EPA ID Number

C. State Transporter's ID: 41317

D. Transporter's Phone: 512-731-7248

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID: 41317

F. Transporter's Phone: 512-731-7248

9. Designated Facility Name and Site Address: HARLINGEN CITY LANDFILL South FM 106 Harlingen

10. US EPA ID Number

G. State Facility's ID: 1662

H. Facility's Phone: 512-425-4303

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID, N.O.S. (ASBESTOS), ORM-E, NA 9188, RQ=1 LB		BA		P	1179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above: 14 D-81 11

15. Special Handling Instructions and Additional Information: DISPOSAL IN ACCORDANCE WITH TDH MSW2 25 TAC 325.136(b)(6)

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date

Printed/Typed Name | Signature | Month Day Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0277

Trip 2 LOAD# 123
00263441
35yds

DATE 4/19/90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:28 04/19/90 18260 LB G — GROSS

07:24 04/18/90 9120 LB G — TARE

9140 — NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co. Webb City, Mo.

Form 510

BRA 0278

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #123 35 Yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 6 3 4 4 1 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NM 0026344

B. State Generator's ID 311084

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	18	BA	9140	P	M 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 04 23 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez | Signature | Date: 04 23 90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: Mioveas Vargas | Signature: Mioveas Vargas | Date

BRA 0279

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the TSD Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0280

EZ LOAD # 123
0026341
35 yds.

DATE 4/19/

SELLER
BUYER
ADDRESS
CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

12:28	04/19/90	18260 LB G	GROSS
07:24	04/18/90	9120 LB G	TARE
		9140	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0281

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

LOAD #123 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	6 3 6 6 1		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc. — 6. US EPA ID Number

7. Transporter 2 Company Name — 8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

A. State Manifest Document Number: [redacted]
B. State Generator's ID: [redacted] 1103
C. State Transporter's ID: [redacted] 1317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: [redacted] 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	18	BA	9140	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[redacted]

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 04/23/90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez — Signature — Date: Month Day Year: 04/23/90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0282

#3 Load # 125

DATE 4-23-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

06:57	04/25/90	18780 LB G	GROSS
12:59	04/22/90	10320 LB G	TARE
		8460	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0283

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load # 125 32 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T·X·D·0·0·8·1·1·4·0·9·2 | Manifest Document No. 8·0·2·7·6

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 00263446

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	J. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	20	BA	5.460	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
ID-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
~~[illegible] I certify the waste minimization statement identified in 40 CFR 262.27(a) (if I am a large quantity generator) or (b) (if I am a small quantity generator) on this manifest which is available to me and which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select~~

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	04 26 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year
Jose R. Jimenez	J R J	04 26 90

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date Month Day Year
Miguel Vargas	Miguel Vargas	

BRA 0284

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0285

#3 LOAD #125

DATE 4-22-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

06:57	04/25/90	18780 LB G	GROSS
12:59	04/22/90	10320 LB G	TARE
		8460	NET

DRIVER ON ☒ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0286

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Load #125 32yds.

Form approved. OMB No. 2050-0039, expires 09-30-9

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 7 6

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 00263446

B. State Generator's ID 31108

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	20	BA	8460	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[redacted]

GENERATOR

Printed/Typed Name: Belia Cortez | Signature | Month Day Year: 12 6 9

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez | Signature | Date: 12 6 9

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Date

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0287

#2 Load #126

DATE 4-23-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

06:54	04/25/90	17980 LB G	GROSS
12:55	04/22/90	8720 LB G	TARE
		9,260	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0288

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #126 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2	Manifest Document No. 6344 5	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: Nº 00263445
B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.		BA	9260	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[redacted]

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 04 26 90

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature
Date: 04 26 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date:

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date:

BRA 0289

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/274

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0290

#2 Load #126

DATE 4-23-90

SELLER ☐
BUYER ☐

ADDRESS

CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

06:54	04/25/90	17980 LB 6	GROSS
12:55	04/22/90	8720 LB 6	TARE
		9,260	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0291

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #126 35 Yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	6 3 4 4 5		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: № 00263445
B. State Generator's ID: 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.		BA	9260	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325,136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] future threats to human health and the environment. OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	Belia Cortez	5 4 21 80

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year
Jose R. Jimenez	[signature]	5 4 21 80

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month Day Year

White - original; Pink - TSD Facility; Yell... - Transporter; Green - Gen...

BRA 0292

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazard... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 277 of 785 asbestosclaims.law/library/16757/277

#3 Load #125

DATE 4-23-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

06:57	04/25/90	18780 LB G	GROSS
12:59	04/22/90	10320 LB G	TARE
		8460	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0293

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load # 125 32 yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 8 0 2 7 6

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NO. 00263446

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	20	BA	8460	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I have made a good faith effort to minimize [illegible]

GENERATOR

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 04 26 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name: Jose R. Jimenez — Signature — Month Day Year: 04 26 90

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: Miguel Vargas — Signature: Miguel Vargas — Date — Month Day Year

BRA 0294

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviaton for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0295

#3 Load #125

DATE 4-22-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

06:57	04/25/90	18780 LB G	GROSS
12:59	04/22/90	10320 LB G	TARE
		8460	NET

DRIVER ON ☒ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0296

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load # 125 32yds.

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-9

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 8 0 2 7 6

2. Page 1 of | Information in the shaded areas is not required by Federal law.

A. State Manifest Document Number Nº 00263446

B. State Generator's ID 31108

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

5. Transporter 1 Company Name
Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	20	BA	8460	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

[redacted]

Printed/Typed Name: Belia Cortez. Signature: [signature] Month Day Year: 12 6 79

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez Signature: [signature] Date: 12 6 79

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: Signature: Date:

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Signature: Date:

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0297

#2 Load #126

DATE 4-23-90

SELLER ☐
BUYER ☐

ADDRESS _____

CITY _____ STATE _____ ZIP _____

WEIGHED ON CARDINAL SCALES

06:54	04/25/90	17980 LB G	GROSS
12:55	04/22/90	8720 LB G	TARE
		9,260	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY _____

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0298

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #126 35 yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2	Manifest Document No. 6 3 4 4 5	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number: Nº 00263445
B. State Generator's ID: 31108
C. State Transporter's ID: 41317
D. Transporter's Phone: 512-831-7288
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1162
H. Facility's Phone: (512) 423-4302

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number:
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: Harlingen City Landfill, South FM 106 Harlingen, Texas
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.		BA	9260	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez
Signature: Belia Cortez
Month Day Year: 04 26 90

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez
Signature:
Date: 04 26 90

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date:

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Miguel Vargas
Signature: Miguel Vargas
Date:

BRA 0299

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/284

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0300

#2 LOAD #126

DATE 4-23-90

SELLER ☐
BUYER ☐

ADDRESS

CITY STATE ZIP

WEIGHED ON CARDINAL SCALES

06:54	04/25/90	17980 LB G	GROSS
12:55	04/22/90	8720 LB G	TARE
		9,260	NET

DRIVER ON ☑ OFF ☐ WEIGHED BY

DIGITAL WEIGHT INDICATOR & PRINTER

Manufactured by Cardinal Scale Mfg. Co., Webb City, Mo.

Form 510

BRA 0301

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Load #126 35 Yds

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 3 4 4 5

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 00263445

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc. — 6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name — 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas — 10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.		BA	9.2.60	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION.

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 5 4 2 79 — Date

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez — Signature — Month Day Year: 5 4 2 79 — Date

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year — Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.
Printed/Typed Name — Signature — Month Day Year — Date

White — original — Pink: TCR Facility — Yellow: Transporter — Green: Gene[illegible]

BRA 0302

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 73711-3087

Load #127

Please print or type. (Form designed for use on elite (12-pitch) typewriter)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 4.1.2.2.3

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NO 00541223

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	3	BA	10 yds	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

GENERATOR

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 06 04 79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name: Jose R. Jimenez | Signature | Month Day Year: 06 05 79

18. Transporter 2 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date

Printed/Typed Name | Signature | Month Day Year

BRA 0303

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3)

BRA 0304

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
T X D 0 0 8 1 1 4 0 9 2	4 1 2 9 3		

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521
4. Generator's Phone ( )

A. State Manifest Document Number NM 00541223
B. State Generator's ID [redacted] 31108
C. State Transporter's ID 41917
D. Transporter's Phone 512-831-7288
E. State Transporter's ID
F. Transporter's Phone

5. Transporter 1 Company Name: Interesales Equip., Inc.
6. US EPA ID Number
7. Transporter 2 Company Name
8. US EPA ID Number

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID [redacted] 1162
H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	3	BA	10 yds	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
[illegible] economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select [illegible]

GENERATOR

Printed/Typed Name	Signature	Month Day Year
Belia Cortez	[signature]	12 6 79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials		Date
Printed/Typed Name: Jose R. Jimenez	Signature [signature]	Month Day Year 12 6 79
18. Transporter 2 Acknowledgement of Receipt of Materials		Date
Printed/Typed Name	Signature	Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date Month Day Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0305

ADDRESSES/PHONE NUMBERS

(WSC)(B&R)

TEXAS INSTRUMENTS STAFFORD - ATTN: DARRELL PUTNAM
12201 S.W. FREEWAY B&R (713) 274-2071
STAFFORD, TEXAS
MAILING ADDRESS: P.O. BOX 1443-MS 698
HOUSTON, TEXAS 77251-1443

DARRELL HARGROVE
BLDG. 01, ROOM 419
FAX NO. (713) 676-8860

(FYI)
AIRBORNE EXPRESS OFFICE
218 N. 2200 W
SLC, UTAH

(1) (UCC) JO MASTER
(TEL) (304)747-2791
(2) DAWNA KESSLER
(TEL) (304) 747-2287
(FAX)(1)(304)747-2469
(FAX)(1)(304)747-2287

(UCC) PAUL NAYLOR - BLDG. 82
(304) 747-3333
437 MAC CORKLE AVE. S.W.
SOUTH CHARLESTON, W. VA. 25303

(UCC) (AIRBORNE) ROY RUDDLE-UCC
318-24 4TH AVE.
ROOM 332
SOUTH CHARLESTON, W.VA.
25303

(UCC) MR. DICK BLACKMORE - W. VA. (304) 747-5415
BLDG. 2000,ROOM 2402 FAX. NO. ((304) 747-5831
3200-3300 KANAWHA TURNPIKE (PHYSICAL)
MAILING ADDRESS: P.O. Box 8361, SOUTH CHARLESTON, W. VA. 25303
TECH CENTER

(TWC)
TEXAS WATER COMMISSION
DISTRICT 11
813 EAST PIKE BLVD.
WESLACO, TEXAS 78596
ATTN: MR. CHARLES F. WEBSTER
FIELD INVESTIGATOR

(TWC)
SAMUEL B. POLE
CHIEF, HAZARDOUS & SOLID WASTE
TWC - ENFORCEMENT SECTION
P.O. BOX 13087-CAPITOL STATION
AUSTIN, TEXAS 78711

(WSC-B&R)
BROWN & ROOT, INC.
ATTN: MAGGIE ANDERSON 01-217
P.O. BOX 3
HOUSTON, TEXAS 77001
(TEL)713-676-8908
(B&R)(FAX)Some*

(B&R)
BROWN & ROOT INC. (Accident/Injury reports)
BLDG. 01, ROOM 418
HOUSTON, TEXAS
(713)676-8209)
(4) FAX # (713) 676-8860

FRED,CONE (FAX) (203) 794-6238
(Law Dept.)
TAPP (FAX) (713) 538-1230
BOOTH (FAX) (304) 747-5448
NUS (FAX) (713) 713-492-0504
KLINE/LASHER (FAX) (203) 794-3133
GERBER (FAX) (409) 948-5005
(TEL) (409) 948-5318
RUDDLE (FAX) (304) 747-3368
IT (DML)(FAX)(713) 339-1128
(713) 339-4547
U.S. ECOLOGY
(KENTUCKY OFFICE) (TEL) 1-800-626-5334
(GREG MURPHY)(TEXAS OFFICE) (TEL) 1-800-242-3209
JIM WRIGHT (FAX) (512) 387-6228
(OFF) 1-800-729-9163
(HOME) (512) 242-2506

(JOSE)
FAX NO. (713) 271-0956

(UPE) TEL NO. (609) 443-4545
FAX NO. (609) 259-0644

(WIEDA)
(713) 334-3510

(EPA)
MR. JOHN RINEHART (6H-PC)
UNITED STATES ENVIRONMENTAL
PROTECTION AGENCY
REGION VI
1445 ROSS AVENUE
1ST INTERSTATE BANK BLDG.
DALLAS, TEXAS 75202

(TWC) MR. CHARLES E. MAUK, HEAD
FACILITY UNIT IV
HAZARDOUS & SOLID WASTE PERMITS SECTION
TEXAS WATER COMMISSION
P.O. BOX 13087
AUSTIN, TEXAS 78711

(STATE)HAZARD COMMUNICATION BRANCH
TEXAS DEPARTMENT OF HEALTH
1100 WEST 49TH STREET
AUSTIN, TEXAS 78756

(UCC)
M.V. EWALD
EMPL. REL. D-3224

(SEAGULL) LYDIA 761-5116
(UCC)BILL BANCROFT
BLDG.2000-2405
LOC. 511(TECH CNTR)

(UCC) SANDRA ARGUS (713) 334-3538
(B&R)**PAUL CHAPMAN (713) 676-8908
* FAX (713)676-8860

(SEADRIFT PIPELINE)

BRA 0306

O. DOUGLAS BEARD (PRESIDENT)

INVESTIGATIVE RESEARCH, INC.
SUITE 100
1620 S. CLYDE MORRIS BLVD.
DAYTONA BEACH, FLORIDA 32019
(TEL) (407) 682-7338 (904) 788-8392
(FAX) (904) 756-7891

HOMER HINES
SDC SERVICES, INC.
855-4551
(FAX) (512) 855-5419

JOSE R. JIMENEZ, JR.
P.O. BOX 1819
BELLAIRE, TEXAS 77402
(TEL) (713) 667-4527

1224 SAN MARCELO BLVD
BROWNSVILLE, TEXAS 78521
(TEL) (512) 548-0843

JOSE'S FAX NO. (713) 271-0956

SRA. MAGE 541-3874
CARLOTA VILLARREAL 541-2280

GABRIEL FLORES
541-7874
(CONCRETE,SHINGLE ROOFING,HSE PNTING

EXPENSE ACCOUNTS - DUB GARNETT

(UCC)
MR. L. SNODGRASS
3200-3300 KANAWHA TURNPIKE
BLDG. 2000
SOUTH CHARLESTON, W. VA. 25303

(UCC) ANDREA
(203) 794-2251

(UCC)
JOE SMITH (IRD)
(304) 747-3368

(UCC LAW DEPT)
JOE TRIPLETT
(TEL) (304)747-3557
(FAX) (304)747-3179

RON WALKER
(TEL) (512) 574-5689
(FAX) (512) 573-5288

(STATE)
TEXAS DEPARTMENT OF WATER RESOURCES
P.O. BOX 13087
CAPITOL STATION
AUSTIN, TEXAS 78711

(EPA)
ENVIRONMENTAL PROTECTION AGENCY
PERMITS BRANCH, REGION VI
FIRST INTL. BLDG.
1201 ELM STREET
DALLAS, TEXAS 75270

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazard... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 292 of 785 asbestosclaims.law/library/16757/292

ADDRESSES/PHONE NUMBERS

(WSC)(B&R)

TEXAS INSTRUMENTS STAFFORD - ATTN: DARRELL PUTNAM
12201 S.W. FREEWAY B&R (713) 274-2071
STAFFORD, TEXAS
MAILING ADDRESS: P.O. BOX 1443-MS 698
HOUSTON, TEXAS 77251-1443

DARRELL HARGROVE
BLDG. 01, ROOM 419
FAX NO. (713) 676-8860

(FYI)
AIRBORNE EXPRESS OFFICE
218 N. 2200 W
SLC, UTAH

(1) (UCC) JO MASTER
(TEL) (304)747-2791
(2) DAWNA KESSLER
(TEL) (304) 747-2287
(FAX)(1)(304)747-2469
(FAX)(1)(304)747-2287

(UCC) PAUL NAYLOR - BLDG. 82
(304) 747-3333
437 MAC CORKLE AVE. S.W.
SOUTH CHARLESTON, W. VA. 25303

(UCC) MR. DICK BLACKMORE - W. VA. (304) 747-5415
BLDG. 2000,ROOM 2402 FAX. NO. ((304) 747-5831
3200-3300 KANAWHA TURNPIKE (PHYSICAL)
MAILING ADDRESS: P.O. Box 8361, SOUTH CHARLESTON, W. VA. 25303
TECH CENTER

(UCC) (AIRBORNE) ROY RUDDLE-UCC
318-24 4TH AVE.
ROOM 332
SOUTH CHARLESTON, W.VA.
25303

(TWC)
TEXAS WATER COMMISSION
DISTRICT 11
813 EAST PIKE BLVD.
WESLACO, TEXAS 78596
ATTN: MR. CHARLES F. WEBSTER
FIELD INVESTIGATOR

(TWC)
SAMUEL B. POLE
CHIEF, HAZARDOUS & SOLID WASTE
TWC - ENFORCEMENT SECTION
P.O. BOX 13087-CAPITOL STATION
AUSTIN, TEXAS 78711

(WSC-B&R)
BROWN & ROOT, INC.
ATTN: MAGGIE ANDERSON 01-217
P.O. BOX 3
HOUSTON, TEXAS 77001
(Tel) 713-676-8908
(B&R) (FAX) Some*

FRED,CONE (FAX) (203) 794-6238
(Law Dept.)
TAPP (FAX) (713) 538-1230
BOOTH (FAX) (304) 747-5448
NUS (FAX) (713) 713-492-0504
KLINE/LASHER (FAX) (203) 794-3133
GERBER (FAX) (409) 948-5005
(TEL) (409) 948-5318
RUDDLE (FAX) (304) 747-3368
IT (DML)(FAX)(713) 339-1128
(713) 339-4547

BROWN & ROOT INC. (Accident/Injury reports)
BLDG. 01, ROOM 418
HOUSTON, TEXAS
(713)676-8209)
(4) FAX # (713) 676-8860

U.S. ECOLOGY
(KENTUCKY OFFICE) (TEL) 1-800-626-5334
(GREG MURPHY)(TEXAS OFFICE) (TEL) 1-800-242-3209

(JOSE)
FAX NO. (713) 271-0956

JIM WRIGHT (FAX) (512) 387-6228
(OFF) 1-800-729-9163
(HOME) (512) 242-2506

(UPE) TEL NO. (609) 443-4545
FAX NO. (609) 259-0644

(WIEDA)
(713) 334-3510

(TWC)
MR. CHARLES E. MAUK, HEAD
FACILITY UNIT IV
HAZARDOUS & SOLID WASTE PERMITS SECTION
TEXAS WATER COMMISSION
P.O. BOX 13087
AUSTIN, TEXAS 78711

(EPA)
MR. JOHN RINEHART (6H-PC)
UNITED STATES ENVIRONMENTAL
PROTECTION AGENCY
REGION VI
1445 ROSS AVENUE
1ST INTERSTATE BANK BLDG.
DALLAS, TEXAS 75202

(STATE)HAZARD COMMUNICATION BRANCH
TEXAS DEPARTMENT OF HEALTH
1100 WEST 49TH STREET
AUSTIN, TEXAS 78756

(UCC)
M.V. EWALD
EMPL. REL. D-3224

(SEAGULL) LYDIA 761-5116
(UCC)BILL BANCROFT
BLDG.2000-2405
LOC. 511(TECH CNTR)

(UCC) SANDRA ARGUS (713) 334-3538
(B&R)**PAUL CHAPMAN (713) 676-8908
* FAX (713)676-8860

(SEADRIFT PIPELINE)

BRA 0308

O. DOUGLAS BEARD (PRESIDENT)

INVESTIGATIVE RESEARCH, INC.
SUITE 100
1620 S. CLYDE MORRIS BLVD.
DAYTONA BEACH, FLORIDA 32019
(TEL) (407) 682-7338 (904) 788-8392
(FAX) (904) 756-7891

HOMER HINES
SDC SERVICES, INC.
855-4551
(FAX) (512) 855-5419

JOSE R. JIMENEZ, JR.
P.O. BOX 1819
BELLAIRE, TEXAS 77402
(TEL) (713) 667-4527

1224 SAN MARCELO BLVD
BROWNSVILLE, TEXAS 78521
(TEL) (512) 548-0843

JOSE'S FAX NO. (713) 271-0956

SRA. MAGE 541-3874
CARLOTA VILLARREAL 541-2280

GABRIEL FLORES
541-7874
(CONCRETE,SHINGLE ROOFING,HSE PNTING

EXPENSE ACCOUNTS - DUB GARNETT

(UCC)
MR. L. SNODGRASS
3200-3300 KANAWHA TURNPIKE
BLDG. 2000
SOUTH CHARLESTON, W. VA. 25303

(UCC) ANDREA
(203) 794-2251

(UCC)
JOE SMITH (IRD)
(304) 747-3368

(UCC LAW DEPT)
JOE TRIPLETT
(TEL) (304)747-3557
(FAX) (304)747-3179

RON WALKER
(TEL) (512) 574-5689
(FAX) (512) 573-5288

(STATE)
TEXAS DEPARTMENT OF WATER RESOURCES
P.O. BOX 13087
CAPITOL STATION
AUSTIN, TEXAS 78711

(EPA)
ENVIRONMENTAL PROTECTION AGENCY
PERMITS BRANCH, REGION VI
FIRST INTL. BLDG.
1201 ELM STREET
DALLAS, TEXAS 75270

BRA 0309

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 73711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter)

LOAD #127

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 4.1.2.2.3

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number No 00541223

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No	Type	13. Total Quantity	14 Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb.	3	BA	10 yds	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 06 04 90

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jose R. Jimenez | Signature | Date: 06 05 90

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: Miguel Vargas | Signature: Miguel Vargas | Date

BRA 0310

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/295

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3)

BRA 0311

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

CDD # 127

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 4 1 2 2 3

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NO 00541223
B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number

C. State Transporter's ID 41317
D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number

G. State Facility's ID 1162
H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) ORM-E NA 9188 RQ = 1 Lb,	3	BA	10 yds	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator and I have certified that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month Day Year
Belia Cortez		10 01 79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date
Jose R. Jimenez		10 1 79

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0312

ADDRESSES/PHONE NUMBERS

(WSC)(B&R)

TEXAS INSTRUMENTS STAFFORD - ATTN: DARRELL PUTNAM
12201 S.W. FREEWAY B&R (713) 274-2071
STAFFORD, TEXAS
MAILING ADDRESS: P.O. BOX 1443-MS 698
HOUSTON, TEXAS 77251-1443

DARRELL HARGROVE
BLDG. 01, ROOM 419
FAX NO. (713) 676-8860

(FYI)

AIRBORNE EXPRESS OFFICE
218 N. 2200 W
SLC, UTAH

(1) (UCC) JO MASTER
(TEL) (304)747-2791
(2) DAWNA KESSLER
(TEL) (304) 747-2287
(FAX)(1)(304)747-2469
(FAX)(1)(304)747-2287

(UCC) PAUL NAYLOR - BLDG. 82
(304) 747-3333
437 MAC CORKLE AVE. S.W.
SOUTH CHARLESTON, W. VA. 25303

(UCC) (AIRBORNE) ROY RUDDLE-UCC
318-24 4TH AVE.
ROOM 332
SOUTH CHARLESTON, W.VA.
25303

(UCC) MR. DICK BLACKMORE - W. VA. (304) 747-5415
BLDG. 2000,ROOM 2402 FAX. NO. ((304) 747-5831
3200-3300 KANAWHA TURNPIKE (PHYSICAL)
MAILING ADDRESS: P.O. Box 8361, SOUTH CHARLESTON, W. VA. 25303
TECH CENTER

(TWC)

TEXAS WATER COMMISSION
DISTRICT 11
813 EAST PIKE BLVD.
WESLACO, TEXAS 78596

ATTN: MR. CHARLES F. WEBSTER
FIELD INVESTIGATOR

(TWC)

SAMUEL B. POLE
CHIEF, HAZARDOUS & SOLID WASTE
TWC - ENFORCEMENT SECTION
P.O. BOX 13087-CAPITOL STATION
AUSTIN, TEXAS 78711

(WSC-B&R)

BROWN & ROOT, INC.
ATTN: MAGGIE ANDERSON 01-217
P.O. BOX 3
HOUSTON, TEXAS 77001
(TEL) 713-676-8908
(B&R) (FAX) Some (*)

BROWN & ROOT INC. (Accident/Injury reports)
BLDG. 01, ROOM 418
HOUSTON, TEXAS
(713)676-8209)
(4) FAX # (713) 676-8860

FRED,CONE (FAX) (203) 794-6238
(Law Dept.)
TAPP (FAX) (713) 538-1230
BOOTH (FAX) (304) 747-5448
NUS (FAX) (713) 713-492-0504
KLINE/LASHER (FAX) (203) 794-3133
GERBER (FAX) (409) 948-5005
(TEL) (409) 948-5318
RUDDLE (FAX) (304) 747-3368
IT (DML)(FAX)(713) 339-1128
(713) 339-4547
U.S. ECOLOGY
(KENTUCKY OFFICE) (TEL) 1-800-626-5334

(JOSE)

FAX NO. (713) 271-0956

(GREG MURPHY)(TEXAS OFFICE) (TEL) 1-800-242-3209

JIM WRIGHT (FAX) (512) 387-6228
(OFF) 1-800-729-9163
(HOME) (512) 242-2506

(UPE) TEL NO. (609) 443-4545
FAX NO. (609) 259-0644

(WIEDA)

(713) 334-3510

(EPA)

MR. JOHN RINEHART (6H-PC)
UNITED STATES ENVIRONMENTAL
PROTECTION AGENCY
REGION VI
1445 ROSS AVENUE
1ST INTERSTATE BANK BLDG.
DALLAS, TEXAS 75202

(TWC)

MR. CHARLES E. MAUK, HEAD
FACILITY UNIT IV
HAZARDOUS & SOLID WASTE PERMITS SECTION
TEXAS WATER COMMISSION
P.O. BOX 13087
AUSTIN, TEXAS 78711

(STATE) HAZARD COMMUNICATION BRANCH
TEXAS DEPARTMENT OF HEALTH
1100 WEST 49TH STREET
AUSTIN, TEXAS 78756

(UCC)
M.V. EWALD
EMPL. REL. D-3224

(SEAGULL) LYDIA 761-5116
(UCC) BILL BANCROFT
BLDG.2000-2405
LOC. 511(TECH CNTR)

(UCC) SANDRA ARGUS (713) 334-3538
(B&R) **PAUL CHAPMAN (713) 676-8908
* FAX (713)676-8860

(SEADRIFT PIPELINE)

BRA 0313

O. DOUGLAS BEARD (PRESIDENT)

INVESTIGATIVE RESEARCH, INC.
SUITE 100
1620 S. CLYDE MORRIS BLVD.
DAYTONA BEACH, FLORIDA 32019
(TEL) (407) 682-7338 (904) 788-8392
(FAX) (904) 756-7891

HOMER HINES
SDC SERVICES, INC.
855-4551
(FAX) (512) 855-5419

JOSE R. JIMENEZ, JR.
P.O. BOX 1819
BELLAIRE, TEXAS 77402
(TEL) (713) 667-4527

1224 SAN MARCELO BLVD
BROWNSVILLE, TEXAS 78521
(TEL) (512) 548-0843

JOSE'S FAX NO. (713) 271-0956

SRA. MAGE 541-3874
CARLOTA VILLARREAL 541-2280

GABRIEL FLORES
541-7874
(CONCRETE,SHINGLE ROOFING,HSE PNTING

EXPENSE ACCOUNTS - DUB GARNETT

(UCC)
MR. L. SNODGRASS
3200-3300 KANAWHA TURNPIKE
BLDG. 2000
SOUTH CHARLESTON, W. VA. 25303

(UCC) ANDREA
(203) 794-2251

(UCC)
JOE SMITH (IRD)
(304) 747-3368

(UCC LAW DEPT)
JOE TRIPLETT
(TEL) (304)747-3557
(FAX) (304)747-3179

RON WALKER
(TEL) (512) 574-5689
(FAX) (512) 573-5288

(STATE)
TEXAS DEPARTMENT OF WATER RESOURCES
P.O. BOX 13087
CAPITOL STATION
AUSTIN, TEXAS 78711

(EPA)
ENVIRONMENTAL PROTECTION AGENCY
PERMITS BRANCH, REGION VI
FIRST INTL. BLDG.
1201 ELM STREET
DALLAS, TEXAS 75270

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazard... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 299 of 785 asbestosclaims.law/library/16757/299

ADDRESSES/PHONE NUMBERS

(WSC)(B&R)

TEXAS INSTRUMENTS STAFFORD - ATTN: DARRELL PUTNAM
12201 S.W. FREEWAY B&R (713) 274-2071
STAFFORD, TEXAS
MAILING ADDRESS: P.O. BOX 1443-MS 698
HOUSTON, TEXAS 77251-1443

DARRELL HARGROVE
BLDG. 01, ROOM 419
FAX NO. (713) 676-8860

(FYI)
AIRBORNE EXPRESS OFFICE
218 N. 2200 W
SLC, UTAH

(1) (UCC) JO MASTER
(TEL) (304)747-2791
(2) DAWNA KESSLER
(TEL) (304) 747-2287
(FAX)(1)(304)747-2469
(FAX)(1)(304)747-2287

(UCC) PAUL NAYLOR - BLDG. 82
(304) 747-3333
437 MAC CORKLE AVE. S.W.
SOUTH CHARLESTON, W. VA. 25303

(UCC) (AIRBORNE) ROY RUDDLE-UCC
318-24 4TH AVE.
ROOM 332
SOUTH CHARLESTON, W.VA.
25303

(UCC) MR. DICK BLACKMORE - W. VA. (304) 747-5415
BLDG. 2000,ROOM 2402 FAX. NO. ((304) 747-5831
3200-3300 KANAWHA TURNPIKE (PHYSICAL)
MAILING ADDRESS: P.O. Box 8361, SOUTH CHARLESTON, W. VA. 25303
TECH CENTER

(TWC)
TEXAS WATER COMMISSION
DISTRICT 11
813 EAST PIKE BLVD.
WESLACO, TEXAS 78596
ATTN: MR. CHARLES F. WEBSTER
FIELD INVESTIGATOR

(TWC)
SAMUEL B. POLE
CHIEF, HAZARDOUS & SOLID WASTE
TWC - ENFORCEMENT SECTION
P.O. BOX 13087-CAPITOL STATION
AUSTIN, TEXAS 78711

(WSC-B&R)
BROWN & ROOT, INC.
ATTN: MAGGIE ANDERSON 01-217
P.O. BOX 3
HOUSTON, TEXAS 77001
(FAX) 713-676-8908

(B&R) (FAX) Some
BROWN & ROOT INC. (Accident/Injury reports)
BLDG. 01, ROOM 418
HOUSTON, TEXAS
(713)676-8209)
FAX # (713) 676-8860

FRED,CONE (FAX) (203) 794-6238
(Law Dept.)
TAPP (FAX) (713) 538-1230
BOOTH (FAX) (304) 747-5448
NUS (FAX) (713) 713-492-0504
KLINE/LASHER (FAX) (203) 794-3133
GERBER (FAX) (409) 948-5005
(TEL) (409) 948-5318
RUDDLE (FAX) (304) 747-3368
IT (DML)(FAX)(713) 339-1128
(713) 339-4547
U.S. ECOLOGY
(KENTUCKY OFFICE) (TEL) 1-800-626-5334

(JOSE)
FAX NO. (713) 271-0956

(GREG MURPHY)(TEXAS OFFICE) (TEL) 1-800-242-3209
JIM WRIGHT (FAX) (512) 387-6228
(OFF) 1-800-729-9163
(HOME) (512) 242-2506

(UPE) TEL NO. (609) 443-4545
FAX NO. (609) 259-0644

(WIEDA)
(713) 334-3510

(EPA)
MR. JOHN RINEHART (6H-PC)
UNITED STATES ENVIRONMENTAL
PROTECTION AGENCY
REGION VI
1445 ROSS AVENUE
1ST INTERSTATE BANK BLDG.
DALLAS, TEXAS 75202

(TWC)
MR. CHARLES E. MAUK, HEAD
FACILITY UNIT IV
HAZARDOUS & SOLID WASTE PERMITS SECTION
TEXAS WATER COMMISSION
P.O. BOX 13087
AUSTIN, TEXAS 78711

(STATE)HAZARD COMMUNICATION BRANCH
TEXAS DEPARTMENT OF HEALTH
1100 WEST 49TH STREET
AUSTIN, TEXAS 78756

(UCC)
M.V. EWALD
EMPL. REL. D-3224

(SEAGULL) LYDIA 761-5116
(UCC)BILL BANCROFT
BLDG.2000-2405
LOC. 511(TECH CNTR)

(UCC) SANDRA ARGUS (713) 334-3538
(B&R)**PAUL CHAPMAN (713) 676-8908
* FAX (713)676-8860

(SEADRIFT PIPELINE)

BRA 0315

O. DOUGLAS BEARD (PRESIDENT)

INVESTIGATIVE RESEARCH, INC.
SUITE 100
1620 S. CLYDE MORRIS BLVD.
DAYTONA BEACH, FLORIDA 32019
(TEL) (407) 682-7338 (904) 788-8392
(FAX) (904) 756-7891

HOMER HINES
SDC SERVICES, INC.
855-4551
(FAX) (512) 855-5419

JOSE R. JIMENEZ, JR.
P.O. BOX 1819
BELLAIRE, TEXAS 77402
(TEL) (713) 667-4527

1224 SAN MARCELO BLVD
BROWNSVILLE, TEXAS 78521
(TEL) (512) 548-0843

JOSE'S FAX NO. (713) 271-0956

SRA. MAGE 541-3874
CARLOTA VILLARREAL 541-2280

GABRIEL FLORES
541-7874
(CONCRETE,SHINGLE ROOFING,HSE PNTING

EXPENSE ACCOUNTS - DUB GARNETT

(UCC)

MR. L. SNODGRASS
3200-3300 KANAWHA TURNPIKE
BLDG. 2000
SOUTH CHARLESTON, W. VA. 25303

(UCC) ANDREA
(203) 794-2251

(UCC)
JOE SMITH (IRD)
(304) 747-3368

(UCC LAW DEPT)

JOE TRIPLETT
(TEL) (304)747-3557
(FAX) (304)747-3179

RON WALKER
(TEL) (512) 574-5689
(FAX) (512) 573-5288

(STATE)
TEXAS DEPARTMENT OF WATER RESOURCES
P.O. BOX 13087
CAPITOL STATION
AUSTIN, TEXAS 78711

(EPA)
ENVIRONMENTAL PROTECTION AGENCY
PERMITS BRANCH, REGION VI
FIRST INTL. BLDG.
1201 ELM STREET
DALLAS, TEXAS 75270

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazard... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 301 of 785 asbestosclaims.law/library/16757/301

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D . 0 . 0 . 8 . 1 . 1 . 4 . 0 . 9 . 2 | Manifest Document No. 8 0 2 7 6

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NO 0054222

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) South ORM-E NA 9188 RQ = 1 Lb.		BA		P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-81

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez				

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
Jose R. Jimenez				

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

BRA 0317

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A—When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated wate/material description.

(B) ITEM 11—Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12—Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TDWR Industrial Solid Waste Rules.

(D) ITEM 13—Enter the total quantity of waste described on each line.

(E) ITEM 14—Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	L = Liter (liquids only)
P = Pounds	K = Kilograms
T = Tons (2000 lbs.)	M = Metric Tons (1000 kg.)
Y = Cubic Yards	N = Cubic Meters

(F) ITEM I—Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print Clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I**.

(4) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR**.

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

BRA 0318

TEXAS WATER COMMISSION
P.O. Box 13087 Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 80276 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

A. State Manifest Document Number NP 005 1222

B. State Generator's ID 1108

4. Generator's Phone ( )

5. Transporter 1 Company Name: Intersales Equip., Inc. | 6. US EPA ID Number

C. State Transporter's ID 1817

D. Transporter's Phone 512-991-7288

7. Transporter 2 Company Name | 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas | 10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) South ORM-E NA 9188 RQ = 1 Lb.		BA		P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION - VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
D-12

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name: Jose R. Jimenez | Signature | Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date

Printed/Typed Name | Signature | Month Day Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0319

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 80276 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

GENERATOR

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number № 00541222
B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.
6. US EPA ID Number
C. State Transporter's ID 41317
D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South FM 106 Harlingen, Texas
10. US EPA ID Number
G. State Facility's ID 1162
H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. HAZARDOUS SUBSTANCE, SOLID N.O.S. (ASBESTOS) South ORM-E NA 9188 RQ = 1 Lb.		BA		P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
DISPOSAL IN ACCORDANCE WITH TDH MSWR 25 325.136 (b) (6)

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jose R. Jimenez | Signature | Date: Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Date: Month Day Year

TWC-0311 (Rev.11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0320

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 12-31-88

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 3 2 | Manifest Document No.

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide Corporation
Star Route Box 90 Brownsville, Texas 78521

4. Generator's Phone ( )

A. State Manifest Document Number NO 00541222

B. State Generator's ID 31108

5. Transporter 1 Company Name: Intersales Equip., Inc.

6. US EPA ID Number

C. State Transporter's ID 41317

D. Transporter's Phone 512-831-7288

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
Harlingen City Landfill
South [illegible] Harlingen, Texas

10. US EPA ID Number

G. State Facility's ID 1162

H. Facility's Phone (512) 423-4302

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. [illegible] SOLID N.O.S. [illegible] RQ = 1 LB.					179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
PIPE INSULATION & VESSEL INSULATION

K. Handling Codes for Wastes Listed Above
"D-81"

15. Special Handling Instructions and Additional Information
[illegible] CC WITH TSD [illegible]

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations including applicable state regulations.
If I am a large quantity generator I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name [illegible] | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name [illegible] | Signature | Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date

Printed/Typed Name | Signature | Month Day Year

TWC-0311 (Rev 11-06-86) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0321

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 0004974
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address: Union Carbide, Star Route Box 90, Brownsville, TX 78521
Contact: Ms. Belia Cortez
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0004974
B. State Generator's ID: 311108
C. State Transporter's ID: 40869
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 40026
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI Transportation
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill, 11013 Old Beaumont Road, Houston, TX 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	11. Waste No.
	a. RQ Hazardous Substance Solid / Asbestos, N.O.S., ORM-E, NA 9188	~~001~~	BA	00204	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos
K. Handling Codes for Wastes Listed Above: BFI # TX/274/93024/815 71

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at (512) 831-4501 day or night.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 03 09 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul B. Cox — Signature: Paul B. Cox — Date: Month Day Year
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space: could not carry 130 yds weight restrictions
Trailer 46X9X8.5 = 130yds only charged 107 yds per Gragin sales
MAR 11 1992

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: T Wilson — Signature: T Wilson — Date: Month Day Year: 3/11/92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0322

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0323

5859 Bags
on 4 trailers

BRA 0324

Chg to
1400 yds

BRA 0325

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-81

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 — Manifest Document No. 049 74
2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address: Union Carbide, Contact: Mr. Belia Cortez, Star Route Box 90, Brownsville, TX 78521
4. Generator's Phone: (512) 831-4501

A. State Manifest Document Number: 000049 74
B. State Generator's ID: TX 1311 08
C. State Transporter's ID: 440369
D. Transporter's Phone: (512) 882-1501
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: HO 261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI Transportation — 6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name — 8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill, 11013 Old Beaumont Road, Houston, TX 77078 — 10. US EPA ID Number:

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid / Asbestos, N.O.S., ORM-E, NA 9188	~~001~~	BA	00204	Y	[illegible]
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos
K. Handling Codes for Wastes Listed Above: BFI 4; TX/274/130224/315.1

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at (512) 831-4501 day or night.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 03 09 79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul B. Cox — Signature: Paul B. Cox — Date: Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date: Month Day Year


FACILITY

19. Discrepancy Indication Space


20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0326



BRA 0327



QUALITY WEIGHTING SERVICES, INC. 669

TRUCK 27 TLR 291821

TRUCK LINE WPI

CUSTOMER

CARGO

35'000

11:46 AM 03 10 92


85980 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Truck Driver

Certified Weigher

BRA 0328


7:54 AM 03 13 92
34100 lb
12:41 PM 03 10 92
10620 lb
36,840
12:41 PM 03 10 92
47460 lb
32,000
12:42 PM 03 10 92
79460 lb

BRA 0329

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 0 4 9 7 5

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact: Ms. Belia Cortez
Star Route Box 90
Brownsville, TX 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004975

B. State Generator's ID: 311086

5. Transporter 1 Company Name: WPI Transportation

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 403699

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont Road
Houston, TX 77078

10. US EPA ID Number

G. State Facility's ID: HO 261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ Hazardous Substance Solid, Asbestos, N.O.S., ORM-E, NA 9188	1470	BA	00204	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. Friable Asbestos

K. Handling Codes for Wastes Listed Above
BFI # TX 274/930224/81571

15. Special Handling Instructions and Additional Information
Wear gloves, glasses and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at (512) 831-4501 day or night.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 03 Day 09 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: C.B. Cox — Signature: C.B. Cox — Date: Month 03 Day 09 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date: Month Day Year

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
MAR 11 1992
11013 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078
713.675.6101

FACILITY

19. Discrepancy Indication Space
truck could not carry 130 yds, weight restrictions
TRAILERS 46X9X85 = 130YDS - ONLY CHARGED 10-TYDS

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: T Wilson — Signature: A Wilson — Date: Month 3 Day 11 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0330

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0331

Cly to 14045

BRA 0332

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/317

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-97

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008141492 Manifest Document No. 04975
2. Page 1 of 1
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact: Ms. Belia Cortez Star Route Box 90
Brownsville, TX 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004975
B. State Generator's ID: 131105
C. State Transporter's ID: 4035.9
D. Transporter's Phone (713) 452-1501
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: HO 12611
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI Transportation
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont Road
Houston, TX 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid, Asbestos, N.O.S., ORM-E, NA 9188	001	BA	00204	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. Friable Asbestos

K. Handling Codes for Wastes Listed Above
BFI #
TX/274/930224/8157

15. Special Handling Instructions and Additional Information
Wear gloves, glasses and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at (512) 831-4501 day or night.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	03	09	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
A.B. Cox	A.B. Cox	03	09	92

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY


19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0333



BRA 0334

QUALITY WEIGHTING SERVICES, INC. 668

TRUCK 28 TLR 29/849

TRUCK LINE WPI

CUSTOMER

CARGO

☐	$3.00	EMPTY ONLY
☐	$5.00	UP TO 65,000 GROSS
☑	$6.00	65,020 TO 85,000 GROSS
☐	$7.00	85,020 TO 105,000 GROSS
☐	$8.50	105,020 TO 125,000 GROSS
☐	$10.00	125,020 TO 145,000 GROSS
☐	$25.00	145,020 AND UP

11:38 AM 03 10 92
10800 lb

34980

11:38 AM 03 10 92
45780 lb

32920


11:38 AM 03 10 92
78700 lb

G.B. Cox

Truck Driver

Certified Weigher

BRA 0335



BRA 0336

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/321

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXDO 08114092 — Manifest Document No. 64034

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE
STAR ROUTE BOX 90, BROWNSVILLE, TX 78521
CONTACT: MS. BELIA CORTEZ

4. Generator's Phone ( )

A. State Manifest Document Number: 0000480[illegible]
B. State Generator's ID: 31108[illegible]

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
G. State Transporter's ID: [illegible]40369
D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number:
G. State Facility's ID: [illegible]H0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	(I) Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E, NA 9188	1	57 B A	140	CY	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A: FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI/TX/2747930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY, FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 03 13 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: Paul B Cox — Signature: Paul B. Cox — Date: 03 13 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name: — Signature: — Date:

FACILITY
19. Discrepancy Indication Space: ONLY charged 107 yds per Greg in Sales (LAR), said truck could only carry 107 yds due to weight
BROWNING-FERRIS, INC.
MCCARTY RD. LANDFILL
TDH PERMIT # 261
MAR 14 1992
11013 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078
713-675-6101
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J Henderson — Signature: J Henderson — Date: 3 18 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0337

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.


(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0338



QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 3931
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291821
TRUCK LINE WPT
CUSTOMER Union Carbide
CARGO

7:54 AM 03 13 92
34100 lb

5:00 PM 03 13 92
79380 lb
34100 lb TR
45280 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHER BOARD OF COMMISSIONERS

Truck Driver

Certified Weigher

BRA 0339

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: TXDO 08114092 — Manifest Document No.: 64034

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE
STAR ROUTE BOX 90, BROWNSVILLE, TX 78521
CONTACT: MS. BELIA CORTEZ

4. Generator's Phone ( )

A. State Manifest Document Number: 00004803

B. State Generator's ID: [illegible]

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: [illegible]40369

D. Transporter's Phone: (713) 432-1504

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number:

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E, NA 9188	1657 / 1	B AA	140 Cu Yd		[illegible]179300
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/8157

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY, FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 03 Day 13 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: PAUL B COX — Signature: Paul B. Cox — Date: Month 03 Day 13 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: — Signature: — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0340

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST # Grad 1202

SERVICE ORDER NUMBER **218697**

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 3-17-72 TRAILER # TRUCK # 77 PICKUP #

OPERATOR OR DRIVER Paul R Cox LABOR

JOB LOCATION: Brownsville Tex DESTINATION Houston Tex

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM (X) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN (X) FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM
TIME ARRIVED	3-18-72	7 45	(AM) PM
LOADING BEGAN			AM PM
LOADING COMPLETED	3-19-72	5 15	(AM) PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Delay due to no one here notified to dispatch manifest.

3-19-72

TRAILER/BIN DROPPED # 291821 DATE/TIME SHIPPER'S SIGNATURE Robin Coates

TRAILER/BIN PU 288808 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Paul R. Cox

ENDING MILEAGE

BEGINNING MILEAGE 344464

TOTAL TRIP MILES

Robin Coates
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0341

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE : CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004804
B. State Generator's ID: 31108
C. State Transporter's ID, etc.: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E, NA 9188	1	B A	140 Cu Yd		179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224781571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA Cortez | Signature: Belia Cortez | Month 0 3 | Day 1 3 | Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: H.B. Cox | Signature: H.B Cox | Date: Month 0 3 | Day 1 3 | Year 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month | Day | Year

BROWNING-FERRIS, INC
McCARTY RD. LANDFILL
TDH PERMIT # 261

FACILITY

19. Discrepancy Indication Space
only charged 107 yds per Greg in sales
said truck could only carry 107 yds due to weight

MAR 14 1992

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19:
Printed/Typed Name: J Henderson | Signature: J Henderson | Date: Month 3 | Day 14 | Year 92

11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0342

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 6403

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE : CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004804
B. State Generator's ID:

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: TXD050641463
C. State Transporter's ID: 40362
D. Transporter's Phone: (713) 452-1501

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E, NA 9188	16 51 1	B.A	140 cu.Yd		179380
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFLFTX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

GENERATOR

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 03 Day 13 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: H.B. COX | Signature: H.B Cox | Date: Month 03 Day 13 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0344

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 3930
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 29160

TRUCK LINE WPI

CUSTOMER Union Carbide

CARGO

7:52 AM 03 13 92
34080 lb

5:11 PM 03 13 92
80040 lb
34080 lb TR
45960 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHER STATE OF TEXAS

Truck Driver

Certified Weigher

BRA 0345

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 H 804

SERVICE ORDER NUMBER 218642

CUSTOMER: Union Carbide P.O.# RELEASE #

DATE: 3-13-92 TRAILER # 291849 291821 TRUCK # 28 PICKUP #

OPERATOR OR DRIVER G. B Cox LABOR

JOB LOCATION: Brownsville, Tx DESTINATION Houston, Tx

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL-OFF ( ) VAN/ FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	3-13-	715	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	3-13-92	515	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Waiting on Union Carbide agent to sign TWC, Haz Mat manifest + Cat Prod. sig.!

TRAILER/BIN DROPPED # 291849

TRAILER/BIN PU 291821

DATE/TIME 8:00 / 3/13/92

DATE/TIME 8:00 / 3/13/92

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE G. B Cox

ENDING MILEAGE

BEGINNING MILEAGE 425 450

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0346

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000480
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: TH 026103
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

7. Transporter 2 Company Name
8. US EPA ID Number

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID ASBESTOS, N.O.S., ORM-E NA 9188	1407 1500	BC B A	130	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 03 Day 16 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.B. COX | Signature: A.B. Cox | Date: Month 03 Day 16 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

BROWNING-FERRIS, INC.
MCCARTY RD. LANDFILL
TDH PERMIT # 261
MAR 17 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

FACILITY

19. Discrepancy Indication Space
only charged 107 yds, truck only had 107 yds of asbestos per Greg in Sales weight receipt

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: TROY CHARLEVILLE | Signature: Troy Charleville | Date: Month 03 Day 17 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0347

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0348

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 864 0 3

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0004805

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 65

C. State Transporter's ID: 00269

D. Transporter's Phone: (713) 4529130

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID ASBESTOS, N.O.S., ORM-E NA 9088	1407 1500	B A	130	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. - FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above: BFI TX/274/930224/8157

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 03 16 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: A.B Cox — Signature: A B Cox — Date: Month Day Year: 03 16 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

FACILITY


19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0349



QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 № 3961
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 29161D
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

7:59 AM 03 16 92
33060 lb
10:30 AM 03 16 92
78600 lb
33060 lb TR
45540 lb NET

1407

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

OB Coy

Truck Driver

PUBLIC WEIGHER
COUNTY OF CAMERON

Certified Weigher

BRA 0350

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/334

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 100848 O.C.

SERVICE ORDER NUMBER 218643

CUSTOMER: Union Carbide

P.O. # RELEASE #

DATE: 3-16-92 TRAILER # 29610 / 291849 TRUCK # 78 PICKUP #

OPERATOR OR DRIVER C.B. Cox LABOR

JOB LOCATION: Brownsville, TX DESTINATION Houston, TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM (X) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	3-16-92	7:30	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	3-16-92	10:30	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
		1475 loads	

WAS JOB COMPLETED SATISFACTORILY? Yes

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: unloading own load

TRAILER/BIN DROPPED # 29610 DATE/TIME SHIPPER'S SIGNATURE Paul Wells

TRAILER/BIN PU 291849 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE C.B. Cox

ENDING MILEAGE

BEGINNING MILEAGE 1126289

TOTAL TRIP MILES

CUSTOMER SIGNATURE Paul Wells
CONFIRMS TIME IN PLANT

BRA 0351

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 1.00004805
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: TDH 026103
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID ASBESTOS, N.O.S., ORM-E NA 9188	1407 1500	BC B A	130	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	03	16	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
A.B COX	A B Cox	03	16	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
MAR 17 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

FACILITY

19. Discrepancy Indication Space
only charged 107 yds, truck only had 107 yds of asbestos per Greg in sales weight station

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year
Troy Charleville	Troy Charleville	03	17	92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0352

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington; DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0353

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-92

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 Manifest Document No. 864 0 5 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (312) 831-4501

A. State Manifest Document Number 00004805

B. State Generator's ID

C. State Transporter's ID

D. Transporter's Phone (713) 675-2975

E. State Transporter's ID

F. Transporter's Phone

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 65

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID H 0261

H. Facility's Phone (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID ASBESTOS, N.O.S., ORM-E NA 9088	1407 1500	B A	130	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. - FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/8157L

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 03 Day 16 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: A.B Cox | Signature: A B Cox | Date: Month 03 Day 16 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19

Printed/Typed Name | Signature | Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0354

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 3961
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291610
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

1407 Bags

7:59 AM 03 16 92
33060 lb
10:30 AM 03 16 92
78600 lb
33060 lb TR
45540 lb NET

☐	$3.00	EMPTY ONLY
☐	$5.00	UP TO 65,000 GROSS
☑	$6.00	65,020 TO 85,000 GROSS
☐	$7.00	85,020 TO 105,000 GROSS
☐	$8.50	105,020 TO 125,000 GROSS
☐	$10.00	125,020 TO 145,000 GROSS
☐	$25.00	145,020 AND UP

PUBLIC WEIGHER
COUNTY OF CAMERON

OB Coy
Truck Driver

Certified Weigher

BRA 0355

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 16084 P.O.

SERVICE ORDER NUMBER **218643**

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 3-16-92 TRAILER # 291610 291849 TRUCK # 28 PICKUP #

OPERATOR OR DRIVER: C.B. Cox LABOR

JOB LOCATION: Brownsville, TX DESTINATION Houston, TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	3-16-92	7:30	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	3-16-92	10:30	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
		1 1475 bags	

WAS JOB COMPLETED SATISFACTORILY? Yes

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: unloading over load

TRAILER/BIN DROPPED # 291610 DATE/TIME SHIPPER'S SIGNATURE Paul Wells

TRAILER/BIN PU 291849 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE C.B. Cox

ENDING MILEAGE

BEGINNING MILEAGE 1126189

TOTAL TRIP MILES

Paul Wells
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0356

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2	Manifest Document No. 6 4 0 3 4	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90, BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004966
B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number:
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-5504

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number:
G. State Facility's ID: TX037121 H 0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1785	B. A	44280	YD	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI waste codes
SFT-ENV/2741/23022/1817

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 03 Day 19 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.B. COX | Signature: A.B. Cox | Date: Month 03 Day 19 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space: ~~130 YDS~~ charged 107 yds | MAR 19 1992

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: TROY CHARLEVILLE | Signature: Troy Charleville | Date: Month 03 Day 19 Year 92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
11013 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078
675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0357

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0358

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T X D 0 0 8 . 1 4 0 9 2	Manifest Document No. 6 4 0 3	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90, BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004966
B. State Generator's ID: 3 1 103

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number:
C. State Transporter's ID: 40169
D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number:
G. State Facility's ID: H 0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-B NA 9188	1785	B	44280	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	03	1	81

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
A.B. Cox	A B Cox	03	1	81

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0359

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 4004
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK [redacted] 28 TLR 291849 / 291610
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

Manifest # 00004966

7:43 AM 03 18 92
34120 lb

10:54 AM 03 18 92
78400 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

ABCo

Truck Driver

PUBLIC WEIGHER COUNTY OF CAMERON

Certified Weigher

BRA 0360

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 4960

SERVICE ORDER NUMBER 218644

CUSTOMER: Union Carbide P.O. # 291849 RELEASE #

DATE: 3-18-92 TRAILER # 291610 TRUCK # 28 PICKUP #

OPERATOR OR DRIVER: Q. B. Cal LABOR

JOB LOCATION: Brownsville 21 DESTINATION Houston 21

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE		UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED				AM PM
TIME ARRIVED	3-18-92	1130	AM PM	UNLOAD BEGAN				AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE				AM PM
LOADING COMPLETED	3-18-92	1055	AM PM	ARRIVED YARD				AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # ~~291610~~ 291849

TRAILER/BIN PU ~~291610~~ 291610

DATE/TIME 3-18-92 1130

DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Q B Cal

ENDING MILEAGE

BEGINNING MILEAGE 427159

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0361

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide : Contact: Ms. Belia Cortez
Star Route Box 90
Brownsville, Texas 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000497O
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI Transportation Inc.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	State Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS N.O.S., ORM-E NA 9188	1820	BA	43380	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 03 Day 18 Year 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: Paul B. Cox — Signature — Date: Month 03 Day 18 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name — Signature — Date: Month Day Year

FACILITY
19. Discrepancy Indication Space: ~~130 YDS~~ changed 107yds — BROWNING-FERRIS, INC. McCARTY RD. LANDFILL TDH PERMIT # 261 — MAR 19 1992
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — 11013 OLD BEAUMONT HWY. HOUSTON, TEXAS 77078 (713) 675-6101 — Printed/Typed Name: TROY CHARLEVILLE — Signature: Troy Charleville — Date: Month 03 Day 19 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0362

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0363

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide ; Contact: Ms. Belia Cortez
Star Route Box 90
Brownsville, Texas 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000497 0

B. State Generator's ID: 31103

5. Transporter 1 Company Name: WPI Transportation Inc.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40360

D. Transporter's Phone: (713) 692-1[illegible]

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID ASBESTOS N.O.S., ORMEE NA 9188	1870	BA	43380	P	170390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	0 3	1 8	9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
Paul B. Cox	Paul B. Cox	0 3	1 8	9 2

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0364

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 4005
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291821/288808
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

7:45 AM 03 18 92
34120 lb

manifest # 00004970

10:39 AM 03 18 92
77500 lb
34120 lb TR
43380 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☐ ~~$6.00~~ 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

P. Coy
Truck Driver

PUBLIC WEIGHER COM OF TEXAS

Certified Weigher

BRA 0365

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0106770

SERVICE ORDER NUMBER
218699

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 3-18-79 TRAILER # 288808 TRUCK # 27 PICKUP #

OPERATOR OR DRIVER Phil B. Co LABOR

JOB LOCATION: Brownsville, Tx DESTINATION Harlingen, Tx

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM
TIME ARRIVED	3-18	7 45	(AM) PM
LOADING BEGAN			AM PM
LOADING COMPLETED	3-18	11 00	(AM) PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291271

TRAILER/BIN PU 288808

DATE/TIME

DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 346247

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0366

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/350

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T·X·D·0·0·8·1·1·4·0·9·2 | Manifest Document No. 6·4·0·34

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000497 1

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T·X·D·0·5·0·6·4·1·4·6·3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name: SAME AS #5

8. US EPA ID Number:

E. State Transporter's ID: SAME AS D

F. Transporter's Phone: SAME AS D

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number:

G. State Facility's ID: TX 261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E, NA 9188	1760	BA	43020	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/B1571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIE INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 03 Day 18 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Paul B Cox | Signature: Paul B. Cox | Date: Month 03 Day 18 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name: Paul B Cox | Signature: Paul B. Cox | Date: Month 03 Day 18 Year 92

FACILITY

19. Discrepancy Indication Space
charged 107 yds

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
MAR 21 1992

107

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

Printed/Typed Name: J HENDERSON | Signature: J Henderson | Date: Month 3 Day 21 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0367

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0368

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STARTROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000497

B. State Generator's ID: 3108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X B 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 432-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY RD
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E, NA 9188	1760	BA	43020	BC P	179990
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIE INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (312) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name | Signature | Month Day Year

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Paul B Cox | Signature: Paul B. Cox | Date: Month 03 Day 18 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0369

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 4049
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291821
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

manifest # 0000491

1:56 PM 03 18 92
77140 lb
34120 lb TR-
43020 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

P.B. Cox
Truck Driver

Tare from 4005

PUBLIC WEIGHER STATE OF OKLAHOMA

Certified Weigher

BRA 0370

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000499

SERVICE ORDER NUMBER 218700

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 3-[illegible]-92 TRAILER # 288808A TRUCK # 27 PICKUP #

OPERATOR OR DRIVER R. L. B. Cox LABOR

JOB LOCATION: Brownsville, TX DESTINATION Houston, TX

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (VAN) / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM
TIME ARRIVED			AM PM
LOADING BEGAN			AM PM
LOADING COMPLETED			AM PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

Weight 41 000 LBS

TRAILER/BIN DROPPED # ____

TRAILER/BIN PU 288808

DATE/TIME ____

DATE/TIME ____

SHIPPER'S SIGNATURE [signature]

CONSIGNEE'S SIGNATURE ____

DRIVER'S SIGNATURE [signature]

ENDING MILEAGE ____

BEGINNING MILEAGE ____

TOTAL TRIP MILES ____

CUSTOMER SIGNATURE [signature]
CONFIRMS TIME IN PLANT

BRA 0371

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-9

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT# MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004964
B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number
G. State Facility's ID: H 02610
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E NA 9188	2300	BA	43200	P T	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 03 23 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.B. COX — Signature: A.B. Cox — Date: Month Day Year: 03 23 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
~~Charged 130 yds~~ we only charged 107 yds - truck could not carry 130 yds because of weight restrictions

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: TROY CHARLEVILLE — Signature: Troy Charleville — Date: Month Day Year: 03 23 92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
MAR 24 1992
11013 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TCD Facility Yellow-Transporter Green-Generator's first copy

BRA 0372

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0373

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 8 9 6 6 | Manifest Document No. 6 4 0 3 4 | 2. Page 1 of 2 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT MS. BELIA CORTEZ
STAR ROUTE BOX 90
4. BROWNSVILLE, TEXAS 78521 (512) 831-4501

A. State Manifest Document Number: 00004964
B. State Generator's ID:
C. State Transporter's ID: [illegible]
D. Transporter's Phone: (713) [illegible]
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: [illegible] H 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY 48, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E NA 9188	2300	BA	43200	P T	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	03	23	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
A.B. Cox	A.B. Cox	03	23	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0374

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 4110
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291849 (291827)

TRUCK LINE WPI

CUSTOMER Union Carbide

CARGO

7:43 AM 03 23 92
34300 lb

Manifest #
DD004964

11:32 AM 03 23 92
77500 lb
34300 lb TR
43200 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHER COUNTY OF CAMERON

QB Coy

Truck Driver

Certified Weigher

BRA 0375

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/359

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 4964

SERVICE ORDER NUMBER 218646

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 3-23-92 TRAILER # 291849/291827 TRUCK # 28 PICKUP #

OPERATOR OR DRIVER O.B. Cox LABOR

JOB LOCATION: Brownsville TX DESTINATION Houston TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	3-23	7:15	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	"	11:45	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: W.O. & our papers unable to be signed d load adjustment

TRAILER/BIN DROPPED # 291849

TRAILER/BIN PU 291827

DATE/TIME 800 3/23/92

DATE/TIME "

SHIPPER'S SIGNATURE L. Fisher

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE O.B. Cox

ENDING MILEAGE

BEGINNING MILEAGE 128721

TOTAL TRIP MILES

L. Fisher
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0376

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE : CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000497251
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: TX 0 0 0 7 H 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONTH HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1873	B A	43720	P X	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month Day Year
M. B. Cortez	M B. Cortez	03 23 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date
PAUL B Cox		03 23 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261

MAR 24 1992

FACILITY

19. Discrepancy Indication Space
~~charged 130 yds~~ only charged 10 Tyds/truck could not carry 130 yds/ weight restrictions

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
11013 OLD BEAUMONTH HWY
HOUSTON, TEXAS 77078
713-676-6101

Printed/Typed Name	Signature	Month Day Year
TROY Charleville	Troy Charleville	03 24 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0377

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds.	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch; PM-223, U.S. Environmental Protection Agency, 401 M Street SW, Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0378

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 — Manifest Document No. 4

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE : CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000497[illegible]

B. State Generator's ID: [illegible]110

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.C

6. US EPA ID Number: TXD050641463

C. State Transporter's ID: [illegible]

D. Transporter's Phone: (713) 432-[illegible]

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONTH HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: TXH 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1873	B A	43720	P Y	BC 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/01571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: M. B. Cortez — Signature: M B. Cortez — Month 12 Day 23 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Paul B Cox — Signature: Paul B. Cox — Month 01 Day 23 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0379

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4109
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291821/291835
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

7:41 AM 03 23 92
33700 lb

☐	$3.00	EMPTY ONLY
☐	$5.00	UP TO 65,000 GROSS
☑	$6.00	65,020 TO 85,000 GROSS
☐	$7.00	85,020 TO 105,000 GROSS
☐	$8.50	105,020 TO 125,000 GROSS
☐	$10.00	125,020 TO 145,000 GROSS
☐	$25.00	145,020 AND UP

Pd

10:38 AM 03 23 92
77420 lb
33700 lb TR
43720 lb NET

PUBLIC WEIGHER
COUNTY OF CAMERON
STATE OF TEXAS

Truck Driver

Certified Weigher

BRA 0380

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 4772

SERVICE ORDER NUMBER 218701

CUSTOMER Union Carbide P.O. # RELEASE #

DATE 3-23-79 TRAILER # 291835 TRUCK # 77 PICKUP #

OPERATOR OR DRIVER Phil Coy LABOR

JOB LOCATION Brownsville, Tx DESTINATION Hou. Tx

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	3-23	7 45	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	3-23	11 45	(AM) PM	ARRIVED YARD	3-23	4 45	AM (PM)

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Mrs Correy not have to sign manifest had to have her employee run to her house to get them signed

TRAILER/BIN DROPPED # 291871 DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU 291835 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Phil Coy

ENDING MILEAGE

BEGINNING MILEAGE 347840

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0381

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 6 4 0 3 4 — Manifest Document No.

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004938
B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY ~~48~~
HOUSTON, TEXAS 77078
10. US EPA ID Number
G. State Facility's ID: TEXAS TO H 0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1800	BA	44260	P	BC 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above: BFI-TX/27/93026/8151

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA Cortez — Signature: Belia Cortez — Month 03 Day 25 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul B Cox — Signature: Paul B. Cox — Month 03 Day 25 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space: Charged 107 yds

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: TROY Charleville — Signature: Troy Charleville — Month 03 Day 26 Year 92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
MAR 26 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0382

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0383

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE/BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004938
B. State Generator's ID: 31108
C. State Transporter's ID: 40363
D. Transporter's Phone #: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: R 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY 48, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1800	BA	44260	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above: DF2-D/27-H/T30E2-D/25-H

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE, CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA Cortez — Signature: Belia Cortez — Month 03 Day 25 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul B Cox — Signature: Paul B. Cox — Date: Month 03 Day 25 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: — Signature: — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0384

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 4177
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291835
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

7:42 AM 03 25 92
34120 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

8:58 AM 03 25 92
78380 lb
34120 lb TR
44260 lb NET

PUBLIC WEIGHER

Truck Driver

Certified Weigher

BRA 0385

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0004938

SERVICE ORDER NUMBER **218702**

CUSTOMER: Union Carbide P.O. #: RELEASE #:

DATE: 7-15-79 TRAILER #: 291827 TRUCK #: 27 PICKUP #:

OPERATOR OR DRIVER: Pam / B Cox LABOR:

JOB LOCATION: Brownsville, Tx DESTINATION: Hwy 4

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN/FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	7-25	7 45	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	7-25	900	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT _____ am ( ) pm IN _____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291832 DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU 291821 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 342644

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0386

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004941
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1800	BA	43580	W	BC 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ 9512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR
Printed/Typed Name: BELIA Cortez | Signature: Belia Cortez | Month 03 | Day 25 | Year 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: H.B. Cox | Signature: H.B. Cox | Date: Month 03 | Day 25 | Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month | Day | Year

FACILITY
19. Discrepancy Indication Space: Charged 107 yds
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: TROY Charleville | Signature: Troy Charleville | Date: Month 03 | Day 26 | Year 92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
MAR 26 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0387

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless specifically requested.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW, Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0388

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 5 4 0 3 — Manifest Document No. 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORREZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000491

B. State Generator's ID: 332080

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 0 4 1 4 6 3

C. State Transporter's ID: 60369

D. Transporter's Phone: (713) 433-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: R0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1800	BA	43580	Y	06 179180
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/920224/8157L

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ 9512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 03 Day 25 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: A.B. Cox — Signature: A.B. Cox — Date: Month 03 Day 25 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0389

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4178
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

00004941

TRUCK 28 TLR 291827/291849
TRUCK LINE WPJ
CUSTOMER Union Carbide
CARGO

7:45 AM 03 25 92
34080 lb

9:40 AM 03 25 92
77660 lb
34080 lb TR
43580 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

OB Cal

Truck Driver

PUBLIC WEIGHER COUNTY OF CAMERON TEXAS

Certified Weigher

BRA 0390

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 2000 (194)

SERVICE ORDER NUMBER 218647

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 3-25-97 TRAILER # 291849 TRUCK # 18 PICKUP #

OPERATOR OR DRIVER: O. Box LABOR

JOB LOCATION: Brownsville TX DESTINATION Houston TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	3-25	745	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	"	945	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	TX	4559 - 4577	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291827

TRAILER/BIN PU # 291849

DATE/TIME 800 3/25/97

DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 429575

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0391

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000946

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATON, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS MA SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORME NA 9188	2/25	BA	43280	P	BC 179390
	b.					
	c.					
	d.					

GENERATOR

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/8157L

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 03 Day 27 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: PAUL B COX — Signature — Date: Month 03 Day 27 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
charged 107 yds

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
MAR 28 1992

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: TROY CHARLEVILLE — Signature — Date: Month 03 Day 27 Year 92

11013 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0392

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0393

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087
Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 5 4 0 3 4
2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 000049[illegible]6
B. State Generator's ID: [illegible]
C. State Transporter's ID: [illegible]
D. Transporter's Phone: (713) 452-[illegible]
E. State Transporter's ID: [illegible]
F. Transporter's Phone: [illegible]
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS ~~MX~~ SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORME NA 9188	2/25	BA	43280	X	[illegible] 79990
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI-TX/27A/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION.CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA Cortez — Signature: Belia Cortez — Month 03 Day 27 Year 9[illegible] — Date

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul B Cox — Signature: Paul B. Cox — Month 03 Day 27 Year 92 — Date
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Month Day Year — Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: — Signature: — Month Day Year — Date

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0394

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 Nº 4232
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291821/291835
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

7:44 AM 03 27 92
34220 lb

11:07 AM 03 27 92
77500 lb
34220 lb TR
43280 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHMASTER STATE OF TEXAS

Truck Driver

Certified Weigher

BRA 0395

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST: 0000-4941

SERVICE ORDER NUMBER: 218703

CUSTOMER: Union Carbide P.O. #: RELEASE #:

DATE: 3-27-79 TRAILER #: 291835 TRUCK #: 27 PICKUP #:

OPERATOR OR DRIVER: Paul B Coy LABOR:

JOB LOCATION: Brownsville, Tx DESTINATION: Hou, Tx

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM
TIME ARRIVED	3-27	7 45	(AM) PM
LOADING BEGAN			AM PM
LOADING COMPLETED	3-27	11 15	(AM) PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291821

TRAILER/BIN PU 291835

DATE/TIME

DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Paul B. Coy

ENDING MILEAGE

BEGINNING MILEAGE 349439

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0396

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No.: 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS (512) 831-4501

4. Generator's Phone

A. State Manifest Document Number: 00004945

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS XX SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2075	BA	43820	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILL OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA Cortez — Signature: Belia Cortez — Month Day Year: 03 27 92

TRANSPORTER — 17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: A.B. Cox — Signature: A B Cox — Date: 03 27 92

18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name — Signature — Date

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261

FACILITY — 19. Discrepancy Indication Space: Charged 107 yds

MAR 28 1992

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

Printed/Typed Name: TROY Charleville — Signature: Troy Charleville — Date: 03 28 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0397

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0398

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
T X D 0 0 8 1 1 4 0 9 2	6 4 0 3 4		

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
SEAR ROUTE BOX 90
BROWNSVILLE, TEXAS (512) 831-4501
4. Generator's Phone

A. State Manifest Document Number: 00004945
B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 222-5012

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number
G. State Facility's ID: H 0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS MA SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2075	BA	43820	P T	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILL OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	03	27	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
A.B. Cox	A B Cox	03	27	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0399

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 4233
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291827
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

Manifest #
0000 4945

7:46 AM 03 27 92
34220 lb

10:18 AM 03 27 92
78040 lb
34220 lb TR
43820 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

PD

AB Cok
Truck Driver

PUBLIC WEIGHER COUNTY OF CAMERON

Certified Weigher

BRA 0400

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 00004945

SERVICE ORDER NUMBER
218648

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 3-27-92 TRAILER # 291849 / 291827 TRUCK # 18 PICKUP #

OPERATOR OR DRIVER O.B. Cox LABOR

JOB LOCATION: Rincon Co. Tx DESTINATION Houston Tx

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN/ FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	3-27	745	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	3-27	1030	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	TX	US 59 - US 77	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291849 DATE/TIME 3/27/92 800 SHIPPER'S SIGNATURE

TRAILER/BIN PU 291827 DATE/TIME 3/27/92 800 CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE O.B. Cox

ENDING MILEAGE

BEGINNING MILEAGE 430 371

TOTAL TRIP MILES

CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0401

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone

A. State Manifest Document Number: 0000 4958

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: R026 1103

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1950	BA	44120	P X	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI-TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month Day Year: 03 30 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.B. COX | Signature: A.B. Cox | Date: Month Day Year: 03 30 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
changed 107 yds 107 y

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Date: Month Day Year: 3 31 92

BROWNING-FERRIS INC.
McCARTY ROAD LANDFILL
TDH PERMIT # 261
MAR 31 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0402

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR**.

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223; U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0403

TEXAS WATER COMMISSION
P.O. Box [illegible], Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 9 8 1 1 4 0 9 2 — Manifest Document No. 2 6 4 0 5
2. Page 1 of 4
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: C0004958
B. State Generator's ID: 3408

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X R 0 5 0 6 4 1 4 6
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number
G. State Facility's ID: 30261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1950	BA	44120	P T	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 02 13 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.B. Cox — Signature: A.B. Cox — Date: Month Day Year: 02 13 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0404

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4244
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291827/291849
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

Manif # 0004958

7:43 AM 03 30 92
34020 lb

9:10 AM 03 30 92
78140 lb
34020 lb TR
44120 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

PD

ABCo

Truck Driver

PUBLIC WEIGHER STATE OF TEXAS

Certified Weigher

BRA 0405

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/389

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 19578

SERVICE ORDER NUMBER 218649

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 3-30-92 TRAILER # 291827 / 291809 TRUCK # 78 PICKUP #

OPERATOR OR DRIVER O.B. Cool LABOR

JOB LOCATION: Brownsville TX DESTINATION Houston Tx

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM
TIME ARRIVED	3-30	745	AM PM
LOADING BEGAN			AM PM
LOADING COMPLETED			AM PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291827

TRAILER/BIN PU 291809

DATE/TIME 3-30-92 900

DATE/TIME ~ 800

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE O.B. Cool

ENDING MILEAGE

BEGINNING MILEAGE 431197

TOTAL TRIP MILES

CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0406

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 0000495
B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number
G. State Facility's ID: TX H 0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORME NA 9188	2080	BA	44120	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI# TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 03 Day 30 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: PAUL B. COX | Signature: Paul B. Cox | Date: Month 03 Day 30 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261

FACILITY

19. Discrepancy Indication Space
charged 107 yds 107 y

MAR 31 1992

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J Henderson | Signature: J Henderson | 11013 OLD BEAUMONT HWY. HOUSTON, TEXAS 77078 713-675-6101 | Date: Month 3 Day 31 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0407

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223; U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0408

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) — Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number: 00004959
B. State Generator's ID: [redacted] 1108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 457-1004
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY 48, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORME NA 9188	2080	BA	44120	P Y	179300
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI# TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 03 Day 30 Year 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: PAUL B. COX — Signature: Paul B. Cox — Month 03 Day 30 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name: — Signature: — Month Day Year

FACILITY
19. Discrepancy Indication Space
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Printed/Typed Name: — Signature: — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0409

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 4243
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291835/291821
TRUCK LINE WPJ
CUSTOMER Union Carbide
CARGO

7:41 AM 03 30 92
34020 lb

9:27 AM 03 30 92
78140 lb
34020 lb TR
44120 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Paid

PUBLIC WEIGHER STATE OF TEXAS

Truck Driver

Certified Weigher

BRA 0410

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000193

SERVICE ORDER NUMBER
218704

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 3-30-82 TRAILER # 291821 TRUCK # 27 PICKUP #

OPERATOR OR DRIVER Paul R. Cox LABOR

JOB LOCATION: Brownsville, Tx DESTINATION Hou, Tx

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM
TIME ARRIVED	3-30	750	(AM) PM
LOADING BEGAN			AM PM
LOADING COMPLETED	3-30	945	(AM) PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
		59 south to 77 south	
		77 south to 59 west	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291835

TRAILER/BIN PU 291821

DATE/TIME

DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 350274

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0411

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T·X·D·0·0·8·1·1·4·0·9·2 | Manifest Document No. 6·4·0·3·5

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004939 4
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T·X·D·0·5·0·6·4·1·4·6·3

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 90 78C
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2380	BA	44020	P/C T	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL. UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA Cortez | Signature: Belia Cortez | Month 04 Day 01 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul B. Cox | Signature: Paul B. Cox | Date: Month 04 Day 01 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
charged 107 yds

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J HENDERSON | Signature: | Month 04 Day 02 Year 92

BROWNING-FERRIS INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 02 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original / Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0412

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0413

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 3

2. Page 1 of 2 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MR. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: # 00004939
B. State Generator's ID:
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 472-7401
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 [illegible] 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 90 78C
HOUSTON, TEXAS 77088
10. US EPA ID Number:

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2380	BA	44020	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
DFLTX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL. UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 0 4 | Day 0 1 | Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date
Printed/Typed Name: PAUL B. COX | Signature: Paul B. Cox | Month 0 4 | Day 0 1 | Year 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials | Date
Printed/Typed Name | Signature | Month | Day | Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date
Printed/Typed Name | Signature | Month | Day | Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0414

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4282
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291821 / 291835
TRUCK LINE WPJ
CUSTOMER Union Carbide
CARGO

7:45 AM 04 01 92
34280 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

9:59 AM 04 01 92
78300 lb
34280 lb TR
44020 lb NET

PUBLIC WEIGHER

Truck Driver

Certified Weigher

BRA 0415

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000.99.1

SERVICE ORDER NUMBER 218705

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 4-1-92 TRAILER # 291835 TRUCK # 27 PICKUP #

OPERATOR OR DRIVER Paul R. Cox LABOR

JOB LOCATION: Brownsville Tex DESTINATION Houston Tex

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-1-92	7:45	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	4-1-92	10:00	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
		59 south to 77 south	
		77 south to 59 south	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291821 DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU 291835 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 351072

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0416

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-92

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number 100004965

B. State Generator's ID 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID 20863

D. Transporter's Phone (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID H026

H. Facility's Phone (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E NA 9188	2275	B A	43780	T	PC 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE, ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/8157J

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 4 | Day 1 | Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: H. B COX | Signature: H. B. Cox | Date: Month 04 | Day 01 | Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month | Day | Year

FACILITY

19. Discrepancy Indication Space
charged 107 yds

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: J HENDERSON | Signature | Date: Month 4 | Day 2 | Year 92

BROWNING-FERRIS, INC
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 02 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

107 yds

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0417

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) * If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0418

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004965

B. State Generator's ID: 31106

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 4026

D. Transporter's Phone: (713) 452-5100

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E NA 9188	2275	B A	43780	T	PC L79300
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: DELIA CORTEZ — Signature: Belia Cortez — Month 4 Day 1 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name: H. B Cox — Signature: H.B. Cox — Month 04 Day 01 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name — Signature — Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0419

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 № 4281
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291849/291827
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

Manifest #
0000 4965

7:44 AM 04 01 92
34280 lb

9:26 AM 04 01 92
78060 lb
34280 lb TR
43780 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHER STATE OF TEXAS

Truck Driver

Certified Weigher

BRA 0420

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 2006426

SERVICE ORDER NUMBER 218650

CUSTOMER: Union Carbide — P.O. # — RELEASE #

DATE: 4-1-92 — TRAILER # 191809 / 291827 — TRUCK # 28 — PICKUP #

OPERATOR OR DRIVER: O.B. Coil — LABOR

JOB LOCATION: Brownsville, Tx — DESTINATION: Houston, Tx

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM (X) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED		7:45	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED		9:45	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	Tx	US 59 - I 1577	Tx mile

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Project Load - add 175 - total 2275

TRAILER/BIN DROPPED # 191809 — DATE/TIME 4-1-92

TRAILER/BIN PU 291827 — DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE O.B. Coil

ENDING MILEAGE

BEGINNING MILEAGE 432010

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0421

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000496

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION , INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2200	BA	43560	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR
Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 4 Day 3 Year 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: PAUL R COY | Signature: Paul R. Coy | Date: Month 04 Day 03 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

BROWNING-FERRIS, INC
McCARTY RD. LANDFILL
TDH PERMIT # 261

FACILITY
19. Discrepancy Indication Space
charged 107 yds

APR 04 1992 107 YDS

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: T Wilson | Signature: T Wilson | Date: Month 4 Day 4 Year 92

11013 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0422

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0423

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/407

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 4

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number: 00004960

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION , INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40367

D. Transporter's Phone: (713) 492-5101

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONTH HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2200	BA	43560	Y	79390
	b.					
	c.					
	d.					

GENERATOR

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month 4 Day 3 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul B Coy | Signature: Paul B. Coy | Date: Month 04 Day 03 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0424

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4323
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291835/291821
TRUCK LINE WPT
CUSTOMER Union Carbide
CARGO

8:01 AM 04 03 92
34280 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

9:27 AM 04 03 92
77840 lb
34280 lb TR
43560 lb NET

PUBLIC WEIGHER

Truck Driver

Certified Weigher

BRA 0425

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 4960

SERVICE ORDER NUMBER 218706

CUSTOMER: Union Carbide P.O. #: RELEASE #:

DATE: 4-3-92 TRAILER # 791821 TRUCK # 27 PICKUP #:

OPERATOR OR DRIVER: Paul B Cox LABOR:

JOB LOCATION: Brownsville Tx DESTINATION: Houston

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN/FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-3-92	8 00	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	4-3-92	9 30	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 791835

TRAILER/BIN PU 221821

DATE/TIME

DATE/TIME

SHIPPER'S SIGNATURE Paul Wells

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Paul B Cox

ENDING MILEAGE

BEGINNING MILEAGE 351871

TOTAL TRIP MILES

CUSTOMER SIGNATURE Paul Wells
CONFIRMS TIME IN PLANT

BRA 0426

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/410

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: T X D 0 0 8 1 1 4 0 9 2
Manifest Document No.: 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004961
B. State Generator's ID: 81108
C. State Transporter's ID: 403693
D. Transporter's Phone: (713) 452-1502
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION , INC.
6. US EPA ID Number: TX D 0 5 0 6 4 1 4 63

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL ~~90~~
11013 OLD BEAUMONT HIGHWAY ~~48~~
HOUSTON, TEXAS 77078

10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2350	BA	44760	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI# TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIE INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	4	3	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
H.B. Cox	H. B. Cox	4	3	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

FACILITY

19. Discrepancy Indication Space
Charged 107 yds

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year
T Wilson	T Wilson	4	9	92

BFI MCCARTY RD. LANDFILL
TDH-ER
APR 04 1992
OLD BEAUMONT HWY
77078
HOUSTON, TEXAS
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0427

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.


(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0428



BRA 0429

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 Manifest Document No. 6 4 0 3 4
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number 00004961
B. State Generator's ID
C. State Transporter's ID
D. Transporter's Phone
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID H 0261
H. Facility's Phone (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: TX D 0 5 0 6 4 1 4 63
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY 48, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, NOO.S. ORM-E NA 9188	2350	BA	44760	Y	179390
	b.					
	c.					
	d.					

GENERATOR

I. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BYLP TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIE INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	4	3	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
A.B. COX	A.B. Cox	04	03	92

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0430

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4322
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291827/291849
TRUCK LINE WPT
CUSTOMER Union Carbide
CARGO

manifest # 4961

8:00 AM 04 03 92
34280 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

9:22 AM 04 03 92
79040 lb
34280 lb TR
44760 lb NET

QB Carl

Truck Driver

PUBLIC WEIGHER STATE OF TEXAS

Certified Weigher

BRA 0431

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 10204/9?

SERVICE ORDER NUMBER
218651

CUSTOMER: Union Carbide — P.O. # — RELEASE #

DATE: 4-3-92 — TRAILER # 291827 / 291849 — TRUCK # 78 — PICKUP #

OPERATOR OR DRIVER: [illegible] — LABOR

JOB LOCATION: Brownsville TX — DESTINATION Houston TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN/ FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE		UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED				AM PM
TIME ARRIVED	4-3	800	(AM) PM	UNLOAD BEGAN				AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE				AM PM
LOADING COMPLETED	~	945	(AM) PM	ARRIVED YARD				AM PM

LUNCH OR NON-WORKING: OUT _____ am ( ) pm IN _____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	TX	US 59 - US 77	TX in

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: — RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291827
TRAILER/BIN PU 291849

DATE/TIME 4/3/92 800
DATE/TIME

SHIPPER'S SIGNATURE [illegible]
CONSIGNEE'S SIGNATURE
DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE
BEGINNING MILEAGE 432768
TOTAL TRIP MILES

[illegible]
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0432

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-92

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number: 00004948

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL 90
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: TH02610

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	11. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2300	BA	43,700	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 04 06 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: PAUL B. COX — Signature: Paul B. Cox — Date: Month Day Year: 04 06 92

18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space: 107 Y

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J. Henderson — Signature: J. Henderson — Date: Month Day Year: 4 7 92

BROWNING FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0433

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0434

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008140816 — Manifest Document No.

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone

A. State Manifest Document Number: 0000498

B. State Generator's ID:

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: TXD050641463

C. State Transporter's ID: 40369

7. Transporter 2 Company Name
8. US EPA ID Number

D. Transporter's Phone: (713) 452-1400

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONTH HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2300	BA	43700	T	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: 2A TRIABEK ASBESTOS

K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 04 04 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name: PAUL B. COX — Signature: Paul B. Cox — Month Day Year: 04 04 92

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name — Signature — Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0435

QUALITY WEIGHING SERVICES, INC.

QWS

8204 E. 14th. Street - Brownsville, Texas 78521 No 4333
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291821/291835
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

~~5:34~~ PM 04 06 92
754 AM 34360 lb

~~6:04~~ PM 04 06 92
832 AM 78060 lb
34360 lb TR
43700 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

PUBLIC WEIGHER

Truck Driver

Certified Weigher

BRA 0436

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000[illegible]

SERVICE ORDER NUMBER 218707

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 4-6-92 TRAILER # 291835 TRUCK # 27 PICKUP #

OPERATOR OR DRIVER Paul B. Coy LABOR

JOB LOCATION: Brownsville Tx DESTINATION Pasadena Tx

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

	LOADING DATE	LOADING TIME	CIRCLE ONE		UNLOADING DATE	UNLOADING TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-6	800	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	4-6	900	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
4-6		Hwy 59 Hwy 77	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291821

DATE/TIME

SHIPPER'S SIGNATURE [signature]

TRAILER/BIN PU 291895

DATE/TIME

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE [signature]

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE [signature]
CONFIRMS TIME IN PLANT

BRA 0437

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No.: 6 4 0 3 4
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 00004949
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H026
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY ~~48~~ 90
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2200	BA	45,480	P X	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR
Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month Day Year: 04 06 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.R. COX | Signature: A.R. Cox | Date: Month Day Year: 04 06 92
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.R. COX ABC | Signature: A.R. ABC | Date: Month Day Year:

FACILITY
19. Discrepancy Indication Space

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 7 1992
1102 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078
713-675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19
Printed/Typed Name: J Henderson | Signature: J Henderson | Date: Month Day Year: 4 7 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0438

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0439

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 00004949
B. State Generator's ID: 3110
C. State Transporter's ID:
D. Transporter's Phone: (713) 452-1501
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: R0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WDE TRANSPORTATION, INC. | 6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name: | 8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY 48, HOUSTON, TEXAS 77078 | 10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2200	BA	45,480	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: K. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 04 Day 06 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: O.B. Cox | Signature: O.B. Cox | Date: Month 04 Day 06 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: O.B. Cox ABC | Signature: O. Pabc | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0440

QUALITY WEIGHING SERVICES, INC.

QWS

8204 E. 14th. Street - Brownsville, Texas 78521 Nº 4334
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291849/291827
TRUCK LINE WPI
CUSTOMER UNION Carbide
CARGO

~~5:38~~ PM 04 06 92
755 34480 lb

9:16 AM 04 06 92
79960 lb
34480 lb TR
45480 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd.

Main 4
4949

AB Cod

PUBLIC WEIGHER

Truck Driver

Certified Weigher

BRA 0441

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 6000 [illegible]

SERVICE ORDER NUMBER
218652

CUSTOMER: Union Carbide P.O. #: RELEASE #:

DATE: 4-6-92 TRAILER #29849/29827 TRUCK # 28 PICKUP #:

OPERATOR OR DRIVER: [illegible] LABOR:

JOB LOCATION: Brownsville Co. 24 DESTINATION Houston

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-6	800	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	—	945	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 29849
TRAILER/BIN PU 29827

DATE/TIME 4/6/92 0800
DATE/TIME —

SHIPPER'S SIGNATURE [illegible]
CONSIGNEE'S SIGNATURE
DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE
BEGINNING MILEAGE 113375
TOTAL TRIP MILES

CUSTOMER SIGNATURE [illegible]
CONFIRMS TIME IN PLANT

BRA 0442

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: T X D 0 0 8 1 1 4 0 92 | Manifest Document No.: 6 4 0 34

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone: (512) 831-4501

A. State Manifest Document Number: 0004942
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 1 4 1 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48-90
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2175	BA	43920	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 04 Day 08 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JOE L. VILLARREAL | Signature: Joe L. Villarreal | Date: Month 04 Day 08 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
Chg'ed 107 yds
107Y

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261

APR 9 1992

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

Printed/Typed Name: J Henderson | Signature: J Henderson | Date: Month 4 Day 9 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0443

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0444

TEXAS WATER COMMISSION
P.O. Box 13087 Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 00940 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000494
B. State Generator's ID:
C. State Transporter's ID:
D. Transporter's Phone:

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: TXD082061416 3

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
WPI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONTHHIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2175	BA	43920	Y	179390
	b.					
	c.					
	d.					

GENERATOR

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFIFTX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 04 Day 08 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: JOE L. VILLARREAL | Signature: Joe L. Villarreal | Date: Month 04 Day 08 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0445

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4445
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 5001 TLR 5001T
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

12:58 PM 04 08 92
79720 lb
35800 lb TR
43920 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHER

Truck Driver

Certified Weigher

BRA 0446

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST

SERVICE ORDER NUMBER 222095

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 4-7 TRAILER # TRUCK # PICKUP #

OPERATOR OR DRIVER LABOR

JOB LOCATION: Brownsville Tex DESTINATION Houston Tex

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN & FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD	4-7	3:00	AM (PM)
TIME ARRIVED	4-8	8:00	(AM) PM
LOADING BEGAN	4-8	9:30	(AM) PM
LOADING COMPLETED	4-8	1:00	AM (PM)

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
4-7	TEX	10 to 59 to 77	320099 E
4-9	TEX	77 to 59 to 610 to 10	L
4-8			2

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 5601A DATE/TIME 4-9 0800 SHIPPER'S SIGNATURE

TRAILER/BIN PU 5601A DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0447

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number: 00004950

B. State Generator's ID: XXXXX 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48 90 W
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E NA 9188	2400	BA	44760	X	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A: FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE: @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 04 Day 08 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: H.B. COX | Signature: H.B. Cox | Date: Month 04 Day 08 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
Chg'ed 107 yds 107YDS

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: TWilson | Signature: T.W Wilson | Date: Month 4 Day 9 Year 92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 9 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0448

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0449

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 6 2 — Manifest Document No.
2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (513) 831-4501

A. State Manifest Document Number: 000049[illegible]
B. State Generator's ID:
C. State Transporter's ID: 40361
D. Transporter's Phone: (713) 457-1405
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E NA 9188	2400	BA	44760	LB	179990
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE: @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 08 08 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.B. Cox — Signature: A.B. Cox — Date: 08 08 92
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Date:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: — Signature: — Date:

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0450

QUALITY WEIGHING SERVICES, INC.

QWS

8204 E. 14th. Street - Brownsville, Texas 78521 No 4401
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291827/291849

TRUCK LINE WPI

CUSTOMER Union Carbide

CARGO

8:15 AM 04 08 92
34420 lb

4950

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

9:53 AM 04 08 92
79180 lb
34420 lb TR
44760 lb NET

PUBLIC WEIGHER STATE OF TEXAS

Truck Driver

Certified Weigher

BRA 0451

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 6000 4950

SERVICE ORDER NUMBER

218653

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 4-8-92 TRAILER # 2791 29549 TRUCK # 28 PICKUP #

OPERATOR OR DRIVER: J.R. Cox LABOR

JOB LOCATION: Brownsville DESTINATION Houston 24

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM
TIME ARRIVED	4-8	815	AM PM
LOADING BEGAN	4-8	1030	AM PM
LOADING COMPLETED			AM PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 201427

TRAILER/BIN PU 291849

DATE/TIME 4/8/92 945

DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE J.R. Cox

ENDING MILEAGE

BEGINNING MILEAGE 432429

TOTAL TRIP MILES

CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0452

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number: 00004951

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 4890
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID ASBESTOS, N.O.S. ORM-E NA 9188	2450	BA	43.800	Y	D Ba 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/2747930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	04	08	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
PAUL B COX	Paul B. Cox	04	08	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space
Chg'ed 107 yds.

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
Tillison		04	09	92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 3 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

107yds

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0453

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW, Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0454

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6

2. Page 1 of 4 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS (512) 831-4501
4. Generator's Phone

A. State Manifest Document Number: 00004951
B. State Generator's ID: 3170
C. State Transporter's ID:
D. Transporter's Phone: (713) 433-5101
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 633-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 2
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID ASBESTOS, N.O.S. ORM-E NA 9188	2450	BA	43 800	-	2175 179920
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BRI#TX/274/930224/81581

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 04 Day 08 Year 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: Paul B Cox — Signature: Paul B. Cox — Date: Month 04 Day 08 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name: — Signature: — Date: Month Day Year

FACILITY
19. Discrepancy Indication Space
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Printed/Typed Name: — Signature: — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0455

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4398
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291835/291821
TRUCK LINE WPJ
CUSTOMER Union Carbide
CARGO

8:10 AM 04 08 92
34240 lb

10:14 AM 04 08 92
78040 lb
34240 lb TR
43800 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

pd.

PUBLIC WEIGHER

Truck Driver

Certified Weigher

BRA 0456

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 00004951

SERVICE ORDER NUMBER **218708**

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 4-8-92 TRAILER # 291821 TRUCK # 27 PICKUP #

OPERATOR OR DRIVER Paul R. Cox LABOR

JOB LOCATION: Brownsville Tex DESTINATION Hou Tex

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-8	8 15	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	4-8	10 45	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
		59 - 77	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291835

TRAILER/BIN PU 291821

DATE/TIME

DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Paul R. Cox

ENDING MILEAGE

BEGINNING MILEAGE 353498

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0457

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No.: 6 4 0 3 4
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 00004943
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 4890 WB
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS N.O.S. ORM-E NA 9188	2200	BA	43880	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

GENERATOR

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 04 10 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul B. Cox | Signature: Paul B. Cox | Date: Month Day Year: 04 10 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month Day Year:

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261

FACILITY

19. Discrepancy Indication Space
Charged 107 yds

APR 11 1992

107N

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101
Printed/Typed Name: M Epsley | Signature: | Date: Month Day Year: 4 11 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0458

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0459

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 | Manifest Document No. 2 6 4 0 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUGHTBOX 90
BROWNSVILLE, TEXAS (512) 831-4501
4. Generator's Phone

A. State Manifest Document Number: 0000494
B. State Generator's ID: 9110
C. State Transporter's ID: 40359
D. Transporter's Phone: (713) 452-1500
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 1
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY 48, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS N.O.S. ORM-E NA 9188	2200	BA	43880	Y	07390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE:@ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR: Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 04 10 92

TRANSPORTER: 17. Transporter 1 Acknowledgement of Receipt of Materials | Printed/Typed Name: Paul B. Cox | Signature: Paul B. Cox | Date: 04 10 92

18. Transporter 2 Acknowledgement of Receipt of Materials | Printed/Typed Name | Signature | Date

FACILITY: 19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Printed/Typed Name | Signature | Date

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0460

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4515
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291821/291835
TRUCK LINE WPI
CUSTOMER UNION CARBIDE
CARGO

7:48 AM 04 10 92
34320 lb

MANIFEST # 04943

8:19 AM 04 10 92
78200 lb
34320 lb TR
43880 lb NET

☐	$3.00	EMPTY ONLY
☐	$5.00	UP TO 65,000 GROSS
☑	$6.00	65,020 TO 85,000 GROSS
☐	$7.00	85,020 TO 105,000 GROSS
☐	$8.50	105,020 TO 125,000 GROSS
☐	$10.00	125,020 TO 145,000 GROSS
☐	$25.00	145,020 AND UP

PUBLIC WEIGHER

Truck Driver

Certified Weigher

BRA 0461

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000493

SERVICE ORDER NUMBER **218709**

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 4-10-92 TRAILER # 291835 TRUCK # 77 PICKUP #

OPERATOR OR DRIVER P. L. B Cox LABOR

JOB LOCATION: Brownsville Texas DESTINATION Houston Texas

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-10-92	8 00	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	4-10	8 30	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
		77 ~~south~~ north 59 south	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291821

TRAILER/BIN PU 291835

DATE/TIME

DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE P L B Cox

ENDING MILEAGE

BEGINNING MILEAGE 354620

TOTAL TRIP MILES

CUSTOMER SIGNATURE

CONFIRMS TIME IN PLANT

BRA 0462

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004944

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 4840 WO
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS N.O.S. ORME NA 9188	2200	BA	44820	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month 04 Day 10 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: A.B. Cox — Signature: G B — Date: Month 04 Day 10 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
Changed 107 yds

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: M Castaneda — Signature — Date: Month 4 Day 11 Year 92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 11 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0463

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0464

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 — Manifest Document No. 6403

2. Page 1 of — Information in the shaded area is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004944

B. State Generator's ID:

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: TXD055064463

C. State Transporter's ID: 2100

D. Transporter's Phone: (210) 532-150[illegible]

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: R026[illegible]

H. Facility's Phone: (713) 675-6101

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS N.O.S. ORME NA 9188	0200	BA	44820	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFIPTX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month 04 Day 10 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: A.B. Cox — Signature: AB Cox — Date: Month 04 Day 11 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0465

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 4516
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 29184S
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

7:50 AM 04 10 92
34320 lb

#04544

8:33 AM 04 10 92
79140 lb
34320 lb TR
44820 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

AB Cof

Truck Driver

PUBLIC WEIGHER BURT COUNTY NEBR.

Certified Weigher

BRA 0466

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/450

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 4/9x14

SERVICE ORDER NUMBER 218654

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE 4-10-97 TRAILER # 291549 / 291827 TRUCK # 28 PICKUP #

OPERATOR OR DRIVER C.R. Cal LABOR

JOB LOCATION: Brownsville TX DESTINATION Houston TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4/10/97	745	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	—	845	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291549

TRAILER/BIN PU 291827

DATE/TIME 4/10/97

DATE/TIME —

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE C.R. Cal

ENDING MILEAGE

BEGINNING MILEAGE 435 905

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0467

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004952
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 90 48 WB
HOUSTON, TEXAS 77078
10. US EPA ID Number:

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2360	BA	45040	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/8157.1

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENICES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month Day Year: 04 13 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.B. COX | Signature: AB Cox | Date: Month Day Year: 04 13 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month Day Year:

FACILITY

19. Discrepancy Indication Space
Changed 107 yds

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: G. HENDERSON | Signature: G Henderson | Date: Month Day Year: 4 14 92

BROWNING-FERRIS, INC
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 14 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0468

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0469

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004952

B. State Generator's ID: 108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6

C. State Transporter's ID: 4036

D. Transporter's Phone: (713) 674-7520

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
WPI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, NOO,S. ORM-E NA 9188	2360	BA	45040	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above: NFI#TX/274/930224781571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: DELIA Cortez — Signature: Belia Cortez — Month Day Year: 04 13 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: H.R. Cox — Signature: HR Cox — Month Day Year: 04 13 92 — Date

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Month Day Year — Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19:
Printed/Typed Name — Signature — Month Day Year — Date

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0470

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 4541
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291827/291849
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

7:49 AM 04 13 92
34100 lb

Main #
D0004952

9:48 AM 04 13 92
79140 lb
34100 lb TR
45040 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

PD

ABCo

Truck Driver

PUBLIC WEIGHER COUNTY OF CAMERON TEXAS

Certified Weigher

BRA 0471

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 2000495

SERVICE ORDER NUMBER
218655

CUSTOMER: Union Carbide P.O. #: RELEASE #:

DATE: 4-13-92 TRAILER # 291827 / 291849 TRUCK # 26 PICKUP #:

OPERATOR OR DRIVER: R. Cox LABOR:

JOB LOCATION: Brownsville DESTINATION: Newton

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN/ FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-13	750	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	"	1015	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	TX	US 59 - US 77	24 mi
		2360 bags net 45040 gross 79140	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291827
TRAILER/BIN PU 291849

DATE/TIME 4-13-92
DATE/TIME "

SHIPPER'S SIGNATURE [signature]
CONSIGNEE'S SIGNATURE
DRIVER'S SIGNATURE R. Cox

ENDING MILEAGE
BEGINNING MILEAGE 436051
TOTAL TRIP MILES

CUSTOMER SIGNATURE [signature]
CONFIRMS TIME IN PLANT

BRA 0472

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/456

TEXAS WATER COMMISSION
P.O. Box 13087, Capital Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000495 3

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY ~~48~~ 90 UO
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E NA 9188	2435	BA	43560	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI-TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 04 13 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name: Paul B Cox — Signature: Paul B. Cox — Month Day Year: 04 13 92

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space
Charged 107 yds

1074

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name — Signature — Date — Month Day Year: 4 14 92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 14 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
(713) 675-6101

TWC-0311 (Rev. 01/01/89) White - original / Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0473

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver, declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0474

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS BELIA CORTEZ
STARTROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004953
B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number
G. State Facility's ID: R0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E NA 9188	2435	BA	43560	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A) FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224781571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 0 4 Day 1 3 Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul B Cox — Signature: Paul B. Cox — Date: Month 0 4 Day 1 3 Year 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0475

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4540
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 29/835/29/821
TRUCK LINE WPJ
CUSTOMER Union Carbide
CARGO

7:48 AM 04 13 92
34040 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

10:08 AM 04 13 92
77600 lb
34040 lb TR
43560 lb NET

PUBLIC WEIGHER COUNTY OF CAMERON, TEXAS

Truck Driver

Certified Weigher

BRA 0476

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/460

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000324 3

SERVICE ORDER NUMBER
218710

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE 4-13-79 TRAILER # 291821 TRUCK # 27 PICKUP #

OPERATOR OR DRIVER L. B. Cox LABOR

JOB LOCATION: Brownsville Tx DESTINATION Hix Tx

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-13	745	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	4/13	10 15	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ( ) am ( ) pm IN ( ) am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291835

TRAILER/BIN PU 291821

DATE/TIME

DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 355121

TOTAL TRIP MILES

CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0477

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512 831-4501

4. Generator's Phone ( )

5. Transporter 1 Company Name
WPI TRANSPORTATION, INC.

6. US EPA ID Number
T X D 0 5 0 6 4 1 4 6 3

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 4890
HOUSTON, TEXAS 77078

10. US EPA ID Number

A. State Manifest Document Number: 00004954
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H 0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E NA 9188	2200	BA	44600	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA Cortez — Signature: Belia Cortez — Month 04 Day 15 Year 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: Paul B. Cox — Signature: Paul B. Cox — Month 04 Day 15 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name — Signature — Month Day Year

FACILITY
19. Discrepancy Indication Space: Chg'ed 107 yds

BROWNING-FERRIS, INC
MCCARTY RD. LANDFILL
TDH PERMIT # 261
APR 16 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J Henderson — Signature: J Henderson — Month 4 Day 16 Year 92

TWC-0311 (Rev. 01/01/89)

White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0478

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0479

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D O 0 6 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone

A. State Manifest Document Number: 00004954

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: A0369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTEYROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E NA 9188	2200	BA	44600	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFL#TX/274/930224/85571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 04 Day 15 Year 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: Paul B. Cox — Signature: Paul B. Cox — Month 04 Day 15 Year 92 — Date
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name — Signature — Month Day Year — Date

FACILITY
19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Printed/Typed Name — Signature — Month Day Year — Date

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0480

QUALITY WEIGHING SERVICES, INC.

QWS

8204 E. 14th. Street - Brownsville, Texas 78521 No 4580

(Located at Port of Brownsville)

Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 274 TLR 291821 / 291827

TRUCK LINE UPI

CUSTOMER Union Carbide

CARGO

7:52 AM 04 15 92

34300 lb

0000 4954

8:38 AM 04 15 92

78900 lb

34300 lb TR

44600 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

PD

PUBLIC WEIGHER

Truck Driver

Certified Weigher

BRA 0481

WPI Transpprtation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 000 [illegible]

SERVICE ORDER NUMBER 222443

CUSTOMER: Union Carbide — P.O. # — RELEASE #

DATE: 4-19-79 — TRAILER # 29122 — TRUCK # 27 — PICKUP #

OPERATOR OR DRIVER: Paul B. Cox — LABOR

JOB LOCATION: Brownsville — DESTINATION Houston

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

	LOADING DATE	LOADING TIME	CIRCLE ONE		UNLOADING DATE	UNLOADING TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-19-79	8:00	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	4-19-79	9:00	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 29122 — DATE/TIME

TRAILER/BIN PU 29122 — DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Paul B. Cox

ENDING MILEAGE

BEGINNING MILEAGE 35511

TOTAL TRIP MILES

CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0482

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE. BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004955

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATON, INC.

6. US EPA ID Number

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONTH HIGHWAY 48 90 W
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARADOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E NA 9188	4200	BA	42360	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/2747930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA Cortez | Signature: Belia Cortez | Month 04 Day 15 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: A. B Cox | Signature: A B Cox | Date: Month 04 Day 15 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
chg'ed 107 yds

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 16 1992
11013 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078
713-675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: A. Henderson | Signature: A. Henderson | Date: Month 4 Day 16 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0483

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0484

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 8 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004956
B. State Generator's ID: 31108
C. State Transporter's ID: 4086Y
D. Transporter's Phone: (713) 452-1900
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H 026
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATON, INC. — 6. US EPA ID Number:
7. Transporter 2 Company Name: — 8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONTH HIGHWAY 48, HOUSTON, TEXAS 77078 — 10. US EPA ID Number:

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARADOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORMBE NA 9188	0200	BA	42360	Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above: BPI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GOOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSHRE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable International and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA Cortez — Signature: Belia Cortez — Month 04 Day 15 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: A. B Cox — Signature: A B Cox — Date: Month 04 Day 15 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name: — Signature: — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: — Signature: — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0485

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4581
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 29/849
TRUCK LINE WPT
CUSTOMER Union Carbide
CARGO

7:54 AM 04 15 92
34360 lb

8:42 AM 04 15 92
76720 lb
34360 lb TR
42360 lb NET

☐	$3.00	EMPTY ONLY
☐	$5.00	UP TO 65,000 GROSS
☑	$6.00	65,020 TO 85,000 GROSS
☐	$7.00	85,020 TO 105,000 GROSS
☐	$8.50	105,020 TO 125,000 GROSS
☐	$10.00	125,020 TO 145,000 GROSS
☐	$25.00	145,020 AND UP

Pd 00004955

AB Co

Truck Driver

PUBLIC WEIGHER

Certified Weigher

BRA 0486

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST # 1000 49[illegible]

SERVICE ORDER NUMBER
218656

CUSTOMER: [illegible] P.O. # RELEASE #

DATE: 11-15-91 TRAILER # 29549 TRUCK # 28 PICKUP #

OPERATOR OR DRIVER A.B.C.D LABOR

JOB LOCATION: [illegible] DESTINATION Harlingen

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED		900	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED		900	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
		1200 [illegible]	
		N. 280 [illegible]	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 91849
DATE/TIME 11-15-91
SHIPPER'S SIGNATURE [illegible]

TRAILER/BIN PU
DATE/TIME
CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE
BEGINNING MILEAGE 431 902
TOTAL TRIP MILES

[illegible]
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0487

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004956
B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number:
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48 90
HOUSTON, TEXAS 77078 WD
10. US EPA ID Number:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2100	BA	43560	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/920224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE. @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 04 20 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: A.B. COF — Signature: A.B. — Date: Month Day Year: 04 20 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name: — Signature: — Date: Month Day Year:

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 21 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

FACILITY
19. Discrepancy Indication Space: 107y
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J. HENDERSON — Signature: J. Henderson — Date: Month Day Year: 4 21 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0488

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0489

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114403 — Manifest Document No. 00004956

2. Page 1 of 4 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004956
B. State Generator's ID: 3110
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 4520504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0251
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC. — 6. US EPA ID Number:

7. Transporter 2 Company Name: — 8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078

10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-B NA 9188	2100	BA	43560	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BRFTX/274/920224/91571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE. @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA Cortez — Signature: Belia Cortez — Month Day Year: 04 20 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: A.B. Cox — Signature: A.B. Cox — Date: Month Day Year: 04 20 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name: — Signature: — Date: Month Day Year:

FACILITY
19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: — Signature: — Date: Month Day Year:

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0490

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4639
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291835/291849
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

8:05 AM 04 20 92
34320 lb

0000 49 56

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

8:42 AM 04 20 92
77880 lb
34320 lb TR
43560 lb NET

AB Carl

Truck Driver

PUBLIC WEIGHER STATE OF CALIFORNIA

Certified Weigher

BRA 0491

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000195 6

SERVICE ORDER NUMBER 21865?

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 4-20-92 TRAILER # TRUCK # 28 PICKUP #

OPERATOR OR DRIVER: O.R. Coy LABOR

JOB LOCATION: Brownsville TX DESTINATION Houston TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-20-92	815	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED		900	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	TX	US 59 · US 77	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 191835 DATE/TIME 4/20/92 SHIPPER'S SIGNATURE

TRAILER/BIN PU DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE O R Coy

ENDING MILEAGE

BEGINNING MILEAGE 437747

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0492

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D Q 0 8 1 1 4 0 92 | Manifest Document No. 0 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004957

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY ~~90~~
HOUSTON, TEXAS 77078
10. US EPA ID Number

G. State Facility's ID: H 0 261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2100	BA	44700	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224781571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 04 Day 20 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Paul B. Cox | Signature: Paul B. Cox | Date: Month 04 Day 20 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
107 Y

BROWNING-FERRIS, INC
McCARTY RD. LANDFILL
TDH PERMIT # 261
APR 21 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713 675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: J HENDERSON | Signature: J Henderson | Date: Month 4 Day 21 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0493

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly).

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0494

TEXAS WATER COMMISSION
P.O. Box 13087 Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 4 | 2. Page 1 of | Information in the shaded area is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004957
B. State Generator's ID: 11108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 5 7 4 6
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 453-1401

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number
G. State Facility's ID: H O 261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2100	BA	44700	LB W	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI TX/27A/930224/91571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 04 | Day 20 | Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul B. Cox | Signature: Paul B. Cox | Month 04 | Day 20 | Year 92 | Date

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Month | Day | Year | Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Month | Day | Year | Date

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0495

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 № 4640
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291827/291821
TRUCK LINE WPJ
CUSTOMER Union Carbide
CARGO

8:06 AM 04 20 92
34260 lb

0000 4957

8:46 AM 04 20 92
78960 lb
34260 lb TR
44700 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

PD

PUBLIC WEIGHER COUNTY OF CAMERON

Truck Driver

Certified Weigher

BRA 0496

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 9257

SERVICE ORDER NUMBER 222444

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 4-20-92 TRAILER # 291821 TRUCK # 177 PICKUP #

OPERATOR OR DRIVER Paul B. Coy LABOR

JOB LOCATION: Brownsville, Tx DESTINATION Hou, Tx

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-20	8 00	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	4-20	9 00	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
		77 to 59	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291827 DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Paul B. Coy

ENDING MILEAGE

BEGINNING MILEAGE 357101

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0497

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No.: 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000493[illegible]

B. State Generator's ID: [illegible]31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40360

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48-90 W
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2100	BA	35320	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BEI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month 04 | Day 22 | Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Paul B Cox | Signature: Paul B. Cox | Date: Month 04 | Day 22 | Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month | Day | Year

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261

FACILITY

19. Discrepancy Indication Space
Chg'ed → 107y

APR 23 1992

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: J Henderson | Signature: J Henderson | 11013 OLD BEAUMONT HWY. HOUSTON, TEXAS 77078 713-675-6101 | Date: Month 04 | Day 23 | Year 92

TWC-031 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0498

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0499

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	TXD088114092
Manifest Document No.	64034
2. Page 1 of	1
Information in the shaded areas is not required by Federal law.	

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (312) 831-4501

A. State Manifest Document Number: 00004936
B. State Generator's ID: 3108
C. State Transporter's ID: 40368
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 80261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: TXB050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY 48, HOUSTON, TEXAS 77078
10. US EPA ID Number:

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2100	BA	35320	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI-TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	04	22	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
PAUL B COX	Paul B. Cox	04	22	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY


19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0500



QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4800
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291821/291835

TRUCK LINE WPJ

CUSTOMER Union Carbide

CARGO

7:54 AM 04 22 92
34480 lb

00004935

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

8:38 AM 04 22 92
69800 lb
34480 lb TR
35320 lb NET

PUBLIC WEIGHER
COUNTY OF CAMERON STATE

Truck Driver

Certified Weigher

BRA 0501

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000/955

SERVICE ORDER NUMBER 22445

CUSTOMER Union Carbide P.O. # RELEASE #

DATE 4-22-79 TRAILER # 291835 TRUCK # 27 PICKUP #

OPERATOR OR DRIVER Paul B. Cox LABOR

JOB LOCATION Brownsville, Tex DESTINATION Elm Tex

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM
TIME ARRIVED	4-22	8:00	AM PM
LOADING BEGAN			AM PM
LOADING COMPLETED	4-22	8:45	AM PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT _____ am ( ) pm IN _____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291821

TRAILER/BIN PU 291835

DATE/TIME

DATE/TIME

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Paul B. Cox

ENDING MILEAGE

BEGINNING MILEAGE 357569

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0502

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 0000493 6
B. State Generator's ID: 31108
C. State Transporter's ID: 40360
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 4890 WB
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O. S ORM-E NA 9188	2100	BA	39120	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 04 22 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: G.B. COX — Signature: G.B. Cox — Date: Month Day Year 04 22 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name: — Signature: — Date: Month Day Year

FACILITY
19. Discrepancy Indication Space

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
Chg'd APR 23 1992
10716

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J. Henderson — Signature: J. Henderson — Date: Month Day Year 4 23 92

11013 OLD BEAUMONT HWY
HOUSTON, TX 77078
713 675 6101

TWC-0311 (Rev. 01/01/89) White-original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0503

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/487

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS).

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0504

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-9

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 640334

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 00004936
B. State Generator's ID: 0108
C. State Transporter's ID:
D. Transporter's Phone:
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: R 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: TXD055064163
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS WUBSTANCE SOLID/ ASBESTOS, N.O, S ORM-E NA 9188	2100	BA	39120	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI TX 274/930224/81371

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE, CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
Belia Cortez	Belia Cortez	04	22	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
O.R. Cox	O.B. Cox	04	22	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0505

QUALITY WEIGHING SERVICES, INC.

QWS

8204 E. 14th. Street - Brownsville, Texas 78521 No 4799
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291849/291827
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO 60004936

7:53 AM 04 22 92
34440 lb

8:51 AM 04 22 92
73560 lb
34440 lb TR
39120 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

AB Carl

Truck Driver

PUBLIC WEIGHER STATE OF TEXAS

Certified Weigher

BRA 0506

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 4932

SERVICE ORDER NUMBER
218658

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 4-22-92 TRAILER # 791829 TRUCK # 28 PICKUP #

OPERATOR OR DRIVER O.R. Cole LABOR

JOB LOCATION: Brownsville DESTINATION Houston TX

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-22	800	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED		915	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	TX	I-5 77 - I-5 69	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 791809
TRAILER/BIN PU 291827

DATE/TIME 4-22-92
DATE/TIME

SHIPPER'S SIGNATURE
CONSIGNEE'S SIGNATURE
DRIVER'S SIGNATURE O.R. Cole

ENDING MILEAGE
BEGINNING MILEAGE 438580
TOTAL TRIP MILES

CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0507

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/491

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000493 7
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY 4890 VD, HOUSTON, TEXAS 77088
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	200	BA	40700	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 04 24 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: A.B. Cox — Signature: A.B. — Date: Month Day Year: 04 24 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name: — Signature: — Date: Month Day Year:

FACILITY
19. Discrepancy Indication Space: chg'ed 107yds
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Printed/Typed Name: T Wilson — Signature: T Wilson — Date: Month Day Year: 4 25 92

BROWNING-FERRIS, INC.
MCCARTY RD. LANDFILL
TDH PERMIT # 261
APR 25 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0508

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "X" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0509

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TTXD008114092 — Manifest Document No. 64034

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000493
B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: TXD050641463
C. State Transporter's ID: A0369
D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONTHHIGHWAY 48
HOUSTON, EXXAS 77088
10. US EPA ID Number:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2100	BA	40700	LB	L79390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFITX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month 04 Day 24 Year 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: H.B. Cox — Signature: H.B. Cox — Month 04 Day 24 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name: — Signature: — Month Day Year

FACILITY
19. Discrepancy Indication Space
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Printed/Typed Name: — Signature: — Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0510

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 4913
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291827 / 291849
TRUCK LINE WPJ
CUSTOMER Union Carebide
CARGO

0000 4937

7:44 AM 04 24 92
34280 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd.

8:39 AM 04 24 92
74980 lb
34280 lb TR
40700 lb NET

PUBLIC WEIGHER COUNTY OF CAMERON

GB Corp
Truck Driver

Certified Weigher

BRA 0511

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 19374

SERVICE ORDER NUMBER **218659**

CUSTOMER: Union C. C.-Ll. P.O. # RELEASE #

DATE: 4-24-79 TRAILER # TRUCK # 28 PICKUP #

OPERATOR OR DRIVER: G.K.Co LABOR

JOB LOCATION: Brownsville, Tx DESTINATION Houston, Tx

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-24	745	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED		845	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	TX	US 77 - US 59	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 791877

DATE/TIME 4-24-79

SHIPPER'S SIGNATURE

TRAILER/BIN PU

DATE/TIME

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 439377

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0512

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000494

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 752-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 4890 WD
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2000	BA	38100	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 04 24 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Paul B. Cox — Signature — Date: Month Day Year: 04 24 92

BROWNING-FERRIS
McCARTY RD. LANDFILL
TDH PERMIT # 261

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

APR 25 1992

FACILITY

19. Discrepancy Indication Space: chg'ed 107 yds

11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: A Wilson — Signature: A Wilson — Date: Month Day Year: 4 25 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0513

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0514

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 000 8 1 1 4 0 9 Manifest Document No. 7 8 4 0 3
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000493
B. State Generator's ID: 3110
C. State Transporter's ID: 0050
D. Transporter's Phone: (713) 452-1400
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: HD261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY 48
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2000	BA	3.8100	LB Y	179.90
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BRI-TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4500 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ
Signature: Belia Cortez
Month 04 Day 24 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul D. Cox
Signature: Paul D. Cox
Date: Month 04 Day 24 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name:
Signature:
Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0515

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No. 4912
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291835/291821
TRUCK LINE WPT
CUSTOMER UNION CARBIDE
CARGO

7:43 AM 04 24 92
34360 lb
8:36 AM 04 24 92
72460 lb
34360 lb TR
38100 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

PD

00004947

PUBLIC WEIGHER COUNTY OF CAMERON TEXAS

Truck Driver

Certified Weigher

BRA 0516

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000494

SERVICE ORDER NUMBER 222446

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE 4-24-92 TRAILER # 791821 TRUCK # 29 PICKUP #

OPERATOR OR DRIVER Paul B. Cox LABOR

JOB LOCATION: Brownsville Tex DESTINATION Hou Tex

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN ( ) FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-24	7 45	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	4-24	8:45	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
		77 South - 59 South	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Full Trailer 38100 NET

TRAILER/BIN DROPPED # 791835

TRAILER/BIN PU 791821

DATE/TIME

DATE/TIME

SHIPPER'S SIGNATURE Earl Wells

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Paul B. Cox

ENDING MILEAGE

BEGINNING MILEAGE 358698

TOTAL TRIP MILES

CUSTOMER SIGNATURE Earl Wells
CONFIRMS TIME IN PLANT

BRA 0517

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000492
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H026[illegible]
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2100	B A	35540	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI-TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA Cortez | Signature: Belia Cortez | Month 04 Day 28 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Paul B. Cox | Signature: Paul B. Cox | Date: Month 04 Day 28 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space: changed → 1074
BROWNING-FERRIS, INC. McCARTY RD. LANDFILL TDH PERMIT # 261
APR 28 1992

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest ~~except as noted in Item 19.~~
Printed/Typed Name: J. Henderson | Signature: J. Henderson | 11013 OLD BEAUMONT HWY. HOUSTON, TEXAS 77078 713-675-6101 | Date: Month 4 Day 29 Year 92

TWC-0011 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0518

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0519

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. / Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	TXD008114092 / 64034		

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004920
B. State Generator's ID: 61108
C. State Transporter's ID: 40169
D. Transporter's Phone: (713) 452-5081
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: TXD050641463 (00004920)
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2100	B A	35540	LB E	170390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	04	28	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Paul B. Cox	Paul B. Cox	04	28	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0520

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 5170
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 27 TLR 291821 / 291835
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

7:45 AM 04 28 92
34500 lb

0000 4920

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

8:39 AM 04 28 92
70040 lb
34500 lb TR
35540 lb NET

PUBLIC WEIGHER STATE OF TEXAS

Truck Driver

Certified Weigher

BRA 0521

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 000049120

SERVICE ORDER NUMBER 22447

CUSTOMER Union Carbide P.O. # RELEASE #

DATE 4-28-79 TRAILER # 291835 TRUCK # 27 PICKUP #

OPERATOR OR DRIVER Paul R. Coy LABOR

JOB LOCATION: Brownsville, Tx DESTINATION Van, Tx

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM
TIME ARRIVED	4-28	7:45	(AM) PM
LOADING BEGAN			AM PM
LOADING COMPLETED	4-28	9:00	(AM) PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ( ) am ( ) pm IN ( ) am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
		US 59 US 77	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 291821 DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU 291835 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Paul R. Coy

ENDING MILEAGE

BEGINNING MILEAGE 359761

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0522

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/506

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T·X·D·0·0·8·1·1·4·0·9·2 Manifest Document No. 6403

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000491
B. State Generator's ID: 91108

5. Transporter 1 Company Name
WPI TRANSPORTATION INC.

6. US EPA ID Number T·X·D·0·5·0·6·4·1·4·6·3

C. State Transporter's ID: 40369
D. Transporter's Phone (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H 0261
H. Facility's Phone (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2100	BA	37200	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI# TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 04 Day 28 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.B. Cox | Signature: BROWNING-FERRIS, INC. McCARTY RD. LANDFILL TDH PERMIT # 261 APR 29 1992 11013 OLD BEAUMONT HWY. HOUSTON, TEXAS 77078 713-675-6101 | Date: Month 04 Day 28 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
Charged 107

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.
Printed/Typed Name: J Henderson | Signature: J Henderson | Date: Month 4 Day 29 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0523

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0524

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number 00004910
B. State Generator's ID 3110R
C. State Transporter's ID 40369
D. Transporter's Phone (713) 452-5004
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID H 0261
H. Facility's Phone (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2100	BA	37200	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI# TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	04	28	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
H.B. Cox	H B Cox	04	28	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0525

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521 No 5171
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 291849
TRUCK LINE WPT
CUSTOMER Union Carbide
CARGO

0000 4919

7:47 AM 04 28 92
34500 lb

8:36 AM 04 28 92
71700 lb
34500 lb TR
37200 lb NET

☐	$3.00	EMPTY ONLY
☐	$5.00	UP TO 65,000 GROSS
☒	$6.00	65,020 TO 85,000 GROSS
☐	$7.00	85,020 TO 105,000 GROSS
☐	$8.50	105,020 TO 125,000 GROSS
☐	$10.00	125,020 TO 145,000 GROSS
☐	$25.00	145,020 AND UP

Pd

A.B. Obj

Truck Driver

PUBLIC WEIGHER STATE OF TEXAS

Certified Weigher

BRA 0526

WPT Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0050 11919

SERVICE ORDER NUMBER **218660**

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 4-28-92 TRAILER # 29827 TRUCK # 28 PICKUP #

OPERATOR OR DRIVER: G.B. Cox LABOR

JOB LOCATION: Brownsville, Tx. DESTINATION Houston, Tx.

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN/ FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM
TIME ARRIVED	4-28	800	AM PM
LOADING BEGAN			AM PM
LOADING COMPLETED		900	AM PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	TX	US 77 - US 59	TX mi only

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 791849

DATE/TIME 4-28-92

SHIPPER'S SIGNATURE

TRAILER/BIN PU 791827

DATE/TIME

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE G.B. Cox

ENDING MILEAGE

BEGINNING MILEAGE 114092

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0527

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0004921

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 48369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID / ASBESTOS, N.O.S. ORM-E NA 9188	1035	BA	13300	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274-9302478157

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES, INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez | Signature | Month 04 Day 29 Year 92

BROWNING-FERRIS IND. LANDFILL
McCARTY RD. LANDFILL
TDH PERMIT #261
1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name: Omie D Milum | Signature | Month 04 Day 29 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space
Changed 107yds 107/105

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: R Matthews | Signature | Date Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0528

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0529

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087
Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 8 0 9 2 | Manifest Document No. 5 4 0 3 4 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004921

B. State Generator's ID:

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID:

D. Transporter's Phone:

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number:

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID / ASBESTOS, N.O.S. ORM-E NA 9188	1035	BA	13300	LB	179390
	b.					
	c.					
	d.					

J. Additional Description for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI TX 474-930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES, INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	04	29	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Omie D Milum	Omie D. Milum	04	29	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0530

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

146875

Tr 818 Tlr 291521

Truck Line M. P. I.

Name

Cargo

Cert. Weigher

(empty weights included)

_____ @ $ 5.00 up to 65,000
_____ @ $ 6.00 65,020 - 85,000
_____ @ $ 7.00 85,020 - 105,000
_____ @ $ 8.50 105,020 - 125,000
_____ @ $ 11.00 125,020 - 145,000
_____ @ $ 25.00 145,020 and up
_____ @ $ 3.00 empty only

PUBLIC WEIGHER CAMERON COUNTY, TEXAS

Truck Driver

1:49 P.M. 29 APR 92 0 ID	10200 G LB	18320
1:49 P.M. 29 APR 92 0 ID	28520 G LB	16180
1:49 P.M. 29 APR 92 0 ID	44700 G LB	

BRA 0531

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 49 21

SERVICE ORDER NUMBER 222700

CUSTOMER: Midwest Steel P.O. # B-114 RELEASE #

DATE: 4-29-92 TRAILER # 29821 TRUCK # 818 PICKUP #

OPERATOR OR DRIVER Ohie D. Milam LABOR N/A

JOB LOCATION: Union Carbide Brownsville, TX DESTINATION

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF (X) VAN / ~~FLAT~~

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	4-29-92		AM PM	TIME ARRIVED			AM PM
TIME ARRIVED		1:00	AM (PM)	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED		2:15	AM (PM)	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Picked up Loaded TRL, # 29821 union Carbide Brownsville, TX.

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0532

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: TXD008114092 | Manifest Document No.: 64034
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000492
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H026T
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	2200	BA	47380	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/8157.1

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	BROWN & ROOT ENVIRONMENTAL/ENERGY SERVICES, INC.	04	29	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Wendell C. Milum	Wendell C. Milum	04	29	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space
changed 107 yds

BFI MCCARTY ROAD LANDFILL
TDH PERMIT # 261
APPROVED
MAY 1 1992
4-30-92
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713/675-6101

107/105

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
J Wilson	J Wilson	4	30	92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0533

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0534

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 2 — Manifest Document No. 6 4 0 3 4

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004922

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1304

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

11A HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	7200	BA	47380	LB	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month 04 Day 12 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: Wendell C. Milum — Signature: Wendell C. Milum — Date: Month 04 Day 29 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0535

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

146876

Tr 820 Tlr 2915U9

Truck Line

Name

Cargo

Carl H. Hahn
Cert. Weigher

(empty weights included)

	@	$ 5.00	up to 65,000
	@	$ 6.00	65,020 - 85,000
	@	$ 7.00	85,020 - 105,000
	@	$ 8.50	105,020 - 125,000
	@	$ 11.00	125,020 - 145,000
	@	$ 25.00	145,020 and up
	@	$ 3.00	empty only

PUBLIC WEIGHER REG. # 1 CAMERON COUNTY, TEXAS

1:57 P.M. 29 APR 92 0 ID — 11560 G LB — 32420

1:57 P.M. 29 APR 92 0 ID — 43980 G LB — 31340

1:58 P.M. 29 APR 92 0 ID — 78320 G LB

Truck Driver W.C.M.

BRA 0536

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

146874

Tr 820 Tlr 791549

Truck Line TP P1

Name

Cargo

Cert. Weigher

(empty weights included)

_____ @ $ 5.00 up to 65,000
_____ @ $ 6.00 65,020 - 85,000
_____ @ $ 7.00 85,020 - 105,000
_____ @ $ 8.50 105,020 - 125,000
_____ @ $ 11.00 125,020 - 145,000
_____ @ $ 25.00 145,020 and up
_____ @ $ 3.00 empty only

Truck Driver

1:44 P.M. 29 APR 92 0 ID — 11280 G LB — 31160
1:45 P.M. 29 APR 92 0 ID — 42440 G LB — 35930
1:45 P.M. 29 APR 92 0 ID — 78420 G LB

BRA 0537

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 4922

SERVICE ORDER NUMBER 222652

CUSTOMER: MIDWEST STEEL P.O. # B-114 RELEASE #

DATE: 4-29-92 TRAILER # 311856 / 291849 TRUCK # C-820 PICKUP #

OPERATOR OR DRIVER WENDELL C. MILUM LABOR N/A

JOB LOCATION: Union Carbide BROWNSVILLE TX DESTINATION B.F.I McCarty.

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	4-29	315	(AM) PM	TIME ARRIVED			AM PM
TIME ARRIVED	4-29	1230	AM (PM)	UNLOAD BEGAN			AM PM
LOADING BEGAN	4-29	100	AM (PM)	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	4-29	315	AM (PM)	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT _____ am ( ) pm IN _____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Take drop-deck to Union Carbide & drop with 1-48' TARP, 10 straps + 2 ratchets. 1 Box of Rubber straps. & Pick-up Van # 29849 loaded & take to B.F.I.

(TRAILER)/BIN DROPPED # 311856

TRAILER/BIN PU 291849

DATE/TIME 4-29-92

DATE/TIME

SHIPPER'S SIGNATURE C. M. Wells

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Wendell C. Mil

ENDING MILEAGE _____

BEGINNING MILEAGE 501249

TOTAL TRIP MILES _____

CUSTOMER SIGNATURE Paul Wells
CONFIRMS TIME IN PLANT

BRA 0538

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/522

..ER COMMISSION
13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 8 1 1 4 0 9 2 | Manifest Document No. 6 4 0 3 4

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number 0000492 TX

B. State Generator's ID 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 2

C. State Transporter's ID 40369

D. Transporter's Phone (713) 452-1502

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID TDH PERMIT #0261

H. Facility's Phone (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. (A) Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1	BC	16860	P	BC 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez | Signature: Belia Cortez | Month Day Year: 05 26 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: PAUL B. COX | Signature: Paul B. Cox | BROWNING-FERRIS | Month Day Year: 05 26 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | McCARTY RD. LANDFILL TDH PERMIT # 261 | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
changed 30yds

MAY 27 1992 30 N

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19:
11013 OLD BEAUMONT HWY. HOUSTON, TEXAS 77078 713-675-6101

Printed/Typed Name: K. Parsons | Signature: K. Parsons | Date: Month Day Year: 5 27 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0539

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0540

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 6 4 0 3 — Manifest Document No. —
2. Page 1 of 4 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE, CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 00004923
B. State Generator's ID:
C. State Transporter's ID: 4016
D. Transporter's Phone: (713) 662-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 672-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID, ASBESTOS, N.O.S. ORM-B NA 9188	1	BA	16860	P	B 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/01871

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 05 Day 26 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date
Printed/Typed Name: PAUL B. COX — Signature: Paul B. Cox — Month 05 Day 26 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Date
Printed/Typed Name — Signature — Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date
Printed/Typed Name — Signature — Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0541

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No 6108

TRUCK 27 TLR 90-25 /26-25
TRUCK LINE WPT
CUSTOMER Union Carbide
CARGO

8:31 AM 05 26 92
40400 lb

☐	$3.00	EMPTY ONLY
☑	$5.00	UP TO 65,000 GROSS
☐	$6.00	65,020 TO 85,000 GROSS
☐	$7.00	85,020 TO 105,000 GROSS
☐	$8.50	105,020 TO 125,000 GROSS
☐	$10.00	125,020 TO 145,000 GROSS
☐	$25.00	145,020 AND UP

Pd

1:00 PM 05 26 92
57260 lb
40400 lb TR
16860 lb NET

PUBLIC WEIGHER COUNTY OF CAMERON STATE

Truck Driver

Certified Weigher

BRA 0542

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 000619923

SERVICE ORDER NUMBER 222463

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 5-24-79 TRAILER # 109 TRUCK # 27 PICKUP #

OPERATOR OR DRIVER Paul B. Cox LABOR

JOB LOCATION: Brownsville DESTINATION Hwy 77

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	5-24	8 30	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	5-24	1 30	AM (PM)	ARRIVED YARD			AM (PM)

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
		115 59 - 115 77	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Problems with box swaps & not enough room for trucks and trailer combination. To be safe

TRAILER/BIN DROPPED # 90 25 union carbide DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU 26 25 to AFI mfanuty DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Paul B. Cox

ENDING MILEAGE

BEGINNING MILEAGE 365853

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0543

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/527

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-92

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 Manifest Document No. 64034

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone

A. State Manifest Document Number 00004924
B. State Generator's ID 31108
C. State Transporter's ID TXXX40360
D. Transporter's Phone 713 452-1501
E. State Transporter's ID SAME AS 5
F. Transporter's Phone SAME AS 5
G. State Facility's ID H0261
H. Facility's Phone (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: TXD050641463

7. Transporter 2 Company Name: SAME AS #5
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1	~~BA~~ BC	27000	~~T~~ P	BC 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE. @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: Belia Cortez — Signature: Belia Cortez — Month Day Year: 05 26 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Ralph Rice — Signature — Date: Month Day Year: 05 26 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: Jerome Cooper — Signature — Date: Month Day Year: 05 27 92

FACILITY

19. Discrepancy Indication Space
chg'ed 30yds

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: Roy White — Signature — Date: Month Day Year: 05 27 92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
MAY 27 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713 675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0544

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0545

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 402 TLR 25-128 /25-8 No 6109

TRUCK LINE WPT

CUSTOMER Union Carbide

CARGO

8:33 AM 05 26 92
42340 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ ~~$6.00~~ 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

1:04 PM 05 26 92
69340 lb
42340 lb TR
27000 lb NET

PUBLIC WEIGHER COUNTY OF CAMERON TEXAS

Truck Driver

Certified Weigher

BRA 0546

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2	Manifest Document No. 0 4 0 5	2. Page 1 of 4	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
RAR ROUTE BOX 90
4. Generator's Phone BROWNSVILLE, TEXAS 78521 (512) 831-4501

A. State Manifest Document Number: 00004924
B. State Generator's ID: TX 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6
C. State Transporter's ID: 388 40369
D. Transporter's Phone:

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:
G. State Facility's ID: H026
H. Facility's Phone: A (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID, ASBESTOS, N.O.S. ORM-E NA 9188	1	BA BA	27000	P Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
DW1/FTE/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE. @ (512) 832-4501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	05	26	93

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
RALPH PRICE	Ralph Price	05	26	93

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0547

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000492-1

SERVICE ORDER NUMBER 222554

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 5-26-92 TRAILER # 600 TRUCK # 402 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: Brownsville, TX DESTINATION Houston, TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	5-26-92	8:30	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	"	8:30	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	"	11:30	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	TX	59 77	465985

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Problems with Box swap, work By Ltd Haul moving Boxes and spotting Boxes

TRAILER/BIN DROPPED #1 25 128 DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU 25 8 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 465985

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0548

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 0 4 0 5 4 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number: 0000492 5 TWC
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1506
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1	BA	24080	LBS T	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES, OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR
Printed/Typed Name: BELIA CORTEZ
Signature: Belia Cortez
Month Day Year: 05 29 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: DARRELL BLACK
Signature: Darrell Black
Date: Month Day Year: 05 29 92
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

FACILITY
19. Discrepancy Indication Space
Charged 107yds
MAY 1992
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: K Parsons
Signature: K Parsons
Date: Month Day Year: 5 3 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0549

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0550

5/29

BELIA,

JOHN KIM # 1

THINK WE SHOULD
CONSIDER ORDERING
ONLY ONE ROLL-OFF
FOR NOW.
WE DON'T THINK
WE WILL NEED THREE
IF YOU HAVE QUESTIONS
CALL ON RADIO.

DUB

BRA 0551

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087
Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 — Manifest Document No. 04525
2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004925
B. State Generator's ID:
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 692-4512
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 1102-1
H. Facility's Phone: (713) 673-1101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: TXD050641466
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S. ORM-E NA 9188	1	BA	24080	LBS Y	79190
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI#TX1274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES ORVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 05 Day 29 Year 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: DARRELL BLACK — Signature: Darrell Black — Date: Month 05 Day 29 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name: — Signature: — Date: Month Day Year

FACILITY
19. Discrepancy Indication Space
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Printed/Typed Name: — Signature: — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink - TSD Facility Yellow - Transporter Green - Generator's first copy

BRA 0552

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 2000 192

SERVICE ORDER NUMBER 2509

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 5-29-79 TRAILER # 609 TRUCK # 822 PICKUP #

OPERATOR OR DRIVER Darrell Black LABOR

JOB LOCATION: Brownsville Tx DESTINATION Houston Tx

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	5-29	7:00	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	5-29	9:00	(AM) PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED		12:00	AM (PM)	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
5-29	TX	511 77 59 610 90	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: had hard time getting to loader because of mud and rain

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE Billie Curtis

TRAILER/BIN PU 25-128 DATE/TIME 5-29 CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Darrell Black

ENDING MILEAGE

BEGINNING MILEAGE 491679

TOTAL TRIP MILES

CUSTOMER SIGNATURE Billie Curtis
CONFIRMS TIME IN PLANT

BRA 0553

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville. Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No. 6330

TRUCK 822 TLR 25-81 25-128
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

4:40 PM 05 28 92
39020 lb

- ☐ $3.00 EMPTY ONLY
- ☑ $5.00 UP TO 65,000 GROSS
- ☐ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

11:10 AM 05 29 92
63100 lb
39020 lb TR
24080 lb NET

PUBLIC WEIGHER
BOARD OF COMMISSIONERS

Darrell Black
Truck Driver

Certified Weigher

BRA 0554

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 0 4 6 6 4 0 2 4

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004926

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: R0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS N.O.S. ORM-E NA 9188	1	BA	23460	LBS	BC 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/8157L

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month Day Year: 05 29 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Jimmy Kidd | Signature: Jimmy Kidd | Date: Month Day Year: 05 29 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
Changed 20 yds

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name: M Epsley | Signature | Date: Month Day Year: 15 BO 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0555

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/matorial description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0556

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 04926 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004926
B. State Generator's ID
C. State Transporter's ID
D. Transporter's Phone
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID: H0761
H. Facility's Phone (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

7. Transporter 2 Company Name
8. US EPA ID Number

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS N.O.S. ORM-E NA 9188	1	BA	23460	LB-Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI-TEX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	05	29	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
Jimmy Kidd	Jimmy Kidd	05	29	92

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0557

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

No 6329

TRUCK 1023 TLR 26-25 / 90-25
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

4:39 PM 05 28 92
39780 lb

☐	$3.00	EMPTY ONLY
☑	$5.00	UP TO 65,000 GROSS
☐	$6.00	65,020 TO 85,000 GROSS
☐	$7.00	85,020 TO 105,000 GROSS
☐	$8.50	105,020 TO 125,000 GROSS
☐	$10.00	125,020 TO 145,000 GROSS
☐	$25.00	145,020 AND UP

Pd

11:08 AM 05 29 92
63240 lb
39780 lb TR
23460 lb NET

PUBLIC WEIGHER
COUNTY OF CAMERON

Truck Driver

Certified Weigher

BRA 0558

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 4926

SERVICE ORDER NUMBER 221810

CUSTOMER: Union Carbide / Brownsville P.O. # RELEASE #

DATE: 5-29-82 TRAILER # 606 TRUCK # 102 PICKUP #

OPERATOR OR DRIVER Tommy Reed LABOR

JOB LOCATION: Union Carbide Brownsville, Tx DESTINATION Houston Ship Channel

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM (X) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	5-29-82	9:30	(AM) PM	TIME ARRIVED			AM PM
TIME ARRIVED	5-29-82	4:00	AM (PM)	UNLOAD BEGAN			AM PM
LOADING BEGAN	5-29-82	8:00	(AM) PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	5-29-82	12:00	AM (PM)	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
5-29-82	TX	511, 77, 59, I-10	391774 L

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Had to back in to mix water in sand to keep it from if we would have had load yesterday before rain it would have ben like cake & would set the truck

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE Bebe Cates

TRAILER/BIN PU DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Tommy Reed

ENDING MILEAGE

BEGINNING MILEAGE 391774

TOTAL TRIP MILES

CUSTOMER SIGNATURE Bebe Cates
CONFIRMS TIME IN PLANT

BRA 0559

206

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 4 0 9 2 | Manifest Document No. 04929 WK

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004929 WK
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID, ASBESTOS N.O.S. ORM-E NA 9188	1	BA	28.360	LBS	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 06 Day 01 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.B. Cox | Signature: A.B. Cox | Date: Month 06 Day 01 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: T Wilson | Signature: T Wilson | Date: Month 06 Day 12 Year 92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT # 261
JUN 02 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

25N

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0560

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW,, Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0561

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 7871l-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, Expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 0 4 9 2 9

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 000004929

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION-INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: (713) 675-6101

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS,N.O.S. ORM-E NA 9188	1	BA	28 360	LBS X	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 06 01 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: A.B. Cox — Signature: A.B. Cox — Date: Month Day Year: 06 01 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0562

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

TRUCK 28 TLR 90-251 No 6345

TRUCK LINE WDI

CUSTOMER Union Carbide

CARGO

8:00 AM 06 01 92
38480 lb

☐	$3.00	EMPTY ONLY
☐	$5.00	UP TO 65,000 GROSS
☒	$6.00	65,020 TO 85,000 GROSS
☐	$7.00	85,020 TO 105,000 GROSS
☐	$8.50	105,020 TO 125,000 GROSS
☐	$10.00	125,020 TO 145,000 GROSS
☐	$25.00	145,020 AND UP

Pd

11:03 AM 06 01 92
66840 lb
38480 lb TR
28360 lb NET

A B Cox
Truck Driver

PUBLIC WEIGHER
STATE OF OKLAHOMA
COUNTY OF OKMULGEE

Certified Weigher

BRA 0563

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST [illegible]

SERVICE ORDER NUMBER 222510

CUSTOMER: Union Carbide — P.O. # — RELEASE # [illegible]

DATE: 6-1-79 — TRAILER # 106 — TRUCK # 78 — PICKUP #

OPERATOR OR DRIVER: O.B. Cox — LABOR

JOB LOCATION: Brownsville 24 — DESTINATION: Houston 24

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

	LOADING DATE	LOADING TIME	LOADING CIRCLE ONE		UNLOADING DATE	UNLOADING TIME	UNLOADING CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-1-79	800	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	"	1115	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
5-31	TX	US 59 - US 77	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Red sweep in mud

TRAILER/BIN DROPPED # 90-25

TRAILER/BIN PU 25-8

DATE/TIME 6-1-79

DATE/TIME

SHIPPER'S SIGNATURE [signature]

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE O.B. Cox

ENDING MILEAGE

BEGINNING MILEAGE 111130

TOTAL TRIP MILES

[signature]
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0564

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 0 4 9 3 0

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004930
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: TX D 0 5 0 6 4 1 4 6 3

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI McCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS N.O.S. ORM-E NA 9188	1	BA	32580	LBS	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ
Signature: Belia Cortez
Month Day Year: 06/01/92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: L. WEDDLE
Signature:
Date: 6/1/92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: T WILSON
Signature:
Date: 6/2/92

BROWNING-FERRIS
McCARTY RD. LANDFILL
TDH PERMIT # 261
JUN 02 1992
11013 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0565

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden; to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0566

TEXAS WATER COMMISSION
P.O. Box 13087 Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 04930

2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number 00004930

B. State Generator's ID 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC. | 6. US EPA ID Number: TXR050641463

C. State Transporter's ID 403606

D. Transporter's Phone (713) 453-1307

7. Transporter 2 Company Name | 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID H026J

H. Facility's Phone (713) 676-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE-SOLID, ASBESTOS N.O.S. ORM-E NA 9188	1	BA	32580	L	179390
	b.					
	c.					
	d.					

GENERATOR

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI-TX/278/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES OR OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	01	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
L. WEDNEZ	[illegible]	06	01	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0567

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 № 6371

TRUCK 1918 TLR R1918 / 2625

TRUCK LINE WPJ

CUSTOMER Union Carbide

CARGO

12:16 PM 06 01 92
37800 lb
Tare Empty 6500
Box 44300
2:03 PM 06 01 92
76880 lb
44300
~~37800 lb TR~~
32580 Tr
39080 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

Truck Driver

PUBLIC WEIGHER COUNTY OF CAMERON

Certified Weigher

NO BOX ON TARE

BRA 0568

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST [illegible]

SERVICE ORDER NUMBER 250858

CUSTOMER: UNION CA 23105 P.O. # RELEASE #

DATE: 5-21-79 TRAILER # 2171 TRUCK # 1975 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: BROWNSVILLE, TX DESTINATION: HOUSTON, TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM (X) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	5-21-79	11:30	AM (PM)	TIME ARRIVED			AM PM
TIME ARRIVED	5-21-79	12:45	AM (PM)	UNLOAD BEGAN			AM PM
LOADING BEGAN	5-21-79	1:15	AM (PM)	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	5-21-79	2:45	AM (PM)	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
5-21-79	TX		

WAS JOB COMPLETED SATISFACTORILY? 2.50 4.00 JF 5.50

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: PICKUP BOX #1 04-25 TO SPOT. PICKUP BOX #10-03 & SPOT IN PLANT. PICKUP BOX 26-25 FOR DELIVERY TO HOUSTON

TRAILER/BIN DROPPED # NONE DATE/TIME 5-21-79 SHIPPER'S SIGNATURE [illegible]

TRAILER/BIN PU 26-45 DATE/TIME 5-21-79 12:45 CONSIGNEE'S SIGNATURE [illegible]

3.50.00 DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT [illegible]

BRA 0569

WPI

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

SERVICE ORDER NUMBER

250858

TOMER

P.O. #

RELEASE #

TRAILER #

TRUCK #

PICKUP #

LABOR

LABOR OR DRIVER

LOCATION

DESTINATION

VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING

UNLOADING

	DATE	TIME	CIRCLE ONE
Y YARD			AM PM
ARRIVED			AM PM
ING BEGAN			AM PM
ING COMPLETED			AM PM

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOADING BEGAN			AM PM
UNLOADING COMPLETED			AM PM
LEFT YARD			AM PM

CH OR NONWORKING: OUT _____ IN _____

ATE	STATE NAME	COUNTY & STATE LINE (IF ON LI

JOB COMPLETED SATISFACTORILY?

TRAILER RETURNED

MARKS

LEFT BIN DROPPED

LEFT BIN FU

SHIPPER'S SIGNATURE

DATE TIME

CONSIGNEE'S SIGNATURE

DATE TIME

PROCESSING SIGNATURE

ING MILEAGE

SHIPPING MILEAGE

AL TRIP MILES

CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0570

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 64034	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004911
B. State Generator's ID: 11108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713-452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transportation, Inc.
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty road Landfill, 11013 Old Beaumont Highway, Houston, Tx 77-78
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	AT Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM_E, NA 9188	1	BA	24/180	LBS	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos
K. Handling Codes for Wastes Listed Above: BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Waer gloves, glasses, and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR
Printed/Typed Name: BELIA CORTEZ
Signature: Belia Cortez
Month Day Year: 06 03 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: A.B. Cox
Signature: A.B Cox
Date: Month Day Year: 06 03 92
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year:

FACILITY
19. Discrepancy Indication Space
Browning Ferris Inc.
11013 Old Beaumont Hwy.
Houston, Tx. 77078
(713) 675-6101
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: M Easley
Signature: M Easley
Date: Month Day Year: 6 4 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0571

When using the Uniform Waste Manifest for rail or water (bulk-shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0572

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 04911 64034	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004911

B. State Generator's ID: 5108

5. Transporter 1 Company Name: WPI Transportation, Inc.

6. US EPA ID Number: TXD050641463

C. State Transporter's ID: 40369

D. Transporter's Phone: 713-452-5[illegible]

7. Transporter 2 Company Name: [illegible]

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI McCarby road Landfill
11013 Old Beaumont Highway
Houston, Tx 77-78

10. US EPA ID Number:

G. State Facility's ID: H0261

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM_E, NA 9188	1	BA	24180	LBS Y	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. Friable Asbestos

K. Handling Codes for Wastes Listed Above
BFI #IX/27A/930224/81371

15. Special Handling Instructions and Additional Information
Waer gloves, glasses, and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	03	72

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
A. B. Cox	A. B Cox	06	03	72

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0573

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST # 0000091

SERVICE ORDER NUMBER 222511

CUSTOMER: [illegible] P.O. # RELEASE #

DATE: 6-3-92 TRAILER # 606 TRUCK # 2 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: [illegible] DESTINATION [illegible]

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP (X) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE		UNLOADING	DATE	TIME	CIRCLE ONE	
LEAVE YARD			AM	PM	TIME ARRIVED			AM	PM
TIME ARRIVED	6-3-92	800	AM	PM	UNLOAD BEGAN			AM	PM
LOADING BEGAN			AM	PM	UNLOAD COMPLETE			AM	PM
LOADING COMPLETED		1100	AM	PM	ARRIVED YARD			AM	PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	TX	1559-1577	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Bad mud

TRAILER/BIN DROPPED #75-8 DATE/TIME 6-3-92 SHIPPER'S SIGNATURE [signature]

TRAILER/BIN PU 10-30 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE [signature]

ENDING MILEAGE

BEGINNING MILEAGE 416936

TOTAL TRIP MILES

[signature]
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0574

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No 6409

TRUCK 28 TLR 25-8 / 10-30

TRUCK LINE UPJ

CUSTOMER Union Carbide

CARGO

7:55 AM 06 03 92
39960 lb

10:32 AM 06 03 92
64140 lb
39960 lb TR
24180 lb NET

Pd

- ☐ $3.00 EMPTY ONLY
- ☑ $5.00 UP TO 65,000 GROSS
- ☐ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

C B Co

Truck Driver

PUBLIC WEIGHER COUNTY OF CAMERON TEXAS

Certified Weigher

BRA 0575

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

0406/0907 (illegible)

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 0 64034	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000491O

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI Transportation, Inc.
6. US EPA ID Number: TXD050641463

C. State Transporter's ID: 40369
D. Transporter's Phone: 713-452-1504

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont Highway
Houston, Tx 77078
10. US EPA ID Number

G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM-E,NA 9188	1	BA	22920	LBS X	BC 179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. Friable Asbestos

K. Handling Codes for Wastes Listed Above
BFI #IX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear Gloves, glasses, and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	23	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year	Date
L. WEBNER	L Webner	06	03	92	

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year	Date

FACILITY

19. Discrepancy Indication Space
Browning Ferris Ind. 2570S
11013 Old Beaumont Hwy.
Houston, Tx. 77078
(713) 675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year	Date
M Easley	M Easley	6	24	92	

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0576

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS).

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0577

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved, OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 — Manifest Document No. 000436

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbidee
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000491

B. State Generator's ID: 3110

5. Transporter 1 Company Name: WPI Transportation, Inc.

6. US EPA ID Number: TXD050641463

C. State Transporter's ID: A0369

D. Transporter's Phone: 713-675-6101

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont Highway
Houston, Tx 77088

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM-E,NA 9188	1	BA	22920	LBS	179390
	b. Debris					
	c.					
	d.					

GENERATOR

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos

K. Handling Codes for Wastes Listed Above: BPI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear Gloves, glasses, and other protective Equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 06 Day 03 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: L. WEIDER — Signature — Date: Month 06 Day 03 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0578

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No. 6414

TRUCK 1918 TLR 26-25/90-25

TRUCK LINE WPJ

CUSTOMER Union Carbide

CARGO

9:50 AM 06 03 92
67440 lb
44520 lb TR
22920 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

PD

PUBLIC WEIGHER COUNTY OF CAMERON TEXAS

Truck Driver

Certified Weigher

BRA 0579

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST

SERVICE ORDER NUMBER 250859

CUSTOMER: UNION CARBIDE P.O. # RELEASE #

DATE: 6-3-92 TRAILER # 19145 TRUCK # 19145 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: BROWNSVILLE, TX DESTINATION HOUSTON, TX

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (✓) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-3-92	10:00	AM (PM)	TIME ARRIVED			AM PM
TIME ARRIVED	6-3-92	9:15	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-3-92	9:15	(AM) PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-3-92	11:15	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 26-25

TRAILER/BIN PU 90-25

DATE/TIME 6-3-92 9:15A

DATE/TIME 6-3-92 10:15A

SHIPPER'S SIGNATURE [signature]

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE [signature]

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

[signature]
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0580

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

0610

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 64034	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville, Tx 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004912
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713-452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transportation, Inc.
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill, 11013 Old Beaumont Hoghway, Houston, Tx 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM_E, NA 9188	1	BA	31.200	LBS	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos
K. Handling Codes for Wastes Listed Above: BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear glasses, gloves, and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	10	79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Abelardo Vela Sr	Abelardo Vela Sr	06	05	79

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
	K. Parsons Browning Ferris Ind. 11013 Old Beaumont Hwy. Houston, Tx. 77078 (713) 675-6101	06	06	79

FACILITY

19. Discrepancy Indication Space: Accidentally signed in section 18 then signed in proper place section 20

254

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
K. Parsons	K. Parsons	06	10	79

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0581

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0582

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087
Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 0 [illegible] 2	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004912

B. State Generator's ID: 3108

C. State Transporter's ID: [illegible]

D. Transporter's Phone: [illegible]

5. Transporter 1 Company Name: WPI Transportation, Inc.

6. US EPA ID Number: TXD050641463

E. State Transporter's ID: [illegible]

7. Transporter 2 Company Name:

8. US EPA ID Number:

F. Transporter's Phone: [illegible]

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont, Hoghway
Houston, Tx 77078

10. US EPA ID Number:

G. State Facility's ID: 80261

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM_E, NA 9188	1	BA	3120	LBS Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. Friable Asbestos

K. Handling Codes for Wastes Listed Above
BFI #DX/27A/930224/81571

15. Special Handling Instructions and Additional Information
Wear glasses, gloves, and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	05	79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Abelardo Ucle Sr	Abelardo Ucle Sr	06	05	79

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY


19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0583



PORT OF BROWNSVILLE PUBLIC SCALE, INC.
(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

147996

Tr 816 Tlr 607

Truck Line W. P. I.

Name Union Carbine

Cargo Asbestos

Cert. Weigher

(empty weights included)

- ✓ @ $ 5.00 up to 65,000
- ____ @ $ 6.00 65,020 - 85,000
- ____ @ $ 7.00 85,020 - 105,000
- ____ @ $ 8.50 105,020 - 125,000
- ____ @ $ 11.00 125,020 - 145,000
- ____ @ $ 25.00 145,020 and up
- ____ @ $ 3.00 empty only

Truck Driver

6.00 RI.

HEIGHT 33860 LB
TIME 07:29 AM 05 JUN 92

TICKET 1427
TRUCK ID 0
GROSS 65660 LB
TARE 33860 LB
NET 31800 LB
TIME 08:29 AM 05 JUN 92

PUBLIC WEIGHMASTER CAMERON COUNTY, TEXAS

BRA 0584

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0221740

SERVICE ORDER NUMBER 0221740

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 6-5-92 TRAILER # 607 TRUCK # 84 PICKUP #

OPERATOR OR DRIVER Abel D. LABOR

JOB LOCATION: DESTINATION

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-5-92	8:00	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-5-92	8:15	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-5-92	8:45	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-5-92	Tx	91-59	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: P/U T.P. - 7:00 a.m. - 7:30 a.m.

D. Kid - Adv Plant

TRAILER/BIN DROPPED # DATE/TIME 6-5-92

TRAILER/BIN PU DATE/TIME

SHIPPER'S SIGNATURE Belia Cortez BVDW

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Abel D.

ENDING MILEAGE

BEGINNING MILEAGE 162112

TOTAL TRIP MILES

Belia Cortez BVDW
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0585

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 0 04914	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

GENERATOR

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
4. Generator's Phone (512-831-4501

A. State Manifest Document Number: 0004914
B. State Generator's ID: 81108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713-452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transportation, Inc.
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill, 11013 Old Beaumont Highway, Houston, Tx 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	State Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S. ORM_E, NA 9188	1 BA	CF	2.9.5.4.0	LBS Y	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos
K. Handling Codes for Wastes Listed Above: BFL #IX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month Day Year
BELIA CORTEZ	Belia Cortez	1 10 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year
L WEAVER	L Weaver	01 05 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year

FACILITY

19. Discrepancy Indication Space: Section 3 Address S/B Brownsville, TX 78521
Browning Ferris Ind. 11013 Old Beaumont Hwy. Houston, Tx. 77078 (713) 675-6101 254

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month Day Year
L Parsons	L Parsons	1 10 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0586

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11. - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0587

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 — Manifest Document No. 04914 — 54034 BC

2. Page 1 of 1 — Information in the shaded area(s) is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
4. Generator's Phone (512-831-4501

A. State Manifest Document Number: 0000491 4

B. State Generator's ID: 5116

5. Transporter 1 Company Name: WPI Transpprtation, Inc.
6. US EPA ID Number: TXD050641463
C. State Transporter's ID: 00369
D. Transporter's Phone: 713-452-1500

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
10013 Old Beaumont Highway
Houston, Tx 77078
10. US EPA ID Number:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S. ORM_E, NA 9188	1 BC ~~BA~~	CT	29540	LB T	BC 179390
	b. Debris					
	c.					
	d.					

GENERATOR

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos

K. Handling Codes for Wastes Listed Above: BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month Day Year
BELIA CORTEZ	Belia Cortez	11 10 592

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year
L-WEDDER		11 0 5 92

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0588

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 04914

SERVICE ORDER NUMBER 250860

CUSTOMER UNION CARBIDE P.O. # RELEASE #

DATE 6-5-92 TRAILER # 12916 TRUCK # 1913 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: DESTINATION

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-5-92	9:00	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-5-92	10:00	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-5-92	10:15	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-5-92	10:00	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 911-25

TRAILER/BIN PU 25-7

DATE/TIME 6-5-92 10:00 A.M. SHIPPER'S SIGNATURE [illegible]

DATE/TIME 6-5-92 10:00 A.M. CONSIGNEE'S SIGNATURE [illegible]

DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

Billie Carter 4 HD
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0589

QUALITY WEIGHING SERVICES, INC.

QWS

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No 6451

TRUCK 1918 TLR 9025 / 258
TRUCK LINE WPT
CUSTOMER Union Carbide
CARGO

8:04 AM 06 05 92
43940 lb

9:43 AM 06 05 92
73480 lb
43940 lb TR
29540 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHER COUNTY OF CAMERON

Truck Driver

Certified Weigher

BRA 0590

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 60434	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union carbide
Star Route Box 90
Brownsville, Tx 77078

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004913 TXD
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713-452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: TXD980610261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transportation, Inc.
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill, 11013 Old Beaumont Highway, Houston, Tx 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM-E, NA 9188	1	BA	30.00	LBS	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos
K. Handling Codes for Wastes Listed Above: BFI #IX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equiptment as necessary. For help in handling emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	05	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year	Date
H.B. Cox	H.B. Cox	06	05	92	

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year	Date

FACILITY

19. Discrepancy Indication Space: section 3 [redacted] zip code 78521
Browning Ferris Ind. 254
11013 Old Beaumont Hwy.
Houston, Tx 77078
(713) 675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year	Date
K Parsons	K Parsons	06	05	92	

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0591

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0592

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 000491	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address: Contact: Ms. Belia Cortez, Union Carbide, Star Route Box 90, Brownsville, Tx 77078			A. State Manifest Document Number: 000491	
4. Generator's Phone (512) 831-4501			B. State Generator's ID: 3108	
5. Transporter 1 Company Name: WPI Transportation, Inc.	6. US EPA ID Number: TXD050641463		C. State Transporter's ID: 0369	
7. Transporter 2 Company Name	8. US EPA ID Number		D. Transporter's Phone: 713-457-1500	
			E. State Transporter's ID	
			F. Transporter's Phone	
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill, 11013 Old Beaumont Highway, Houston, Tx 77078	10. US EPA ID Number		G. State Facility's ID: 1026J	
			H. Facility's Phone: 713-675-6101	

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM-E, NA 9188	1	DM	3000	LB	179890
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos

K. Handling Codes for Wastes Listed Above: BFI #DX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equiptment as necessary. For help in handling emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	05	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
H.B. Cox	H.B. Cox	06	05	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0593

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No. 6452

TRUCK 28 TLR 10-30 25/N

TRUCK LINE WDI

CUSTOMER Union Carbide

CARGO

8:05 AM 06 05 92
40340 lb
9:23 AM 06 05 92
70380 lb
40340 lb TR
30040 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHER COUNTY OF CAMERON TEXAS

Truck Driver

Certified Weigher

BRA 0594

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 2000 4915

SERVICE ORDER NUMBER 222512

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 1-5-92 TRAILER # 106 TRUCK # 280 PICKUP #

OPERATOR OR DRIVER O.B. Cole LABOR

JOB LOCATION: Brownsville, TX DESTINATION Houston, TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

	LOADING DATE	LOADING TIME	CIRCLE ONE			UNLOADING DATE	UNLOADING TIME	CIRCLE ONE	
LEAVE YARD			AM	PM	TIME ARRIVED			AM	PM
TIME ARRIVED	1-5	8:00	(AM)	PM	UNLOAD BEGAN			AM	PM
LOADING BEGAN			AM	PM	UNLOAD COMPLETE			AM	PM
LOADING COMPLETED	1-5	9:45	(AM)	PM	ARRIVED YARD			AM	PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
	TX	US 59 US 77 E	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Bed Swap

TRAILER/BIN DROPPED #30-10 DATE/TIME 1-5-92 SHIPPER'S SIGNATURE Billie Cole Jr. BJD

TRAILER/BIN PU 25-15 DATE/TIME L CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE O.B. Cole

ENDING MILEAGE

BEGINNING MILEAGE US 77 L/O

TOTAL TRIP MILES

CUSTOMER SIGNATURE Billie Cole Jr. BJD
CONFIRMS TIME IN PLANT

BRA 0595

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/579

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 0 6403 5

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512-831-4501

A. State Manifest Document Number 0004915

B. State Generator's ID 31108

5. Transporter 1 Company Name: WPI Transportation, Inc.
6. US EPA ID Number: TXD050641463
C. State Transporter's ID 40369
D. Transporter's Phone 713-452-1504

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont Highway
houston, tx 77078
10. US EPA ID Number
G. State Facility's ID H0261
H. Facility's Phone 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Substance Solid/ Asbestos, N.O.S. ORM-E, NA 9188	1	BA	32620	LBS	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. Friable Asbestos

K. Handling Codes for Wastes Listed Above
BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information Wear gloves, glasses, and other protective equiptment as necessary. For help in handling chemical emergencied involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 06 Day 09 Year 87

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: L. NEDDER | Signature | Date: Month 06 Day 09 Year 87

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
- No Placards on Vehicle
Browning Ferris Ind
11013 Old Beaumont Hwy.
Houston, Tx 77078
(713) 675-6101
25 Y

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J. Henderson | Signature: J. Henderson | Date: Month 6 Day 8 Year 87

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0596

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "X" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver, acknowledging receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223; U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0597

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 0 [illegible] 5 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512-831-4501

A. State Manifest Document Number: 00004915

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI Transportation, Inc.

6. US EPA ID Number: TXD050641463

C. State Transporter's ID: 40369

D. Transporter's Phone: 713-452-1506

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont Highway
houston, tx 77078

10. US EPA ID Number

G. State Facility's ID: 80261

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/ Asbestos, N.O.S. ORM-E, NA 9188	1	BA	32620	LBS	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos

K. Handling Codes for Wastes Listed Above: DFL #TX/276/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equipment as necessary. For help in handling chemical emergencied involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	08	79

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
L. WEDD-2	[illegible]	06	08	79

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0598

QUALITY WEIGHING SERVICES, INC.

QWS

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No 6508

TRUCK 1918 TLR 25-8
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

8:49 AM 06 08 92
44760 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

10:53 AM 06 08 92
77380 lb
44760 lb TR
32620 lb NET

PUBLIC WEIGHER
COUNTY OF CAMERON

Truck Driver

Certified Weigher

BRA 0599

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST

SERVICE ORDER NUMBER 25086

CUSTOMER: Union Carbide P.O. # RELEASE # X

DATE 6-8-92 TRAILER # 1291 TRUCK # 1916 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: 1500 Miller Cut Off Rd DESTINATION Hwy 77 N Harlingen Tx

(X) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM (X) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

	LOADING DATE	LOADING TIME	LOADING CIRCLE ONE		UNLOADING DATE	UNLOADING TIME	UNLOADING CIRCLE ONE
LEAVE YARD	6-7-92	2:15	AM (PM)	TIME ARRIVED			AM PM
TIME ARRIVED	6-8-92	9:15	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-8-92	9:15	(AM) PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-8-92	11:15	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 1291 DATE/TIME 6-8-92 9:15 SHIPPER'S SIGNATURE [signature]

TRAILER/BIN PU 1628 DATE/TIME 6-8-92 11:15 CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE [signature]

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

[signature]
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0600

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 0 64034 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004916
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713-452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transportation, Inc.
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill, 11013 old Beaumont Highway, Houston, Tx 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	ST	Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM-E, NA 9188		BA	30180	LBS Y	BC	179390
	b. Debris						
	c.						
	d.						

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos
K. Handling Codes for Wastes Listed Above: BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR
Printed/Typed Name: BELIA CORTEZ
Signature: Belia Cortez
Month Day Year: 06 08 82

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: FRANK Holubecu
Signature: Frank Holubeck
Date: 06 08 82
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature: Browning Ferris Ind.
Date:

FACILITY
19. Discrepancy Indication Space: 11013 Old Beaumont Hwy. Houston, Tx. 77078 (713) 675-6101
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J. Henderson
Signature: J. Henderson
Date: 6 9 82

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0601

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW, Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0602

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-92

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD009114092 | Manifest Document No. 64094 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004916
B. State Generator's ID: 4108
C. State Transporter's ID:
D. Transporter's Phone:
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transportation, Inc
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill, 11013 old Beaumont Highway, Houston, Tx 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM-E, NA 9188		BA	30180	165 T	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos
K. Handling Codes for Wastes Listed Above: BFI #DX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	08	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
FRANK Holubecic	Frank Holubecic	06	08	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0603

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No 6509

TRUCK 1923 TLR 2515 / 1030

TRUCK LINE WDT

CUSTOMER Union Carbide

CARGO

8:50 AM 06 08 92
46920 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

1:25 PM 06 08 92
77100 lb
46920 lb TR
30180 lb NET

PUBLIC WEIGHER COUNTY OF CAMERON

Frank Holebeck
Truck Driver

Certified Weigher

BRA 0604

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST [illegible]

SERVICE ORDER NUMBER 251173

CUSTOMER: Union Carbide

P.O. # RELEASE #

DATE: 6-12-92 TRAILER # 603 TRUCK # 192 PICKUP #

OPERATOR OR DRIVER: Frank Holbrook LABOR

JOB LOCATION: Brownsville, Tx. DESTINATION Houston, Tx.

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

	LOADING DATE	LOADING TIME	CIRCLE ONE		UNLOADING DATE	UNLOADING TIME	CIRCLE ONE
LEAVE YARD	6-9-92	1215	AM (PM)	TIME ARRIVED			AM PM
TIME ARRIVED		2pm	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED		130	AM (PM)	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-9-92	Tx	I-10 69-77	MT 416 Tx
6-12-92	Tx	77-69-I-10	Lanes

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: [illegible] to Remove 60-LP Rail

[illegible] 4½ Hrs. Unloading

TRAILER/BIN DROPPED #603 DATE/TIME

TRAILER/BIN PU 603 DATE/TIME 6/9/92 1:20 PM.

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Frank Holbrook

ENDING MILEAGE

BEGINNING MILEAGE 603905

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0605

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFFST

1. Generator's US EPA ID No. TXD008114092 — Manifest Document No. 64034

2. Page 1 of 1

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact Ms. Belia Cortez Union Carbide
Star Route BOx 90

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number 0000917

B. State Generator's ID 31108

C. State Transporter's ID 40369

D. Transporter's Phone 713-452-1504

5. Transporter 1 Company Name: WPI Transportation, Inc.
6. US EPA ID Number: TXD050641463

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont Highway
Houston, Tx 77078

10. US EPA ID Number

G. State Facility's ID H0261

H. Facility's Phone 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/Asbestos,N.O.S., ORM-E, NA 9188	1	BA	28420	LBS Y	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. Friable Asbestos

K. Handling Codes for Wastes Listed Above
BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information
Wear gloves, glasses, and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ
Signature: Belia Cortez
Month Day Year: 06 10 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Abelardo Vela Sr
Signature: Abelardo Vela Sr
Date: Month 06 Day 10 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
section 3
Address Brownsville TX 78521
Browning Ferris Ind.
11013 Old Beaumont Hwy.
Houston, Tx. 77078
(713) 675-6101
25YDS

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J HENDERSON
Signature: J Henderson
Date: Month 6 Day 10 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0606

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0607

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087
Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 64035	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact Ms. Belia Cortez Union Carbide
Star Route Box 90
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004917
B. State Generator's ID: 1108
C. State Transporter's ID: 40569
D. Transporter's Phone: 713-452-1502
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 7132675-6101

5. Transporter 1 Company Name: WPI Transportation, Inc.
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill, 11013 Old Beaumont Highway, Houston, Tx 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Substance/Solid/Asbestos,N.O.S., ORM-E OBM-E, NA 9188	1	BA	27420	LBS W	BC 179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos
K. Handling Codes for Wastes Listed Above: BFI #DV/174/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equiptment as necessary. For help in handling chemical emergencies involving spills of exposure call Union Carbide at 512-831-4501 day or night

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	09	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
Abelardo Vela Jr	Abelardo Vela Jr	06	09	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0608

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148088

Tr C 565 Tlr 6 CC

Truck Line

Carl H. Hulsey

Name WPI Union Carbide

Cert. Weigher

Cargo Asbestos

(empty weights included)

1	@	$ 5.00	up to 65,000
	@	$ 6.00	65,020 - 85,000
	@	$ 7.00	85,020 - 105,000
	@	$ 8.50	105,020 - 125,000
	@	$ 11.00	125,020 - 145,000
	@	$ 25.00	145,020 and up
	@	$ 3.00	empty only

160 60 R.

WEIGHT 43900 LB
TIME 07:52 AM 09 JUN 92

TICKET 1507
TRUCK ID 0
GROSS 72320 LB
K TARE 43900 LB
NET 28420 LB
TIME 09:44 AM 09 JUN 92

PUBLIC WEIGHMASTER CAMERON COUNTY, TEXAS

Truck Driver Abel V. Jr.

BRA 0609

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 2.10.24

SERVICE ORDER NUMBER C22190

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 6-1-12 TRAILER # 600 TRUCK # 203 PICKUP #

OPERATOR OR DRIVER Hall LABOR

JOB LOCATION: Brownsville Tex. DESTINATION B.J. - Houston Texas

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-1-12	5:00	AM PM
TIME ARRIVED	6-1-12	8:00	AM PM
LOADING BEGAN	6-1-12	8:20	AM PM
LOADING COMPLETED	6-1-12	11:15	AM PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Pick it up Box at P

TRAILER/BIN DROPPED # DATE/TIME 6-1-12 SHIPPER'S SIGNATURE Bill Potts & Wayne

TRAILER/BIN PU DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Hall

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE Bill Potts & Wayne
CONFIRMS TIME IN PLANT

BRA 0610

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST NUMBER

SERVICE ORDER NUMBER 0221902

CUSTOMER: [illegible] P.O. # RELEASE #

DATE: 6-9-12 TRAILER # [illegible] TRUCK # 209 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: [illegible] DESTINATION Brownsville, Tex

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM (X) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF (X) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-7-12	5:00	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-9-12	8:00	AM PM	UNLOAD BEGAN	6-12-12	2:15	AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE	6-12-12	3:30	AM PM
LOADING COMPLETED			AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT _____ am ( ) pm IN _____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Pit #1 - 11:30 am - 5:00 pm
Took Int. 2625 to Brownsville

TRAILER/BIN DROPPED # 2625 DATE/TIME SHIPPER'S SIGNATURE [illegible]

TRAILER/BIN PU DATE/TIME CONSIGNEE'S SIGNATURE [illegible]

DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE 000360

BEGINNING MILEAGE 000174

TOTAL TRIP MILES 186

CUSTOMER SIGNATURE [illegible] CONFIRMS TIME IN PLANT

BRA 0611

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 8 1 1 4 0 9 2 | Manifest Document No. [illegible] | 2. Page 1 of 4 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE ATTN: MS. BELIA CORTEZ
STAR ROUTE BOX XXX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004931
B. State Generator's ID: 31108
C. State Transporter's ID: 40359
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	BA	28940	LBS Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
a. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	10	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
L. WEBBER	[signature]	06	10	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space
254
Browning Ferris ind.
11013 Old Beaumont Hwy.
Houston, Tx. 77078
(713) 675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
J Henderson	J Henderson	6	19	92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0612

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0613

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 8 1 1 4 0 9 2 | Manifest Document No. 0 0 0 0 4 9 3 1 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE ATTN: MS. BELIA CORTEZ
STAR ROUTE BOX XXX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone

A. State Manifest Document Number: 00004931
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 453-5211
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS,DEBRIS N.O.S. ORMSE NA 9188	1	BA	28940	LBS V	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI#12/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 06 Day 19 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: [illegible] | Signature: [illegible] | Month 06 Day 19 Year 92 | Date
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Month Day Year | Date


FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Month Day Year | Date

EPA C-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0614



PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148148

Tr 1918 Tlr 90-25

Truck Line 26-25 FVL

Name W P I Union Carbine

Cert. Weigher

Cargo Contaminated dirt

(empty weights included)

- ____ @ $ 5.00 up to 65,000
- V @ $ 6.00 65,020 - 85,000
- ____ @ $ 7.00 85,020 - 105,000
- ____ @ $ 8.50 105,020 - 125,000
- ____ @ $ 11.00 125,020 - 145,000
- ____ @ $ 25.00 145,020 and up
- ____ @ $ 3.00 empty only

Truck Driver

WEIGHT 44080 LB
TIME 07:24 AM 10 JUN 92

60.00 Pd.

TICKET 1556
TRUCK ID 0
GROSS 73020 LB
K TARE 44080 LB
NET 28940 LB
TIME 08:19 AM 10 JUN 92

PUBLIC WEIGHMASTER CAMERON COUNTY, TEXAS

BRA 0615

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 4 73 1

SERVICE ORDER NUMBER 230862

CUSTOMER: UNION CARBIDE P.O. # RELEASE #

DATE: 6-9-92 TRAILER # 12 1942 TRUCK # 1942 PICKUP #

OPERATOR OR DRIVER JOE DOE LABOR

JOB LOCATION: BROWNSVILLE TX DESTINATION HOUSTON, TX

( ) VACTOR ( ) CYCLONE (X) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-9-92	1:00	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-10-92	3:30	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-10-92	12:30	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-10-92	4:00	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 90-25

TRAILER/BIN PU 76-25

DATE/TIME 6-10-92 7:30A

DATE/TIME 6-10-92 9:00A

SHIPPER'S SIGNATURE Karla Cortez By: J. Wayne

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE JW

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

Karla Cortez By: J. Wayne
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0616

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 04934

2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 10000491 8

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI Transportation, Inc.

6. US EPA ID Number: TXD050641463

C. State Transporter's ID: 40369

D. Transporter's Phone: 713-452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont Highway
Houston, Tx 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM-E, NA 9188	1	BA	28280	LBS	B2 179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos

K. Handling Codes for Wastes Listed Above

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	10	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
FRANK Holubecek	Frank Holubecek	06	10	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space: Browning Ferris Inc. 11013 Old Beaumont Hwy. Houston, Tx. 77078 (713) 675-6101 25y

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
J Henderson	J Henderson	06	19	92

TWC-0311 (Rev. 01/04/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0617

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW, Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0618

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 04024	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address		A. State Manifest Document Number
Contact: Ms. Belia Cortez	Union Carbide Star Route Box 90 Brownsville, Tx 78521	00004918
4. Generator's Phone (512) 831-4501		B. State Generator's ID 3108
5. Transporter 1 Company Name: WPI Transportation, Inc.	6. US EPA ID Number: TXD050641463	C. State Transporter's ID 40369
7. Transporter 2 Company Name	8. US EPA ID Number	D. Transporter's Phone 713-455-1400
		E. State Transporter's ID
		F. Transporter's Phone
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill 11013 Old Beaumont Highway Houston, Tx 77078	10. US EPA ID Number	G. State Facility's ID R026
		H. Facility's Phone 713-635-6101

	11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
GENERATOR		a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM-E, NA 9188	1	BA	28280	LBS	129300
		b. Debris					
		c.					
		d.					

J. Additional Descriptions for Materials Listed Above	K. Handling Codes for Wastes Listed Above
A. Friable Asbestos	

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equiptment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	19	92

TRANSPORTER	17. Transporter 1 Acknowledgement of Receipt of Materials				
	Printed/Typed Name: FRANK Hollabaugh	Signature: Frank E. Hollabaugh	Month: 06	Day: 19	Year: 92
	18. Transporter 2 Acknowledgement of Receipt of Materials				
	Printed/Typed Name	Signature	Month	Day	Year

FACILITY	19. Discrepancy Indication Space
	20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0619

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No 6594

TRUCK 1923 TLR 10-301
TRUCK LINE WPJ
CUSTOMER Union Carbide
CARGO

7:28 AM 06 10 92
46400 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

8:48 AM 06 10 92
74680 lb
46400 lb TR
28280 lb NET

FRANK Holbeck
Truck Driver

PUBLIC WEIGHER COUNTY OF CAMERON STATE

Certified Weigher

BRA 0620

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 6400-42

SERVICE ORDER NUMBER 25117

CUSTOMER Union Carbide P.O. # RELEASE #

DATE: 6-9-92 TRAILER # 602 TRUCK # 192 PICKUP #

OPERATOR OR DRIVER Frank Hollabaugh LABOR

JOB LOCATION Brownsville Tx. DESTINATION Houston Tx.

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE		UNLOADING	DATE	TIME	CIRCLE ONE	
LEAVE YARD	6-9-92	1:00	AM	PM	TIME ARRIVED			AM	PM
TIME ARRIVED	6-10-92	7:30	AM	PM	UNLOAD BEGAN			AM	PM
LOADING BEGAN	6-10-92	9:00	AM	PM	UNLOAD COMPLETE			AM	PM
LOADING COMPLETED	6-10-92	2:45	AM	PM	ARRIVED YARD			AM	PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-10-92	TX	I-10 59-77-511	406
6-10-92	TX	511-77-59-I-10	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED #603 1030 DATE/TIME 6-10-92 SHIPPER'S SIGNATURE

TRAILER/BIN PU 603 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 100402

TOTAL TRIP MILES

CUSTOMER SIGNATURE

CONFIRMS TIME IN PLANT

BRA 0621

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | 0 Manifest Document No. 3 6 4 0 3 4 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000493
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	23420	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#: TX 274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECSSARY. FOR HELP IN HANDLING EMERGENCIES INVOLVING SPILLS OR EXPOSURE. CALL UNION CARBIDE AT @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	11	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
Johnny R. Cisneros	Johnny R. Cisneros	06	11	92

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space
Browning Ferris Ind.
11013 Old Beaumont Hwy
Houston, Tx. 77078
(713) 675-6101
25

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year
J Henderson	J Henderson	06	12	92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0622

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0623

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 Manifest Document No. 0 4 8 3 3 4 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004933
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1506
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0262
H. Facility's Phone: (713) 675-6100

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	BA	23420	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A: FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI4, TX 274/930284/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECSSARY. FOR HELP IN HANDLING EMERGENCIES INVOLVING SPILLSSOR EXPOSURE. CALL UNION CARBIDE AT @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	11	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Johnny P. Cisneros	Johnny P. Cisneros	06	11	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0624

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No. 6625

TRUCK 816 TLR 25113/9025
TRUCK LINE WPJ
CUSTOMER Union Carbide
CARGO

8:51 AM 06 11 92
43160 lb

11:07 AM 06 11 92
66580 lb
43160 lb TR
23420 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHER STATE OF CALIFORNIA

Truck Driver

Certified Weigher

BRA 0625

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0822067

SERVICE ORDER NUMBER 022151

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 6.11.82 TRAILER # 607 TRUCK # 816 PICKUP #

OPERATOR OR DRIVER: Johnny R Chavez LABOR

JOB LOCATION: Brownsville, Tx. DESTINATION Houston, Tx.

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD	6.11.82	5:30	(AM) PM
TIME ARRIVED	6-11-82	8:30	(AM) PM
LOADING BEGAN	6-11-82	9:15	(AM) PM
LOADING COMPLETED	6-11-82	11:45	(AM) PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Pickup Box # 90-25 to BEI

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Johnny R Chavez

ENDING MILEAGE

BEGINNING MILEAGE 163258

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0626

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T·X·D·0·8·1·1·4·0·9·2	Manifest Document No. 0 6 4 0 3 4	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004932
B. State Generator's ID:
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T·X·D·0·5·0·6·4·1·4·6·3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B ~~B~~	2 4080.0	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI #TX/2747930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month Day Year
BELIA CORTEZ	Belia Cortez	06/11/92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year
Abelardo Vela Sr	Abelardo Vela Sr	06/11/92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month Day Year

FACILITY

19. Discrepancy Indication Space: Browning Ferris Ind. 11013 Old Beaumont Hwy. Houston, Tx. 77078 (713) 675-6101 — 25 y

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Date: Month Day Year
J. Henderson	J. Henderson	6/12/92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0627

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0628

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	T X D 0 8 1 1 4 0 9 2
Manifest Document No.	64034
2. Page 1 of	
Information in the shaded areas is not required by Federal law.	

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004932

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1501

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: 80261

H. Facility's Phone: (713) 675-6101

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	BA	24080	P Y	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI: #TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	11	82

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Abelardo Vela Jr	Abelardo Vela Jr	06	11	82

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0629

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No. 6624

TRUCK C808 TLR 25-8/1030
TRUCK LINE WPT
CUSTOMER Union Carbide
CARGO

8:50 AM 06 11 92
43300 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Rd.

11:11 AM 06 11 92
67380 lb
43300 lb TR
24080 lb NET

PUBLIC WEIGHER
COUNTY OF CAMERON, TEXAS

Truck Driver

Certified Weigher

BRA 0630

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 10 00 41832

SERVICE ORDER NUMBER G221905

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 6-11-92 TRAILER # 604 TRUCK # 308 PICKUP #

OPERATOR OR DRIVER: Abel Ucha LABOR

JOB LOCATION: Brownsville, Texas DESTINATION Houston, Texas

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE		UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-11-92	5:30	(AM) PM	TIME ARRIVED				AM PM
TIME ARRIVED	6-11-92	8:30	(AM) PM	UNLOAD BEGAN				AM PM
LOADING BEGAN	6-11-92	9:45	(AM) PM	UNLOAD COMPLETE				AM PM
LOADING COMPLETED	6-11-92	11:45	(AM) PM	ARRIVED YARD				AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-11-92	Tx	Hi-77 - 59	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Pick-up Box # 10-30

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU # 10-30 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 001630

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

TOTAL TRIP MILES

BRA 0631

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.	T X D 0 0 8 1 1 4 0 9 2
Manifest Document No.	0 4 8 0 7
2. Page 1 of	

Information in the shaded areas is not required by Federal law.

GENERATOR

3. Generator's Name and Mailing Address
UNION CARBIDE
CONTACT: MS BELIA CORTEZ, STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000480 7
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S., ORME NA 9188	1	B	27580	P	BC 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI-TX/274/930224/8157I

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	12	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
FRANK HOLUBECK	Frank Holubeck	06	12	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
M Easley		6	12	92

Browning Ferris Inc
11013 Old Beaumont Hwy.
Houston, TX 77078
(713) 675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink - TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0632

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0633

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 0 0 0 0 0 0 7

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE
CONTACT: MS BELIA CORTEZ, STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone: (512) 831-4501

A. State Manifest Document Number: 0000480 7

B. State Generator's ID:

C. State Transporter's ID: 40361

D. Transporter's Phone: (713) 452-1902

E. State Transporter's ID:

F. Transporter's Phone:

5. Transporter 1 Company Name: WPI TRANSPORTATION INC
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S., ORME NA 9188	1	B	27580	P	179390
	b.					
	c.					
	d.					

GENERATOR

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI TX/276/930224/8157

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-8501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	0 6	1 2	9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
FRANK Holubecik	Frank Holubecik	06	12	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0634

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148232

Tr 1923 Tlr 103

Truck Line M. P. I.

Name Union Carbide

Cargo H. Waste

Cert. Weigher

(empty weights included)

	@	$ 5.00	up to 65,000	60 Pd.
V	@	$ 6.00	65,020 - 85,000	
	@	$ 7.00	85,020 - 105,000	
	@	$ 8.50	105,020 - 125,000	
	@	$ 11.00	125,020 - 145,000	
	@	$ 25.00	145,020 and up	
	@	$ 3.00	empty only	

PUBLIC WEIGHER REG. # CAMERON COUNTY, TEXAS

7:34 A.M.		46160 G LB
12 JUN 92		
0	ID	
9:47 A.M.		73740 G LB
12 JUN 92		46160 T LB
0	ID	27580 N LB

Truck Driver Frank Gonzalez

BRA 0635

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0200 4107

SERVICE ORDER NUMBER 251175

CUSTOMER Atlas Chemical P.O. # RELEASE #

DATE 6-11-92 TRAILER # 607 TRUCK # 927 PICKUP #

OPERATOR OR DRIVER Frank Holubek LABOR

JOB LOCATION: Brownsville TX DESTINATION Houston TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-12-92		AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-11-92	7PM	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-12-92	8:30	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-12-92	9:30	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-11-92	TX	I-10-59-77-610	(E) 403
6-12-92	TX	610-77-59-I-10-610	2 miles

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED #603 2515 DATE/TIME SHIPPER'S SIGNATURE Bill Coit

TRAILER/BIN PU WH 95113 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Frank Holubek

ENDING MILEAGE

BEGINNING MILEAGE 605457 Bill Coit

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

TOTAL TRIP MILES

BRA 0636

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T·X·D·0·0·8·1·1·4·0·9·2	Manifest Document No. 64034	2. Page 1 of	Information in the shaded areas is not required by Federal law

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone

A. State Manifest Document Number: 00004934 BC
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261-02
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T·X·D·0·5·0·6·4·1·4·6·3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B ~~BA~~	BC 29220	P ~~Y~~	BC 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ABESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI TX/7274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR OTHER EXPOSURE. CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT .

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	12	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
L-WEBBER		06	13	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space
Browning Ferris Ind.
11013 Old Beaumont Hwy.
Houston, Tx. 77078
25 YDS

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19

Printed/Typed Name	Signature	Month	Day	Year
M Casler		6	13	92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0637

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0638

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No.: 0 4 0 4 4 6 4 0 3

2. Page 1 of 4 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNIONCCARBIDEL CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone

A. State Manifest Document Number: 00004934

B. State Generator's ID: 5508

5. Transporter 1 Company Name: WPL TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
C. State Transporter's ID: 5010
D. Transporter's Phone: (713) 675-5101

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
1013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:
G. State Facility's ID: 1026
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	BA	29720	P	179390
	b.					
	c.					
	d.					

GENERATOR

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR OTHER EXPOSURE, CALL UNION CARBIDE @ (512) 831-3501 DAY OR NIGHT .

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	12	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
[illegible]	[illegible]	06	12	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0639

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 548-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148233

Tr 1918 Tlr 90.75

Truck Line T. P. T

Name Travis Carlisle

Cargo Fly Ash

Carl N. Hale
Cert. Weigher

(empty weights included)

✓	@ $ 5.00	up to 65,000	60.00 Pd.
	@ $ 6.00	65,020 - 85,000	
	@ $ 7.00	85,020 - 105,000	
	@ $ 8.50	105,020 - 125,000	
	@ $ 11.00	125,020 - 145,000	
	@ $ 25.00	145,020 and up	
	@ $ 3.00	empty only	

PUBLIC WEIGHER CAMERON COUNTY, TEXAS

7:36 A.M. 12 JUN 92 0 ID	45220 G LB
9:46 A.M. 12 JUN 92 0 ID	74440 G LB 45220 T LB 29220 N LB

Truck Driver L Duvall

BRA 0640

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0001434

SERVICE ORDER NUMBER 250863

CUSTOMER: UNION CARBIDE P.O. # RELEASE #

DATE: 6-12-92 TRAILER # 2-1913 TRUCK # 1914 PICKUP #

OPERATOR OR DRIVER WEDDEL LABOR

JOB LOCATION: BROWNSVILLE TX DESTINATION HOUSTON, TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK (✓) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-11-92	11:00	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-12-92	7:30	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-12-92	8:00	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-12-92	9:30	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 6-12-92 DATE/TIME 6-12-92 8:00AM SHIPPER'S SIGNATURE

TRAILER/BIN PU 6-12-92 DATE/TIME 6-12-92 9:30AM CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 135840

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0641

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 04809

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004809
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1500
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S., ORM-E NA 9188	1	B	24880	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ
Signature: Belia Cortez
Month Day Year: 06 15 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: L WEDDLE
Signature: L Weddle
Date: Month Day Year

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
Browning Ferris Inc
11013 Old Beaumont Hwy
Houston, Tx. 77078
(713) 675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in item 19.
Printed/Typed Name: K Parsons
Signature: K Parsons
Date: Month Day Year: 6 16 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0642

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0643

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD088114092 — Manifest Document No. 04809

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004809
B. State Generator's ID:

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: TXD050641463
C. State Transporter's ID:
D. Transporter's Phone:

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:
G. State Facility's ID:
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S., ORM-E NA 9188	1	B	24880	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFITX/274/930224/8257

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	15	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
L WEDDEL	L Wedel			

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0644

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148299

Tr 1918 Tlr 25-8

Truck Line N.P.I.

Name Union Carbide

Cargo Dirt

Carl H. Helm
Cert. Weigher

WEIGHT 44940 LB
TIME 08:24 AM 15 JUN 92

(empty weights included)

_____ @ $ 5.00 up to 65,000
_____ @ $ 6.00 65,020 - 85,000
_____ @ $ 7.00 85,020 - 105,000
_____ @ $ 8.50 105,020 - 125,000
_____ @ $ 11.00 125,020 - 145,000
_____ @ $ 25.00 145,020 and up
_____ @ $ 3.00 empty only

10(C) L.R.

TICKET 1640
TRUCK ID 0
GROSS 69820 LB
K TARE 44940 LB
NET 24880 LB
TIME 09:46 AM 15 JUN 92

PUBLIC WEIGHMASTER CAMERON COUNTY, TEXAS

Truck Driver Lonnie

BRA 0645

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 42020427

SERVICE ORDER NUMBER 25086

CUSTOMER: UNION CARBIDE P.O. # RELEASE #

DATE: 6-15-92 TRAILER # 12 19 18 TRUCK # 1919 PICKUP #

OPERATOR OR DRIVER LABOR

JOB LOCATION: BROWNSVILLE, TX DESTINATION HOUSTON, TX

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (✓) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-19-92	7:00	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-15-92	8:30	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-15-92	8:45	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-15-92	10:00	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 25-X DATE/TIME 6-15-92 8:45 SHIPPER'S SIGNATURE

TRAILER/BIN PU 25-25 DATE/TIME 6-15-92 10:00 CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0646

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2	0 4 8 0 8		

GENERATOR

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 0000480 8 P
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 026193
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS DEBRIS N.O.S., ORM-E NA 9188	1	B.	31980 ~~24000~~ BC	P	BC 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	0 6	1 5	9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
FRANK Holobeck	Frank Holobeck	06	15	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space
Browning Ferris Inc.
11013 Old Beaumont Hwy.
Houston, Tx. 77078
(713) 675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
K Parsons	K Parsons	06	16	92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0647

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0648

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 0 4 8 0 8
2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 00004808
B. State Generator's ID: 31105
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 852-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: R 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ ASBESTOS DEBRIS N.O.S., ORM-E NA 9188	1	B	31980 24880 lbs	P Y	BE 79390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/27A/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GAASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	0 6	1 5	9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
FRANK Holsbeck	Frank Holsbeck	06	15	92

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0649

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148298

Tr 1923 Tlr 25113

Truck Line WPI

Name Union Carbide

Cargo dirt

Carl H. Hudson
Cert. Weigher

WEIGHT 46760 LB
TIME 08:23 AM 15 JUN 92

(empty weights included)

_____	@	$ 5.00	up to 65,000
_____	@	$ 6.00	65,020 - 85,000
_____	@	$ 7.00	85,020 - 105,000
_____	@	$ 8.50	105,020 - 125,000
_____	@	$ 11.00	125,020 - 145,000
_____	@	$ 25.00	145,020 and up
_____	@	$ 3.00	empty only

6.00

TICKET 1639
TRUCK ID 0
GROSS 78740 LB
TARE 46760 LB
NET 31980 LB
TIME 09:44 AM 15 JUN 92

PUBLIC WEIGHER CAMERON COUNTY, TEXAS

Truck Driver Frank Gonzalez

BRA 0650

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0006420

SERVICE ORDER NUMBER 251176

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 6-15-92 TRAILER # 603 TRUCK # 1923 PICKUP #

OPERATOR OR DRIVER: Frank Holubec LABOR

JOB LOCATION: Brownsville, Tx DESTINATION Houston, Tx

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

GH

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED			AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETE			AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6/14-92	Tx	I-10 - 59 - 77 - 511	400

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED 603 2511 3

DATE/TIME 6-15-92 830

SHIPPER'S SIGNATURE

TRAILER/BIN PU 603 2515

DATE/TIME 6-15-92 1230

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Frank Holubec

ENDING MILEAGE

BEGINNING MILEAGE 606253

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0651

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 0 0 0 4 8 1 0

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number 0000481012

B. State Generator's ID 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID 40369

D. Transporter's Phone (713) 672-5201

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID HA0+261U96

H. Facility's Phone (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E, NA 9188		B	31.72.0	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BEI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 06 Day 16 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Abelardo Vela Sr | Signature: Abelardo Vela Sr | Date: Month 06 Day 16 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
Browning Ferris Ind.
11013 Old Beaumont Hwy.
Houston Tx. 77078
(713) 675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: K Parsons | Signature: K Parsons | Date: Month 6 Day 16 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0652

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0653

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 0 0 4 8 1 0

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000481 0
B. State Generator's ID:
C. State Transporter's ID: 40369
D. Transporter's Phone:
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: B.C.261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E, NA 9188		B	3120	P	27939D
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI-TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ
Signature: Belia Cortez
Month Day Year: 0 6 | 1 6 | 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Abelardo Ulloa Sr
Signature: Abelardo Ulloa Sr
Date — Month Day Year: 06 | 16 | 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date — Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name:
Signature:
Date — Month Day Year:

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0654

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No. 6704

TRUCK C808 TLR 4-25
TRUCK LINE WPT
CUSTOMER Union Carbide
CARGO

7:43 AM 06 16 92
43660 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

10:03 AM 06 16 92
75380 lb
43660 lb TR
31720 lb NET

PUBLIC WEIGHER COUNTY OF CAMERON

Truck Driver

Certified Weigher

BRA 0655

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 20[illegible]

SERVICE ORDER NUMBER C221965

CUSTOMER: [illegible] P.O. # RELEASE #

DATE: [illegible] TRAILER # [illegible] TRUCK # [illegible] PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: [illegible] DESTINATION [illegible]

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-11-79	5:00	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-11-79	6:00	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-11-79	6:30	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED			AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT _____ am ( ) pm IN _____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Picked up 55-gal drums from [illegible] Brownsville, Tex.

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE [illegible]

TRAILER/BIN PU 25-113 DATE/TIME CONSIGNEE'S SIGNATURE [illegible]

DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE

BEGINNING MILEAGE [illegible]

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT [illegible]

BRA 0656

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T·X·D·0·0·8·1·1·4·0·9·2 | Manifest Document No. 0·4·8·1·1

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone

A. State Manifest Document Number 0000481 XXV

B. State Generator's ID 31108 BRA

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T.X.D.0.5.0.6.4.1.4.6.3

C. State Transporter's ID 40369

D. Transporter's Phone (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID H-0261

H. Facility's Phone (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	A1. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	30520	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month Day Year: 06 16 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Johnny R. Cisneros | Signature: Johnny R. Cisneros | Date: 06 16 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date

FACILITY

19. Discrepancy Indication Space

Browning Ferris Ind.
11013 Old Beaumont Hwy
Houston, Tx. 77078

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: R Parsons | Signature: R Parsons | Date: 10 16 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0657

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0658

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 0 0 0 0 4 8 1 1

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000481

B. State Generator's ID: [illegible]

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
1013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: TX 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	30520	P	179399
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BYL TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	0 6	1 6	9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Johnny R. Cisneros	Johnny R. Cisneros	0 6	1 6	9 2

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0659

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No 6705

TRUCK 816 TLR 25-135
TRUCK LINE WDI
CUSTOMER Union Carbide
CARGO

7:43 AM 06 16 92
42660 lb

10:05 AM 06 16 92
73180 lb
42660 lb TR
30520 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHER
STATE OF TEXAS

Truck Driver

Certified Weigher

BRA 0660

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST [illegible]

SERVICE ORDER NUMBER C 221986

CUSTOMER Union Carbide P.O. # RELEASE #

DATE 6-16-92 TRAILER # 602 TRUCK # 810 PICKUP #

OPERATOR OR DRIVER John P. Cowan LABOR

JOB LOCATION: Union Carbide Brownsville, Tx. DESTINATION Brownsville Plant To BFI

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE		UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-16-92	5:00	AM PM	TIME ARRIVED				AM PM
TIME ARRIVED	6-16-92	8:00	AM PM	UNLOAD BEGAN				AM PM
LOADING BEGAN	6-16-92	8:30	AM PM	UNLOAD COMPLETE				AM PM
LOADING COMPLETED	6-16-92	10:30	AM PM	ARRIVED YARD				AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Pickup Boy #75-8 To B.F.J. Plant To

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE John P. Cowan

ENDING MILEAGE

BEGINNING MILEAGE 164363

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

TOTAL TRIP MILES

BRA 0661

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 048 1

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 000048127TX 01

B. State Generator's ID: 31108

C. State Transporter's ID: 4036

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

D. Transporter's Phone: (713) 452-1502

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: TX 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	28520	P	179390 X80XX
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month Day Year: 06 17 82

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: FRANK Holubecik | Signature: Frank Holubecik | Date: Month Day Year 06 17 82

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
25 YDS

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: J HENDERSON | Signature | Date: Month Day Year 6 18 82

Browning Ferris Ind.
11013 Old Beaumont Hwy.
Houston, Tx. 77078
(713) 675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0662

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0663

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 | Manifest Document No. 2 0 88 1 | 2. Page 1 of 2 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-5501

A. State Manifest Document Number: 000048[illegible]
B. State Generator's ID: [illegible]

5. Transporter 1 Company Name: WFI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 [illegible] 6 3
C. State Transporter's ID: [illegible]
D. Transporter's Phone: [illegible]

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number:
G. State Facility's ID: [illegible] 0261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ. HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	28,520	P	179390 [illegible]
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
[illegible]/274/930224781571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	17	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
FRANK Holubecik	Frank Holubecik	06	17	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0664

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148405

Tr 1923 Tlr 23513

Truck Line TTPI

Name Union Carbide

Cargo Empty

Carl H. Holm
Cert. Weigher

(empty weights included)

	@	$ 5.00	up to 65,000
✓	@	$ 6.00	65,020 - 85,000
	@	$ 7.00	85,020 - 105,000
	@	$ 8.50	105,020 - 125,000
	@	$ 11.00	125,020 - 145,000
	@	$ 25.00	145,020 and up
	@	$ 3.00	empty only

PUBLIC WEIGHER PREC. 11 CAMERON COUNTY, TEXAS

7:13 A.M. 17 JUN 92 0 ID — 47440 G LB

8:59 A.M. 17 JUN 92 0 ID — 75960 G LB, 47440 T LB, 28520 N LB

Truck Driver Frank Schubert

BRA 0665

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST [illegible]

SERVICE ORDER NUMBER 251178

CUSTOMER [illegible] P.O.# RELEASE #

DATE 6-11-79 TRAILER # 4-3 TRUCK # 123 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION [illegible] DESTINATION [illegible]

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-11-79	11:30	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-11-79	7:15	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-12-79	9:00	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-12-79	9:15	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-11-79	Tx	610 I-10 45 77 511	2-C
6-12-79	Tx	511 77 I-10 610 45	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED #603 2515 DATE/TIME 6-11-79

TRAILER/BIN PU #603 4-25 DATE/TIME 6-11-79

SHIPPER'S SIGNATURE Bella Cotte

CONSIGNEE'S SIGNATURE [illegible]

DRIVER'S SIGNATURE Frank Wilson

ENDING MILEAGE

BEGINNING MILEAGE 60715-2

TOTAL TRIP MILES

CUSTOMER SIGNATURE Bella Cotte
CONFIRMS TIME IN PLANT

BRA 0666

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 0 0 0 4 8 1 3

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number 00004813

B. State Generator's ID 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID 40369

D. Transporter's Phone (713) 452-1500

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID H-026(?)

H. Facility's Phone (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	25800	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI/TX/274+9302247 81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 06 Day 17 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: L. WEDDEL | Signature | Date: Month 06 Day 17 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
Browning Ferris Ind.
11013 Old Beaumont Hwy.
Houston, Texas 77078
(713) 675-6101
25?

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: J. Henderson | Signature: J. Henderson | Date: Month 06 Day 18 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0667

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0668

WATER COMMISSION
P. O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. / Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2 / 0 0 0 4 8 1 3		

3. Generator's Name and Mailing Address UNION CARBIDE; CONTACT: MS. BELIA CORTEZ STAR ROUTE BOX 90 BROWNSVILLE, TEXAS 78521 (512) 831-4501 4. Generator's Phone ( )	A. State Manifest Document Number 00004813
	B. State Generator's ID 31103
5. Transporter 1 Company Name WPI TRANSPORTATION INC.	6. US EPA ID Number T X D 0 0 0 6 4 1 4 6
	C. State Transporter's ID 40369
7. Transporter 2 Company Name	8. US EPA ID Number
	D. Transporter's Phone E. State Transporter's ID F. Transporter's Phone
9. Designated Facility Name and Site Address BFI MCCARTY ROAD LANDFILL 11013 OLD BEAUMONT HIGHWAY HOUSTON, TEXAS 77078	10. US EPA ID Number
	G. State Facility's ID 026 H. Facility's Phone (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	25800	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above	K. Handling Codes for Wastes Listed Above
A. F. RIABLE ASBESTOS DEBRIS	BFI FIX/274/9302247-81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR	Printed/Typed Name	Signature	Month Day Year
	BELIA CORTEZ	Belia Cortez	06 17 79

TRANSPORTER			
	17. Transporter 1 Acknowledgement of Receipt of Materials		Date
	Printed/Typed Name: L. WEDDEL	Signature	Month Day Year: 06 17 79
	18. Transporter 2 Acknowledgement of Receipt of Materials		Date
	Printed/Typed Name	Signature	Month Day Year

FACILITY			
	19. Discrepancy Indication Space		
	20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Date
	Printed/Typed Name	Signature	Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0669

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148407

Tr 1915 Tlr 26-23

Truck Line WPI

Name Union Carbide

Cargo Lint

Carl H. Hahn
Cert. Weigher

(empty weights included)

_____ @ $ 5.00 up to 65,000
_____ @ $ 6.00 65,020 - 85,000
_____ @ $ 7.00 85,020 - 105,000
_____ @ $ 8.50 105,020 - 125,000
_____ @ $ 11.00 125,020 - 145,000
_____ @ $ 25.00 145,020 and up
_____ @ $ 3.00 empty only

$6.00
Ok

7:31 A.M. 45080 G LB
17 JUN 92
0 ID

9:05 A.M. 70880 G LB
17 JUN 92 45080 T LB
0 ID 25800 N LB

PUBLIC WEIGHER REG. # 1 CAMERON COUNTY, TEXAS

Truck Driver Winnie

BRA 0670

WPI Trucking, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000-4813

SERVICE ORDER NUMBER 221801

CUSTOMER: UNION CARBIDE P.O. # RELEASE #

DATE: 6-17-93 TRAILER # V-1412 TRUCK # 191-2 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: BROWNSVILLE, TX DESTINATION [illegible], TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK (✓) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-15-93	1100	(AM) PM
TIME ARRIVED	6-15-93	7:30	(AM) PM
LOADING BEGAN	6-15-93	8	(AM) PM
LOADING COMPLETED	6-15-93	9:30	(AM) PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ___ am ( ) pm IN ___ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-16-93	TX	T-109 610 / 59 / 100 / 77 / 511 48	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 26-25

TRAILER/BIN PU 25-135

DATE/TIME 6-17-93

DATE/TIME

SHIPPER'S SIGNATURE Delia Cortez

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE

BEGINNING MILEAGE 137191

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0671

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/655

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2	Manifest Document No. 5	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 0000481 5
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H-026
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	35460	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BEL/TX/274-930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT .

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	18	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Johnny Cisneros	John R. Cisneros	06	18	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space
Browning Ferris Ind.
11013 Old Beaumont Hwy.
Houston, Tx. 77078
(713) 675-6101
25

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
K Parsons	K Parsons	06	19	92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0672

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. T.is includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0673

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 5

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
SEAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 00004815

B. State Generator's ID:

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 450-1504

E. State Transporter's ID:

F. Transporter's Phone:

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 2

7. Transporter 2 Company Name

8. US EPA ID Number

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. BRM-E NA 9188	1	B	35460	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI/TX/27A-930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT .

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	0 6	1 8	9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Johnny Cisneros	John R. Cisneros	0 6	1 8	9 2

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0674

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 № 6755

TRUCK 816 TLR 25-8/26-25

TRUCK LINE WPT

CUSTOMER Union Carbide

CARGO

7:59 AM 06 18 92
42720 lb

10:36 AM 06 18 92
78180 lb
42720 lb TR
35460 lb NET

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☑ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHER
STATE OF CALIFORNIA

Truck Driver

Certified Weigher

BRA 0675

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST

SERVICE ORDER NUMBER C221985

CUSTOMER

P.O. #

RELEASE #

DATE

TRAILER #

TRUCK #

PICKUP #

OPERATOR OR DRIVER

LABOR

JOB LOCATION

DESTINATION

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM
TIME ARRIVED			AM PM
LOADING BEGAN			AM PM
LOADING COMPLETED			AM PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0676

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 0 4 8 14 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone ( ) (512) 831-4501

A. State Manifest Document Number: 000048 14 X

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1500

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H 0 26 Mod 48

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	31880	P	E 179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month Day Year: 06 18 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Abelardo Vela Sr | Signature: Abelardo Vela Sr | Date: 06 18 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date

FACILITY

19. Discrepancy Indication Space
Browning Ferris Ind
11013 Old Beaumont Hwy.
Houston, Tx. 77078
(713) 675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19

Printed/Typed Name: K Parsons | Signature: K Parsons | Date: 10/19/92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0677

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0678

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087
Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T-X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 0 4 8 1 4
2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MR. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 000048141
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-2504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: 8 0 261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	31880	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS DEBRIS
K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable International and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 06 Day 18 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Abelardo Ulla Jr. — Signature: Abelardo Ulla E — Date: Month 06 Day 18 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: — Signature: — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0679

QUALITY WEIGHING SERVICES, INC.

QWS

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No. 6754

TRUCK C808 TLR 25113 / 2515

TRUCK LINE WPT

CUSTOMER Union Carbide

CARGO

7:58 AM 06 18 92
43480 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

10:34 AM 06 18 92
75360 lb
43480 lb TR
31880 lb NET

PUBLIC WEIGHMASTER
STATE OF TEXAS

Truck Driver

Certified Weigher

BRA 0680

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST [illegible]

SERVICE ORDER NUMBER C221968

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 6-12-92 TRAILER # 4110 TRUCK # 208 PICKUP #

OPERATOR OR DRIVER: [illegible] LABOR

JOB LOCATION: Brownsville, Texas DESTINATION B.F.I. Houston, Texas

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

	LOADING DATE	LOADING TIME	CIRCLE ONE		UNLOADING DATE	UNLOADING TIME	CIRCLE ONE
LEAVE YARD	6-12-92	5:00	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-18-92	8:00	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-18-92	9:30	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-18-92	11:00	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-12-92	Tx	77-59	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Pick up B-Tote at Brownsville Texas to B.F.I. Houston, Texas

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE [signature]

TRAILER/BIN PU B-Pac-14 DATE/TIME CONSIGNEE'S SIGNATURE [signature]

DRIVER'S SIGNATURE [signature]

ENDING MILEAGE

BEGINNING MILEAGE 003212

TOTAL TRIP MILES

[signature]
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0681

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 04816

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 000048162
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H 026103
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: TXD050641466

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	20340	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY . FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 06 Day 19 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: FRANK Holubeck | Signature: Frank Holubeck | Date: Month 06 Day 19 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
25
11013 Old Beaumont Hwy.
Houston, Tx. 77078
(713) 675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: K. Parsons | Signature: K Parsons | Date: Month 10 Day 20 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0682

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0683

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. / Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.
	T X D 0 0 8 1 1 4 0 9 2 / 0 0 0 0 4 8 1 6		

GENERATOR

3. Generator's Name and Mailing Address
UNIONCCARBIDE; CONTACT: MS. BELIA BORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 0000481B
B. State Generator's ID:

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 5 1 4 6
C. State Transporter's ID: 4030
D. Transporter's Phone: (713) 452-[illegible]

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:
G. State Facility's ID: 0261
H. Facility's Phone: (713) 675-61D[illegible]

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	20340	P	179320
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BEL TX/276/930226/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY . FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	0[illegible]	[illegible]9	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
FRANK HOLUBECK	Frank Holubeck	06	19	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY


19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0684



PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148514

Tr 1923 Tlr 603

Truck Line T&D1

Name Union Carbide

Cargo Lint

Carl H. Hulse
Cert. Weigher

(empty weights included)

- ____ @ $ 5.00 up to 65,000
- ✓ @ $ 6.00 65,020 - 85,000 — 6.00 Pd.
- ____ @ $ 7.00 85,020 - 105,000
- ____ @ $ 8.50 105,020 - 125,000
- ____ @ $ 11.00 125,020 - 145,000
- ____ @ $ 25.00 145,020 and up
- ____ @ $ 3.00 empty only

PUBLIC WEIGHER SEC. 11 CAMERON COUNTY, TEXAS

Truck Driver Frank Holcomb

7:49 A.M. 19 JUN 92 0 ID — 46900 G LB

9:08 A.M. 19 JUN 92 0 ID — 67240 G LB, 46900 T LB, 20340 N LB

Manufactured by Border Press, Inc.
620 East Price • Brownsville, Texas 78521 • 512/831-2793

BRA 0685

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST

SERVICE ORDER NUMBER 251719

CUSTOMER: P.O. # RELEASE #

DATE: TRAILER # TRUCK # PICKUP #

OPERATOR OR DRIVER: LABOR

JOB LOCATION: DESTINATION

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-14-82	1000	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-19-82	900	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-19-82	911	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-19-82	951	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-18-82	TX	610-59-10-59-77-511	403-71
6-19-82	TX	511-77	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED 403-4-23 DATE/TIME 6-19-82

TRAILER/BIN PU 403-3-113 DATE/TIME 6-15-82

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MEASURE

BEGINNING MEASURE 403.000

TOTAL TRIP MILES

CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0686

Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2	Manifest Document No. 0 4 8 1 7	2. Page 1 of	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number: 0000481 7

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 60369

D. Transporter's Phone: (512) 452-1507

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
10. US EPA ID Number

G. State Facility's ID: H0361

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	24820	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	0 6	~~1 9~~ 22	9 2

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Frank Holubeck	Frank Holubeck	0 6	2 2	9 2

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

19. Discrepancy Indication Space
Brownie Ferris Ind.
11013 Old Beaumont Hwy
Houston, Tx. 77078
(713) 675-6101

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
J. HENDERSON	J. Henderson	06	23	92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0687

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applic

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223; U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0688

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 0 0 4 8 1 7

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number 0000481[illegible]
B. State Generator's ID [illegible]
C. State Transporter's ID [illegible]
D. Transporter's Phone [illegible]
E. State Transporter's ID
F. Transporter's Phone
G. State Facility's ID
H. Facility's Phone

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
10. US EPA ID Number

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188	1	B	24820	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
RFI TX(276/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE. UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	0 6	1 9	9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Frank Holubeck	Frank Holubeck	0 6	2 9	9 2

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0689

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/673

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148543

Tr 1923 Tlr

Truck Line WPI

Name Union Carbide

Cargo Mist

Carl N. Holm
Cert. Weigher

(empty weights included)

	@	$ 5.00	up to 65,000
✓	@	$ 6.00	65,020 - 85,000
	@	$ 7.00	85,020 - 105,000
	@	$ 8.50	105,020 - 125,000
	@	$ 11.00	125,020 - 145,000
	@	$ 25.00	145,020 and up
	@	$ 3.00	empty only

6.00 Pd.

PUBLIC WEIGHER INSP. CAMERON COUNTY, TEXAS

7:11 A.M.		46760 G LB
22 JUN 92		
0	ID	
9:29 A.M.		71580 G LB
22 JUN 92		46760 T LB
0	ID	24820 N LB

Truck Driver Frank Schubeck

BRA 0690

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 4817

SERVICE ORDER NUMBER 251715

CUSTOMER: [illegible] P.O. # RELEASE #

DATE: 1-31-79 TRAILER # 7002 TRUCK # 1043 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: [illegible] DESTINATION [illegible]

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	1-31-79	[illegible]	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED			AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED			AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
(1-31-79)	TEXAS	[illegible]	[illegible]

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 1-31-79 DATE/TIME

TRAILER/BIN PU 1-31-79 DATE/TIME 1-31-79

SHIPPER'S SIGNATURE [illegible]

CONSIGNEE'S SIGNATURE [illegible]

DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE

BEGINNING MILEAGE [illegible]

TOTAL TRIP MILES

CUSTOMER SIGNATURE [illegible]
CONFIRMS TIME IN PLANT

BRA 0691

...AS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 0 4 8 1 8

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 00004818 XK
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1506
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H 026
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY ROAD LANDFILL, 11013 OLD BEAUMONT HIGHWAY, HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S., ORM-E NA 9188	1	B	28600	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS DEBRIS
K. Handling Codes for Wastes Listed Above: BFI/TX/274/930224/8157

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 06 Day 22 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: L. WOODS | Signature: | Month 06 Day 22 Year 92 | Date

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Month Day Year | Date

FACILITY

19. Discrepancy Indication Space: 254

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J HENDERSON | Signature: | Month 6 Day 23 Year 92 | Date

Browning Ferris Ind.
11013 Old Beaumont Hwy.
Houston, Tx. 77078
(713) 675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0692

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0693

AS WATER COMMISSION
O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 8 8 1 1 4 0 9 2 | Manifest Document No. 0 0 0 0 4 8 1 8

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000481

B. State Generator's ID: 3610

5. Transporter 1 Company Name: WPI TRANSPORTATION, INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 1

C. State Transporter's ID: 30481

D. Transporter's Phone: (713) 674-1101

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: 0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S., ORM-E NA 9188	1	B	28600	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI TX/274/9902247 81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 0 6 | Day 2 8 | Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: C. WEDDER | Signature | Date: Month 0 6 | Day 2 8 | Year 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date: Month | Day | Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Date: Month | Day | Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0694

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148563

Tr 1918 Tlr

Truck Line W. P. ut.

Name

Cargo Dirt

Cert. Weigher

(empty weights included)

- ____ @ $ 5.00 up to 65,000
- ✓ @ $ 6.00 65,020 - 85,000
- ____ @ $ 7.00 85,020 - 105,000
- ____ @ $ 8.50 105,020 - 125,000
- ____ @ $ 11.00 125,020 - 145,000
- ____ @ $ 25.00 145,020 and up
- ____ @ $ 3.00 empty only

6.00 Pd.

PUBLIC WEIGHMASTER REG. 77 CAMERON COUNTY, TEXAS

Truck Driver

8:53 A.M. 44980 G LB
22 JUN 92
0 ID
9:27 A.M. 73580 G LB
22 JUN 92 44980 T LB
0 ID 28600 N LB

BRA 0695

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST

SERVICE ORDER NUMBER 250042

CUSTOMER: UNION CARBIDE P.O.# RELEASE #

DATE: 6-22-92 TRAILER # 12-194 TRUCK # 1998 PICKUP #

OPERATOR OR DRIVER LABOR

JOB LOCATION: DESTINATION

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-21-92	2:00	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-22-92	8:45	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-22-92	9:00	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-22-92	9:45	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-22-92	TX	1-10/59/225/146/59/10/1998	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 25-12

TRAILER/BIN PU 6-25-92

DATE/TIME 6-22-92 9:00A

DATE/TIME 6-22-92 9:45A

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0696

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/680

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 0 0 0 4 8 2 0

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number: 00004820

B. State Generator's ID: 31108

5. Transporter 1 Company Name: BPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: TX D 261 [illegible]

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S., ORM-E NA 9188	1	B	18300	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 06 24 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: FRANK HOLUBECK — Signature: Frank Holubeck — Date: 06 24 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date

FACILITY

19. Discrepancy Indication Space
Browning Ferris Ind.
11013 Old Beaumont Hwy.
HOUSTON, TX 77078
(713) 675-6101
264

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name: J HENDERSON — Signature: J Henderson — Date: 06 25 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0697

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0698

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 | Manifest Document No. 2 0 4 8 2 0

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE; CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number: 0000820

B. State Generator's ID:

5. Transporter 1 Company Name: BFI TRANSPORTATION INC.

6. US EPA ID Number: TXX D 0 5 0 6 4 1 4 6

C. State Transporter's ID:

D. Transporter's Phone:

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number:

G. State Facility's ID:

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S., ORM-E NA 9188	1	B	18300	P	
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI/TX/274/910226/81571

15. Special Handling Instructions and Additional Information WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT IS NECESSARY FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 0 6 | Day 2 4 | Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: FRANK Holubeck | Signature: Frank Holubeck | Month 0 6 | Day 2 4 | Year 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Month | Day | Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Month | Day | Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0699

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148660

Tr 1923 Tlr _____

Truck Line TX P1

Name Union Carbide

Cargo Pitch

Cert. Weigher

(empty weights included)

1	@	$ 5.00	up to 65,000
_____	@	$ 6.00	65,020 - 85,000
_____	@	$ 7.00	85,020 - 105,000
_____	@	$ 8.50	105,020 - 125,000
_____	@	$ 11.00	125,020 - 145,000
_____	@	$ 25.00	145,020 and up
_____	@	$ 3.00	empty only

5.00 Pd.

PUBLIC WEIGHER PERMIT CAMERON COUNTY, TEXAS

7:35 A.M. 46140 G LB
24 JUN 92
0 ID

9:19 A.M. 64440 G LB
24 JUN 92 46140 T LB
0 ID 18300 N LB

Truck Driver Frank Holubec

BRA 0700

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1564

MANIFEST 0000420

SERVICE ORDER NUMBER 251718

CUSTOMER Union Carbide P.O. # RELEASE #

DATE 6-13-79 TRAILER # 602 TRUCK # 1223 PICKUP #

OPERATOR OR DRIVER Frank Maldonado LABOR

JOB LOCATION Brownsville DESTINATION Houston

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-13-79	1100	AM (PM)	TIME ARRIVED			AM PM
TIME ARRIVED	6-13-79	1230	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-13-79	1300	(AM) PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-13-79	1600	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-13-79	TX	100-37-44-59 77-511	100

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED 6-13-79 1600

TRAILER/BIN PU 602

DATE/TIME 6-14-79 9:00 AM

DATE/TIME 6-14-79 9:00 AM

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 109677

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0701

BRA 0702

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 0 4 8 1 9

2. Page 1 of

Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501

4. Generator's Phone ( )

A. State Manifest Document Number: 0000819 BFI

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: (713) 452-1502

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: TX0261

H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S., ORM-E NA 9188	1	B	22640	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A/ FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/B1571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month Day Year: 0 6 | 2 4 | 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name: L. WEDDOR | Signature | Month Day Year: 0 6 | 2 4 | 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month Day Year

FACILITY

19. Discrepancy Indication Space
Browning Ferris Ind.
11013 Old Beaumont Hwy.
Houston, Tx 77078
(713) 675-6101
25 Y

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date

Printed/Typed Name: S HENDERSON | Signature | Month Day Year: 6 | 25 | 9 2

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0703

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0704

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087
Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. / Manifest Document No.: TXD008114092 04819
2. Page 1 of
Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521
4. Generator's Phone: (512) 831-4501

A. State Manifest Document Number: 00004819
B. State Generator's ID:

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: TXD050641467
C. State Transporter's ID:
D. Transporter's Phone:

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:
G. State Facility's ID: 810261
H. Facility's Phone: (713) 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S., ORM-E NA 9188	1	B	22640	P	179350
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
#/ FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	24	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
L WEDDE		06	24	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0705

-PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148661

Tr 1918 Tlr

Truck Line WPI

Name [illegible]

Cargo [illegible]

Carl W. Hinton
Cert. Weigher

(empty weights included)

- ✓ @ $ 5.00 up to 65,000
- _____ @ $ 6.00 65,020 - 85,000
- _____ @ $ 7.00 85,020 - 105,000
- _____ @ $ 8.50 105,020 - 125,000
- _____ @ $ 11.00 125,020 - 145,000
- _____ @ $ 25.00 145,020 and up
- _____ @ $ 3.00 empty only

5.00 Pd.

PUBLIC WEIGHER PMC. 11 CARTERON COUNTY, TEXAS

7:36 A.M. 40680 G LB
24 JUN 92
0 ID

9:34 A.M. 63320 G LB
24 JUN 92 40680 T LB
0 ID 22640 N LB

Truck Driver [illegible]

BRA 0706

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 2004484

SERVICE ORDER NUMBER 251168

CUSTOMER: UNION CARBIDE P.O.# RELEASE #

DATE: 6-21-93 TRAILER #: 201 TRUCK #: 1219 PICKUP #:

OPERATOR OR DRIVER: [illegible] LABOR

JOB LOCATION: Brownsville TX DESTINATION: Harlingen TX

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM
( ) END DUMP ( ) DROP DECK (✓) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

	LOADING DATE	LOADING TIME	CIRCLE ONE		UNLOADING DATE	UNLOADING TIME	CIRCLE ONE
LEAVE YARD	6-22-93	7:00	AM (PM)	TIME ARRIVED			AM PM
TIME ARRIVED	6-23-93	7:30	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-23-93	8:00	(AM) PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-24-93		AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-23-93	TX	I-10/I-69/US77/US11/US83	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 4-135 DATE/TIME 6-24-93 8:00A

TRAILER/BIN PU # 3C-135 DATE/TIME 6-24-93 9:45A

SHIPPER'S SIGNATURE [signature]

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE [signature]

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE [signature]
CONFIRMS TIME IN PLANT

BRA 0707

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 — Manifest Document No. 04828

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512)831-4501

A. State Manifest Document Number: 000004828 P
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713-452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transportation, Inc
6. US EPA ID Number: TXD050641463

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI McCarty Landfill
11013 Old Beaumont Highway
Houston, Tx 77078

10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM-E, NA 9188		B	Van Volume Total Cap.	P	179390
	b. Debris			24220		
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. Friable Asbestos

K. Handling Codes for Wastes Listed Above
BFI # TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure, call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ
Signature: x Belia Cortez
Month 06 Day 25 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Eduardo Vela Sr
Signature: x Eduardo Vela Sr
Date: Month 06 Day 25 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature: Browning Ferris Ind.
Date: Month . Day . Year .

FACILITY

19. Discrepancy Indication Space
11013 Old Beaumont Hwy.
Houston, Tx. 77078
(713) 675-6101
25

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: K Parsons
Signature: K Parsons
Date: Month 06 Day 26 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0708

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0709

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.) Form approved. OMB No. 2050-0039. Expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 048 8	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact: Ms. Bella Cortez
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000482

B. State Generator's ID:

C. State Transporter's ID:

D. Transporter's Phone:

E. State Transporter's ID:

F. Transporter's Phone:

5. Transporter 1 Company Name: WPI Transportation, Inc
6. US EPA ID Number: TXD050641663

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI McCarty Landfill
11013 Old Beaumont Highway
Houston, Tx 77078

10. US EPA ID Number:

G. State Facility's ID: 1016

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.U.S., ORM-E, NA 9188		B.	Van Volume Total Cap.	P	179-550
	b. Debris			24220		
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A, Friable Asbestos

K. Handling Codes for Wastes Listed Above
D-1: TX/2/4/990224/81371

15. Special Handling Instructions and Additional Information: Wear gloves, glasses and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure, call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	06	25	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Abelardo Vela Sr	x Abelardo Vela Sr	06	25	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0710

QUALITY WEIGHING SERVICES, INC.

QWS

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No 7213

TRUCK 808 TLR 16325
TRUCK LINE WPT
CUSTOMER Union Carbide
CARGO

8:08 AM 06 25 92
43060 lb

- ☐ $3.00 EMPTY ONLY
- ☐ $5.00 UP TO 65,000 GROSS
- ☒ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

9:44 AM 06 25 92
67280 lb
43060 lb TR
24220 lb NET

Truck Driver

PUBLIC WEIGHER
COMMISSIONED

Certified Weigher

BRA 0711

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST

SERVICE ORDER NUMBER G221970

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE 6-25-79 TRAILER # 609 TRUCK # 893 PICKUP #

OPERATOR OR DRIVER Herb Vick LABOR

JOB LOCATION: Brownsville, Texas DESTINATION B.F.I. Houston, Texas

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	6-25-79	8:00	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	6-25-79	9:00	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	6-25-79	10:00	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
6-25-79	Tx		

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Pick up Bay at Box #25-8. Take to B.F.I. Houston, Texas

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU Box #25-8 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 105-122

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0712

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No. 0 4 8 2 1 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521 (512) 831-4501
4. Generator's Phone ( )

A. State Manifest Document Number: 00004821 PM
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: (713) 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: TH 0261
H. Facility's Phone: (713) 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.
6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6 3
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	(I.) Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS DEBRIS N.O.S. ORM-E NA 9188		B	19420	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS DEBRIS
K. Handling Codes for Wastes Listed Above: BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the presently and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month Day Year
BELIA CORTEZ	Belia Cortez	06 25 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year
R.G. BRISTOW	R.G. Bristow	06 25 92

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19B

Browning Ferris Ind.
11013 Old Beaumont Hwy.
Houston, TX. 77078
(713) 675-6101

Printed/Typed Name	Signature	Date Month Day Year
K. Parsons	K. Parsons	06 26 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0713

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do **not** send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0714

TEXAS WATER COMMISSION
P.O. Box 13087 Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 | Manifest Document No.

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE: CONTACT: MS. BELIA CORTEZ
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4001

A. State Manifest Document Number: 0000482

B. State Generator's ID:

5. Transporter 1 Company Name: WPI TRANSPORTATION INC.

6. US EPA ID Number: T X D 0 5 0 6 4 1 4 6

C. State Transporter's ID: 49369

D. Transporter's Phone:

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY ROAD LANDFILL
11013 OLD BEAUMONT HIGHWAY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: TX 0261

H. Facility's Phone: (713) 675-6101

11A HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ, HAZARDOUS SUBSTANCE SOLID/ASBESTOS BOUND N.O.S. ORM-E NA 9188		B	19420	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS DEBRIS

K. Handling Codes for Wastes Listed Above
BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE @ (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month Day Year: 06 25 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: R.C. BRISTOL | Signature: R.C. Bristol | Date: 06 25 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Date

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0715

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No. 7212

TRUCK 817 TLR 25/132/425

TRUCK LINE WPI

CUSTOMER Union Carbide

CARGO

8:05 AM 06 25 92
39180 lb

☐	$3.00	EMPTY ONLY
☑	$5.00	UP TO 65,000 GROSS
☐	$6.00	65,020 TO 85,000 GROSS
☐	$7.00	85,020 TO 105,000 GROSS
☐	$8.50	105,020 TO 125,000 GROSS
☐	$10.00	125,020 TO 145,000 GROSS
☐	$25.00	145,020 AND UP

Pd

9:41 AM 06 25 92
58600 lb
39180 lb TR
19420 lb NET

PUBLIC WEIGHER

Truck Driver

Certified Weigher

BRA 0716

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0660H821

SERVICE ORDER NUMBER 251249

CUSTOMER: Union Carbide P.O. #: RELEASE #:

DATE: 6-25-92 TRAILER #: 1607 TRUCK #: 87 PICKUP #:

OPERATOR OR DRIVER: R. Bristol LABOR:

JOB LOCATION: Brownsville, Tx DESTINATION: BFI - Houston, Tx

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE		UNLOADING	DATE	TIME	CIRCLE ONE	
LEAVE YARD	6-25-92	5 15	AM	PM	TIME ARRIVED			AM	PM
TIME ARRIVED	6-25-92	8 00	AM	PM	UNLOAD BEGAN			AM	PM
LOADING BEGAN	6-25-92	8 15	AM	PM	UNLOAD COMPLETE			AM	PM
LOADING COMPLETED	6-25-92		AM	PM	ARRIVED YARD			AM	PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Deliver Empty Box #25-132 Pick-up Box #4-25 Deliver To 5 15/A - 5 45/A Pre-Trip 1/2 HR

TRAILER/BIN DROPPED # ____ DATE/TIME ____ SHIPPER'S SIGNATURE Billie Cortez

TRAILER/BIN PU 4-25 DATE/TIME ____ CONSIGNEE'S SIGNATURE Byd Wayne

DRIVER'S SIGNATURE R Bristol

ENDING MILEAGE ____

BEGINNING MILEAGE ____

TOTAL TRIP MILES ____

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT Billie Cortez Byd Wayne

BRA 0717

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 — Manifest Document No. 104879

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact: Ms. Belia Cortez
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000482 9 [illegible]
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713-452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transportation, Inc
6. US EPA ID Number: TXD050641463

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI McCarty Landfill
11013 Old Beaumont highway
Houston, Tx 77078

10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ Hazardous Substance Solid/ Asbestos, N.O.S., ORM-E, NA 9188		B	23300	P	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos

K. Handling Codes for Wastes Listed Above: BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: X Belia Cortez — Month 0 7 Day 0 1 Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: L. WEBBER — Signature: X [signature] — Date: Month 0 7 Day 0 1 Year 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: K Parsons — Signature: K Parsons — Date: Month 0 7 Day 1 3 Year 9 2

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT #261
JUL 13 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0718

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0719

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 — Manifest Document No. 04829
2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact: Ms. Belia Cortez
Union Carbide
Star Route Box 90
Brownsville Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004829
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713-450-1300
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transportation, Inc.
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address
BFI McCarty Landfill
11013 Old Beaumont Highway
Houston, Tx 77078
10. US EPA ID Number:

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/ Asbestos, N.O.S., ORM-E, NA 9188		B	23300	P	179890
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A - Friable Asbestos

K. Handling Codes for Wastes Listed Above
BFI #IX/Z74/930224/81571

15. Special Handling Instructions and Additional Information
Wear gloves, glasses, and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ
Signature: X Belia Cortez
Month Day Year: 07 01 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: C. WEDDEL
Signature: X
Date — Month Day Year: 07 01 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name:
Signature:
Date — Month Day Year:

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name:
Signature:
Date — Month Day Year:

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0720

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148955

Tr 1918 Tlr

Truck Line M. P. I.

Name Texas Coastal

Cargo Asbestos Ore

Carl H. Holm
Cert. Weigher

(empty weights included)

11.5 mt
30

	@	$ 5.00	up to 65,000
	@	$ 6.00	65,020 - 85,000
	@	$ 7.00	85,020 - 105,000
	@	$ 8.50	105,020 - 125,000
	@	$ 11.00	125,020 - 145,000
	@	$ 25.00	145,020 and up
	@	$ 3.00	empty only

PUBLIC WEIGHER REG. BY CAMERON COUNTY, TEXAS

Truck Driver

12:21 P.M. 01 JUL 92 0 ID — 39280 G LB

1:40 P.M. 01 JUL 92 0 ID — 62580 G LB, 39280 T LB, 23300 N LB

BRA 0721

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST [illegible]

SERVICE ORDER NUMBER 250515

CUSTOMER: UNION C... P.O. # RELEASE #

DATE 7-1-95 TRAILER # 606 TRUCK # 191X PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: BROWNSVILLE, TX DESTINATION HOUSTON, TX

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-30-95	6:00	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	7-1-95	12:15	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	7-1-95	12:15	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	7-1-95	3:15	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 606-25 DATE/TIME

TRAILER/BIN PU 2-2-132- DATE/TIME

SHIPPER'S SIGNATURE [signature]

CONSIGNEE'S SIGNATURE [signature]

DRIVER'S SIGNATURE [signature]

ENDING MILEAGE

BEGINNING MILEAGE 140739

TOTAL TRIP MILES

CUSTOMER SIGNATURE [signature]
CONFIRMS TIME IN PLANT

BRA 0722

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: TXD008114092 | Manifest Document No.: 04830
2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact: Ms. Belia Cortez Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000480 BFK
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713-452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transprtation, Inc.
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Landfill, 11013 Old Beaumont Highway, Houston, Tx 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM-E, NA 9188	1	B	16580	P	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos
K. Handling Codes for Wastes Listed Above: BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: X Belia Cortez | Month 0 7 | Day 0 1 | Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: FRANK HOLUBECK | Signature: X Frank Holubeck | Date: Month 0 7 | Day 0 1 | Year 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month | Day | Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: K Parsons | Signature | Date: Month 7 | Day 13 | Year 9

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT #261
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Gold-Generator's first copy

BRA 0723

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0724

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD093114092 | Manifest Document No. 04830 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address: Union Carbide, Contact: Ms. Belia Cortez, Star Route Box 90, Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004830

B. State Generator's ID: 4110

5. Transporter 1 Company Name: WPI Transportation, Inc.

6. US EPA ID Number: TXD050641463

C. State Transporter's ID: 5

D. Transporter's Phone: 713-675-6101

7. Transporter 2 Company Name:

8. US EPA ID Number:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address: BFI McCarty Landfill, 11033 Old Beaumont Highway, Houston, Tx 77078

10. US EPA ID Number:

G. State Facility's ID: H026?

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazaddous Substance Solid/Asbestos, N.O.S., ORM-E, NA 9188	1	B	16580	P	19390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos

K. Handling Codes for Wastes Listed Above: BRA #TX/274/93024/8157

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: X Belia Cortez | Month 0 7 | Day 0 1 | Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: FRANK Holubeck | Signature: X Frank Holubeck | Month 0 7 | Day 0 1 | Year 9 2 | Date

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Month | Day | Year | Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Month | Day | Year | Date

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0725

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148956

Tr 1923 Tlr _____

Truck Line W.P.I.

Name Union Carbide

Cargo Asbestos Ashes

Carl N. Hahn
Cert. Weigher

(empty weights included)

- ✓ @ $ 5.00 up to 65,000
- _____ @ $ 6.00 65,020 - 85,000
- _____ @ $ 7.00 85,020 - 105,000
- _____ @ $ 8.50 105,020 - 125,000
- _____ @ $ 11.00 125,020 - 145,000
- _____ @ $ 25.00 145,020 and up
- _____ @ $ 3.00 empty only

12:22 P.M. 01 JUL 92 0 ID — 47540 G LB

1:34 P.M. 01 JUL 92 0 ID — 64120 G LB, 47540 T LB, 16580 N LB

Truck Driver Frank Hubbard

BRA 0726

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST

SERVICE ORDER NUMBER 251180

CUSTOMER Union Carbide P.O. # RELEASE #

DATE 7-1-92 TRAILER # 603 TRUCK # 1225 PICKUP #

OPERATOR OR DRIVER Frank Hinojosa LABOR

JOB LOCATION Brownsville Tx DESTINATION Houston Tx

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	6-30-92	6:30	AM (PM)	TIME ARRIVED			AM PM
TIME ARRIVED	7-1-92	12:30	AM (PM)	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED			AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
7-1-92	Tx	Rte-59-175-77-511	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED 603 25112 DATE/TIME SHIPPER'S SIGNATURE Bill Coats

TRAILER/BIN PU 603 1625 DATE/TIME CONSIGNEE'S SIGNATURE Frank Hinojosa

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 611993

TOTAL TRIP MILES

Bill Coats
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0727

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-92

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 04831	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact: Ms. Belia Cortez Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000483104 WAS
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713-452-1506
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name	6. US EPA ID Number
WPI Transportation, Inc.	TXD050641463
7. Transporter 2 Company Name	8. US EPA ID Number

9. Designated Facility Name and Site Address
BFI McCarty Landfill
11013 Old Beaumont Highway
Houston, Tx 77078

10. US EPA ID Number

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid/Asbestos, N.O.S., ORM-E, NA 9188	1	B	20580	P	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. Fraible Asbestos

K. Handling Codes for Wastes Listed Above
BFI#TX/274/930224/81571

15. Special Handling Instructions and Additional Information
Wear gloves,glasses, and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union carbide at 5 12-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	X Belia Cortez	07	02	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
L. WEDAEL	X L Wedael	07	02	92

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year
H Parsons	H Parsons	07	31	92

BROWNING-FERRIS, INC.
McCARTY RD LANDFILL
TDH PERMIT #261
JUL 31 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0728

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0729

TEXAS WATER COMMISSION
P.O. Box 13087 Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 04831 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact: Ms. Belia Cortez
Star Route Box 90
Brownsville, Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number 0000483

B. State Generator's ID 1101

5. Transporter 1 Company Name: WPIMTransportation, Inc.
6. US EPA ID Number: TXD050641463
C. State Transporter's ID 4036
D. Transporter's Phone 713-845-[illegible]

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Landfill
11013 Old Beaumont Highway
Houston, Tx 77078
10. US EPA ID Number
G. State Facility's ID 110761
H. Facility's Phone 713-676-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Substabce Solid/Asbestos, N.O.S., ORM-E, NA 9188	1	B	20580	P	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos

K. Handling Codes for Wastes Listed Above: BFI #DX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other protective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union carbide at 5 12-831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	X Belia Cortez	0 7	0 2	9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year
L. WEDDEL	X L Weddel	0 7	0 2	9 2

18. Transporter 2 Acknowledgement of Receipt of Materials — Date

Printed/Typed Name	Signature	Month	Day	Year

FACILITY


19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0730



PORT OF BROWNSVILLE PUBLIC SCALE, INC.
(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148981

Tr 1918 Tlr

Truck Line WP I

Name

Cargo Asbestos Cloth

(empty weights included)

- @ $ 5.00 up to 65,000
- @ $ 6.00 65,020 - 85,000
- @ $ 7.00 85,020 - 105,000
- @ $ 8.50 105,020 - 125,000
- @ $ 11.00 125,020 - 145,000
- @ $ 25.00 145,020 and up
- @ $ 3.00 empty only

Truck Driver

Cert. Weigher

8:58 A.M. 02 JUL 92 0 ID — 38260 G LB

9:50 A.M. 02 JUL 92 0 ID — 58840 G LB / 38260 T LB / 20580 N LB

PUBLIC WEIGHER PREC. 4 CAMERON COUNTY, TEXAS

BRA 0731

BRA 0732

WPI Transportation, Inc

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 000421

SERVICE ORDER NUMBER

250058

CUSTOMER UNION CARBIDE P.O. # RELEASE #

DATE 7-2-92 TRAILER # 606 TRUCK # 1913 PICKUP #

OPERATOR OR DRIVER LOUIS DIAZ LABOR

JOB LOCATION: BROWNSVILLE TX DESTINATION HOUSTON, TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (✓) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	7-1-92	7:30	AM (PM)	TIME ARRIVED			AM PM
TIME ARRIVED	7-2-92	8:30	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	7-2-92	9:00	(AM) PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	7-2-92	11:30	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
7-1-92	TX		

WAS JOB COMPLETED SATISFACTORILY? ✓

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 3569 DATE/TIME 7-2-92 9:00AM SHIPPER'S SIGNATURE D Diaz Costa

TRAILER/BIN PU 1976-5 DATE/TIME 7-2-92 CONSIGNEE'S SIGNATURE Boyd Wagner

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

Robin Cortez
CUSTOMER SIGNATURE Boyd Wagner
CONFIRMS TIME IN PLANT

BRA 0733

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: TXD 008114092 — Manifest Document No.: 04834
2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address:
UNION CARBIDE
STAR ROUTE BOX 90
BROWNSVILLE, TX 78521
CONTACT MS: BELIA CORTEZ

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0004834 (WX)
B. State Generator's ID: 91108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address:
BFI MCCARTY LANDFILL
11013 OLD BEAUMONT HWY
HOUSTON, TX 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ HAZERDOUS SUBSTANCE SOLID/ ASBESTOES, N.O.S., ORM-E, NA 9188		B	24360 xxxxxxxxx	P	179390
	b. DEBRIS					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: FRIABLE ASBESTOES
K. Handling Codes for Wastes Listed Above: BFI /TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT 512 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 07 Day 02 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: FRANK Holubeck — Signature: Frank Holubeck — Date: Month 07 Day 02 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: — Signature: — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: K Parsons — Signature: K Parsons — Date: Month 7 Day 13 Year 92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT #261
JUL 3 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0734

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0735

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 04834	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address	A. State Manifest Document Number
UNION CARBIDE STAR ROUTE BOX 90 CONTACT MS: BELIA CORTEZ BROWNSVILLE, TX 78521	0000004834
4. Generator's Phone (512) 831-4501	B. State Generator's ID [redacted]
5. Transporter 1 Company Name: BFI TRANSPORTATION	6. US EPA ID Number: TXD050641463
	C. State Transporter's ID 40369
7. Transporter 2 Company Name	8. US EPA ID Number
	D. Transporter's Phone 713 452-1304
	E. State Transporter's ID
	F. Transporter's Phone
9. Designated Facility Name and Site Address: BFI MCCARTY LANDFILL 11013 OLD BEAUMONT HWY HOUSTON, TX 77078	10. US EPA ID Number
	G. State Facility's ID H0261
	H. Facility's Phone 713 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ HAZERDOUS SUBSTANCE SOLID/ ASBESTOES, N.O.S., ORM-E, NA 9188	1	B	24360	P	179390
	b. DEBRIS					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above	K. Handling Codes for Wastes Listed Above
FRIABLE ASBESTOES	BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT 512 831-4501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	07	02	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
FRANK Holubeck	Frank Holubeck	07	02	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0736

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

148976

Tr 1923 Tlr _____

Truck Line W.P.C.

Name _____

Cargo Rubbish

Hilda G. Espinoza
Cert. Weigher

(empty weights included)

_____	@	$ 5.00	up to 65,000
✓	@	$ 6.00	65,020 - 85,000
_____	@	$ 7.00	85,020 - 105,000
_____	@	$ 8.50	105,020 - 125,000
_____	@	$ 11.00	125,020 - 145,000
_____	@	$ 25.00	145,020 and up
_____	@	$ 3.00	empty only

60.00 Pd.

PUBLIC WEIGHER #1 CAMERON COUNTY, TEXAS

Truck Driver Jose Valdez

8:02 A.M. 02 JUL 92 0 ID — 46420 G LB

10:30 A.M. 02 JUL 92 0 ID — 70780 G LB
46420 T LB
24360 N LB

BRA 0737

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 000[illegible]

SERVICE ORDER NUMBER 251182

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 7-2-92 TRAILER # 603 TRUCK # 193? PICKUP #

OPERATOR OR DRIVER: Frank Holbrook LABOR

JOB LOCATION: Brownsville, TX DESTINATION Houston, TX

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

	LOADING DATE	LOADING TIME	CIRCLE ONE		UNLOADING DATE	UNLOADING TIME	CIRCLE ONE
LEAVE YARD	7-2-92		AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	7-2-92	8:00	(AM) PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	7-2-92	8:30	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	7-2-92	11:30	(AM) PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
7-2-92	TX		

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Loading 4 Sacks

TRAILER/BIN DROPPED #603 163-25 DATE/TIME 7-2-92 11:11

TRAILER/BIN PU 603 2568 DATE/TIME 7-2-92 12:40

SHIPPER'S SIGNATURE Bibi Conte

CONSIGNEE'S SIGNATURE Eby D. Wagner

DRIVER'S SIGNATURE Frank Holbrook

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT Bibi Conte Eby D. Wagner

BRA 0738

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: TXD008114092 | Manifest Document No.: 04835

2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE
STAR ROUTE BOX 90
BROWNSVILLE, TX 78521
CONTACT : MS. BELIA CORTEZ

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 0000835 KJK

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION
6. US EPA ID Number: TXD050641463

C. State Transporter's ID: 40369

D. Transporter's Phone: 713 452-1504

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address: BFI MCCARTY RD. LANDFILL
10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ HAZERDOUS SUBSTANCE SOLID/ ASBESTOES N.O.S., ORM-E, NA 9188	1	B	14560	P	179390
	b. DEBRIS					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOES

K. Handling Codes for Wastes Listed Above: BFI-J TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGECIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT 512 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	07	06	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
FRANK Holubeck	Frank Holubeck	07	06	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space
Section 9- Address incomplete
SIB 11013 old Beaumont Hwy Houston, TX 77078 7 1992

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT #261
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713/675-6101

2545

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
J HENDERSON	J Henderson	7	7	92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0739

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, searching existing data sources, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0740

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008614092 | Manifest Document No. 04835 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE
STAR ROUTE BOX 90
CONTACT : MS. BELIA CORTEZ BROWNSVILLE, TX 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number 00004835

B. State Generator's ID 91008

5. Transporter 1 Company Name: WPI TRANSPORTATION | 6. US EPA ID Number: TXD050641463

C. State Transporter's ID 40369

D. Transporter's Phone 713 [illegible]

7. Transporter 2 Company Name | 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address: BFI MCCARTY RD. LANDFILL | 10. US EPA ID Number

G. State Facility's ID 80261

H. Facility's Phone

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ HAZERDOUS SUBSTANCE SOLID/ ASBESTOES N.O.S., ORM-E, NA 9188	1	B	14560	P	179390
	b. DEBRIS					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOES

K. Handling Codes for Wastes Listed Above: BFI # TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES, AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGECIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT 512 831-4501 DAY OR NIGHT?

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 0 7 | Day 0 6 | Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name: FRANK Holubeck | Signature: Frank Holubeck | Month 0 7 | Day 0 6 | Year 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials | Date

Printed/Typed Name | Signature | Month | Day | Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. | Date

Printed/Typed Name | Signature | Month | Day | Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0741

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER-HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

149009

Tr 1923 Tlr

Truck Line U.P.J.

Name Union Carbide

Cargo Waste

Cert. Weigher

6:56 A.M. 06 JUL 92 0 ID — 47740 G LB

9:22 A.M. 06 JUL 92 0 ID — 62300 G LB / 47740 T LB / 14560 N LB

(empty weights included)

- V @ $ 5.00 up to 65,000 — 5.00 pd.
- _____ @ $ 6.00 65,020 - 85,000
- _____ @ $ 7.00 85,020 - 105,000
- _____ @ $ 8.50 105,020 - 125,000
- _____ @ $ 11.00 125,020 - 145,000
- _____ @ $ 25.00 145,020 and up
- _____ @ $ 3.00 empty only

PUBLIC WEIGHER PWC 1 CAMERON COUNTY, TEXAS

Truck Driver Lonnie Holwood

BRA 0742

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000 4735

SERVICE ORDER NUMBER 251188

CUSTOMER: Union Carbide P.O.# RELEASE #

DATE: 7-5-79 TRAILER # 683 TRUCK # 1732 PICKUP #

OPERATOR OR DRIVER: Frank Hillebrick LABOR

JOB LOCATION: Brownsville Tx DESTINATION: Houston Tx

(X) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM (X) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD	7-5-79	1:00	AM (PM)
TIME ARRIVED	7-6-79	2:00	(AM) PM
LOADING BEGAN	7-6-79	2:30	(AM) PM
LOADING COMPLETED	7-6-79		AM PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
7-6-79	TX	E-10-59-610-59-59	
7-6-79	TX	59-59-10-610-610	
	TX		

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: (LOADING) NOT MUCH FROM TO PICK UP BIN

TRAILER/BIN DROPPED #602-2513 DATE/TIME 7-6-79 9 AM SHIPPER'S SIGNATURE Bella Cortez By A. Wagner

TRAILER/BIN PU 602-3567 DATE/TIME 7-6-79 CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Frank Hillebrick

ENDING MILEAGE

BEGINNING MILEAGE 613663

TOTAL TRIP MILES

Bella Cortez By A. Wagner
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0743

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 04836	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE
STAR ROUTE BOX 90
CONTACT: MS. BELIA CORTEZ BROWNSVILLE, TX 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004836 X

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION
6. US EPA ID Number: TXD050641463
C. State Transporter's ID: 40369
D. Transporter's Phone: 713 452-1504

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY RD. LANDFILL
11013 OLD BEAUMONT HWY
HOUSTON, TX 77078
10. US EPA ID Number
G. State Facility's ID: H0261
H. Facility's Phone: 713 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ HAZERDOUS SUBSTANCE SOLID/ ASBESTOES,N.O.S., ORM-E, NA 9188	1	B	16120	P	179390
	b. DEBRIS					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A: FRIABL ASBESTOES

K. Handling Codes for Wastes Listed Above
BFI#:TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT 512 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	0 7	0 6	9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year
L. NIEDDA		0 7	0 6	9 2

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Date: Month	Day	Year

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT #261
JUL 7 1992

FACILITY

19. Discrepancy Indication Space
25Y

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
11013 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078

Printed/Typed Name	Signature	Date: Month	Day	Year
J. Henderson	J. Henderson	7	7	92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0744

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/728

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0745

TEXAS WATER COMMISSION
P.O. Box 3087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 — Manifest Document No. 04836
2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE
STAR ROUTE BOX 90
CONTACT: MS. BELIA CORTEZ BROWNSVILLE, TX 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004836

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPT TRANSPORTATION
6. US EPA ID Number: TXD050641463
C. State Transporter's ID: 40360
D. Transporter's Phone: 713 452-7510

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY LANDFILL
11013 OLD BEAUMONT HWY
HOUSTON, TX 77078
10. US EPA ID Number
G. State Facility's ID: H026
H. Facility's Phone: 713 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ HAZERDOUS SUBSTANCE SOLID/ ASBESTOES,N.O.S., ORM-E, NA 9188	1	B	16120	P	179390
	b. DEBRIS					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABL ASBESTORS

K. Handling Codes for Wastes Listed Above: BFI# TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NEC NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIESSINVOLVING SPILLS OR EXPOSURE.CALL UNION CARBIDE AT 512 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 0 7 Day 0 6 Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials — Date
Printed/Typed Name: L. WEDDEL — Signature — Month 0 7 Day 0 6 Year 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials — Date
Printed/Typed Name — Signature — Month Day Year


FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. — Date
Printed/Typed Name — Signature — Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0746



PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(51. 31-9223
AFTL. HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

149011

Tr 1918 Tlr 1997

Truck Line W.P.I.

Name Union Carbide

Cargo Waste

Cert. Weigher

(empty weights included)

✓	@	$ 5.00	up to 65,000	5.00
	@	$ 6.00	65,020 - 85,000	
	@	$ 7.00	85,020 - 105,000	
	@	$ 8.50	105,020 - 125,000	
	@	$ 11.00	125,020 - 145,000	
	@	$ 25.00	145,020 and up	
	@	$ 3.00	empty only	

Pd.

PUBLIC WEIGHER SEC. 41 CAMERON COUNTY, TEXAS

Truck Driver Driver

7:13 A.M. 06 JUL 92 0 ID 39180 G LB

10:11 A.M. 06 JUL 92 0 ID 55300 G LB
39180 T LB
16120 N LB

BRA 0747

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 0000483

SERVICE ORDER NUMBER 250043

CUSTOMER UNION CARBIDE P.O. # RELEASE #

DATE 2-6-92 TRAILER # 606 TRUCK # 418 PICKUP #

OPERATOR OR DRIVER WILDER LABOR

JOB LOCATION BROWNSVILLE, TX DESTINATION HOUSTON, TX

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	2-5-92	2:00	AM (PM)	TIME ARRIVED			AM PM
TIME ARRIVED	2-6-92	7:15	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED			AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
2-5-92	TX		

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 606-25 DATE/TIME 2-6-92 2:45 PM SHIPPER'S SIGNATURE Billie Coats by D. Wagner

TRAILER/BIN PU 25-68 DATE/TIME 2-10-92 11:30 AM CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE Billie Coats by D. Wagner
CONFIRMS TIME IN PLANT

BRA 0748

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-9

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 04837	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE
STAR ROUTE BOX 90
BROWNSVILLE, TX 78521
CONTACT: BELIA CORTEZ
4. Generator's Phone ( )

A. State Manifest Document Number: 000048374
B. State Generator's ID: 3168
C. State Transporter's ID: 40369
D. Transporter's Phone: 713 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: HO261
H. Facility's Phone: 713 675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY RD. LANDFILL
11013 OLD BEAUMONT HWY
HOUSTON, TX 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	12. Containers Type	13. Total Quantity	14. Unit Wt/Vol	I.A. Waste No.
	a. RQ HAZERDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S.,ORM-E, NA 9188	1	B	21000	P	179390
	b. DEBRIS					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT 512 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	07	07	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
R.C. BRASTOW	R.C. Brastow	07	07	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space
25 YDS

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
J. HENDERSON	J. Henderson	07	18	92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT #261
JUL 8 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0749

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden to Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0750

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 04837	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE
STAR ROUTE BOX 90
BROWNSVILLE, TX 78521
CONTACT: BELIA CORTEZ
4. Generator's Phone ( )

A. State Manifest Document Number: 000004837
B. State Generator's ID: 31008

5. Transporter 1 Company Name: WPI TRANSPORTATION
6. US EPA ID Number: TXD050641463
C. State Transporter's ID: 40369
D. Transporter's Phone: 713 472-1401

7. Transporter 2 Company Name
8. US EPA ID Number
E. State Transporter's ID
F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY RD. LANDFILL
11013 OLD BEAUMONT HWY
HOUSTON, TX 77078
10. US EPA ID Number
G. State Facility's ID: H0261
H. Facility's Phone: 7136955-6101

	11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
GENERATOR		a. RQ HAZERDOUS SUBSTANCE SOLID/ ASBESTOS N.N.S.,ORM-E, NA 9188	1	B	21000	P	179390
		b. DEBRIS					
		c.					
		d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI #TX/274/930324/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT 512 831-4501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	07	07	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
R.C. BASTOL	R.C. Bastol	07	07	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0751

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/735

QUALITY WEIGHING SERVICES, INC.

QWS

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No. 8126

TRUCK 816 TLR 25-114/175-25

TRUCK LINE WPI

CUSTOMER Union Carbide

CARGO

8:05 AM 07 07 92
42440 lb

Pd

- ☐ $3.00 EMPTY ONLY
- ☑ $5.00 UP TO 65,000 GROSS
- ☐ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

10:55 AM 07 07 92
63440 lb
42440 lb TR
21000 lb NET

PUBLIC WEIGHER STATE OF TEXAS

Truck Driver

Certified Weigher

BRA 0752

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 4837

SERVICE ORDER NUMBER 251378

CUSTOMER Union Carbide P.O. # RELEASE #

DATE 7-7-92 TRAILER # 602 TRUCK # 218 PICKUP #

OPERATOR OR DRIVER R. Brister LABOR

JOB LOCATION Union Carbide - Brownsville, Tx. DESTINATION BFI - Houston, Tx

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD		8	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	7-7-92	830	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	7-7-92	830	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	7-7-92	1115	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: 80 Hazardous Substance Solid
Asbestos NOS ORM-E NA9187

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU 25-176 DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 169912

TOTAL TRIP MILES

CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0753

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD008114092	Manifest Document No. 04838	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE
STAR ROUTE BOX 90
CONTACT: MS. BELIA CORTEZ
BROWNSVILLE, TX 78521
4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004838
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713-452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: H0261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI TRANSPORTATION
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI MCCARTY RD. LANDFILL, 11013 OLD BEAUMONT HWY, HOUSTON, TX 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	15. Waste No.
	a. RQ HAZERDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S., ORM-E, NA 9188	1	B	19720	P	179390
	b. DEBRIS					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI/TX/2747930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HELP IN HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT 512 831-4501 DAY OR NIGHT

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	07	07	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Billy Guerra		07	07	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space: 25YDS

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
J HENDERSON	J Henderson	7	21	92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT #261
JUL 8 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0754

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of the Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0755

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: TXD008114092 | Manifest Document No.: 04838
2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
UNION CARBIDE
STAR ROUTE BOX 90
BROWNSVILLE, TX 78521
CONTACT: MS. BELIA CORTEZ

A. State Manifest Document Number: 00004838
B. State Generator's ID: 3108

4. Generator's Phone (512) 831-4501

5. Transporter 1 Company Name: WPI TRANSPORTATION
6. US EPA ID Number: TXD050681463
C. State Transporter's ID: 20368
D. Transporter's Phone: 713 [illegible]

7. Transporter 2 Company Name:
8. US EPA ID Number:
E. State Transporter's ID:
F. Transporter's Phone:

9. Designated Facility Name and Site Address
BFI MCCARTY RD. LANDFILL
11013 OLD BEAUMONT HWY
HOUSTON, TX 77078
10. US EPA ID Number:
G. State Facility's ID: 80261
H. Facility's Phone: 713 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ HAZERDOUS SUBSTANCE SOLID/ ASBESTOS, N.O.S$, ORM-E, NA 9188	1	B	19720	P	179390
	b. DEBRIS					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. FRIABLE ASBESTOS
K. Handling Codes for Wastes Listed Above: BFI TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT AS NECESSARY. FOR HANDLINGHANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE CALL UNION CARBIDE AT 512 83104501 DAY OR NIGHT

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	07	07	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
Billy GUERRO	Billy Guerro	07	07	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0756

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No 8127

TRUCK C-824 TLR 2575 / 25113
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

8:06 AM 07 07 92
41200 lb

☐	~~$3.00~~	EMPTY ONLY
☑	$5.00	UP TO 65,000 GROSS
☐	$6.00	65,020 TO 85,000 GROSS
☐	$7.00	85,020 TO 105,000 GROSS
☐	$8.50	105,020 TO 125,000 GROSS
☐	$10.00	125,020 TO 145,000 GROSS
☐	$25.00	145,020 AND UP

Pd

10:56 AM 07 07 92
60920 lb
41200 lb TR
19720 lb NET

PUBLIC WEIGHER COUNTY OF CAMERON

Truck Driver

Certified Weigher

BRA 0757

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 7037

SERVICE ORDER NUMBER G221775

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 07-07-92 TRAILER # 1000 TRUCK # 824 PICKUP #

OPERATOR OR DRIVER Billy C. Cuellar LABOR

JOB LOCATION: Brownsville Texas DESTINATION Houston Texas

( ) VACTOR (X) CYCLONE ( ) 70 BBL VACUUM (X) 130 BBL VACUUM

( ) END DUMP (X) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED			AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	07-07-92	8:30	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	07-07-92	11:15	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
070792	Texas	77 - 511	446086

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: NO HAZ - Substance Solid
Asbestos NOS ORM-E NA 9189
½ HR Dwl Tp 0

TRAILER/BIN DROPPED # DATE/TIME

TRAILER/BIN PU # 25113 DATE/TIME 07-07-92

SHIPPER'S SIGNATURE

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE 446086

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

BRA 0758

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD00811409 2	Manifest Document No. 04841	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address: Union Carbide, Contact Ms. Belia Cortez, Star Route Box 90, Brownsville Tx 78521
4. Generator's Phone (512)831-4501

A. State Manifest Document Number: 0000484 1
B. State Generator's ID: 31108
C. State Transporter's ID: 713-9351504
D. Transporter's Phone:
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: HO-261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transportation
6. US EPA ID Number: TXD 050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill, 11013 Old Beaumont Highway, Houston Texas 77078
10. US EPA ID Number:

	11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
GENERATOR		a. R Q hazardous Substance Solid Asbestos, N.O.S. Orm-e NA 9188	1	B	21480	P	179390
		b. Debris					
		c.					
		d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos
K. Handling Codes for Wastes Listed Above: BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other proctective equipment as necessary. For help in handling chemical mergencies involving spills or exposure, call Union Carbide at 512 831-4501 day or night

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

	Printed/Typed Name	Signature	Month	Day	Year
GENERATOR	BELIA CORTEZ	Belia Cortez	07	08	92
TRANSPORTER	17. Transporter 1 Acknowledgement of Receipt of Materials				Date
	FRANK Holubeck	Frank Holubeck	07	08	92
	18. Transporter 2 Acknowledgement of Receipt of Materials				Date
	Printed/Typed Name	Signature	Month	Day	Year
FACILITY	19. Discrepancy Indication Space				
	20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.				Date
	J. HENDERSON	J. Henderson	7	9	92

BROWNING-FERRIS, INC. McCARTY RD. LANDFILL TDH PERMIT #261 JUL - 1992 11013 OLD BEAUMONT HWY. HOUSTON, TEXAS 77078 713-675-6101

25Y

TWC-03/1 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0759

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0760

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 04841 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address: Union Carbide
Contact Ms. Belia Cortez Saar Route Box 90
Brownsville Tx 78521

A. State Manifest Document Number: 000048411

4. Generator's Phone (512) 831-4501

B. State Generator's ID: 1102

5. Transporter 1 Company Name: WPI Transportation | 6. US EPA ID Number: TXD 050641463 | C. State Transporter's ID: 40369

D. Transporter's Phone:

7. Transporter 2 Company Name | 8. US EPA ID Number | E. State Transporter's ID | F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont Highway
Houston Texas 77078

10. US EPA ID Number | G. State Facility's ID: HO 261 | H. Facility's Phone

GENERATOR

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. R Q hazardous Substance Solid Asbestos, N.O.S. Orm-e NA 9188	1	B	21480	P	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos

K. Handling Codes for Wastes Listed Above: BFI-1 TX/274/980224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses, and other proctective equipment as necessary. For help in handling chemical mergencies involving spills or exposure, call Union Carbide at 512 831-4501 day or night

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 0 7 | Day 0 8 | Year 9 2 | Date

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: FRANK Holubeck | Signature: Frank Holubeck | Month 0 7 | Day 0 8 | Year 9 2 | Date

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Month | Day | Year | Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Month | Day | Year | Date

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0761

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

149093

Tr 1923 Tlr _____

Truck Line _____

Name WPT

Cargo SCRAP

Cert. Weigher

(empty weights included)

_____ @ $ 5.00 up to 65,000
_____ @ $ 6.00 65,020 - 85,000
_____ @ $ 7.00 85,020 - 105,000
_____ @ $ 8.50 105,020 - 125,000
_____ @ $ 11.00 125,020 - 145,000
_____ @ $ 25.00 145,020 and up
_____ @ $ 3.00 empty only

7:37 A.M. 47200 G LB
08 JUL 92
0 ID

8:47 A.M. 68680 G LB
08 JUL 92 47200 T LB
0 ID 21480 N LB

PUBLIC WEIGHER PREC. #1 CAMERON COUNTY, TEXAS

Truck Driver Juan Hollebeck

BRA 0762

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST [illegible]

SERVICE ORDER NUMBER 25118

CUSTOMER Union Carbide P.O.# RELEASE #

DATE 7-7-92 TRAILER # 6013 TRUCK # 120 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION Brownsville, TX DESTINATION Houston, TX

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	7-7-92	1[illegible]	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	7-7-92	[illegible]	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	7-7-92	7[illegible]	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED			AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT _____ am ( ) pm IN _____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
7-7-92	TX	77-511	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED [illegible] DATE/TIME 7-7-92 7[illegible] SHIPPER'S SIGNATURE Bobbie Cotts By L. Wagner

TRAILER/BIN PU 2575 DATE/TIME 7-7-92 [illegible] CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE

BEGINNING MILEAGE 611457

TOTAL TRIP MILES

Bobbie Cotts By L. Wagner
CUSTOMER SIGNATURE
CONFIRMS TIME IN PLANT

BRA 0763

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST	1. Generator's US EPA ID No. TXD 008114092	Manifest Document No. 04842	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact Ms. BElia Cortez Star Route Box 90
Brownsville Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004842
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713 452 1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: HO 261
H. Facility's Phone: 713 675-6101

5. Transporter 1 Company Name	6. US EPA ID Number
WPI Transportation	TXD050641463
7. Transporter 2 Company Name	8. US EPA ID Number
9. Designated Facility Name and Site Address	10. US EPA ID Number
BFI McCarty Road Landfill 11013 Old Beaumont Highway Houston Texas 77078	

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid Asbestos, NOS ORM-E NA 9188	1	B	16260	P	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. Friable Asbestos

K. Handling Codes for Wastes Listed Above
BFI #: TX/274/930224/81571

15. Special Handling Instructions and Additional Information
Wear gloves, glasses and other proctective equipment as necessay. For help in handling chemical emergencies involving spills or exposure, call Union Caride at 512 831-4501 day or night

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	07	08	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
L. WEDDER		07	08	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year
		07	09	92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT #261
JUL 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101
25YDS

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0764

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

*(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0765

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD 988008114092 — Manifest Document No. 04842

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact Ms. BElia Cortez Star Route Box 90
Brownsville Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004842

B. State Generator's ID: 3008

5. Transporter 1 Company Name: WPI Transportation — 6. US EPA ID Number: TXD050642463

C. State Transporter's ID: 4036

D. Transporter's Phone: 512 451 5171

7. Transporter 2 Company Name — 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont Highway
Houston Texas 77078

10. US EPA ID Number

G. State Facility's ID: HO-261

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Substance Solid Asbestos, NOS ORM-B NA 9188	1	B	16260	P	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable Asbestos

K. Handling Codes for Wastes Listed Above: BFI # TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves, glasses and other proctective equipment as necessay. For help in handling chemical emergencies involving spills or exposure, call Union Carbide at 512 831-4501 day or night

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name	Signature	Month	Day	Year
BELIA CORTEZ	Belia Cortez	07	08	92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year
C. WEBBER	C OWENS	07	08	92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name	Signature	Month	Day	Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name	Signature	Month	Day	Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0766

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

149092

Tr 1915 Tlr 25114

Truck Line

Name UPT

Cargo Asbestos waste

Cert. Weigher

(empty weights included)

✓	@	$ 5.00	up to 65,000
	@	$ 6.00	65,020 - 85,000
	@	$ 7.00	85,020 - 105,000
	@	$ 8.50	105,020 - 125,000
	@	$ 11.00	125,020 - 145,000
	@	$ 25.00	145,020 and up
	@	$ 3.00	empty only

7:35 A.M. 08 JUL 92 0 ID — 45260 G LB

8:44 A.M. 08 JUL 92 0 ID — 61520 G LB, 45260 T LB, 16260 N LB

PUBLIC WEIGHER PREC. #1 CAMERON COUNTY, TEXAS

Truck Driver

BRA 0767

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 40016-24

SERVICE ORDER NUMBER 251168

CUSTOMER: UNION CARBIDE P.O. # RELEASE #

DATE 7-2-79 TRAILER # 12914 TRUCK # 1914 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: BROWNSVILLE, TX DESTINATION HOUSTON, TX

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (✓) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD	7-2-79	7:00	AM (PM)
TIME ARRIVED	7-2-79	7:30	(AM) PM
LOADING BEGAN	7-2-79	7:32	(AM) PM
LOADING COMPLETED	7-2-79	9:12	(AM) PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT _____ am ( ) pm IN _____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
7-2-79	TX	T-511, 9/12-77/511/48	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 9152 DATE/TIME 7-2-79 8:30A SHIPPER'S SIGNATURE Billie Cantu By a Wayne

TRAILER/BIN PU 25-114 DATE/TIME 7-2-79 9:15A CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE

TOTAL TRIP MILES

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT Billie Cantu By a Wayne

BRA 0768

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/752

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 04843 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact Ms Belia Cortez Star Route Box 90
Brownsville Texas 78521

4. Generator's Phone 512)831-4501

A. State Manifest Document Number: 0000484
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: HO 261
H. Facility's Phone: 713 675-6101

5. Transporter 1 Company Name: WPI Transportation
6. US EPA ID Number: TXD050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill
11031 Old Beaumont Highway
Houston Texas 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid Asbestos, N. O. S. ORM E NA 9188	1	B	19160	P	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Firable asbestos

K. Handling Codes for Wastes Listed Above: BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: WEar gloves glasses, and other proctective equipment as necessary. For help in handling chemical emergencies in - volving spills or exposure, call Union Carbide at 512 831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 07 Day 09 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Johnny R Guerra | Signature: Johnny R Guerra | Date: Month 07 Day 09 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT #261
JUL 10 1992
25Y

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

Printed/Typed Name: J HENDERSON | Signature: J Henderson | Date: Month 07 Day 10 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0769

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0770

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039; expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD008114092 | Manifest Document No. 04843 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address: Union Carbide, Contact Ms Belia Cortez, Star Route Box 90, Brownsville Texas 78521

4. Generator's Phone 512) 831-4501

A. State Manifest Document Number: 000004843

B. State Generator's ID: 3108

5. Transporter 1 Company Name: WPI Transportation | 6. US EPA ID Number: TXD050641463

C. State Transporter's ID: 40369

D. Transporter's Phone: 713 452-1501

7. Transporter 2 Company Name | 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address: BFI McCarty Road Landfill, 11031 Old Beaumont Highway, Houston Texas 77078 | 10. US EPA ID Number

G. State Facility's ID: HO 261

H. Facility's Phone: 713 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazadous Substance Solid Asbestos, N. O. S. ORM E NA 9188	1	B	19160	P	179350
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Firable asbestos

K. Handling Codes for Wastes Listed Above: BFD 4TX/2A4/930284/81571

15. Special Handling Instructions and Additional Information: WEar gloves glasses, and other proctective equipment as necessary. For help in handling chemical emergencies involving spills or exposure, call Union Carbide at 512 831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 0 7 | Day 0 9 | Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: Johnny R Cuevas | Signature: Johnny R Cuevas | Month 0 7 | Day 0 9 | Year 9 2 | Date

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name | Signature | Month | Day | Year | Date

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name | Signature | Month | Day | Year | Date

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0771

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No 8237

TRUCK C808 TLR 16625 4-25
TRUCK LINE WPT
CUSTOMER Union Carbide
CARGO

8:20 AM 07 09 92
40580 lb
9:56 AM 07 09 92
59740 lb
40580 lb TR
19160 lb NET

- ☐ $3.00 EMPTY ONLY
- ☑ $5.00 UP TO 65,000 GROSS
- ☐ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Pd

PUBLIC WEIGHER STATE OF TEXAS

Truck Driver

Certified Weigher

BRA 0772

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST [illegible]

SERVICE ORDER NUMBER C221832

CUSTOMER: Union Carbide P.O. # RELEASE #

DATE: 7-9-92 TRAILER # 627 TRUCK # 608 PICKUP #

OPERATOR OR DRIVER J. Ray R. Cantu LABOR

JOB LOCATION Brownsville DESTINATION Hwy 77N

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (V) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD	7-9-92	5:00	AM PM
TIME ARRIVED	7-9-92	8:00	AM PM
LOADING BEGAN	7-9-92	9:05	AM PM
LOADING COMPLETED	7-9-92	9:40	AM PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Pickup Box # 23-41

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE

TRAILER/BIN PU DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE

ENDING MILEAGE

BEGINNING MILEAGE

CUSTOMER SIGNATURE CONFIRMS TIME IN PLANT

TOTAL TRIP MILES

BRA 0773

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-9

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TX0 08114092 — Manifest Document No. 04844

2. Page 1 of — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
union Carbide
Contact Ms. Belia Cortez Star Route Box 90
Brownsville Tx 78521

4. Generator's Phone (512 831-4501

A. State Manifest Document Number: 00004844

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI Transportation
6. US EPA ID Number: TXD050641463

C. State Transporter's ID: 40369

D. Transporter's Phone: 713 452-1504

7. Transporter 2 Company Name
8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11013 Old Beaumont Highway
Houston Texas 77078
10. US EPA ID Number

G. State Facility's ID: BO 261

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid Asbestos, N. O. S. ORM E NA 9188	1	B	21420	P	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable asbestos

K. Handling Codes for Wastes Listed Above: BFI# TX/274/930223/81571

15. Special Handling Instructions and Additional Information: Wear gloves glasses and other proctective equipment as necessary. For help handling chemical emergencies in - volving spills or exposure call Union Carbide at 512 831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 0 7 Day 0 9 Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Billy C. GUERRA — Signature: Billy C. Guerra — Date: Month 0 7 Day 0 9 Year 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: J HENDERSON — Signature — Date: Month 7 Day 10 Year 92

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT #261
JUL 10 1992
11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

25Y

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0774

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0775

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087
Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved, OMB No. 2050-0039, expires 09-30-81

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TX0 08114092 | Manifest Document No. 04844 | 2. Page 1 of | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address: union Carbide
Contact Ms. Belia Cortez Star Route Box 90
Brownsville Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 000004844

B. State Generator's ID:

5. Transporter 1 Company Name: WPI Transportation | 6. US EPA ID Number: TXD050661463

C. State Transporter's ID:

7. Transporter 2 Company Name | 8. US EPA ID Number

D. Transporter's Phone:

E. State Transporter's ID:

F. Transporter's Phone:

9. Designated Facility Name and Site Address: BFI McCarty Road Landfill
11013 Old Beaumont Highway
Houston Texas 77078 | 10. US EPA ID Number

G. State Facility's ID: 80261

H. Facility's Phone: 713 675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid Asbestos, N. O. S. ORM E NA 9188	1	B	21420	P	
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable asbestos

K. Handling Codes for Wastes Listed Above: BFI TX/274/930223/81571

15. Special Handling Instructions and Additional Information: Wear gloves glasses and other proctective equipment as necessayy. For help handling chemical emergencies in - volving spills or exposure call Union Carbide at 512 831-4501 day or night

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 0 7 | Day 0 9 | Year 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Billy C Guerra | Signature: Billy C Guerra | Date: Month 0 7 | Day 0 9 | Year 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month | Day | Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name | Signature | Date: Month | Day | Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0776

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649 No. 8235

TRUCK C824 TL 2539 / 2559
TRUCK LINE WDI
CUSTOMER Union Carbide
CARGO

7:47 AM 07 09 92
42320 lb

9:55 AM 07 09 92
63740 lb
42320 lb TR
21420 lb NET

Pd

- ☐ $3.00 EMPTY ONLY
- ☒ $5.00 UP TO 65,000 GROSS
- ☐ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

Truck Driver

PUBLIC WEIGHER COUNTY OF CAMERON STATE

Certified Weigher

BRA 0777

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST [illegible]

SERVICE ORDER NUMBER 022178

CUSTOMER [illegible] P.O. # RELEASE #

DATE 07/09/79 TRAILER # 600 TRUCK # 12 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: Brownsville, Texas DESTINATION Laredo, Texas (BFI)

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	07 07 79	5:00	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	07 07 79	9:00	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	07 09 79	9:00	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	07 09 79	9:30	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
07 09 79	Texas	77-511-37-59	
			414853

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

½" R.-TR.P

TRAILER/BIN DROPPED # DATE/TIME

TRAILER/BIN PU 2559 DATE/TIME 07 09 79

SHIPPER'S SIGNATURE [illegible]

CONSIGNEE'S SIGNATURE [illegible]

DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE

BEGINNING MILEAGE 414853

TOTAL TRIP MILES

CUSTOMER SIGNATURE [illegible]
CONFIRMS TIME IN PLANT

BRA 0778

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: TXD 008114092 | Manifest Document No.: 04845 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact Ms. Belia Cortex Union Carbide
Star Route Box 90
Brownsville Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 00004845
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: HO-261
H. Facility's Phone: 713 675-6101

5. Transporter 1 Company Name: WPI Transportation
6. US EPA ID Number: TXD 050641463
7. Transporter 2 Company Name:
8. US EPA ID Number:
9. Designated Facility Name and Site Address: BFI McCarty Road Landfill
11031 Old Beaumont Highway
Houston Texas 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Substance Asbestos, N. O. S. NA 9188 ORM-E	1	B	24940	P	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable asbestos
K. Handling Codes for Wastes Listed Above: BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves glasses and other procetective equipment as necessary/ For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512 831-4501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 07 Day 10 Year 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: FRANK HOLUBECIC | Signature: Frank Holubecic | Date: Month 07 Day 10 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name: | Signature: McCARTY RD. LANDFILL TDH PERMIT #261 | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space: JUL 11 1992 | 25YDS

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
11013 OLD BEAUMONT HWY. HOUSTON, TEXAS 77078 713-675-6101
Printed/Typed Name: | Signature: | Date: Month 7 Day 1 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0779

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

* (4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0780

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD 008114092 — Manifest Document No. 04845 — 2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Contact Ms. Belia Cortez Union Carbide
Star Route Box 90
Brownsville Tx 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: 000001845

B. State Generator's ID: 31106

5. Transporter 1 Company Name: WPI Transportation — 6. US EPA ID Number: TXD 050641463

C. State Transporter's ID: 40369

D. Transporter's Phone: 713 452 1500

7. Transporter 2 Company Name — 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11031 Old Beaumont Highway
Houston Texas 77078

10. US EPA ID Number

G. State Facility's ID: HO 261

H. Facility's Phone: 713 675-6001

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
	a. RQ Hazardous Substance Asbestos, N. O. S. NA 9188 ORM-E	1	B	24940	P	1793
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable asbestos

K. Handling Codes for Wastes Listed Above: BFI TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves glasses and other protective equipment as necessary/ For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512 831-4501 day or night

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR — Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month 07 Day 10 Year 92

TRANSPORTER
17. Transporter 1 Acknowledgement of Receipt of Materials — Printed/Typed Name: FRANK Holubecic — Signature: Frank Holubecic — Date: Month 07 Day 10 Year 92
18. Transporter 2 Acknowledgement of Receipt of Materials — Printed/Typed Name — Signature — Date: Month Day Year

FACILITY
19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0781

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

149177

Tr 1923 Tlr _____

Truck Line W. P. I.

Name Union Carbide

Cargo Asbestos dust

Carl H. Hilton
Cert. Weigher

(empty weights included)

- ✓ @ $ 5.00 up to 65,000
- _____ @ $ 6.00 65,020 - 85,000
- _____ @ $ 7.00 85,020 - 105,000
- _____ @ $ 8.50 105,020 - 125,000
- _____ @ $ 11.00 125,020 - 145,000
- _____ @ $ 25.00 145,020 and up
- _____ @ $ 3.00 empty only

5.00 Pd.

7:04 A.M. 10 JUL 92 0 ID — 39820 G LB
8:36 A.M. 10 JUL 92 0 ID — 64760 G LB, 39820 T LB, 24940 N LB

PUBLIC WEIGHER PREC. 1 CAMERON COUNTY, TEXAS

Truck Driver Jack Holmes

BRA 0782

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 000048445

SERVICE ORDER NUMBER 25064

CUSTOMER: [illegible] P.O. # RELEASE #

DATE: 7-10-92 TRAILER # 602 TRUCK # 162 PICKUP #

OPERATOR OR DRIVER Frank Holbrook LABOR

JOB LOCATION: Brownsville TX DESTINATION Houston TX

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM ( ) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK (X) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING

	DATE	TIME	CIRCLE ONE
LEAVE YARD	7-9-92		AM PM
TIME ARRIVED	7-10-92	7:45	AM PM
LOADING BEGAN	7-10-92	7:10	AM PM
LOADING COMPLETED	7-10-92		AM PM

UNLOADING

	DATE	TIME	CIRCLE ONE
TIME ARRIVED			AM PM
UNLOAD BEGAN			AM PM
UNLOAD COMPLETE			AM PM
ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
7-10-92	TX	I-69-281-I-15-69-(Hou)	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: LOAD NOT WEIGHED

TRAILER/BIN DROPPED # DATE/TIME

TRAILER/BIN PU # 602 166-35 DATE/TIME 7-10-92 7:45 AM

SHIPPER'S SIGNATURE Billie Cotts Byd. Wages

CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Frank Holbrook

ENDING MILEAGE

BEGINNING MILEAGE 615566

TOTAL TRIP MILES

CUSTOMER SIGNATURE Billie Cotts Byd. Wages
CONFIRMS TIME IN PLANT

BRA 0783

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No.: TXD 008114092 | Manifest Document No.: 04846 | 2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact Ms Belia Cortez Star Route Box 90
Brownsville Tx 78521

4. Generator's Phone ( )

A. State Manifest Document Number: 0004846
B. State Generator's ID: 31108
C. State Transporter's ID: 40369
D. Transporter's Phone: 713 452-1504
E. State Transporter's ID:
F. Transporter's Phone:
G. State Facility's ID: HO261
H. Facility's Phone: 713-675-6101

5. Transporter 1 Company Name: WPI Transportation
6. US EPA ID Number: TXD050641463

7. Transporter 2 Company Name:
8. US EPA ID Number:

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11031 Old Beaumont Highway
Houston Texas 77078
10. US EPA ID Number:

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid Asbestos, N.O.S. NA 9188 ORM-E	1	B	11 980	P	179390
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above: A. Friable asbestos

K. Handling Codes for Wastes Listed Above: BFI #TX/274/930224/81571

15. Special Handling Instructions and Additional Information: Wear gloves glasses and other proctective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512 8314501 day or night

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month Day Year: 07 10 92

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: L. WEDDER | Signature | Date: Month Day Year: 07 10 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

BROWNING-FERRIS, INC.
MCCARTY RD. LANDFILL
TDH PERMIT #261

FACILITY

19. Discrepancy Indication Space

JUL 11 1992

25YDS

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: M Easley | Signature | Date: Month Day Year: 7 1 92

11013 OLD BEAUMONT HWY.
HOUSTON, TEXAS 77078
713-675-6101

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0784

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS)

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids Only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

* (12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the TSD Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type or Print Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do <u>not</u> send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0785

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. TXD 008114092 — Manifest Document No. 04846

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
Union Carbide
Contact Ms Belia Cortez Star Route Box 90
Brownsville Tx 78521

4. Generator's Phone ( )

A. State Manifest Document Number: 00004846

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI Transportation — 6. US EPA ID Number: TXD050641463

C. State Transporter's ID: 40369

D. Transporter's Phone: 71[illegible] 452-[illegible]

7. Transporter 2 Company Name — 8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI McCarty Road Landfill
11031 Old Beaumont Highway
Houston Texas 77078

10. US EPA ID Number

G. State Facility's ID: HO261

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ Hazardous Substance Solid Asbestos, N.O.S. NA 9188 ORM-E	1	B	11 980	P	179350
	b. Debris					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. Friable asbestos

K. Handling Codes for Wastes Listed Above
BFL #TX/274/930224/8157

15. Special Handling Instructions and Additional Information: Wear gloves glasses and other proctective equipment as necessary. For help in handling chemical emergencies involving spills or exposure call Union Carbide at 512 8314501 day or night

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature: Belia Cortez — Month Day Year: 07 11 092

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name: C. WEBBER — Signature: [signature] — Date: Month Day Year: 07 11 92

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0786

PORT OF BROWNSVILLE PUBLIC SCALE, INC.

(7 A.M. to 6 P.M. - MONDAY THRU FRIDAY)

(512) 831-9223
AFTER HOURS:
JULIO 546-5289
CARL 425-1801

BROWNSVILLE, TEXAS
MAILING ADDRESS:
1801 FLAMINGO LANE
HARLINGEN, TEXAS 78550

149176

Tr 4918 Tlr _____

Truck Line W. P1

Name Union Carbide

Cargo Asbestos dehi

Carl H. N. Helm
Cert. Weigher

(empty weights included)

✓ @ $ 5.00 up to 65,000 — 65.00

✓ @ $ 6.00 65,020 - 85,000

_____ @ $ 7.00 85,020 - 105,000

_____ @ $ 8.50 105,020 - 125,000

_____ @ $ 11.00 125,020 - 145,000

_____ @ $ 25.00 145,020 and up

_____ @ $ 3.00 empty only

PUBLIC WEIGHMASTER CAMERON COUNTY, TEXAS

7:02 A.M. 10 JUL 92 0 ID — 44760 G LB

9:41 A.M. 10 JUL 92 0 ID — 56740 G LB
44760 T LB
11980 N LB

Truck Driver Darrell

BRA 0787

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/771

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 00004[illegible]

SERVICE ORDER NUMBER 250013

CUSTOMER: UNION CARBIDE P.O. # RELEASE #

DATE: 7-10-92 TRAILER # 12191 TRUCK # 1911 PICKUP #

OPERATOR OR DRIVER [illegible] LABOR

JOB LOCATION: BROWNSVILLE TX DESTINATION [illegible] TX

( ) VACTOR ( ) CYCLONE ( ) 70 BBL VACUUM (X) 130 BBL VACUUM

(X) END DUMP ( ) DROP DECK (✓) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

LOADING	DATE	TIME	CIRCLE ONE	UNLOADING	DATE	TIME	CIRCLE ONE
LEAVE YARD	7-9-92	[illegible]	AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	7-10-92	7:[illegible]	AM PM	UNLOAD BEGAN			AM PM
LOADING BEGAN	7-10-92	7:30	AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	7-10-92	10:00	AM PM	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT ____ am ( ) pm IN ____ am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)
7-11-92	TX	[illegible]	

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS:

TRAILER/BIN DROPPED # 25-178

TRAILER/BIN PU 25-39

DATE/TIME 7-11-92 1:30PM

DATE/TIME

SHIPPER'S SIGNATURE [illegible]

CONSIGNEE'S SIGNATURE [illegible]

DRIVER'S SIGNATURE [illegible]

ENDING MILEAGE

BEGINNING MILEAGE 113992

TOTAL TRIP MILES

CUSTOMER SIGNATURE [illegible]
CONFIRMS TIME IN PLANT

BRA 0788

ATER COMMISSION
13087, Capitol Station
, Texas 78711-3087

print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T.X.D.0.0.8.1.1.4.0.9.2 | Manifest Document No. 5.7.6.5.8

2. Page 1 of 1 | Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
CONTACT: MS. BELIA CORTEZ
UNION CARBIDE
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: No 00357658

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION

6. US EPA ID Number: T X D 0 5 0 6 3 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: 713-452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY RD. LANDFILL
11013 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: H0261

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ HAZARDOUS SUBSTANCE SOLID/ASBESTOS, N.O.SS, ORM-E, NA 9188	1	B	8160	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI# TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT NECESSARY, FOR HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE, CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT.

16. **GENERATOR'S CERTIFICATION:** I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ | Signature: Belia Cortez | Month 0.7 Day 3.1 Year 9.2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Johnny R. Cisneros | Signature: Johny R. Cisneros | Date: Month 7 Day 31 Year 92

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name | Signature | Date: Month Day Year

FACILITY

19. Discrepancy Indication Space
30 YDS

BROWNING-FERRIS, INC.
McCARTY RD. LANDFILL
TDH PERMIT #261

AUG 5 1992

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name: K Parsons | Signature: K Parsons | 11013 OLD BEAUMONT HWY. HOUSTON, TEXAS 77078 | 713-675-6101 | Date: Month 8 Day 5 Year 92

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0789

When using the Uniform Waste Manifest for rail or water (bulk shipment) or international shipments refer to the applicable TWC regulations.

REPORT SPILLS AND/OR DISCHARGES TO THE TEXAS SPILL RESPONSE CENTER AT 512/463-7727 (24 HOURS).

INSTRUCTIONS TO GENERATOR (Please Type or Print Clearly)

(1) Enter the Generator's U.S. EPA twelve digit identification number and the unique five digit number assigned to this manifest by the generator, if you are shipping hazardous waste.

(2) Enter the total number of pages used to complete this manifest.

(3) Enter the company name and mailing address.

(4) Provide a phone number where an authorized agent of your firm may be reached in the event of an emergency.

(5) Enter the company name of the first transporter and their U.S. EPA ID Number.

(6) If applicable, enter the company name of the second transporter and their U.S. EPA ID Number. If more than two transporters are used, enter each additional transporter's information on the Continuation Sheet (EPA form 8700-22A).

(7) Enter the company name, site address, and U.S. EPA ID Number of the facility designated to receive the waste listed on this manifest.

(8) **COMPLETE ALL STATE OF TEXAS INFORMATION A. THROUGH H. IN THE SHADED AREAS.**

(9) Complete the waste description table as follows:

(A) ITEM 11A - When shipping an EPA/DOT regulated hazardous waste or material in conjunction with solely state regulated waste enter an "x" in the HM box before each EPA/DOT regulated waste/material description.

(B) ITEM 11 - Enter the U.S. DOT Proper Shipping Name, Hazard Class, and ID Number (UN/NA) for each waste identified. If it is a Class I nonhazardous waste use the Texas Waste Code description.

(C) ITEM 12 - Enter the number of containers for each waste and the appropriate abbreviation for type located in Subchapter A of the TWC Industrial Solid Waste Rules.

(D) ITEM 13 - Enter the total quantity of waste described on each line.

(E) ITEM 14 - Enter the appropriate letter from the table below for the unit of measure.

G = Gallons (liquids only)	Y = Cubic Yards	M = Metric Tons (1000 kg.)
P = Pounds	L = Liter (Liquids only)	N = Cubic Meters
T = Tons (2000 lbs.)	K = Kilograms	

(F) ITEM I - Enter the appropriate TWC State Waste Code for each waste you are shipping.

(10) The Generator must read, sign (by hand), and date the certification statement. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water or air) inserted in the space below. In signing the waste minimization certification statement, those generators shipping hazardous waste who have not been exempted by statute or regulation from the duty to make a waste minimization certification are also certifying that they have complied with the waste minimization requirements.

(11) The manifest must be signed and dated by the first transporter in the presence of the Generator. If more than one transporter is to be used, the Generator must provide additional copies for their use.

*(12) Generator retains green copy, sending remaining copies with the driver.

INSTRUCTIONS FOR THE TRANSPORTER (Please Type or Print clearly)

(1) As driver of the transport vehicle, you are responsible for ensuring that all waste received by you arrives at the specified destination.

(2) Sign and date the space provided, certifying the waste amounts in **PART I** were received for transport. **NOTE:** If you are unable to carry out the delivery of the shipment as specified, dial the emergency phone numbers given in **PART I** notifying the **GENERATOR.**

(3) Upon delivery of the shipment, the **TSD** Facility Owner/Operator is to sign for the shipment in your presence and fill in "date received".

(4) Separate the yellow copy and retain for your records. Leave the remaining copies with the **TSD** Facility Owner/Operator.

INSTRUCTIONS TO TREATMENT, STORAGE AND DISPOSAL (TSD) FACILITY OWNER/OPERATOR (Please Type onPrint Clearly)

(1) The authorized representative of the designated (or alternate) facility's owner or operator must note in **ITEM 19** any significant discrepancy between the waste described on the manifest and the waste actually received at the facility.

(2) Enter date received and sign in the presence of the driver declaring receipt of the wastes and verifying the quantities in the table in **PART I.**

(3) Retain the pink copy for your records and return the completed original (white) copy to the **GENERATOR.**

* U.S. EPA and TWC regulations require that copies of this Uniform Hazardous Waste Manifest be retained for a period of three (3) years in your company records. Do not send to TWC unless otherwise notified by these departments.

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street SW., Washington, DC 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, DC 20503.

BRA 0790

TEXAS WATER COMMISSION
P.O. Box 13087, Capitol Station
Austin, Texas 78711-3087

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form approved. OMB No. 2050-0039, expires 09-30-91

UNIFORM HAZARDOUS WASTE MANIFEST

1. Generator's US EPA ID No. T X D 0 0 8 1 1 4 0 9 2 — Manifest Document No. 5 7 6 5 8

2. Page 1 of 1 — Information in the shaded areas is not required by Federal law.

3. Generator's Name and Mailing Address
CONTACT: MS. BELIA CORTEZ
UNION CARBIDE
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78521

4. Generator's Phone (512) 831-4501

A. State Manifest Document Number: NO. 00357658

B. State Generator's ID: 31108

5. Transporter 1 Company Name: WPI TRANSPORTATION

6. US EPA ID Number: T X D 0 5 0 6 3 1 4 6 3

C. State Transporter's ID: 40369

D. Transporter's Phone: 713-452-1504

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

F. Transporter's Phone

9. Designated Facility Name and Site Address
BFI MCCARTY RD. LANDFILL
11013 OLD BEAUMONT HWY
HOUSTON, TEXAS 77078

10. US EPA ID Number

G. State Facility's ID: HO261

H. Facility's Phone: 713-675-6101

11A. HM	11. US DOT Description (including Proper Shipping Name, Hazard Class, and ID Number)	12. Containers No.	Type	13. Total Quantity	14. Unit Wt/Vol	Waste No.
	a. RQ HAZARDOUS SUBSTANCE SOLID/ASBESTOS, N.O.SS, ORM-E, NA 9188	1	B	8160	P	179390
	b.					
	c.					
	d.					

J. Additional Descriptions for Materials Listed Above
A. FRIABLE ASBESTOS

K. Handling Codes for Wastes Listed Above
BFI# TX/274/930224/81571

15. Special Handling Instructions and Additional Information
WEAR GLOVES, GLASSES AND OTHER PROTECTIVE EQUIPMENT NECESSARY, FOR HANDLING CHEMICAL EMERGENCIES INVOLVING SPILLS OR EXPOSURE, CALL UNION CARBIDE AT (512) 831-4501 DAY OR NIGHT.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations, including applicable state regulations.
If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

GENERATOR

Printed/Typed Name: BELIA CORTEZ — Signature — Month Day Year: 0 7 3 1 9 2

TRANSPORTER

17. Transporter 1 Acknowledgement of Receipt of Materials
Printed/Typed Name: Johnny R Cisneros — Signature — Date: Month Day Year: 0 7 3 1 9 2

18. Transporter 2 Acknowledgement of Receipt of Materials
Printed/Typed Name — Signature — Date: Month Day Year

FACILITY

19. Discrepancy Indication Space

20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.
Printed/Typed Name — Signature — Date: Month Day Year

TWC-0311 (Rev. 01/01/89) White - original Pink-TSD Facility Yellow-Transporter Green-Generator's first copy

BRA 0791

QUALITY WEIGHING SERVICES, INC.

8204 E. 14th. Street - Brownsville, Texas 78521
(Located at Port of Brownsville)
Phone: 512/831-8253 Fax: 512/831-8649

No. 08625

TRUCK R46303 TLR (607) 194867
TRUCK LINE WPI
CUSTOMER Union Carbide
CARGO

1:28 PM 07 31 92
~~1:28 PM 07 31 92~~
33460 lb
2:31 PM 07 31 92
41620 lb
33460 lb TR
8160 lb NET

- ☐ $3.00 EMPTY ONLY
- ☑ $5.00 UP TO 65,000 GROSS
- ☐ $6.00 65,020 TO 85,000 GROSS
- ☐ $7.00 85,020 TO 105,000 GROSS
- ☐ $8.50 105,020 TO 125,000 GROSS
- ☐ $10.00 125,020 TO 145,000 GROSS
- ☐ $25.00 145,020 AND UP

PUBLIC WEIGHER STATE OF TEXAS

X _____
Truck Driver

_____
Certified Weigher

BRA 0792

WPI Transportation, Inc.

P.O. Box 909
Channelview, Texas 77530-0909
(713) 452-1504

MANIFEST 2075116

SERVICE ORDER NUMBER 252181

CUSTOMER: Union Carbide P.O.# RELEASE #

DATE: 7-31-92 TRAILER # 609 TRUCK # 824 PICKUP #

OPERATOR OR DRIVER Johnny Gomez LABOR

JOB LOCATION: Brownsville TX DESTINATION Houston TX - BFI

(*) VACTOR (*) CYCLONE ( ) 70 BBL VACUUM (*) 130 BBL VACUUM

( ) END DUMP ( ) DROP DECK ( ) ROLL OFF ( ) VAN / FLAT

TIME SCHEDULE

	LOADING DATE	LOADING TIME	CIRCLE ONE		UNLOADING DATE	UNLOADING TIME	CIRCLE ONE
LEAVE YARD			AM PM	TIME ARRIVED			AM PM
TIME ARRIVED	7-31-92	1:40	AM (PM)	UNLOAD BEGAN			AM PM
LOADING BEGAN			AM PM	UNLOAD COMPLETE			AM PM
LOADING COMPLETED	7-31-92	2:40	AM (PM)	ARRIVED YARD			AM PM

LUNCH OR NON-WORKING: OUT am ( ) pm IN am ( ) pm

DATE	STATE NAME	ROUTES TRAVELED	ODOMETER @ STATE LINE (E OR L)

WAS JOB COMPLETED SATISFACTORILY?

GENERATOR APPROVED: RECEIVER APPROVED:

REMARKS: Pickup Boi 25-28 From Union Carbide to B.F.T.

TRAILER/BIN DROPPED # DATE/TIME SHIPPER'S SIGNATURE Brian Lantz

TRAILER/BIN PU DATE/TIME CONSIGNEE'S SIGNATURE

DRIVER'S SIGNATURE Johnny Gomez

ENDING MILEAGE

BEGINNING MILEAGE 95111 96

TOTAL TRIP MILES

CUSTOMER SIGNATURE Brian Lantz CONFIRMS TIME IN PLANT

BRA 0793

BRA 0794

MEMO AVOID ORAL INSTRUCTIONS DATE_____ 198__

TO_____

disposal 2B.10 —

Try → McQuity —

Tex Sinton

✚ DO IT THE SAFE WAY ✚ SIGNED_____ 46 = 8 yd

72 = 12 "

SK80-1878-3

BRA 0795

Union Carbide Chemicals and Plastics Company Inc.
Health, Safety and Environmental Affairs - P-2
39 Old Ridgebury Road Danbury, CT 06817-0001

Memo

To: *UCC&P Division Environmental Managers*
UCC&P Component Environmental Coordinators
CC: *SWIG*
From: *L.S. Magelssen*
Date: *March 12, 1992*
Re: ***DOT Waste Descriptions***

Please share the attached with people in your organization who fill out waste manifests.

Scott Magelssen
L.S. Magelssen

LSM/dd
Attachment

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazard... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 780 of 785 **asbestosclaims.law/library/16757/780**

UNION CARBIDE CHEMICALS AND PLASTICS COMPANY INC. 39 Old Ridgebury Road
Transportation Safety & Regulations (C-1) Danbury, CT 06817-0001

To: J. Nesmith

Copies: See Attached

From: W. G. Kahler II

Date: March 10, 1992

Subject: Describing Non-U.S. DOT/U.S. EPA Regulated Wastes on Uniform Hazardous Waste Manifest

File: R.1.2.7.6 (D)

This responds to your request for comments regarding the describing of non-U.S. DOT/U.S. EPA regulated wastes on the Uniform Hazardous Waste Manifest.

I have reviewed TS&R files for the U.S. Department of Transportation's (DOT's) position on this matter. While I don't have copies of DOT's formal interpretations, I do have several items appearing in an industry newsletter (*Hazardous Materials Transportation*) from 1985 to 1991 which are supposedly based on written DOT interpretations. Copies of the actual interpretations should be able to be obtained from DOT if necessary.

The newsletter items make it clear that DOT has no problem with someone describing a non-DOT/EPA regulated waste on the hazardous waste manifest provided the description does not include a DOT hazard class and four-digit identification number. According to the newsletter items, DOT takes the position that waste materials not hazardous under DOT's defining criteria nor subject to EPA manifest requirements are not hazardous wastes as defined by DOT and may not be described using a DOT basic description (i.e., proper shipping name, hazard class and four-digit identification number) on a shipping paper thereby indicating that it is a hazardous material. According to the newsletter items, DOT agrees that the manifest can be used for non-DOT/EPA regulated wastes but such wastes should be described using descriptions not containing DOT hazard classes and identification numbers. Such descriptions can even include the word "waste."

The newsletter items do not address placement of the non-DOT description on the manifest but I see no reason not to include it in Block 11 (US DOT Description) of the Uniform Hazardous Waste Manifest.

I am including HAMTRAC Members and DOT Site Coordinators on the distribution of this communication for their information.

If you or others receiving this correspondence have any questions regarding the previous comments, please give me a call (UNICOM 421-7121).

Union Carbide trial exhibit UC-1672: Union Carbide Brownsville Asbestos Waste Shipping Tickets (1979), Hazard... Published by AsbestosClaims.Law
ACL Doc 16757 · Page 781 of 785 asbestosclaims.law/library/16757/781

Date : START 3-[illegible]-82

	DRIVER	Items	TRAILER NO.	TIME IN	TIME OUT	TIME IN	TIME OUT	IN	OUT	TOTAL
1	[illegible]		00 004424 29[illegible]1	8[illegible]	3-5-82					
2	ARR[illegible]		00004995 291817	8[illegible]	3-5-82		25[illegible]			
3	COX		00004803 288208	5[illegible]	5PM 3-[illegible]		224[illegible]			
4	"		00004804 291[illegible]	[illegible]	5PM 3-[illegible]		136[illegible]		5859 BAGS	4 Trailers
5	"	S	291821	[illegible]	11am 3-16		6709 5859			
6	"	B	291[illegible]9	[illegible]	11am 3-16		1501 Bags			
7	"	S	288808	8[illegible] 3-16	11am 3-18		1409 Bags			
8	"	B	291610	8[illegible] 3-16	11AM 3-18		1870 Bags			
9	"	B	291849 #1	8[illegible] 3-18	12[illegible] 3-18	LEFT IN PARKING LOT	1785 Bags			
10	"	S	291821 #2	8[illegible] 3-19	2[illegible] 3-18	"	1575 Bags			
11	"	B	291827	10[illegible] 3-19	11[illegible] 3-23		1760 Bags			
12	"	S	291835	10[illegible] 3-19	11am 3-23		2300 Bags			
13	COX	B	291849	8[illegible] 3-23	9[illegible] 3-25		1873 Bags			
14	"	S	291821	8[illegible] 3-23	9[illegible] 3-25		1800 Bags			
15	"	S	291835	8[illegible] 3-25	11[illegible] 3-27		1800 Bags			
16	"	B	2918[illegible]27	8[illegible] 325	10[illegible] 3-27		2135 Bags			
17	"	S	291821	8[illegible] 3-27	9[illegible] - 3-30		2075 Bags			
18	[illegible]	B	291849	8[illegible] 327	9[illegible] 3-30		2080 Bags			
19	IEC's WORK	S	291835	8[illegible] 3-30	10[illegible] 4-1		1950 Bags	TOTAL	31760 BAGS	
20	"	B	291827	8[illegible] 3-30	9[illegible] 4-1		2380 Bags		IEC — 300 Bags MINUS	
21	"	B	291849	8[illegible] 4-1	9[illegible] 4-3		2275 Bags		300 Bags NO TRC	
22	"	S	2918[illegible]21	8[illegible] 4-1	9[illegible] 4-3		2350 Bags		FIRST TRAILER CAME FROM MWS	
23	"	B	291827	8[illegible] 4-3	9[illegible] 4-6		2200 Bags		WORK.	
24	"	S	291835	8[illegible] 4-3	9[illegible] 4-6		2200 Bags			
25	"	S	291821	8[illegible] 4-6	10[illegible] 4-8		2300 Bags			
26	"	B	291849	8[illegible] 4-6	10[illegible] 4-8		2450 Bags		32,060	MWS
							2400 Bags		18255	IEC
						(50)	315 TOTAL Bags			

BRA 0798

DRAFT

Instructions for Completing the Uniform Hazardous Waste Manifest (Texas Version, TWC Form 0311) for shipments of municipal asbestos (friabl containing waste

Form Blank Number/Letter	Required Information to be used
1	no entry required or not applicable because asbestos is not identified as a hazardous waste by EPA under RCRA
2	to be used if shipment (single) requires mutiple page to complete--for asbestos shipments there should not be any need for multiple manifest pages (more than 4 items)
3,4,5,7	self explanatory
6,8,10	not required (see 1 above)
11A	leave blank
11	The following information is mandatory for shipments friable asbestos:
	Hazardous substance, solid N.O.S. (asbestos), ORM-E, NA 9188, RQ = 1 pound
	for nonfriable asbestos use the following entry:
	- waste which contains non-friable asbestos
12	Enter the number of containers and the container code type (see attached sheet)
13	enter total quantity with decimal as needed
14	Enter code for weight or volume (see code sheet)
15	Enter the following:
	Disposal must be in accordance with TDH MSWMR 25 TAC 325.136(b)(6) or other handling plan approved by TDH in writing
16	mark out second part of certification because asbestc is not a hazardous waste (starting with Unless I am.
17,18, 20	self explanatory
19	Disposal site must note any discrepancies with mater received as compared with items listed in 11a-d
A	information already entered
B	State Generator's ID number must be obtained from Tx Department of Health unless generator already has a state solid waste registration number due to hazar waste program requirements
C	Not required by TDH
D	self explanatory
E	not required by TDH
F	self explanatory
G	Enter Disposal site TDH (Tx Dept of Health) permit n prefixed with letter "H"
H	self explanatory
I	Texas Waste Code for asbestos--see attached sheet

BRA 0799

manifest instructions page 2


J — Use this space to describe the shipment: for example ceiling tile, pipe insulation, sprayed on insultaion, etc

K — enter "D 81"

Texas Waste Codes for Municipal Asbestos Containing Waste

asbestos insulation	179390	
other friable asbestos	170750	(dust from brake shoes, etc)
material contaminated with asbestos	179370	to be used when friable asbestos has been spilled and has contaminate other material such as dirt lumber e
asbestos encapsulated	178970	asbestos which was encapsulated ther removed
abestos roofing material	172320	when friable
	272320	when nonfriable
asbestos pipe scrape	170870	when friable
	270870	when nonfriable
asbestos containing floor tiles	172270	when friable
	272270	when nonfriable
asbestos waste nonfriable	276030	use for siding, transite sheets etc if not listed above

BRA 0800



BRA 0801

Published by AsbestosClaims.Law
asbestosclaims.law/library/16757/785