1991-09-20 10:03
1991-09-13 11:00

8:30

PLAINTIFF'S EXHIBIT
UC-1679

Page 1 F.M.C 9-4-91

1. Some of contractors doesn't isolate work area's.

2. Contractor doesn't wash bags out of enclosure.

3. Some of workers are going into clean Rm. with contaminated coveralls, when working inside enclosure.

4. Some of workers are removing there respiratars inside enclosure.

5. Some of workers are drinking water in dirty Rm, water cooler is set in shower in dirty Rm, also in bag trailor.

6. Respirators are not properly stored.

7. Some of ~~crew~~ workers wear street shoes & clothing when working inside enclosure.

8. Neg Air systems are not properly seal after clearances.

9. Some times negative pressure is not maintained.

BRA 1099

Published by AsbestosClaims.Law
asbestosclaims.law/library/16764/1

9. Some times, Negative pressure isn't maintained.

1991-09-20 10:10 602 492 9094 MIDWEST STEEL CO INC PHX AZ 002 P03

Page 2

10. After glove bagging, contractor doesn't encapsulate.

11. Sometimes HEPA vacuums are not used when glove bagging.

12. Open wet removal.

13. Rarely wash metal tie-rod glass pipes.

before:

14. Some of workers weren't taking a shower after working inside enclosure.

15. Leave warning sign & Tape up after clearances.

BRA 1100

Published by AsbestosClaims.Law
asbestosclaims.law/library/16764/2