PLAINTIFF'S EXHIBIT

UC-1742

ASBESTOS HANDLING

INSPECTION AND AUDIT

UNIT/AREA/BLDG. RECOVERY - 539 DATE 3/25/81

INSPECTION BY MARIO GUTIERREZ

	YES	NO	SEE COMMENT
A. WORK SITE REQUIREMENTS			
1. Is area effectively barricaded?	X		
2. Are caution signs posted?	X		
3. Is water available?	X		
4. Are special plastic bags available?	X		
5. Are stick-on caution labels available?	X		
B. PERSONNEL REQUIREMENTS			
1. Wearing disposable coveralls.	X		
2. Wearing gloves.	X		
3. Wearing disposable dust respirator.	X		
4. Foot gear that can be easily cleaned.	X		
5. Properly trained.	X		
C. WORK PRACTICE REQUIREMENTS			
1. SHARE Department notified.	X		
2. Asbestos kept wet at all times.	X		
3. Avoid dropping asbestos from high places.	X		
4. Area free of asbestos dust.	X		
5. Asbestos put in plastic bags.	X		
6. Plastic bags sealed and labeled.	X		
7. Area thoroughly cleaned.	X		
8. Disposable protective equipment put in sealed bags.	X		
9. Asbestos waste properly stored and disposed of.	X		

BRE 0188

ASBESTOS HANDLING
INSPECTION AND AUDIT

D. GENERAL REQUIREMENTS	YES	NO	SEE COMMENT
1. Use of friable asbestos insulation prohibited.	X		
2. In Stores all material which contains asbestos is properly stored and labeled.	X		
3. Asbestos storage area vacuumed regularly.		X	
4. Garage personnel trained in dangers of asbestos.	X		
5. Dust masks worn when repairing brakes.		X	(1)
6. Dust from drums and floor is vacuumed.		X	(1)
7. Asbestos dust from vacuum cleaners is disposed of in sealed and labeled plastic bags.	X		
8. Trip ticket procedure is followed when taking asbestos bags to city dump.	X		
9. Truck driver properly trained.	X		

E. COMMENTS

(1) No dust is created, the drums are water washed outside. Of greater concern is the wirebrushing of stuck-on gasket material from distillation column sections when columns are unstacked for repairs. The worker doing the buffing is wearing a dust mask but the gasket material (which contains asbestos) is sent flying in all directions exposing other personnel.

Union Carbide trial exhibit UC-1742: Asbestos Handling Inspection and Audit of Recovery Unit, Building 539, by Ma... Published by AsbestosClaims.Law
ACL Doc 16815 · Page 2 of 2 asbestosclaims.law/library/16815/2