PLAINTIFF'S EXHIBIT

UC-1777

January 26, 1972

TO: B&R Personnel

SUBJECT: Exposure to Asbestos Dust

To avoid excessive exposure to asbestos dust, the following procedure must be followed when working with or handling asbestos or asbestos cement, mortar, coatings, grout and plaster:

(1) No dry sweeping is permitted when cleaning up asbestos or asbestos dust.

(2) Asbestos waste, scrap and dust must be placed in closed containers until it is disposed of. (Use shipping carton or bag when cleaning up job)

(3) Dust particle respirators must be worn when exposure exceeds 15 minutes of an 8 hour day while performing any of the following operations:

A. Removing asbestos insulation from vessels, piping, structures or buildings.

B. Cleaning up asbestos waste, dust or scrap.

C. Loading or unloading asbestos or asbestos cement, mortar, coatings, grout and plaster.

D. Restacking or handling of asbestos in cardboard shipping containers.

E. Fabricating and/or installing asbestos insulation.

(4) Dust particle respirators must be worn at all times while mixing asbestos cements, mortars, coatings, grout and plaster.

BRA 1604

Published by AsbestosClaims.Law
asbestosclaims.law/library/16847/1

SUBJ: Exposure to Asbestos Dust (Cont'd)
DATE: January 26, 1972

(5) Dust partical LE respirators must be worn at all times while performing any task with asbestos materials inside enclosed structures or buildings.

(6) The Wilson style 600A Mono-mask that is available from the tool room is to be used as a dust partical LE respirator until further notice.

Jerry DeLay

BRA 1605

Published by AsbestosClaims.Law
asbestosclaims.law/library/16847/2