PLAINTIFF'S EXHIBIT

UC-1823

BREATHING AIR

INSPECTION AND AUDIT

AREA/UNIT/BLDG. REACTION #2 DATE 4Q 1981

INSPECTION BY Maria Gutierrez

	YES	NO	SEE COMMENT
A. FIXED INSTALLATIONS			
1. Pipe line systems are color coded and labeled.	✓		
2. Breathing line couplings are incompatible with outlets for other services.	✓		
3. Manifolding of breathing air containers with non-breathing air containers is not allowed.	✓		
4. Drain valves have threads deformed.	✓		
5. Pressure gages are installed at each users location.	✓		
6. Low pressure alarm is within audible range of all use locations.	✓		
B. COMPRESSOR SYSTEMS			
1. Dedicated solely to breathing air service.	✓		
2. Intake located to avoid contaminated air.	✓		
3. Equipped with high temperature alarm if oil lubricated/ or trip and low pressure alarm.	✓		
4. Equipped with carbon monoxide alarm/or the air is frequently tested for CO.	✓		
5. Equipped with purifying beds and filters.	✓		
6. Alarm systems are periodically inspected and maintained with appropriate records.	✓		
7. Filter systems are periodically inspected and maintained with appropriate records.	✓		
8. Cylinders used as backup for escape.	✓		

BRE 0203

Union Carbide trial exhibit UC-1823: Breathing Air Inspection and Audit and Sanitation Inspection Forms for Reactio… Published by AsbestosClaims.Law
ACL Doc 16890 · Page 1 of 4 asbestosclaims.law/library/16890/1

	YES	NO	SEE COMMENT
C. CYLINDER SYSTEMS			
1. Cylinders are properly certified by vendor.	✓		
2. Oxygen content is verified by laboratory and an analytical tag is attached (this is not a certification tag).	✓		
3. Cylinders are properly installed in permanent rack.	✓		
4. Regulators, lines, and manifolds are properly maintained.	✓		
5. Cylinders not connected are capped.	✓		
6. Manifold equipped with low pressure alarm.	✓		
7. When used in conjunction with a compressor, the main regulator is set to open 10 psi below the low pressure alarm, to alert of compressor failure.	✓		
D. GENERAL REQUIREMENTS			
1. Is RM inspection schedule up-to-date?	✓		
2. Are OSHA required inspection records maintained?	✓		
3. Are the laboratory procedures and records adequate?	✓		

E. COMMENTS

Union Carbide trial exhibit UC-1823: Breathing Air Inspection and Audit and Sanitation Inspection Forms for Reactio... Published by AsbestosClaims.Law
ACL Doc 16890 · Page 2 of 4 asbestosclaims.law/library/16890/2

SANITATION INSPECTION

BUILDING NUMBER 731-821

AREA OF RESPONSIBILITY REACTION

INSPECTED BY Maria Gutierrez DATE 4Q 1981

	YES	NO	SEE COMMENT
HOUSEKEEPING WORK AREAS			
Floors dry	✓		
Floors clean	✓		
WASTE DISPOSAL			
Containers provided	✓		
Lid on containers for putrescible solids, or containers are emptied daily	✓		
Vermin controlled	✓		
POTABLE WATER SUPPLIED			
For washing person	✓		
Hot, if required in area	✓		
For personal service rooms	✓		
For drinking purposes	✓		
Drinking fountain is clean	✓		(1)
Portable drinking water dispensers are sanitary	✓		
Ice handling is sanitary	✓		
Not Potable Water outlets labeled	✓		
TOILET FACILITIES			
Toilet facilities adequate	✓		
Privacy assured	✓		
Toilet paper and holder	✓		
Floors, walls, etc. made of easily cleaned material	✓		
Toilets are clean	✓		
Floor, walls, enclosures are clean	✓		
Urinals are clean	✓		
WASHING FACILITIES			
Lavatories supplied as required	✓		
Lavatories clean	✓		
Hot or tepid water supplied	✓		
Hand soap supplied	✓		
Towels supplied	✓		
Receptacle for used towels supplied	✓		

BRE 0205

SANITATION INSPECTION

EATING AND DRINKING AREAS	YES	NO	SEE COMMENT
Waste disposal containers supplied	✓		
Waste disposal containers are in sanitary condition	✓		
Food and beverages are stored and consumed outside of toilet rooms and areas exposed to toxic substances	✓		
Floors clean	✓		
Walls clean	✓		
Stove or oven clean	✓		
Cooking utensils clean	✓		
Cabinets clean	✓		(2)
Utensil storage area clean	✓		
Refrigerator clean	✓		
Sink clean	✓		(1)
Counter top clean	✓		
Hot and cold water supplied where food is prepared	✓		

Any items checked "NO" must be corrected and action taken to prevent recurrence.
Department head will report action taken to resolve problem to SHARE department.
All inspection reports will be summarized and sent to Ben Brown and Dr. Glenn.

COMMENTS: (1) TOBACCO CHEWERS ARE SPITTING AND WASHING THEIR MOUTHS IN THE DRINKING FOUNTAIN AND KITCHEN SINK.

(2) THE CABINET UNDER THE SINK HAS SOME MOISTURE FROM A LEAKING TRAP.

BRE 0206