PLAINTIFF'S EXHIBIT

UC-2087

WV-0204
#40

1/29/87

ASBESTOS MTG. – CHUCK ROTTHOFF

- Installing new jacket over ~~of~~ good as ~~beston~~ – Negative pressure enclosure not required Monitor to prove exposure is below the action level.
- Only exception for small jobs is that shower can be remote from work site.
- ✱ Can remote shower be same as shower used by others or does it have to be dedicated to asbestos workers? – Rotthoff will check.
- ✱ Is shower required before eating? – Rotthoff will check
- ✱ Do we have to have lead covers?
- ✱ Do we have to have shoe covers or are ~~to~~ rubber boots acceptable?
- ✱ Is protective clothing required on glove-bag job?
- ✱ If we must have dedicated hygiene facilities, can we have one for entire plant?
- Competent person is required for large scale jobs only.
- Contractor will supply competent person for their jobs.
- Plant will have at least one competent person.
- Qualitative fit testing must be repeated every six months. – All types of respirators
- Medical certification must be repeated every year.

Union Carbide trial exhibit UC-2087: Handwritten Notes of Asbestos Meeting with Chuck Rotthoff on Showers, Prot... Published by AsbestosClaims.Law
ACL Doc 17108 · Page 1 of 1 asbestosclaims.law/library/17108/1