WV-0207 #35

PLAINTIFF'S EXHIBIT

UC-2137

BUILDING 156

ASBESTOS-REPAIRS

(Immediate Attention: 9401 Insulation)

#1 Priority

1st Level - south entrance - steam header lines and overhang. (Strip and seal).

#2 Priority

1st Level - south piperack - DMEA transfer line from tank 5115 to 6060 reactor. (Strip)

#3 Priority

1st Level - south side of tank 4074 - transfer line and tank insulation. (Strip and seal).

#4 Priority

1st Level - transfer line between tanks 5105 and 5018. (Strip)

#5 Priority

1st Level - transfer line between tanks 5107 and 5110, including steam line by the piston pump at the southwest S/B. (Strip)

#6 Priority

1st Floor - inside Bldg. 156:

1. Lines above the east end of 5230 kettle. (Strip)
2. Line above the spare pump room. (Strip)
3. Lines above 4180 kettle. (Strip)
4. 180# and 30# steam main headers. (Seal)
5. 4620 accumulator pot. (Strip)
6. Steam lines to the air compressor behind the #1 SAP. (Strip)
7. Lines above the east end of 4130 kettle. (Strip)
8. Lunch room area steam lines. (Seal)
9. Maintenance shop lines. (Strip)
10. Steam lines above 4150 S/B. (Seal)
11. 4140 kettle insulation. (Seal)
12. Drumming room steam lines. (Seal)

3/12/87

UCC 006622

Published by AsbestosClaims.Law
asbestosclaims.law/library/17155/1

BUILDING 156
ASBESTOS-REPAIRS

(Immediate Attention: 9401 Insulation)
(cont'd)

#7 Priority

1st level - lines above the northwest S/B. (Strip and seal).

#8 Priority

1st level - tanks 4041/5051/5052. (Seal??)

#9 Priority

6060/5050/4040 Areas:

1. Steam lines between 4040 hotwell and the Bldg. 1st level. (Strip)
2. 5050 vacuum jet legs - 2nd and 3rd levels. (Strip)
3. Steam supply line to 5050 vacuum jets - 2nd and 3rd levels. (Strip)
4. 6060 vent line to the vacuum jets - 3rd and 4th levels. (Strip)
5. Disconnected piping laying on the grating - 4th level. (Strip)

#10 Priority

1st level - 600 lb steam header along the east side of the building. (Strip)

#11 Priority

1st level - lines between tanks 9411 and 9401. (Strip)

#12 Priority

1st level - lines along the north outside wall of Bldg. 156. (Strip)

#13 Priority

1st level - tank 5115 insulation (Seal??)

#14 Priority

1st level - steam lines between Pads #2 and #3. (Strip)

#15 Priority

1st level - steam lines on Pad #6 by tank 4613. (Strip and Seal)

3/12/87

Union Carbide trial exhibit UC-2137: Building 156 Asbestos-Repairs Priority List for 9401 Insulation (1987)
ACL Doc 17155 · Page 2 of 2
Published by AsbestosClaims.Law
asbestosclaims.law/library/17155/2