WV-0191 #111

ASBESTOS HANDLING-CHECKLIST

DATE 6-25-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION

ESTIMATED QUANTITY REMOVED 120 FEET

LOCATION III / C / 174 / EAST TANK FARM
AREA ZONE BLDG. ETC.

CRAFTSMEN W. M. SHIRKEY, P. J GIBSON, N. E. RAMSEY, D. L. SHAFFER

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. W. Spangler
Supervisor

PLAINTIFF'S EXHIBIT
UC-2283

UCC 002061

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/1

ASBESTOS HANDLING-CHECKLIST

DATE 6-24-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION

ESTIMATED QUANTITY REMOVED 200 FEET

LOCATION III / C / 174 / EAST TANK FARM
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN W. M. SHIRKEY, P. J. GIBSON, D. L. SHAFFER, G. L. SHULER, N. E. RAMSEY

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. W. Spangler
Supervisor

UCC 002062

ASBESTOS HANDLING-CHECKLIST

DATE 6-25&26-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION

ESTIMATED QUANTITY REMOVED 1 10" VALVE

LOCATION III / C / 135 / NORTH
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN J. F. ADAMS

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☐	☑

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.W.B.
M D. Grim
Supervisor

UCC 002063

ASBESTOS HANDLING-CHECKLIST

DATE 6-27-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION

ESTIMATED QUANTITY REMOVED 3 FEET

LOCATION II / A / B.156 / EAST SIDE 2ND LEVEL
AREA ZONE BLDG. ETC.

CRAFTSMEN N.E. RAMSEY, D.L. SHAFFER

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☐	☑

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.W. Spangler
Supervisor

UCC 002064

ASBESTOS HANDLING-CHECKLIST

DATE 6-13-86

JOB DESCRIPTION 9646 TK Transfer Line at #6 SE. Plant

ESTIMATED QUANTITY REMOVED Approx. 40'

LOCATION ONE / A / 36 / Tank Farm
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN J. E. Oneal, G. L. Shuler

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☒

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

K. L. Loggins
Supervisor

UCC 002065

ASBESTOS HANDLING-CHECKLIST

DATE 6-10-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION
160 FEET

ESTIMATED QUANTITY REMOVED

LOCATION III / C / 174 / EAST TANK FARM
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN W.M. SHIRKEY, J.A. HUDSON, G.L. SHULER, P.J. GIBSON, [redacted]
N.E. RAMSEY, D.L. SHAFFER

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.W. Spangler
Supervisor

UCC 002066

ASBESTOS HANDLING-CHECKLIST

DATE 6-4-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION

ESTIMATED QUANTITY REMOVED 200 SQUARE FEET, 140 LINEAL FEET

LOCATION III / C / 174 / EAST TANK FARM
AREA ZONE BLDG. ETC.

CRAFTSMEN N.E. RAMSEY, G.L. SHULER, D.L. SHAEFFER, P.J. GIBSON, J.A. HUDSON

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. W. Spangler
Supervisor

UCC 002067

ASBESTOS HANDLING-CHECKLIST

DATE 6-3-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION

ESTIMATED QUANTITY REMOVED 150 SQUARE FEET, 120 LINEAL FEET

LOCATION III / C / 174 / EAST TANK FARM
AREA ZONE BLDG. ETC.

CRAFTSMEN W.M SHIRKEY, J.A. HUDSON, P.J. GIBSON, D.L. SHAFFER, G.L. SHULER, N.E. RAMSEY

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. W. Spangler
Supervisor

UCC 002068

ASBESTOS HANDLING-CHECKLIST

DATE 6-2-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION

ESTIMATED QUANTITY REMOVED 250 FEET

LOCATION 3 / C / 174 / EAST TANK FARM
AREA ZONE BLDG. ETC.

CRAFTSMEN P.J. GIBSON, G.L. SHULER, D.L. SHAFFER, N.E. RAMSEY, W.M. SHIRKEY

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L W Spangler
Supervisor

UCC 002069

ASBESTOS HANDLING-CHECKLIST

DATE 5-30-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION

ESTIMATED QUANTITY REMOVED 700 FEET

LOCATION III / C / 174 / EAST TANK FARM
AREA ZONE BLDG. ETC.

CRAFTSMEN R.J. SKEEN, P.J. GIBSON, W.M. SHIRKEY, D.L. SHAFFER, R.M. HUGGET, G.L. SHULER

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.W. Spangler
Supervisor

UCC 002070

ASBESTOS HANDLING-CHECKLIST

DATE 5-28-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION

ESTIMATED QUANTITY REMOVED 120 FEET

LOCATION III / C / 174 / EAST TANK FARM
AREA ZONE BLDG. ETC.

CRAFTSMEN H. WHITE, D.E. RICKS, G.L. STULER, J.S. DORSEY

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. W. Spangler
Supervisor

UCC 002071

ASBESTOS HANDLING-CHECKLIST

DATE 5-27-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION

ESTIMATED QUANTITY REMOVED 120 FEET

LOCATION III (AREA) / C (ZONE) / 174 (BLDG.) / EAST TANK FARM (ETC.)

CRAFTSMEN D.E. RICKS, H. WHITE, C.L. SHULER, P.J. GIBSON

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.W. Spurgle
Supervisor

UCC 002072

ASBESTOS HANDLING-CHECKLIST

DATE 5-20-86

JOB DESCRIPTION Removal of asbestos insulation from east K farm BLDG-174

ESTIMATED QUANTITY REMOVED 120'

LOCATION 3 / / 174 east York farm
AREA ZONE BLDG. ETC.

CRAFTSMEN B. J. Sheen, P. J. Gibson, R. Huggett, G. Shuler D. Shaffer, J. Ponsey.

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John E. Adams
Supervisor

UCC 002073

ASBESTOS HANDLING-CHECKLIST

DATE 5-16-86

JOB DESCRIPTION Removal of Asbestos insulation From East TK Farm BLDG-174

ESTIMATED QUANTITY REMOVED 150'

LOCATION 3 / / 174 / East TK. Farm
AREA ZONE BLDG. ETC.

CRAFTSMEN SHeen, B.J. P.J. Gibson, D. Shaffer, G. Shuler R. Hubbett, J. Cline J. Dorsey

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John E. Adams Jr.
Supervisor

UCC 002074

ASBESTOS HANDLING-CHECKLIST

DATE 5-19-86

JOB DESCRIPTION Removal of asbestos insulation BLDG 151

ESTIMATED QUANTITY REMOVED 20'

LOCATION 3 / / 151 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN W. M. Shirley, N. E. Ramsey

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John E. Adams
Supervisor

UCC 002075

ASBESTOS HANDLING-CHECKLIST

DATE 5-19-86

JOB DESCRIPTION Removal of Asbestos insulation from East Tk. Farm BLDG-174

ESTIMATED QUANTITY REMOVED 115'

LOCATION 3 / / 174 / East Tk. Farm
AREA ZONE BLDG. ETC.

CRAFTSMEN Sheen B.J. P.J. Gibson, O. Shaffer, G. Shuler
R. Dorsey

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☑	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John E Adams
Supervisor

UCC 002076

ASBESTOS HANDLING-CHECKLIST

DATE 5-15-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION IN B.174 EAST TANK FARM PIPERACK

ESTIMATED QUANTITY REMOVED _____

LOCATION III (AREA) / C (ZONE) / 174 (BLDG.) / TANK FARM (ETC.)

CRAFTSMEN B.J. SHEEN, P.J. GIBSON, D.L. SHAFFER, J.S. DARSEY R.M. HUBBARD, G.L. SHULER

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS _____

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.W. Spangler
Supervisor

UCC 002077

ASBESTOS HANDLING-CHECKLIST

DATE 5-15-86

JOB DESCRIPTION Removal of Asbestos insulation

B106-323

ESTIMATED QUANTITY REMOVED 20'

LOCATION / / C / 323 / /
AREA ZONE BLDG. ETC.

CRAFTSMEN D. Ricks, H. White

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☐	☑

COMMENTS small job not [redacted] To be checked

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

J. E. Adams
Supervisor

UCC 002078

ASBESTOS HANDLING-CHECKLIST

DATE 5-29-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION

ESTIMATED QUANTITY REMOVED 125 FEET

LOCATION III / C / 174 / EAST TANK FARM
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN H. WHITE, G. L. SHULER, D. E. RICKS, P. J. GIBSON, W. M. SHIRKEY

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. W. Spangler
Supervisor

UCC 002079

ASBESTOS HANDLING-CHECKLIST

DATE 5-15-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION IN BLDG. 151-2ND FLOOR

ESTIMATED QUANTITY REMOVED _____

LOCATION III (AREA) / A (ZONE) / 151 (BLDG.) / 2ND FLOOR (ETC.)

CRAFTSMEN W.M. SHIRKEY, N.E. RAMSEY

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used.	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☐	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS _____

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. W. Spangler
Supervisor

UCC 002080

ASBESTOS HANDLING-CHECKLIST

DATE 5-14-86

JOB DESCRIPTION STRIP ASBESTOS INSULATION IN PIPERACK WEST OF BLDG. 151

ESTIMATED QUANTITY REMOVED _____

LOCATION III / B / 174 / _____
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN B.J. Sheen, M.E. Ramsey, J.S. Dorsey, P.J. Gibson, D.L. Shaffer, W.M. Skinky

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS _____

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.W. Spangler
Supervisor

UCC 002081

ASBESTOS HANDLING-CHECKLIST

DATE 5-14-86

JOB DESCRIPTION Removal of Asbestos insulation

ESTIMATED QUANTITY REMOVED

LOCATION / / C / 303 /
AREA ZONE BLDG. ETC.

CRAFTSMEN D. Bicks H. White.

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☐	☐

COMMENTS Small Job.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John E. Adams
Supervisor

UCC 002082

ASBESTOS HANDLING-CHECKLIST

DATE 5-12-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION IN PIPERACK WEST OF BLDG 151

ESTIMATED QUANTITY REMOVED 100 LINEAL FEET

LOCATION III / B / 174 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN W. M. SHIRKEY, N. E. RAMSEY, J. S. DORSEY, D. L. SHAFFER, B. J. SKEEN

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. W. Spangler
Supervisor

UCC 002083

ASBESTOS HANDLING-CHECKLIST

DATE 5-13-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION IN PIPERACK WEST OF BLDG. 151

ESTIMATED QUANTITY REMOVED 140 LINEAL FEET

LOCATION III / 8 / 174 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN W. M. SHIRKEY, N. E. RAMSEY, J. S. DORSEY, D. L. SHAFFER, B. J. SKEEN, P. J. GIBSON

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. W. Spangler
Supervisor

UCC 002084

ASBESTOS HANDLING-CHECKLIST

DATE 5-13-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION SOUTHEAST OF BLDG. 323

ESTIMATED QUANTITY REMOVED 25 LINEAL FEET

LOCATION I / C / 323 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN D.E. RICKS, H. WHITE

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☑	☐	☑

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.W. Spangler
Supervisor

UCC 002085

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/25

ASBESTOS HANDLING-CHECKLIST

DATE 5-15-8..

JOB DESCRIPTION Removal of Insulation from Pipe

ESTIMATED QUANTITY REMOVED 3'

LOCATION / / B / 4 /
AREA ZONE BLDG. ETC.

CRAFTSMEN J. Hudson

	N/A	Yes	No
Barrier Tape Used		✓	
Warning Signs Used		✓	
Protective Clothing Used		✓	
Coveralls Changed Daily	✓		
Respirators Used		✓	
Drop Cloth Used	✓		
Wet Down Area		✓	
Proper Disposal - (Bags to Land Fill)		✓	
Dumpster Sealed or Wet Down	✓		
Proper Clean-up (Area Housekeeping)		✓	
Barricades Down (After Clean-up Only)		✓	
Plant 514 Hygienist Notified	✓		✓

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Supervisor

UCC 002086

ASBESTOS HANDLING-CHECKLIST

S.O. 300020

DATE 5-9-86

JOB DESCRIPTION Removal of Asbestos Insulation and Reinsulate ½" line to Austin

ESTIMATED QUANTITY REMOVED 6'

LOCATION 2 / B / 308 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN J. Cline, H. White

	N/A	Yes	No
Barrier Tape Used	✓		
Warning Signs Used		✓	
Protective Clothing Used		✓	
Coveralls Changed Daily		✓	
Respirators Used		✓	
Drop Cloth Used		✓	
Wet Down Area		✓	
Proper Disposal - (Bags to Land Fill)		✓	
Dumpster Sealed or Wet Down	✓		
Proper Clean-up (Area Housekeeping)		✓	
Barricades Down (After Clean-up Only)	✓		
Plant 514 Hygienist Notified			✓

COMMENTS This Job was To small for notification

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John E. Adams
Supervisor

UCC 002087

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/27

ASBESTOS HANDLING-CHECKLIST

DATE 5-9-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION IN PIPERACK WEST OF BLDG. 151

ESTIMATED QUANTITY REMOVED 140 LINEAL FEET

LOCATION III / B / 174 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN N.E. RAMSEY, G.L. SHULER, J.S. DORSEY, D.L. SHAFFER, W.M. SHIRKEY, P.J. GIBSON

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.W. Spangler
Supervisor

UCC 002088

ASBESTOS HANDLING-CHECKLIST

DATE 5-8-86

JOB DESCRIPTION STRIP ASBESTOS INSULATION IN PIPERACK WEST OF BLDG 151

ESTIMATED QUANTITY REMOVED 120 LINEAL FT.

LOCATION III / B / 174 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN W. M. SHIRKEY, D. L. SHAFFER, J. S. DORSEY, P. J. GIBSON, G. L. SHULER, N. E. RAMSEY

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☑	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. W. Spangler
Supervisor

UCC 002089

ASBESTOS HANDLING-CHECKLIST

DATE 5-7-86

JOB DESCRIPTION Removal of Asbestos insulation AND Reinsulate Feed Heater B106-4

ESTIMATED QUANTITY REMOVED 3'

LOCATION 1 (AREA) / 13 (ZONE) / 42 (BLDG.) / (ETC.)

CRAFTSMEN J. Hudson

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☑	☐	☑
Respirators Used	☐	☑	☐
Drop Cloth Used	☑	☐	☐
Wet Down Area	☐	☐	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☑	☐	☐

COMMENTS Job was To small for notification

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John E Adams Jr
Supervisor

UCC 002090

ASBESTOS HANDLING-CHECKLIST

DATE 5-7-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION IN PIPERACK FROM WEST SIDE B.151 TO EAST SIDE B.157

ESTIMATED QUANTITY REMOVED 360 LINEAL FEET

LOCATION III / B / 174 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN P.J. GIBSON, W.M. SHIRKEY, D.L. SHAFFER, J.S. DORSEY, G.L. SHULER, N.E. RAMSEY

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☑
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS _____

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.W. Spangler
Supervisor

UCC 002091

ASBESTOS HANDLING-CHECKLIST

DATE 5-6-85

JOB DESCRIPTION REMOVE ASBESTOS INSULATION IN PIPERACK (4 LINES) FROM B.151 WEST TO B.174 NORTHEAST

ESTIMATED QUANTITY REMOVED 240 LINEAL FEET

LOCATION III (AREA) / B (ZONE) / 174 (BLDG.) / NORTHEAST (ETC.)

CRAFTSMEN W.M. SHIRKEY, D.L. SHAFFER, N.E. RAMSEY, P.J. GIBSON, G.L. SHULER, J.S. DORSEY

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.W. Spangler
Supervisor

UCC 002092

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 1 ZONE _____ BLDG 36 UNIT _____ DATE 5-2-86

JOB DESCRIPTION Removal of asbestos insulation 2nd Level

ESTIMATED LINEAL FEET REMOVED 4' JOB SUPERVISOR J. F. Adams

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS D. Ricks, L. E. Clayton

	YES	NO	N/A
Plant 514 Hygienist Notified			✓
Plant E.P. Department Notified (large jobs only)	✓		
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS 1 Hr of removal of insulation

John E. Adams
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

Union Carbide trial exhibit UC-2283: Asbestos Handling and Asbestos Removal/Disposal Checklists for Insulation… Published by AsbestosClaims.Law
ACL Doc 17275 · Page 33 of 145 asbestosclaims.law/library/17275/33

ASBESTOS HANDLING-CHECKLIST

DATE 5-2-86

JOB DESCRIPTION Asbestos Clean-Up
East tank farm BLDG-42

ESTIMATED QUANTITY REMOVED

LOCATION 1 / 1 (AREA) / B (ZONE) / 42 (BLDG.) / (ETC.)

CRAFTSMEN D. Ricks, H. White, B. J. Sheen's

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☐	☑
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS Comp. 5-2-86
S.O. # 184064

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John E. Adams
Supervisor

UCC 002094

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 1 ZONE B BLDG 42 UNIT _____ DATE 5-1-86

JOB DESCRIPTION Removal of Asbestos insulation and Clean-up

ESTIMATED LINEAL FEET REMOVED 60' JOB SUPERVISOR J. F. Adams.

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS J. Cline, H. White, P. Ricks, B. J. Sheens

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)	✓		
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS 8 Hr's 7.30/hr T.L 40.00/hr Asbestos Removal

John E. Adams Jr.
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

Union Carbide trial exhibit UC-2283: Asbestos Handling and Asbestos Removal/Disposal Checklists for Insulation… Published by AsbestosClaims.Law
ACL Doc 17275 · Page 35 of 145 asbestosclaims.law/library/17275/35

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 1 ZONE B BLDG 42 UNIT _____ DATE 4-30-84

JOB DESCRIPTION Removal of Asbestos insulation from East, N. Lam B106. 42

ESTIMATED LINEAL FEET REMOVED 150' JOB SUPERVISOR J. F. Adams

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS P. J. Tatum, B. T. Shinn, H. Davis, D. E. Clayton, J. S. Davey, E. D. Cole, S. M. Cartledge, O. L. Shaffer

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)	✓		
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS Removal and Clean-up

Over Time 4.5 Hr's

J. F. Adams
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002096

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/36

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 1 ZONE C BLDG 42 UNIT _____ DATE 4-30-86

JOB DESCRIPTION Removal of Asbestos insulation from Cont TK Farm Bldg 42

ESTIMATED LINEAL FEET REMOVED 175' JOB SUPERVISOR J. F. Adams

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS J. Dorsey, B. Stivers, P. L. Gibson, H. White, D. Ricks

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)	✓		
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS 8 Hrs Removal and Clean-up. Safety dept checked for asbestos with vacuum. 65 Hrs

John F. Adams
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

Union Carbide trial exhibit UC-2283: Asbestos Handling and Asbestos Removal/Disposal Checklists for Insulation… Published by AsbestosClaims.Law
ACL Doc 17275 · Page 37 of 145 asbestosclaims.law/library/17275/37

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 3 ZONE A BLDG 151 UNIT _____ DATE 4-30-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION IN BLDG 151 AND REPLACE WITH KAYLO INSULATION

ESTIMATED LINEAL FEET REMOVED 30 JOB SUPERVISOR L.W. Spangler

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS R.M HUGGETT, H. Shuler,

	YES	NO	N/A
Plant 514 Hygienist Notified	✓	—	—
Plant E.P. Department Notified (large jobs only)	—	—	✓
Barrier Tape Used	✓	—	—
Warning Signs Used	✓	—	—
Protective Clothing Used	✓	—	—
Coveralls Changed Daily	✓	—	—
Respirators Used	✓	—	—
Drop Cloth Used	✓	—	—
Wet Down Area	—	—	✓
Proper Disposal - (Bags to Landfill)	✓	—	—
Dumpster Sealed or Wet Down	✓	—	—
Proper Clean-up (Area Housekeeping)	✓	—	—
Barricades Down (After Clean-up Only)	✓	—	—

COMMENTS 8 Hrs

L.W. Spangler
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002098

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 1 ZONE B BLDG 42 UNIT _____ DATE 4-29-86

JOB DESCRIPTION Removal of asbestos insulation East tank farm Bldg 42

ESTIMATED LINEAL FEET REMOVED 80' JOB SUPERVISOR J. E. Adams

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS D. Ricks, B. Sheets P. J. Gibson A. White

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)	✓		
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS 8 Hrs Working

John E Adams Jr
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002099

ASBESTOS HANDLING-CHECKLIST

DATE 4-29-86

JOB DESCRIPTION REMOVE ASBESTOS INSULATION IN BLDG. 151 AND REPLACE WITH KAYLO INSULATION

ESTIMATED QUANTITY REMOVED _____

LOCATION III (AREA) / A (ZONE) / 151 (BLDG.) / 2ND FLOOR (ETC.)

CRAFTSMEN HUGGETT, CLINE

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS _____

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. W. Spangler
Supervisor

UCC 002100

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 1 ZONE B BLDG 42 UNIT _____ DATE 4-19-84

JOB DESCRIPTION Removal of asbestos insulation East tank farm BLDG 42

ESTIMATED LINEAL FEET REMOVED 200' JOB SUPERVISOR J. F. Adams

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS A. Davis, G. Wood, J. Oneal P. Gibson, B. Shaw, D. Shaffer, S. Cookshaw, M. Ramsey

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)	✓		
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS 5 Hr's Working Over Time

John E Adams Jr
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002101

ASBESTOS HANDLING-CHECKLIST

DATE 4-24-86

JOB DESCRIPTION Cleaning up asbestos insulation Top of Bldg 5

ESTIMATED QUANTITY REMOVED 8'

LOCATION / (AREA) / (ZONE) / 42 (BLDG.) / (ETC.)

CRAFTSMEN B. Stevens H. White D. Shaffer

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John E Adams Jr
Supervisor

UCC 002102

ASBESTOS HANDLING-CHECKLIST

DATE 4-23-86

JOB DESCRIPTION Cleaning asbestos insulation

ESTIMATED QUANTITY REMOVED 4 ft.

LOCATION 1 (AREA) / 1 C (ZONE) / 42 (BLDG.) / 2ND Floor (ETC.)

CRAFTSMEN B. Stevens 11872, D. Shaffer 11868, H. White 11345, J. L. Ellis 11336

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☑	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS Safety dept. said job to small to check for dust

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John E Adams Jr
Supervisor

UCC 002103

ASBESTOS HANDLING-CHECKLIST

DATE 4-23-86

JOB DESCRIPTION Cleaning up insulation Bldg 42 2nd floor may contain asbestos

ESTIMATED QUANTITY REMOVED

LOCATION / AREA / ZONE / 42 BLDG. / ETC.

CRAFTSMEN B. Simon 11872 — H. Cubit 11345 — D. Shaffer 11868

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☑	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS Talked to safety Dept. this job is to board to be checked for dust

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John F. Adams Jr
Supervisor

UCC 002104

ASBESTOS HANDLING-CHECKLIST

DATE Apr-18-86

JOB DESCRIPTION Removing Asbestos insulation EAST Tk. Farm TK 570

ESTIMATED QUANTITY REMOVED 15 ft

LOCATION 1 (AREA) 1 (ZONE) 1 (BLDG.) 42 EAST Tank Farm TK 570 (ETC.)

CRAFTSMEN B. Sheen - 11872 D. Shaffer - 11868
H. White 11345

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John L Adams Jr
Supervisor

UCC 002105

ASBESTOS HANDLING-CHECKLIST

DATE Apr-17-86

JOB DESCRIPTION Cleaning up Asbestos insulation

ESTIMATED QUANTITY REMOVED 10 ft

LOCATION 1 / / 42 / 2nd floor
AREA ZONE BLDG. ETC.

CRAFTSMEN 11872 Sheen, Shaffer-11868 - 11345 White
Dorsey-11191 - Oneal 11148

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

John E Adams Jr
Supervisor

UCC 002106

ASBESTOS HANDLING-CHECKLIST

DATE 4-11-86

JOB DESCRIPTION Stripping asbestos from 3" Steam Line

ESTIMATED QUANTITY REMOVED 30'

LOCATION 1 / 1 / 42 / 2nd Level
AREA ZONE BLDG. ETC.

CRAFTSMEN B.J. Skeen, H. White, D.L. Shaffer

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☒

COMMENTS Called Hygienist and line was busy

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Supervisor

UCC 002107

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 2 ZONE _____ BLDG 200 UNIT _____ DATE 3-25-86

JOB DESCRIPTION Remove asbestos insulation from 1, 2-3 floors of Building 200

ESTIMATED LINEAL FEET REMOVED 400 JOB SUPERVISOR W. Shirley

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS 6 men

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)	✓		
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS Dumpster will be sealed twice and area to be Wetted Down.

Warren M. Shirley
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

Union Carbide trial exhibit UC-2283: Asbestos Handling and Asbestos Removal/Disposal Checklists for Insulation... Published by AsbestosClaims.Law
ACL Doc 17275 · Page 48 of 145 asbestosclaims.law/library/17275/48

ASBESTOS HANDLING-CHECKLIST

DATE 3-25-86

JOB DESCRIPTION Stripping Asbestos from dead lines

ESTIMATED QUANTITY REMOVED 75'

LOCATION 1 / / 3235 /
AREA ZONE BLDG. ETC.

CRAFTSMEN D.L. Shaffer, H. White, B.J. Skeen 4hrs.

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucking will Pickup	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Did not monitor

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Carter
Supervisor

UCC 002109

ASBESTOS HANDLING-CHECKLIST

DATE 3-24-86

JOB DESCRIPTION Stripping Steam Lines from 309 to 307

ESTIMATED QUANTITY REMOVED 45'

LOCATION 1 / / / /
AREA ZONE BLDG. ETC.

CRAFTSMEN B.J. Skeen, D.L. Shaffer, H. White

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucking will pick up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Told Hygienist we would start after 9:30 AM break. He never did show up

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Carter
Supervisor

UCC 002110

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/50

ASBESTOS HANDLING-CHECKLIST

DATE 3-18-86

JOB DESCRIPTION Stripping Asbestos from DEAD LINE

ESTIMATED QUANTITY REMOVED 100'

LOCATION 1 / 1 South oil yard / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN B.J. Skeen, D.L. Shaffer, H. White, J.A. Hudson

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucking will pick up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist will call back. (7:40AM) (called back at 1:15PM) Called trucking at 1:05 PM to pick up bags between 3:00 & at 3:30 P.M.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Carter
Supervisor

UCC 002111

ASBESTOS HANDLING-CHECKLIST

DATE 3-17-86

JOB DESCRIPTION strip dead air line

ESTIMATED QUANTITY REMOVED 60'

LOCATION 1 / 1 / South 303 /
AREA ZONE BLDG. ETC.

CRAFTSMEN H. White, B.J. Sheen, D.L. Shaffer

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) trucking will pick up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☒

COMMENTS Hygienist Phone Busy

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Carter
Supervisor

UCC 002112

ASBESTOS HANDLING-CHECKLIST

DATE 3-1-86

JOB DESCRIPTION Stripping Asbestos in Bldg 80

ESTIMATED QUANTITY REMOVED

LOCATION / / 80 /
AREA ZONE BLDG. ETC.

CRAFTSMEN J.L. Cline, B.J. Steen

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucking will pick up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☒	☐	☐

COMMENTS Hygienist did not want to monitor

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Supervisor

UCC 002113

ASBESTOS HANDLING-CHECKLIST

DATE 2-28-86

JOB DESCRIPTION Stripping asbestos from steam Lines

ESTIMATED QUANTITY REMOVED 150'

LOCATION 1 / / 80 / /
AREA ZONE BLDG. ETC.

CRAFTSMEN B.J. Skeen, J.A. Hudson, D.L. Shaffer
(W.M. Shirkey 4hrs)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) trucking will pick up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☒	☐	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. A. Carter
Supervisor

UCC 002114

ASBESTOS HANDLING-CHECKLIST

DATE 2/23/86

JOB DESCRIPTION Stripped Asbestos from Area 3 Office

ESTIMATED QUANTITY REMOVED 90' - ½" - ¾" - 1" Pipe

LOCATION 3 / / 185 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN T. R. Burns, J. Adams, W. M. Shirley

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plastic	☐	☒	☐
Wet Down Area	☐	☐	☒
Proper Disposal - (Bags to Land Fill) Trucking Pick-up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist did not monitor. After stripping, all office equip, desks, etc. were wiped down. All office floors were mopped and vacummed. Done a good job.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

G. Woods
Supervisor

UCC 002115

ASBESTOS HANDLING-CHECKLIST

DATE 2-25-86

JOB DESCRIPTION Strip Asbestos from Steam Lines

ESTIMATED QUANTITY REMOVED 150' 200'

LOCATION / / 1 South 751
AREA ZONE BLDG. ETC.

CRAFTSMEN L.E. Clayton, J.E. O'NEAL, B.J. Sheets
J.A. Hudson, D.L. Shaffer, W.A. Shirley

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucking will pick up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist did monitor

A.L. Casey
Supervisor

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

UCC 002116

ASBESTOS HANDLING-CHECKLIST

DATE 2/21/76

JOB DESCRIPTION [illegible] 2-13"

ESTIMATED QUANTITY REMOVED [illegible]

LOCATION 5 / [illegible] / 131 / [illegible]
AREA ZONE BLDG. ETC.

CRAFTSMEN [illegible] D.E Ricks
G.L. Shuler T.R. Bruce

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☐

COMMENTS Hygienist did not monitor. All procedures were followed.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

G. L. [illegible]
Supervisor

UCC 002117

ASBESTOS HANDLING-CHECKLIST

DATE 2-21-86

JOB DESCRIPTION Strip asbestos from Steam oven

ESTIMATED QUANTITY REMOVED 12'

LOCATION 1 / / 305 / /
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN W.M. Shirkey, D.L. Shaffer

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used plastic	☐	☒	☐
Wet Down Area	☒	☐	☐
Proper Disposal - (Bags to Land Fill) trucking will pick up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☒

COMMENTS Not enough asbestos to monitor

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.A. Cartes
Supervisor

UCC 002118

ASBESTOS HANDLING-CHECKLIST

DATE 2-20-86

JOB DESCRIPTION Stripping Asbestos

ESTIMATED QUANTITY REMOVED 75'

LOCATION / / / 323 /
AREA ZONE BLDG. ETC.

CRAFTSMEN B.J. Skeen, J.A. Hudson

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucking will Pickup	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Told him we would be stripping everyday at 323 if he wants to monitor he can.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. A. Carter
Supervisor

UCC 002119

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/59

ASBESTOS HANDLING-CHECKLIST

DATE 2/19/86

JOB DESCRIPTION Stripping Misc. Asbestos Lines in 134.

ESTIMATED QUANTITY REMOVED 100'

LOCATION 3 / / 134-2nd /
AREA ZONE BLDG. ETC.

CRAFTSMEN D.E Ricks R.M. Haggett, G.L. Shuler, T.R. Lyons, (J.L. Cline, J.S. Dorsey - 4 hours only)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucking pick-up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist did not monitor All procedures were followed.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

G. Woods
Supervisor

UCC 002120

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/60

ASBESTOS HANDLING-CHECKLIST

DATE 2/20/86

JOB DESCRIPTION Tying in New Asbestos lines in P4

ESTIMATED QUANTITY REMOVED 130'

LOCATION 3 / [illegible] / 3rd /
AREA ZONE BLDG. ETC.

CRAFTSMEN D.E. Ricks [illegible] Hall, G.L. Shipp, J.L. Cline, J.S. Dorsey

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist did not monitor this job. All procedures were followed.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

[signature]
Supervisor

UCC 002121

ASBESTOS HANDLING-CHECKLIST

DATE 2-19-86

JOB DESCRIPTION Stripping transfr. lines East of Bldg. 36

ESTIMATED QUANTITY REMOVED 80'

LOCATION / / / Tank Farm / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN J.E. O'Neal, T. Burns, L.E. Clayton (2hr)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☐	☒	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☒

COMMENTS Insulation is saturated with water. In the past Hygienist has not monitored because insulation is already wet.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

[signature] Supervisor

UCC 002122

ASBESTOS HANDLING-CHECKLIST

DATE 2-19-86

JOB DESCRIPTION Stripping Asbestos from dead & live Piping.

ESTIMATED QUANTITY REMOVED 75'

LOCATION / / / 303-S1
AREA ZONE BLDG. ETC.

CRAFTSMEN J.A. Hudson, B.J. Skeen

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☒	☐	☐

COMMENTS Hygienist did not monitor

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. P. Carter
Supervisor

UCC 002123

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/63

ASBESTOS HANDLING-CHECKLIST

DATE 2-19-86

JOB DESCRIPTION Strip Asbestos in men's room & replace with Kayle

ESTIMATED QUANTITY REMOVED 3'

LOCATION 1 / 1 / 308-21
AREA ZONE BLDG. ETC.

CRAFTSMEN W.M. Shirkey, D.L. Shaffer

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☒

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. A. Parks
Supervisor

UCC 002124

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/64

ASBESTOS HANDLING-CHECKLIST

DATE 2/18/86

JOB DESCRIPTION Stripping Misc. Asbestos Lines in 134.

ESTIMATED QUANTITY REMOVED 60'

LOCATION 3 / / 134-2nd /
AREA ZONE BLDG. ETC.

CRAFTSMEN J.S. Dorsey, D.E. Ricks, J.L. Cline.

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucks on Pick up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist did not Monitor. All procedures were followed.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

E. Woods
Supervisor

UCC 002125

ASBESTOS HANDLING-CHECKLIST

DATE 2-18-86

JOB DESCRIPTION Strip Asbestos from dead & live piping

ESTIMATED QUANTITY REMOVED 150'

LOCATION 1 / / 1 303 S / along back fence
AREA ZONE BLDG. ETC.

CRAFTSMEN W. M. Shirkey, D. L. Shaffer

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist did not want to monitor

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. M. Curtis
Supervisor

UCC 002126

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/66

ASBESTOS HANDLING-CHECKLIST

DATE 2/17/86

JOB DESCRIPTION Stripping Misc. Asbestos Insul. on 2nd level of 134.

ESTIMATED QUANTITY REMOVED

LOCATION 3 / / 134 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN C.H. Hensley, N.E. Ramsey, R.M. Huggett, D.E. [illegible], J.L. Cline, G.L. [illegible], T.R. Burns

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist did not monitor. All procedures were followed.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

G. L. [illegible]
Supervisor

UCC 002127

ASBESTOS HANDLING-CHECKLIST

DATE 2-16-86

JOB DESCRIPTION Stripping Asbestos

ESTIMATED QUANTITY REMOVED 300'

LOCATION 1 / / 80 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN J.E. O'Neal, R.M. Huggett, S.M. Crookshank L.E. Claytor, N.E. Ramsey

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☒

COMMENTS 2-14-86 I called Hygienist 5 times, line was always busy

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

J. A. Carter
Supervisor

UCC 002128

ASBESTOS HANDLING-CHECKLIST

DATE 2/14/86

JOB DESCRIPTION Steam by 6" steam header And 12" steam header

ESTIMATED QUANTITY REMOVED 140'

LOCATION 3 / / 134-1 / /
AREA ZONE BLDG. ETC.

CRAFTSMEN R.M. Huggett, G.L. Shuler, D.E. Ricks, J.L Clive, T.R. Burns, C.H. Hensley, N.E. Ramsey

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plast.c	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucking Pick-up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Plant Hygiewist did not monitor this job. All procedures were followed. This job was finished At 1:20 pm.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

G. Woods
Supervisor

UCC 002129

ASBESTOS HANDLING-CHECKLIST

DATE 2/13/86

JOB DESCRIPTION Stripping 6" steam header

ESTIMATED QUANTITY REMOVED 75'

LOCATION 3 / / 134-1 / /
AREA ZONE BLDG. ETC.

CRAFTSMEN R.M. Huggett, D.E. Ricks, G.L. Shuler

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) (Trucking Pick-up)	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Plant Hygienist monitored this job. All procedures followed.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

G. Wood
Supervisor

UCC 002130

ASBESTOS HANDLING-CHECKLIST

DATE 2/12/86

JOB DESCRIPTION Strip Misc. Asbestos piping

ESTIMATED QUANTITY REMOVED 80'-120'

LOCATION 3 / / 134 1st /
AREA ZONE BLDG. ETC.

CRAFTSMEN R.M. Huggett, J.L Clive, J.S. Dorsey, D.E. Ricks, T.R. Burns, G.L. Shuler

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used – Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucking Pick-up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Job not monitored. All guide lines were met.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

G. Wrotos
Supervisor

UCC 002131

ASBESTOS HANDLING-CHECKLIST

DATE 2/11/86

JOB DESCRIPTION Strip Misc. Asbestos Piping

ESTIMATED QUANTITY REMOVED 80' - 100'

LOCATION 3 / / 134 1st /
AREA ZONE BLDG. ETC.

CRAFTSMEN R.M. Huggett, J.L. Cline, J.S. Dorsey, D.E. Ricks

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucking Pick-up	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Job was not monitored by Hygienist, All guide lines were met.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

A. Woods
Supervisor

UCC 002132

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/72

ASBESTOS HANDLING-CHECKLIST

DATE 2/10/86

JOB DESCRIPTION Stripping Misc. insulation 1st Floor Bldg. 134

ESTIMATED QUANTITY REMOVED 60'

LOCATION 3 / / 134 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN R.M. Huggett, G.L Shuler, D.E. Ricks

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Bags were tied And set Along Road. All procedures were followed.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

G. Woods
Supervisor

UCC 002133

ASBESTOS HANDLING-CHECKLIST

DATE 2-9-86

JOB DESCRIPTION STRIP Asbestos from Bldg. 80

ESTIMATED QUANTITY REMOVED 150'

LOCATION 1 / / 80 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN B.J. Skeen, J.E. O'NEAL, J.S. Dorsey
N.E. Ramsey

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☒

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. A. Carter
Supervisor

UCC 002134

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/74

ASBESTOS HANDLING-CHECKLIST

DATE 12/19/85

JOB DESCRIPTION Stripping Misc. Asbestos lines at Bldg. 149

ESTIMATED QUANTITY REMOVED 60'

LOCATION 3 / / 149 /
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Trucking will Pick-up	☐	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS No Monitor Available. All Regulations were met.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Greg Woods
Supervisor

UCC 002135

ASBESTOS HANDLING-CHECKLIST

DATE 12/18/85

JOB DESCRIPTION Stripping Asbestos from Misc. Lines At Bldg. 149.

ESTIMATED QUANTITY REMOVED 75'

LOCATION 3 / / 144 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN L.A. Carter - 11142, R.M. Huggett - 11245, T.R. Burns - 11860

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Pick-up Wed.	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☒	☒	☐

COMMENTS Safety Dept. Could not Monitor. All Regulations were followed.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

G. Woods
Supervisor

UCC 002136

ASBESTOS HANDLING-CHECKLIST

DATE 12/17/85

JOB DESCRIPTION Stripping Misc. Asbestos covered Lines N. of Bldg. 744

ESTIMATED QUANTITY REMOVED 100'

LOCATION 3 / / 144-N / /
AREA ZONE BLDG. ETC.

CRAFTSMEN L.A. Carter - 11142, R.M. Haggett - 11245

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used - Plastic	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Tracking Mat-up used.	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS No Monitor Available. All guide lines were met.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Supervisor

UCC 002137

ASBESTOS HANDLING-CHECKLIST

DATE 12/16/85

JOB DESCRIPTION Stripping Misc. Asbestos Covered Lines N. Piping of 144'

ESTIMATED QUANTITY REMOVED 100'

LOCATION 3 / / 144 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN L A. Carter - 11142, R.M. Huggett - 11245

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
~~Drop Cloth Used~~ Plast.c	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill) Pick-up Wed	☒	☐	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS No Monitor Available. All guide lines were met.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Greg Weeks
Supervisor

UCC 002138

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/78

ASBESTOS HANDLING-CHECKLIST

DATE 12-16-

JOB DESCRIPTION [illegible]

ESTIMATED QUANTITY REMOVED

LOCATION / / 42 /
AREA ZONE BLDG. ETC.

CRAFTSMEN [illegible]

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☐	☐
Drop Cloth Used	☐	☐	☐
Wet Down Area	☐	☐	☐
Proper Disposal - (Bags to Land Fill)	☐	☐	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☐	☐
Barricades Down (After Clean-up Only)	☐	☐	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS Two many People On Vacation
Talk To Bill Young

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

[illegible]
Supervisor

UCC 002139

ASBESTOS HANDLING-CHECKLIST

DATE 12-14-85

JOB DESCRIPTION Strip Asbestos at Bldg. 149

ESTIMATED QUANTITY REMOVED 100'

LOCATION 3 / / 149 /
AREA ZONE BLDG. ETC.

CRAFTSMEN J. S. Dorsey - B. J. Skeen, [redacted] R. M. Huggett

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☒	☐	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☒

COMMENTS Finished Winterization jobs for Enviromental and moved to 149

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. A. Carter
Supervisor

UCC 002140

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/80

ASBESTOS HANDLING-CHECKLIST

DATE 12-14-85

JOB DESCRIPTION Remove Asbestos From Bldg. 80

ESTIMATED QUANTITY REMOVED There

LOCATION 1 / 1 / 80 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN Hensley, Shirkey, Clayton, O'Neal, Crookshanks and Shaffer

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS W.C. Young was told about the removal of Asbestos. He said he would not monitor. Because no one was in the bldg. on Sat.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept

UCC 002141

J. E. Shelling
Supervisor

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/81

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 2 ZONE _____ BLDG 195 UNIT _____ DATE 10-28-25

JOB DESCRIPTION Take Fab Cloth off mud + reseal

ESTIMATED LINEAL FEET REMOVED 120 JOB SUPERVISOR C.E. Davis

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS R.M. Haggett, H.D. Strickland, B.E. Leslie, G.L. Shuler

	YES	NO	N/A
Plant 514 Hygienist Notified	—	—	✓
Plant E.P. Department Notified (large jobs only)	—	—	✓
Barrier Tape Used	✓	—	—
Warning Signs Used	✓	—	—
Protective Clothing Used	✓	—	—
Coveralls Changed Daily	✓	—	—
Respirators Used	✓	—	—
Drop Cloth Used plastic on Concrete	✓	—	—
Wet Down Area	✓	—	—
Proper Disposal - (Bags to Landfill)	✓	—	—
Dumpster Sealed or Wet Down	—	—	✓
Proper Clean-up (Area Housekeeping)	✓	—	—
Barricades Down (After Clean-up Only)	✓	—	—

COMMENTS After starting job all insulation fell off in staging of column. This is why Hygienist was not notified

H.D. Carter
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002142

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 2 ZONE _____ BLDG 195 UNIT _____ DATE 10-14-85

JOB DESCRIPTION strip & Patch on 8400 Columns

ESTIMATED LINEAL FEET REMOVED _____ JOB SUPERVISOR L.A. Carter

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS J.L. Cline

D.E. Ricks

	YES	NO	N/A
Plant 514 Hygienist Notified	—	✓	—
Plant E.P. Department Notified (large jobs only)	—	—	✓
Barrier Tape Used	✓	—	—
Warning Signs Used	✓	—	—
Protective Clothing Used	✓	—	—
Coveralls Changed Daily	✓	—	—
Respirators Used	✓	—	—
Drop Cloth Used	✓	—	—
Wet Down Area	✓	—	—
Proper Disposal - (Bags to Landfill)	✓	—	—
Dumpster Sealed or Wet Down	—	—	✓
Proper Clean-up (Area Housekeeping)	✓	—	—
Barricades Down (After Clean-up Only)	✓	—	—

COMMENTS Safety Dept. Did not answer phone

L A Carter
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002143

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 3 ZONE _____ BLDG 134 UNIT _____ DATE 10-14-85

JOB DESCRIPTION Strip Asbestos off of Steam Line & Replace

ESTIMATED LINEAL FEET REMOVED 40' JOB SUPERVISOR L.A. Carter

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS R.M. Huggett P.J. Allen

	YES	NO	N/A
Plant 514 Hygienist Notified	—	✓	—
Plant E.P. Department Notified (large jobs only)	—	✓	✓
Barrier Tape Used	✓	—	—
Warning Signs Used	✓	—	—
Protective Clothing Used	✓	—	—
Coveralls Changed Daily	✓	—	—
Respirators Used	✓	—	—
Drop Cloth Used	✓	—	—
Wet Down Area	✓	—	—
Proper Disposal - (Bags to Landfill)	✓	—	—
Dumpster Sealed or Wet Down	—	—	✓
Proper Clean-up (Area Housekeeping)	✓	—	—
Barricades Down (After Clean-up Only)	✓	—	—

COMMENTS Safety Dept. Did not answer phone

L A Carter
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002144

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 2 ZONE _____ BLDG 195 UNIT _____ DATE 10-12-85

JOB DESCRIPTION Strip Asbestos off of Line

ESTIMATED LINEAL FEET REMOVED 200' JOB SUPERVISOR L.A. Carter

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS G.R. Woods, J.S. Dorsey, J.F. Adams, G.L. Shuler

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)			✓
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used plastic over grating	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS Safety Dept. DID NOT MONITOR

R.A. Carter
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002145

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 2 ZONE _____ BLDG 195 UNIT _____ DATE 10-11-85

JOB DESCRIPTION Take Fab cloth off of 8400 Column and reseal 2nd level

ESTIMATED LINEAL FEET REMOVED _____ JOB SUPERVISOR L.A. Carter

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS J.L. Cline, T.R. Burns G.R. Woods,

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)			✓
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used plastic overgrading	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS Safety Dept. DID NOT Monitor

Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

Union Carbide trial exhibit UC-2283: Asbestos Handling and Asbestos Removal/Disposal Checklists for Insulation… Published by AsbestosClaims.Law
ACL Doc 17275 · Page 86 of 145 asbestosclaims.law/library/17275/86

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 3 ZONE _____ BLDG 208 UNIT _____ DATE 10-11-85

JOB DESCRIPTION Stripped 2nd layer of Column

ESTIMATED LINEAL FEET REMOVED 150' JOB SUPERVISOR L.A. Carter

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS J.S. Dorsey - J.L. Cline

T.R. Burns - G.L. Sluter

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)		✓	
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used Plastic overgrading	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS Safety Dept. did Monitor

L.A. Carter
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002147

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 3 ZONE _____ BLDG 208 UNIT _____ DATE 10-10-85

JOB DESCRIPTION Stripped 1st Layer of insulation
Will Strip 2nd Layer 10-11-85

ESTIMATED LINEAL FEET REMOVED 150' JOB SUPERVISOR L. A. Carter

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS A.L. Davis, J.F. Adams
R.M. Huggett, C.R. Woods

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)			✓
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used Plastic on grating	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down	✓		
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS Safety Dept. Did Not Monitor

L A Carter
Form filled by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002148

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 3 ZONE _____ BLDG 208 UNIT _____ DATE 10-10-85

JOB DESCRIPTION Strip Residue Line 2nd Level

ESTIMATED LINEAL FEET REMOVED 30' JOB SUPERVISOR L.A. Carter

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS R.M. Haggett & P.J. Allen

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)		✓	
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used	✓		
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS Did Monitor By Safety Dept.

L.A. Carter
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002149

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA I ZONE B BLDG 42 UNIT AA DATE 5-8-85

JOB DESCRIPTION STRIP ASBESTOS PIPE COVERING 2" LINE BY 10'

ESTIMATED LINEAL FEET REMOVED 10' JOB SUPERVISOR M.E. KNOPP C.A. Childress

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS H. White ; JA. Hudson

	YES	NO	N/A
Plant 514 Hygienist Notified	X		
Plant E.P. Department Notified (large jobs only)			X
Barrier Tape Used	X		
Warning Signs Used	X		
Protective Clothing Used	X		
Coveralls Changed Daily	X		
Respirators Used	X		
Drop Cloth Used			X
Wet Down Area	X		
Proper Disposal - (Bags to Landfill)	X		
Dumpster Sealed or Wet Down			X
Proper Clean-up (Area Housekeeping)	X		
Barricades Down (After Clean-up Only)	X		

COMMENTS JOB TOO SMALL TO MONITOR

M.E. Knopp
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002150

ASBESTOS HANDLING-CHECKLIST

DATE 3-27-85

JOB DESCRIPTION Remove wall partition

ESTIMATED QUANTITY REMOVED 4' x 8' x 3" sheet

LOCATION 5 / B / 303 Lab Workspace
AREA ZONE BLDG. ETC.

CRAFTSMEN D.C. Smith, P.M. Short

	N/A	Yes	No
Barrier Tape Used	☑	☐	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☑	☐	☐
Wet Down Area	☑	☐	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☐	☑

COMMENTS Could not find anyone to notify before I started job

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

D. E. Carmon
Supervisor

UCC 002151

ASBESTOS HANDLING-CHECKLIST

DATE 3-21-85

JOB DESCRIPTION Strip & Remove insulation on 12" pipe
Turnover Area

ESTIMATED QUANTITY REMOVED 3' of 3" Insulation

LOCATION 01 / A / 56 / Line 7 Area
AREA ZONE BLDG. ETC.

CRAFTSMEN T.E. Oneal, L.E. Clayton

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS Not monitored Small amount - Placed insulation in double Plastic bags —

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

T. E. Oneal
Supervisor

UCC 002152

To CRG.

ASBESTOS HANDLING-CHECKLIST

DATE 3-18-85

JOB DESCRIPTION Load Asbestos Insulation in Bags and Dumpster

ESTIMATED QUANTITY REMOVED 1 LARGE DUMPSTER

LOCATION I / A / 46-1 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN Hudson, Williams, Hensley, Dorsey

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☒	☐	☐
Dumpster Sealed or Wet Down	☐	☒	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Had to re-load and double line dumpster
Did not monitor

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002153

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/93

ASBESTOS HANDLING-CHECKLIST

DATE 3-19-85

JOB DESCRIPTION STRIP & LOAD ASBESTOS INSULATION INTO DUMPSTERS AT UPPER N/C STORAGE

ESTIMATED QUANTITY REMOVED 1 LARGE DUMPSTER

LOCATION I / UPPER N/C / / / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN HENSLEY, PORSEY, HUDSON

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☒	☐	☐
Dumpster Sealed or Wet Down ✓	☐	☒	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS DOUBLE SEALED DUMPSTERS DID NOT MONITOR

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002154

ASBESTOS HANDLING-CHECKLIST

DATE 3-20-85

JOB DESCRIPTION Load ASBESTOS STRIPPED FROM SALVAGED TANKS AT UPPER N/C STORAGE

ESTIMATED QUANTITY REMOVED 1 LARGE DUMPSTER

LOCATION I / UPPER N/C / / /
AREA ZONE BLDG. ETC.

CRAFTSMEN DORSEY, HENSLEY

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☒	☐	☐
Dumpster Sealed or Wet Down	☐	☒	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Double Lined Dumpster Did not MONITOR

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knapp
Supervisor

UCC 002155

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/95

ASBESTOS HANDLING-CHECKLIST

DATE 3-16-85

JOB DESCRIPTION STRIP ASBESTOS FROM SALVAGED EQUIPMENT : UPPER N/C STORAGE

ESTIMATED QUANTITY REMOVED

LOCATION T / / UPPER N/C /
AREA ZONE BLDG. ETC.

CRAFTSMEN J.E. ONEAL, C.H. Hensley, A.L. DAVIS, Ron Hilgeth, J.S. Dorsey, H.G. Smith, T.E. Washington, PERSINGER, E.R. Bird, J. Cotie /

	N/A	Yes	No
Barrier Tape Used	☐	☐	☒
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☐	☒	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS DID NOT MONITOR BUT WERE NOTIFIED

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002156

ASBESTOS HANDLING-CHECKLIST

DATE _____

JOB DESCRIPTION STRIP ASBESTOS FROM SALVAGED EQUIPMENT : UPPER N/C STORAGE

ESTIMATED QUANTITY REMOVED _____

LOCATION I / N/C / UPPER N/C /
AREA ZONE BLDG. ETC.

CRAFTSMEN ONEAL, CLAYTOR, CLINE, HENSLEY, WILLIAMS, DORSEY BIRD, COTTRELL, SMITH, WASHINGTON, PERSINGER, BOOKER

	N/A	Yes	No
Barrier Tape Used — WORKED whole YARD	☐	☐	☒
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used — WHERE NEEDED	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☒	☐	☐
Dumpster Sealed or Wet Down	☐	☒	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS DID NOT MONITOR

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002157

ASBESTOS HANDLING-CHECKLIST

DATE 2-18-85

JOB DESCRIPTION Strip Insulation from 65' Line. LB misc. #4 S.B.

ESTIMATED QUANTITY REMOVED 65' x 3" Line

LOCATION ONC / A / 36 / NORTH
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN R. M. Huggett - Cline

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☐	☑
Wet Down Area	☑	☐	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☐	☑

COMMENTS This job was done on overtime No Hygienist was in plant.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

R. L. Boggard
Supervisor

UCC 002158

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/98

ASBESTOS HANDLING-CHECKLIST

DATE 11-17-84

JOB DESCRIPTION Remove ASBESTO, BLDG. 436

ESTIMATED QUANTITY REMOVED 100 Ft

LOCATION 5 / - / 436 / .
AREA ZONE BLDG. ETC.

CRAFTSMEN C.H. Hensley, J.S. Dorsey, J.E. Williams
L.E. Claytor, R.M. Hugget, W.M. Shirley and G.R. Woods

	N/A	Yes	No
Barrier Tape Used OPEN BOTH DOORS & ROPE OFF KEEP PEOPLE OUT	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☑	☐
Wet Down Area USE SPRAY CAN BEFORE REMOVAL	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping) Sweeper	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS Safety Dept. did Monitor

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Jeff Means
Supervisor

UCC 002159

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/99

ASBESTOS HANDLING-CHECKLIST

DATE 10-25-84

JOB DESCRIPTION STRIP CABLE TRAYS

ESTIMATED QUANTITY REMOVED 4' x 3/4" x 42'

LOCATION A-1 / A / SC / _____
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN J.C. ARMSTRONG ; J.A. JONES ; G.B. WYMER
B.J. PAGE ; P.G. BOSTIC

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☒	☐	☐
Dumpster Sealed or Wet Down	☐	☒	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Didn't monitor

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M.E. Knopp
Supervisor

UCC 002160

ASBESTOS HANDLING-CHECKLIST

DATE 10-24-84

JOB DESCRIPTION STRIP CABLE TRAYS

ESTIMATED QUANTITY REMOVED 4'x¾"x60'

LOCATION I / A / 56 /
AREA ZONE BLDG. ETC.

CRAFTSMEN J.A. JONES ; P.G. BOSTIC
B.J. PAGE ; G.B. WYMER

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☐	☒	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS DID NOT MONITOR

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knapp
Supervisor

UCC 002161

ASBESTOS HANDLING-CHECKLIST

DATE 10-25-84

JOB DESCRIPTION STRIP #2 EVAPORATOR

ESTIMATED QUANTITY REMOVED 42" X 10'

LOCATION I / A / 36-1 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN J. E. CLINTON
E. W. CHAMBERS

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☐	☒
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS DID NOT MONITOR

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knapp
Supervisor

UCC 002162

ASBESTOS HANDLING-CHECKLIST

DATE 10-13-84

JOB DESCRIPTION STRIP CABLE TRAYS

ESTIMATED QUANTITY REMOVED 120' x 2'

LOCATION I / A / 36 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN 10200 (P.G. Bostic) 11863 (A.C. Geyer)
11869 (G.B. Wymer)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☐	☒	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS could not monitor because of manpower

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knapp
Supervisor

UCC 002163

ASBESTOS HANDLING-CHECKLIST

DATE 10-9-84

JOB DESCRIPTION STRIP CABLE TRAYS

ESTIMATED QUANTITY REMOVED Sheets of ASBEST BOARD 2X12 X 3/4

LOCATION I / A / 36 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN J.A. Jones (11623) ; P.G. Rustic (10200)
G.B. Wymer (11869) ; A.C. Geyer (11863)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☐	☒	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist Notified But did not monitor

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. King
Supervisor

UCC 002164

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/104

ASBESTOS HANDLING-CHECKLIST

DATE 10-10-84

JOB DESCRIPTION STRIP CABLE TRAYS

ESTIMATED QUANTITY REMOVED 60' x 2 x 30"

LOCATION I / A / 36 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN J.A. JONES (11623); P.G. BOSTIC (10200)
G.B. WYMER (11849); B.J. PAGE (11203)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☐	☒	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS HYGIENIST did not MONITOR

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. [illegible]
Supervisor

UCC 002165

ASBESTOS HANDLING-CHECKLIST

DATE 10-2-84

JOB DESCRIPTION STRIP 12" WATER LINE

ESTIMATED QUANTITY REMOVED 20 LINEAR Ft. ASBESTOS PAPER

LOCATION I / B / 42-1 / _____
AREA ZONE BLDG. ETC.

CRAFTSMEN L.A. CARTER (11142)
J.A. Hudson (11248)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☐	☒
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Did not monitor JOB, ASBESTOS PAPER WITH VERY LITTLE DUST.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Krupp
Supervisor

UCC 002166

ASBESTOS HANDLING-CHECKLIST

DATE 10-3-84

JOB DESCRIPTION STRIP 2" WATER LINE

ESTIMATED QUANTITY REMOVED 30' LINEAR FT.

LOCATION I / B / TANK FARM 42-1
AREA ZONE BLDG. ETC.

CRAFTSMEN L.A. CARTER (11142)
J.A. Hudson (11248)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS NO MANPOWER TO MONITOR JOB
UNI-BESTOS MATERIAL

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002167

ASBESTOS HANDLING-CHECKLIST

DATE 8-28-84

JOB DESCRIPTION STRIP 2" STEAM LINE TO FIND LEAK

ESTIMATED QUANTITY REMOVED 5 LINEAR FT. PLUS 1 VALVE

LOCATION I / C / 303-1 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN C.H. Hensley - 2928

J.R. Rice - 11691

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☐	☒
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS This JOB WAS MONITORED By HENRY Jackson

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002168

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/108

ASBESTOS HANDLING-CHECKLIST

DATE 9-29-84

JOB DESCRIPTION STRIP WATER LINES

ESTIMATED QUANTITY REMOVED 20 LINEAR FT. 1½" PIPE COVERING

LOCATION T / A / 36 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN A. C. FISHMAN 11340

J. E. ONGLE 11148

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☐	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☐

COMMENTS DID NOT MONITOR, HYGIENIST ON OTHER JOBS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. [illegible]
Supervisor

UCC 002169

ASBESTOS HANDLING-CHECKLIST

DATE 9-24-84

JOB DESCRIPTION STRIP 4" ASBESTOS LINE

ESTIMATED QUANTITY REMOVED 15 LINEAR FT.

LOCATION I / G / 42-1 / 1
AREA ZONE BLDG. ETC.

CRAFTSMEN J.P. Hudson 11248
T.S. DORSEY 11191

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS HYGIENIST WERE ON OTHER JOBS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

J. E. Kirby
Supervisor

UCC 002170

ASBESTOS HANDLING-CHECKLIST

DATE 9-20-84

JOB DESCRIPTION STEAM STEAM VALVE E. MAIN.

ESTIMATED QUANTITY REMOVED 3' 12" PIPE COVERING

LOCATION T / C / MPH / /
AREA ZONE BLDG. ETC.

CRAFTSMEN J.E. WILLIAMS (11155)
H. WADE (11345)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS JOB TO SMALL TO MONITOR, PART OF THE INSULATION HAD BEEN BLOWN OFF BY STEAM OR KNOCKED OFF BY OTHER CRAFTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

W. E. Knapp
Supervisor

UCC 002171

ASBESTOS HANDLING-CHECKLIST

DATE 9-19-84

JOB DESCRIPTION [illegible] STEAM [illegible] FR. TOP OF BLDG. 309

ESTIMATED QUANTITY REMOVED 10 LINEAR FT. OF 6" [illegible]

LOCATION I / C / 309 / [illegible]
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN [illegible]
J.A Hudson (1248)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☐	☒
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist was notified but due to manpower this job was not attended. Aprx 5" water standing on roof of Bldg.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. [illegible]
Supervisor

UCC 002172

ASBESTOS HANDLING-CHECKLIST

DATE 9-12-84

JOB DESCRIPTION STRIP 6" WATER LINE Bldg. 5

ESTIMATED QUANTITY REMOVED 12' 6 X 1/2" UNI-BESTOS

LOCATION I / B / 5 /
AREA ZONE BLDG. ETC.

CRAFTSMEN J.E. WILLIAMS (11155)
H. White (11345)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist tied up on BIGGER JOBS WILL NOT BE MONITORED.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

W. E. Knopp
Supervisor

UCC 002173

ASBESTOS HANDLING-CHECKLIST

DATE 9-11-84

JOB DESCRIPTION STRIP 12" WATER VALVE AND FLANGE

ESTIMATED QUANTITY REMOVED 12 LINEAR FT.

LOCATION I / B / 42-1 /
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN J. E. WILLIAMS
H. WHITE

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☐	☒
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS This JOB WAS MONITORED. THREE types OF INSULATION WAS REMOVED. UNI-BESTOS; HAIR FELT AND REGULAR ASBESTOS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knapp
Supervisor

UCC 002174

ASBESTOS HANDLING-CHECKLIST

DATE 9-6-84

JOB DESCRIPTION STRIP ASBESTOS FROM 1" WATER LINE

ESTIMATED QUANTITY REMOVED 2 LINEAL FEET

LOCATION I / C / 314-2 /
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN J. E. WILLIAMS
H. White

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS JOB WAS MONITORED BY HYGIENIST

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002175

ASBESTOS HANDLING-CHECKLIST

DATE 7-5-84

JOB DESCRIPTION STRIP 6 FT. OF 4" LINE

ESTIMATED QUANTITY REMOVED 6 FT. 4" TRACED LINE.

LOCATION I / C / 323 / ETC.
AREA ZONE BLDG.

CRAFTSMEN L.A. CARTER ; J.A. Hudson

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☐	☒
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS JOB WAS TOO SMALL TO BE MONITORED
ENDS WERE SEALED.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002176

ASBESTOS HANDLING-CHECKLIST

DATE 8-24-84

JOB DESCRIPTION Strip Insulation from (3) Lines

ESTIMATED QUANTITY REMOVED 30'

LOCATION 01 / A / 75 North Roadway /
AREA ZONE BLDG. ETC.

CRAFTSMEN J. E. Oneal, S. M. Crookshanks

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☐	☒

COMMENTS Called Hygienist did not monitor

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

R. L. Boggan
Supervisor

UCC 002177

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/117

ASBESTOS HANDLING-CHECKLIST

DATE 8-15-84

JOB DESCRIPTION STRIP ASBESTOS COVERED LINE

ESTIMATED QUANTITY REMOVED 10' OF 3"

LOCATION AREA I / "B" / 42-1 / 2172
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN C. H. HENSLEY (2928)
J. E. WILLIAMS (11155)

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☐	☒
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS JOB WAS TOO SMALL & OUTSIDE, SO HYGIENIST DID NOT MONITOR

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002178

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/118

ASBESTOS HANDLING-CHECKLIST

DATE 6-19-84

JOB DESCRIPTION Strip insulation around flanges so P.F. can put in blanks

ESTIMATED QUANTITY REMOVED 3'

LOCATION 1 / B / 42 / #2 Kettle
AREA ZONE BLDG. ETC.

CRAFTSMEN S.M. Crookshank 10463 J.E. O'Neal 11148
H. White 11345

	N/A	Yes	No	
Barrier Tape Used	☐	☒	☐	
Warning Signs Used	☐	☒	☐	
Protective Clothing Used	☐	☒	☐	
Coveralls Changed Daily	☐	☒	☐	
Respirators Used	☐	☒	☐	
Drop Cloth Used	☐	☒	☐	plastic
Wet Down Area	☐	☒	☐	
Proper Disposal - (Bags to Land Fill)	☐	☒	☐	
Dumpster Sealed or Wet Down	☒	☐	☐	
Proper Clean-up (Area Housekeeping)	☐	☒	☐	
Barricades Down (After Clean-up Only)	☐	☒	☐	
Plant 514 Hygienist Notified	☐	☒	☐	

COMMENTS Plant 514 Hygienist Notified. MR. Young said he would not monitor.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

S.A. Carter
Supervisor

UCC 002179

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA I ZONE A BLDG 36-1 UNIT _____ DATE 5-18-84

JOB DESCRIPTION STRIP 40 Ft. ASBESTON INSULATION 1½" COVERING

ESTIMATED LINEAL FEET REMOVED 40' JOB SUPERVISOR M. E. Knopp

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS L.A. CARTER, K.D. PECK J.A Hudson

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)			✓
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used		✓	
Wet Down Area	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS Job could not be completed. When a scaffold is built the remainder of the insulation is to be removed.

M. E. Knopp
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002180

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA I ZONE A BLDG LOWER BRIDGE UNIT _____ DATE 3-17-84

JOB DESCRIPTION STRIP 8" LINE CROSSING LOWER BRIDGE TO Bldg. 75

ESTIMATED LINEAL FEET REMOVED 500' JOB SUPERVISOR M.E. Knopp

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS D.L. Hively, C.H. Hensley, J.S. Dorsey, R.L. Price, J. Jones, L.E. Clayton

	YES	NO	N/A
Plant 514 Hygienist Notified	X		
Plant E.P. Department Notified (large jobs only)	X		
Barrier Tape Used	X		
Warning Signs Used	X		
Protective Clothing Used	X		
Coveralls Changed Daily	X		
Respirators Used	X		
Drop Cloth Used	X		
Wet Down Area	X		
Proper Disposal - (Bags to Landfill)	X		
Dumpster Sealed or Wet Down			X
Proper Clean-up (Area Housekeeping)	X		
Barricades Down (After Clean-up Only)	X		

COMMENTS JOB WAS MONITORED BY Young + Jackson

M.E. Knopp
Form filed by

Copies

1. **Area Safety File**
2. **W. C. Young - Safety Dept.**
3. **B. P. Johnson - Trucking**

Union Carbide trial exhibit UC-2283: Asbestos Handling and Asbestos Removal/Disposal Checklists for Insulation… Published by AsbestosClaims.Law
ACL Doc 17275 · Page 121 of 145 asbestosclaims.law/library/17275/121

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA I ZONE A BLDG Lower Bridge UNIT _____ DATE 3-24-84

JOB DESCRIPTION STRIP ASBESTOS INSULATION FROM 106-21 LINE ON LOWER BRIDGE TO Bldg. 75.

ESTIMATED LINEAL FEET REMOVED 500' JOB SUPERVISOR M.E. Knopp

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS _____

	YES	NO	N/A
Plant 514 Hygienist Notified	X		
Plant E.P. Department Notified (large jobs only)	X		
Barrier Tape Used	X		
Warning Signs Used	X		
Protective Clothing Used	X		
Coveralls Changed Daily	X		
Respirators Used	X		
Drop Cloth Used	X		
Wet Down Area	X		
Proper Disposal - (Bags to Landfill)	X		
Dumpster Sealed or Wet Down			X
Proper Clean-up (Area Housekeeping)	X		
Barricades Down (After Clean-up Only)	X		

COMMENTS The first part of this job was monitored the week-end of 3-17-84, it was determined that the reading was so low, Mr. Bill Young decided not to monitor again.

M.E. Knopp A-I Insulator Supervisor
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

UCC 002182

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/122

ASBESTOS HANDLING-CHECKLIST

DATE 3-12-84

JOB DESCRIPTION STRIP 1" LINE

ESTIMATED QUANTITY REMOVED 6" OF 1" LINE

LOCATION I / A / 46-1 / RESTROOM
AREA ZONE BLDG. ETC.

CRAFTSMEN L.A. CARTER, J.A. Hudson

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☐	☒
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☒
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist said job was too small to get a reading.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002183

ASBESTOS HANDLING-CHECKLIST

DATE 3-3-84

JOB DESCRIPTION STRIP STACK ON MAINLAND POWERHOUSE

ESTIMATED QUANTITY REMOVED 2500 SQ. FT.

LOCATION I / B / MPH 571
AREA ZONE BLDG. ETC.

CRAFTSMEN D.M. FLESHMAN ; J.E ONEAL
S.M. CROOKSHANK

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☐	☑
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☑	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS Hygienist notified & monitored job, Dumpster lined with plastic, covered & sealed

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knapp
Supervisor

UCC 002184

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/124

ASBESTOS HANDLING-CHECKLIST

DATE 2/23/84

JOB DESCRIPTION STRIP 4" LINE FOR REPAIRS

ESTIMATED QUANTITY REMOVED 100 FT 4X1 COVERING

LOCATION I / A / 36 / PIPE RACK
AREA ZONE BLDG. ETC.

CRAFTSMEN J.E. WILLIAMS ; J.A. HUDSON ; L.A. CARTER

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used ← PLASTIC ON GRATING	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS GRATING WAS COVERED BY PLASTIC SO THAT INSULATION COULDN'T GET TO SEWER

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002185

ASBESTOS HANDLING-CHECKLIST

DATE 2-17-84

JOB DESCRIPTION STRIP TANK 2nd FLOOR

ESTIMATED QUANTITY REMOVED Approx. 35 sq. Ft.

LOCATION I / A / 36-2 /
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN J. E. WILLIAMS -11155
J. A. HUDSON -11248

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☐	☒
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS INSULATION WAS WET DOWN AND DISPOSED OF IN PLASTIC BAGS, DUST MASK WERE USED.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knapp
Supervisor

UCC 002186

ASBESTOS HANDLING-CHECKLIST

DATE 2-8-83

JOB DESCRIPTION STRIP INSULATION FROM TANK AT 303-1 WEST END

ESTIMATED QUANTITY REMOVED 12 sq. FT.

LOCATION I / C / 303-1 / WEST DOCK
AREA ZONE BLDG. ETC.

CRAFTSMEN L.A. CARTER ; J.E. WILLIAMS

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☒
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS INSULATION WAS WET & FALLING OFF, REMOVED to REPLACE WITH NON-ASBESTOS INSULATION. MONITORED by W.C. Young.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002187

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/127

ASBESTOS HANDLING-CHECKLIST

DATE 2/10/84

JOB DESCRIPTION STRIP INSULATION FROM 1" WATER LINE

ESTIMATED QUANTITY REMOVED 40'-1" PIPE COVERING

LOCATION I / B / 36 / North Maint. Shop
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN L.A. CARTER, J.E. WILLIAMS

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☒	☐	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Hygienist NOTIFIED AND JOB WAS MONITORED. PROPERLY MARKED BAGS WERE USED.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

M. E. Knopp
Supervisor

UCC 002188

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/128

ASBESTOS HANDLING-CHECKLIST

DATE 1-11-84

JOB DESCRIPTION Stripping Asbestos

ESTIMATED QUANTITY REMOVED 3 sq ft

LOCATION 327-811 / C / 309 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN J E Oneal

	N/A	Yes	No
Barrier Tape Used Had guard at door	☐	☐	☑
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☐	☑
Wet Down Area	☑	☐	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☐	☑
Plant 514 Hygienist Notified	☐	☑	☐

COMMENTS

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

S. A. Carter
Supervisor

UCC 002189

Terry, for your information Jock

ASBESTOS HANDLING-CHECKLIST

DATE 12-9-83

JOB DESCRIPTION Strip Steam Line for Silicone II Shop heater

ESTIMATED QUANTITY REMOVED 15' of 4" Pipe

LOCATION 5 / / 430 / Shop
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN L. A. Carter

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☒	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS W. C. Young Monitored this job

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

R. L. Boggess
Supervisor

UCC 002190

ASBESTOS HANDLING-CHECKLIST

DATE 11-28-83

JOB DESCRIPTION 1/2" Steam Value in office to heater Leaking removed Insulation

ESTIMATED QUANTITY REMOVED 6" of 1/2" Insulation

LOCATION 1 / A / 46-1 / office
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN C.R. Dixon

	N/A	Yes	No
Barrier Tape Used	X		
Warning Signs Used			
Protective Clothing Used		X	
Coveralls Changed Daily		X	
Respirators Used		X	
Drop Cloth Used		X	
Wet Down Area Insulation Saturated	X		
Proper Disposal - (Bags to Land Fill)		X	
Dumpster Sealed or Wet Down	X		
Proper Clean-up (Area Housekeeping)		X	
Barricades Down (After Clean-up Only)		X	
Plant 514 Hygienist Notified		X	

COMMENTS Notified Hygenist Small amount to be Striped did not monitor. (BK)

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

R. L. Boggen
Supervisor

UCC 002191

ASBESTOS HANDLING-CHECKLIST

DATE 11-2-83

JOB DESCRIPTION Strip Asbestos Insulation from Line that has been removed from Service

ESTIMATED QUANTITY REMOVED 4pc. 40' - 3" pipe covering

LOCATION 1 / C / 303 / Platform
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN L.E. Claytor, J.S. Dorsey

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☒	☐
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☐	☐	☒
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Samples taken by plant hygienist —

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L. L. Boggess
Supervisor

UCC 002192

ASBESTOS HANDLING-CHECKLIST

DATE 10-24-83

JOB DESCRIPTION Remove Asbestos Insulation from 3" steam line in tunnel

ESTIMATED QUANTITY REMOVED 20'

LOCATION 1 / C / 303 / (AREA / ZONE / BLDG. / ETC.)

CRAFTSMEN J.E. Williams, M.E. Knapp, J.S. Darsey

	N/A	Yes	No
Barrier Tape Used	☐	☒	☐
Warning Signs Used	☐	☒	☐
Protective Clothing Used	☐	☒	☐
Coveralls Changed Daily	☐	☒	☐
Respirators Used	☐	☒	☐
Drop Cloth Used	☐	☐	☒
Wet Down Area	☐	☒	☐
Proper Disposal - (Bags to Land Fill)	☐	☒	☐
Dumpster Sealed or Wet Down	☐	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☒	☐
Barricades Down (After Clean-up Only)	☐	☒	☐
Plant 514 Hygienist Notified	☐	☒	☐

COMMENTS Safety Dept. was notified and a monitor was used while the stripping was performed.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

Matt Hedman
Supervisor

UCC 002193

10-17-83 Terry, This job was monitored by the Safety Dept. Jock

ASBESTOS HANDLING-CHECKLIST

DATE 10-17-83

JOB DESCRIPTION Strip Tank 9612/26 to find Leak

ESTIMATED QUANTITY REMOVED App. Nine Square Feet

LOCATION 01 (AREA) / A (ZONE) / 36 (BLDG.) / North Roadway (ETC.)

CRAFTSMEN L.A. Carter, H. White, C.R. Dixon, M.E. Knopp

		N/A	Yes	No
Barrier Tape Used		[ ]	[X]	[ ]
Warning Signs Used		[ ]	[X]	[ ]
Protective Clothing Used		[ ]	[X]	[ ]
Coveralls Changed Daily		[ ]	[X]	[ ]
Respirators Used		[ ]	[X]	[ ]
Drop Cloth Used		[X]	[ ]	[ ]
Wet Down Area		[ ]	[X]	[ ]
Proper Disposal - (Bags to Land Fill)		[ ]	[X]	[ ]
Dumpster Sealed or Wet Down	*1	[ ]	[ ]	[ ]
Proper Clean-up (Area Housekeeping)		[ ]	[X]	[ ]
Barricades Down (After Clean-up Only)		[ ]	[X]	[ ]
Plant 514 Hygienist Notified	*2	[ ]	[X]	[ ]

COMMENTS *1 Used Plastic Bags with Asbestos Warning.
*2 William Young notified.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

R. L. Boggess
Supervisor

UCC 002194

Published by AsbestosClaims.Law
asbestosclaims.law/library/17275/134

[redacted]

ASBESTOS HANDLING-CHECKLIST

DATE 10-11-83

JOB DESCRIPTION Strip Value and about 2' of Line.

ESTIMATED QUANTITY REMOVED 4 Sq. Ft.

LOCATION 01 (AREA) / C (ZONE) / 303 (BLDG.) / Drum Bay (ETC.)

CRAFTSMEN H. White, L. A Carter

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☐	☑
Wet Down Area	☐	☑	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☐	☐	☑
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	*☑	☐

COMMENTS [redacted]

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

R. L. Bogard
Supervisor

UCC 002195

ASBESTOS HANDLING-CHECKLIST

DATE 9-22-83

JOB DESCRIPTION Strip Insulation from top of #1 Reactor.

ESTIMATED QUANTITY REMOVED 45 sq. ft.

LOCATION 01 (AREA) / B (ZONE) / 36 (BLDG.) / East (ETC.)

CRAFTSMEN J. S. Dorsey, J.A. Hudson, J.E. Williams, H. White

		N/A	Yes	No
Barrier Tape Used		☐	☑	☐
Warning Signs Used		☐	☑	☐
Protective Clothing Used		☐	☑	☐
Coveralls Changed Daily		☐	☑	☐
Respirators Used		☐	☑	☐
Drop Cloth Used		☐	☐	☑
Wet Down Area		☐	☐	☐
Proper Disposal - (Bags to Land Fill)	*1	☐	☐	☑
Dumpster Sealed or Wet Down	*2	☐	☐	☐
Proper Clean-up (Area Housekeeping)		☐	☑	☐
Barricades Down (After Clean-up Only)		☐	☑	☐
Plant 514 Hygienist Notified		☑	☐	☐

COMMENTS *1 Material Saturated with water

*2 Used Properly Marked Plastic Bags

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

R. L. Boggess
Supervisor

UCC 002196

ASBESTOS HANDLING-CHECKLIST

DATE 8-17-83

JOB DESCRIPTION Cut windows in Insulation on #1 RX for Tank Inspection

ESTIMATED QUANTITY REMOVED 10 Sq. Ft.

LOCATION 01 (AREA) / A (ZONE) / 36 (BLDG.) / EAST (ETC.)

CRAFTSMEN J. S. Dorsey - J. E. ONeal

		N/A	Yes	No
Barrier Tape Used		[ ]	[X]	[ ]
Warning Signs Used		[ ]	[X]	[ ]
Protective Clothing Used		[ ]	[X]	[ ]
Coveralls Changed Daily		[ ]	[X]	[ ]
Respirators Used		[ ]	[X]	[ ]
Drop Cloth Used		[ ]	[ ]	[X]
Wet Down Area		[ ]	[X]	[ ]
Proper Disposal - (Bags to Land Fill)		[ ]	[X]	[ ]
Dumpster Sealed or Wet Down	*	[ ]	[ ]	[ ]
Proper Clean-up (Area Housekeeping)		[ ]	[X]	[ ]
Barricades Down (After Clean-up Only)		[ ]	[X]	[ ]
Plant 514 Hygienist Notified		[ ]	[ ]	[X]

COMMENTS Used Properly marked Plastic Bags.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

R. L. Boggess 2172
Supervisor

UCC 002197

ASBESTOS HANDLING-CHECKLIST

DATE 6-19-84

JOB DESCRIPTION Strip insulation around flanges so P.E. can put in blanks

ESTIMATED QUANTITY REMOVED 3'

LOCATION 1 / B / 42 / #2 Kettle
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN S.M. Crookshank 10463 J.E. O'Neal 11148
H. White 11345

	N/A	Yes	No	
Barrier Tape Used	☐	☒	☐	
Warning Signs Used	☐	☒	☐	
Protective Clothing Used	☐	☒	☐	
Coveralls Changed Daily	☐	☒	☐	
Respirators Used	☐	☒	☐	
Drop Cloth Used	☐	☒	☐	plastic
Wet Down Area	☐	☒	☐	
Proper Disposal - (Bags to Land Fill)	☐	☒	☐	
Dumpster Sealed or Wet Down	☒	☐	☐	
Proper Clean-up (Area Housekeeping)	☐	☒	☐	
Barricades Down (After Clean-up Only)	☐	☒	☐	
Plant 514 Hygienist Notified	☐	☒	☐	

COMMENTS Plant 514 Hygienist Notified. MR. Young said he would not monitor.

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

L.B. Carter
Supervisor

UCC 002198

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA 3 ZONE _____ BLDG 146 UNIT _____ DATE 10-9-85

JOB DESCRIPTION Strip Asbestos off tank # 1682

ESTIMATED LINEAL FEET REMOVED 150' JOB SUPERVISOR L.A. Carter

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS G.R. Woods, A.L. Davis
J. Adams

	YES	NO	N/A
Plant 514 Hygienist Notified	✓		
Plant E.P. Department Notified (large jobs only)		✓	
Barrier Tape Used	✓		
Warning Signs Used	✓		
Protective Clothing Used	✓		
Coveralls Changed Daily	✓		
Respirators Used	✓		
Drop Cloth Used Plastic over gravel	✓		
Wet Down Area washed down after stripped	✓		
Proper Disposal - (Bags to Landfill)	✓		
Dumpster Sealed or Wet Down			✓
Proper Clean-up (Area Housekeeping)	✓		
Barricades Down (After Clean-up Only)	✓		

COMMENTS Trucking Picked up bags at 6:55 P
10-9-85

L.A. Carter
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002199

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA I ZONE C BLDG 303 UNIT Drumming DATE ? 8-21-85

JOB DESCRIPTION STRIP 2X1 pipe COVERING

ESTIMATED LINEAL FEET REMOVED 10' JOB SUPERVISOR M. E. Knopp

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS Williams, White, SHAFFER

	YES	NO	N/A
Plant 514 Hygienist Notified	X		
Plant E.P. Department Notified (large jobs only)		X	
Barrier Tape Used	X		
Warning Signs Used	X		
Protective Clothing Used	X		
Coveralls Changed Daily	X		
Respirators Used	X		
Drop Cloth Used			X
Wet Down Area	X		
Proper Disposal - (Bags to Landfill)	X		
Dumpster Sealed or Wet Down			X
Proper Clean-up (Area Housekeeping)	X		
Barricades Down (After Clean-up Only)	X		

COMMENTS Job was too small to get a MONITOR READING

M. E. Knopp
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002200

ASBESTOS HANDLING-CHECKLIST

DATE 1-15-85

JOB DESCRIPTION [illegible]

ESTIMATED QUANTITY REMOVED [illegible]

LOCATION ONC / A / 36 / NORTH
AREA / ZONE / BLDG. / ETC.

CRAFTSMEN [illegible] - ONC

	N/A	Yes	No
Barrier Tape Used	☐	☑	☐
Warning Signs Used	☐	☑	☐
Protective Clothing Used	☐	☑	☐
Coveralls Changed Daily	☐	☑	☐
Respirators Used	☐	☑	☐
Drop Cloth Used	☐	☐	☑
Wet Down Area	☑	☐	☐
Proper Disposal - (Bags to Land Fill)	☐	☑	☐
Dumpster Sealed or Wet Down	☑	☐	☐
Proper Clean-up (Area Housekeeping)	☐	☑	☐
Barricades Down (After Clean-up Only)	☐	☑	☐
Plant 514 Hygienist Notified	☐	☐	☑

COMMENTS [illegible]

Routing
1. Area Safety File
2. W. C. Young - Safety Dept.

[illegible]
Supervisor

UCC 002201

DAY 1

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA I ZONE A BLDG 36- UNIT OXIDE DATE 5-21-85

JOB DESCRIPTION STRIP ASBESTOS INSULATION FROM TANK 9612/22

ESTIMATED LINEAL FEET REMOVED 11½ FT OD By 47' high JOB SUPERVISOR M. E. Knopp

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS John ONEAL; Jim Williams; Judy Hudson; Susie Strickland; Janice Coiner;

	YES	NO	N/A
Plant 514 Hygienist Notified	X	—	—
Plant E.P. Department Notified (large jobs only)	X	—	—
Barrier Tape Used	X	—	—
Warning Signs Used	X	—	—
Protective Clothing Used	X	—	—
Coveralls Changed Daily	X	—	—
Respirators Used	X	—	—
Drop Cloth Used	—	—	X
Wet Down Area	X	—	—
Proper Disposal - (Bags to Landfill)	X	—	—
Dumpster Sealed or Wet Down	—	—	X
Proper Clean-up (Area Housekeeping)	X	—	—
Barricades Down (After Clean-up Only)	AFTER JOB IS completed		

COMMENTS Labors GIVEN ASBESTOS SAFETY REVIEW.

M. E. Knopp: Supervisor
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

Union Carbide trial exhibit UC-2283: Asbestos Handling and Asbestos Removal/Disposal Checklists for Insulation… Published by AsbestosClaims.Law
ACL Doc 17275 · Page 142 of 145 asbestosclaims.law/library/17275/142

DAY 2

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA I ZONE B BLDG 36- UNIT OXIDE Addn DATE 5-22-85

JOB DESCRIPTION STRIP ASBESTON FROM TK 9612/22

ESTIMATED LINEAL FEET REMOVED 12'OD X 4? TK JOB SUPERVISOR M.E. Knopp

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS H. White, T. Williams, J. Hudson
L. Claytor, J. ONEAL, J. Colner, H. Johnson

	YES	NO	N/A
Plant 514 Hygienist Notified	X	—	—
Plant E.P. Department Notified (large jobs only)	X	—	—
Barrier Tape Used	X	—	—
Warning Signs Used	X	—	—
Protective Clothing Used	X	—	—
Coveralls Changed Daily	X	—	—
Respirators Used	X	—	—
Drop Cloth Used	—	—	X
Wet Down Area	X	—	—
Proper Disposal - (Bags to Landfill)	X	—	—
Dumpster Sealed or Wet Down	—	—	X
Proper Clean-up (Area Housekeeping)	X	—	—
Barricades Down (After Clean-up Only)	when Job is completed		

COMMENTS LABORS GIVEN ASBESTOS SAFETY REVIEW

M. E. Knopp, Super.
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002203

DAY 3

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA I ZONE B BLDG 36-1 UNIT OXIDE ADDUCTS DATE 5-23-85

JOB DESCRIPTION STRIP ASBESTOS FROM TK 9612/22

ESTIMATED LINEAL FEET REMOVED 47' High 11½' OD JOB SUPERVISOR M. E. Knopp

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS J. WILLIAMS, J. ONEAL, J. Hudson J. Coiner, H. White, L. Clayton, SHAFFER

	YES	NO	N/A
Plant 514 Hygienist Notified	X	—	—
Plant E.P. Department Notified (large jobs only)	X	—	—
Barrier Tape Used	X	—	—
Warning Signs Used	X	—	—
Protective Clothing Used	X	—	—
Coveralls Changed Daily	X	—	—
Respirators Used	X	—	—
Drop Cloth Used	—	—	X
Wet Down Area	X	—	—
Proper Disposal - (Bags to Landfill)	X	—	—
Dumpster Sealed or Wet Down	—	—	X
Proper Clean-up (Area Housekeeping)	X	—	—
Barricades Down (After Clean-up Only)	X	—	—

COMMENTS LABORS GIVEN ASBESTOS SAFETY REVIEW

M. E. Knopp
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002204

MAINTENANCE CHECKLIST FOR ASBESTOS REMOVAL/DISPOSAL

AREA I ZONE B BLDG 36-1 UNIT _____ DATE 5-24-85

JOB DESCRIPTION STRIP ASBESTOS IK 9612 122

ESTIMATED LINEAL FEET REMOVED _____ JOB SUPERVISOR M. E. Knopp

NAMES OF PEOPLE INVOLVED IN ACTUAL JOBS Hudson, Williams, Clator White

	YES	NO	N/A
Plant 514 Hygienist Notified	X	—	—
Plant E.P. Department Notified (large jobs only)	X	—	—
Barrier Tape Used	X	—	—
Warning Signs Used	X	—	—
Protective Clothing Used	X	—	—
Coveralls Changed Daily	X	—	—
Respirators Used	X	—	—
Drop Cloth Used	—	—	X
Wet Down Area	X	—	—
Proper Disposal - (Bags to Landfill)	X	—	—
Dumpster Sealed or Wet Down	—	—	X
Proper Clean-up (Area Housekeeping)	X	—	—
Barricades Down (After Clean-up Only)	X	—	—

COMMENTS MINOR CLEANUP REMAINS, WILL NOT USED BORROWED LABORS to FINISH the JOB. LABORS WERE ADVISED OF SAFETY RULES FOR ASBESTOS. JOB COMPLETED 5-24-85

M. E. Knopp
Form filed by

Copies

1. Area Safety File
2. W. C. Young - Safety Dept.
3. B. P. Johnson - Trucking

April 1984

UCC 002205