PLAINTIFF'S EXHIBIT

UC-2355

PROCEDURE FOR HANDLING AND DISPOSAL OF ASBESTOS WASTE FROM THE SOUTH CHARLESTON PLANT

All asbestos waste leaving the plant must be hauled to Goff Mountain disposal site in the proper individual marked containers (dust proof polyethylene bags with all OSHA specified warnings printed thereon).

The truck drivers must have in their possession a properly filled-out manifest as prescribed by RCRA. The truck bed will be covered to avoid asbestos fibers from being dispensed to the atmosphere.

Specific large truck beds will be used in hauling asbestos waste outside the plant to Goff Mountain; however, other types and sizes of waste containers can be used to collect asbestos waste within the plant and then transfer to the larger (15 to 20 Cu Yd) bed south of building 251. The manifest will be issued by the trucking function of the Maintenance Department and approved by E.P.D.

From Conversation - w/ Lynn Phair 6/17/82

need! Asbestos Handling

1. audits ?
2. Follow-up ?
3. frequency ?

BPJ
7/29/80

UCC 003288