FILE COPY
UNION CARBIDE

INTERNAL
CORRESPONDENCE

FILE C

PLAINTIFF'S EXHIBIT
UC-2681

UNION CARBIDE CORPORATION TECHNICAL CENTER
P O BOX 8361, SOUTH CHARLESTON WV 25303

W. L. Browning
J. W. Perry, Jr.
Institute Plant

October 23, 1981

IH/EP

C. W. Carman
M. L. Mills
L. R. Noble
D. R. Paugh
R. E. Peele
H. H. Frazier
R. J. Sexton, M.D.
F. Williams

Asbestos Monitoring in Gasket Shop, 512 Construction

Gentlemen:

In my letter of October 20, 1981, concerning asbestos monitoring in the Gasket Shop - 512 Construction, an error was made due to misinterpretation of the data we received from the 512 Industrial Hygiene group. Please replace the letter dated October 20, 1981 from your file with the one attached to this note.

Very truly yours,

Manhar A. Patel

Manhar A. Patel

MAP/sc

Attachment

Union Carbide trial exhibit UC-2681: M. A. Patel to W. L. Browning, J. W. Perry Jr. and Others on Asbestos Monitori... Published by AsbestosClaims.Law
ACL Doc 17615 · Page 1 of 3 asbestosclaims.law/library/17615/1

INTERNAL
CORRESPONDENCE

UNION CARBIDE CORPORATION TECHNICAL CENTER
P O BOX 8361, SOUTH CHARLESTON, WV 25303

To: W. L. Browning
From: J. W. Perry, Jr.
Location: Institute Plant

Date: October 23, 1981
Organization Code: IH/EP

Copies to: C. W. Carman
M. L. Mills
L. R. Noble
D. R. Paugh
R. E. Peele
H. H. Frazier
R. J. Sexton, M.D.
F. Williams

Subject: Asbestos Monitoring in Gasket Shop, 512 Construction

(Replaces letter of October 20, 1981 - front page only.)

Gentlemen:

Attached are the results of the area and personal exposure monitoring done for asbestos in the Gasket Shop - laundry, Building 3 of the Construction Department, Institute Plant. This monitoring was done by the Institute Plant Industrial Hygiene group on October 2, and 9, 1981.

The gasket cutting is done infrequently and it would generally last for a short period of time. The results of the survey indicate that the asbestos exposure in excess of the permissible limit of 2 fibers per centimeter cube of air did not occur.

The workers did not wear a respiratory protective device while working with the gasket material. It is emphasized that all workers wear a disposable 3M #8710 dust respirator which is approved by NIOSH for protection from asbestos exposure. Please notify the monitored workers of their exposure results.

If I can be of further assistance, please give me a call at extension 3750.

Very truly yours,

Manhar A. Patel

Manhar A. Patel

MAP/sc
Attachment

UCC 024507

BUSINESS CONFIDENTIAL

ASBESTOS MONITORING CONSTRUCTION GASKET SHOP

INSTITUTE PLANT

#	Name/Area Monitored	Date	Sampling Time Minutes	Asbestos Conc. Fibers >5 μm/cm^3
1	F. M. Hatfield	10/2/81	18	< 0.1
2	3 Feet from cutting blade	10/2/81	17	< 0.1
3	F. M. Hatfield	10/9/81	15	0.4
4	3 Feet from cutting blade	10/9/81	15	0.2

UCC 024508