WV-0234#78

ASBESTOS INSULATION REMOVAL AND DISPOSAL
CONSTRUCTION/SERVICES DEPARTMENT SUPERVISOR'S REPORT

(LOCATION OF JOB:) PLANT: 380 AREA: 7 ZONE: — BLDG: — UNIT: Bldg I

JOB SUPERVISOR: R.R. Thaxton DATE JOB PERFORMED: 1-4-88

DESCRIPTION OF JOB: Removeing asbestos from ½" Steam Lines

LOCATION ASBESTOS INSULATION DISPOSED: Sisterville Asbestos Dump

ESTIMATED FEET REMOVED: 20' LINEAL FEET _____ SQUARE FEET

EMPLOYEES INVOLVED IN ACTUAL JOB(S): R.O. Deweese

	YES	NO	N/A
Plant 511 Hygienist notified (M. A. Patel - ext. 3750)	✓	—	
Negative pressure enclosure feasible?	—	✓	—
Negative pressure enclosure installed?	—	✓	—
Use of Glove Bag feasible?	✓	—	—
Glove Bag used?	✓	—	—
Barrier tape used	✓	—	—
Warning signs used	✓	—	—
Protective clothing used - boots, head cover, gloves, coveralls	✓		
Outer coverall vacuumed before removing	✓	—	
Outer coverall removed before leaving barricaded area	✓	—	
Plastic used on floor and over equipment	✓	—	—
Area vacuumed	✓	—	—
Employee showered before reapplying street clothes	✓	—	
Proper clean-up (area housekeeping)	✓	—	—
Barricades down (after clean-up only)	✓	—	—
Employee(s) monitored by Industrial Hygiene	✓	—	—
Type of respirator used:			
Half-face AO R57-A (HEPA)	✓		
Half-face Willson R-12 (HEPA)	—		
Supplied Air-Full Face - Positive Pressure	—		
Employee trained for respirator in last 6 months (If not using Supplied Air - Positive Pressure)	✓	—	—
Employee trained for OSHA Asbestos Standard in last 12 months	✓	—	

PLAINTIFF'S EXHIBIT
UC-3050

COMMENTS: _____

R.O. Deweese Telephone : 652-3211 ex 54

(Form Filed By:)

Return filled out form (original) after completion of the job to: M. A. Patel - Bldg. 701/330

1791P

UCC 001961

Call Warren [illegible]

WV-0234 #79

ASBESTOS INSULATION REMOVAL AND DISPOSAL
CONSTRUCTION/SERVICES DEPARTMENT SUPERVISOR'S REPORT

(LOCATION OF JOB:) PLANT: 390 AREA: _____ ZONE: _____ BLDG: 411 UNIT: Poly II

JOB SUPERVISOR: R D Dawson DATE JOB PERFORMED: 10-15-87

DESCRIPTION OF JOB: Removing Asbestos from water line

LOCATION ASBESTOS INSULATION DISPOSED: Sistersville Plant Land Fill

ESTIMATED FEET REMOVED: 15- LINEAL FEET -0- SQUARE FEET

EMPLOYEES INVOLVED IN ACTUAL JOB(S): R L Hilkerding R D Dawson

	YES	NO	N/A
Plant 511 Hygienist notified (M. A. Patel - ext. 3750)	✓		
Negative pressure enclosure feasible?	—	✓	—
Negative pressure enclosure installed?	—	✓	—
Use of Glove Bag feasible?	✓	—	—
Barrier tape used	✓	—	—
Warning signs used	✓	—	—
Protective clothing used - boots, head cover, gloves, coveralls	✓		
Outer coverall vacuumed before removing	✓	—	
Outer coverall removed before leaving barricaded area	✓	—	
Plastic used on floor and over equipment	✓	—	—
Area vacuumed	✓	—	—
Employee showered before reapplying street clothes	✓	—	
Proper clean-up (area housekeeping)	✓	—	—
Barricades down (after clean-up only)	✓	—	—
Employee(s) monitored by Industrial Hygiene	✓	—	—
Type of respirator used:			
Half-face AO R57-A (HEPA)	✓		
Half-face Willson R-12 (HEPA)	—		
Supplied Air-Full Face - Positive Pressure	—		
Employee trained for respirator in last 6 months (If not using Supplied Air - Positive Pressure)	✓	—	—
Employee trained for OSHA Asbestos Standard in last 12 months	✓	—	

COMMENTS: _____

R D Dawson Telephone: 652-3211

(Form Filed By:)

Return filled out form (original) after completion of the job to: M. A. Patel - Bldg. 701/330

1791P

UCC 001962

Clark Wagner

ASBESTOS INSULATION REMOVAL AND DISPOSAL
CONSTRUCTION/SERVICES DEPARTMENT SUPERVISOR'S REPORT

(LOCATION OF JOB:) PLANT: 330 AREA: -0- ZONE: -0- BLDG: 44 UNIT: Poly II
JOB SUPERVISOR: R.D. Dewease DATE JOB PERFORMED: 10-19-87
DESCRIPTION OF JOB: Stripping Asbestos from 3" Water Line
LOCATION ASBESTOS INSULATION DISPOSED: Sisterville Plant landfill
ESTIMATED FEET REMOVED: 12' LINEAL FEET -00 SQUARE FEET
EMPLOYEES INVOLVED IN ACTUAL JOB(S): R.D. Dewease R.L. Hilverding

	YES	NO	N/A
Plant SII Hygienist notified (M. A. Patel - ext. 3750)	✓	—	
Negative pressure enclosure feasible?	—	✓	
Negative pressure enclosure installed?	—	✓	—
Use of Glove Bag feasible?	—	✓	—
Barrier tape used	✓	—	—
Warning signs used	✓	—	—
Protective clothing used - boots, head cover, gloves, coveralls	✓	—	—
Outer coverall vacuumed before removing	✓		
Outer coverall removed before leaving barricaded area	✓	—	
Plastic used on floor and over equipment	✓	—	
Area vacuumed	✓	—	—
Employee showered before reapplying street clothes	✓	—	—
Proper clean-up (area housekeeping)	✓	—	
Barricades down (after clean-up only)	✓	—	—
Employee(s) monitored by Industrial Hygiene	✓	—	—
Type of respirator used:	✓	✓	—
Half-face AO R57-A (HEPA)	✓		
Half-face Willson R-12 (HEPA)	—		
Supplied Air-Full Face - Positive Pressure	—		
Employee trained for respirator in last 6 months (If not using Supplied Air - Positive Pressure)	✓	—	—
Employee trained for OSHA Asbestos Standard in last 12 months	✓	—	

COMMENTS: 4 @ 1:00 45

R.D. Dewease Telephone : 652-2211
(Form Filed By:)

Return filled out form (original) after completion of the job to: M. A. Patel - Bldg. 701/330

1791P

UCC 001963

Call Hilverding

ASBESTOS INSULATION REMOVAL AND DISPOSAL
CONSTRUCTION/SERVICES DEPARTMENT SUPERVISOR'S REPORT

(LOCATION OF JOB:) PLANT: 380 AREA: _____ ZONE: _____ BLDG: 44 UNIT: Plant II
JOB SUPERVISOR: R D Deweese DATE JOB PERFORMED: 10-16-87
DESCRIPTION OF JOB: Removing Asbestos from 8" Vent line
LOCATION ASBESTOS INSULATION DISPOSED: Sisterville Plant Landfill
ESTIMATED FEET REMOVED: 15' LINEAL FEET ~0 SQUARE FEET
EMPLOYEES INVOLVED IN ACTUAL JOB(S): R D Deweese R L. Hilverding

	YES	NO	N/A
Plant 511 Hygienist notified (M. A. Patel - ext. 3750)	✓	✓	
Negative pressure enclosure feasible?	—	✓	—
Negative pressure enclosure installed?	—	✓	—
Use of Glove Bag feasible?	✓	—	—
Barrier tape used	✓	—	—
Warning signs used	✓	—	—
Protective clothing used - boots, head cover, gloves, coveralls	✓		
Outer coverall vacuumed before removing	✓	—	
Outer coverall removed before leaving barricaded area	✓	—	
Plastic used on floor and over equipment	✓	—	—
Area vacuumed	✓	—	—
Employee showered before reapplying street clothes	✓	—	
Proper clean-up (area housekeeping)	✓	—	—
Barricades down (after clean-up only)	✓	—	—
Employee(s) monitored by Industrial Hygiene	✓	—	—
Type of respirator used:			
Half-face AO R57-A (HEPA)	✓		
Half-face Willson R-12 (HEPA)	—		
Supplied Air-Full Face - Positive Pressure	—		
Employee trained for respirator in last 6 months (If not using Supplied Air - Positive Pressure)	✓	—	—
Employee trained for OSHA Asbestos Standard in last 12 months	✓	—	

COMMENTS: _____

R D Deweese Telephone : 652-3211
(Form Filed By:)

Return filled out form (original) after completion of the job to: M. A. Patel - Bldg. 701/330

1791P

UCC 001964

ASBESTOS INSULATION REMOVAL AND DISPOSAL

CONSTRUCTION/SERVICES DEPARTMENT SUPERVISOR'S REPORT

(LOCATION OF JOB:) PLANT: 380 AREA: -0- ZONE: -0- BLDG: 30 UNIT: -0-

JOB SUPERVISOR: R.D. Dewees DATE JOB PERFORMED: 11-4-87

DESCRIPTION OF JOB: Removing Transite Heads in Lab

LOCATION ASBESTOS INSULATION DISPOSED: 380 Plant Disposal site

ESTIMATED FEET REMOVED: _____ LINEAL FEET 10 SQUARE FEET

EMPLOYEES INVOLVED IN ACTUAL JOB(S): RL Hilverding G. Taylor G. Grant

	YES	NO	N/A
Plant 511 Hygienist notified (M. A. Patel - ext. 3750)	✓		
Negative pressure enclosure feasible?		✓	
Negative pressure enclosure installed?		✓	
Use of Glove Bag feasible?		✓	
Glove Bag used?		✓	
Barrier tape used	✓		
Warning signs used	✓		
Protective clothing used - boots, head cover, gloves, coveralls	✓		
Outer coverall vacuumed before removing	✓		
Outer coverall removed before leaving barricaded area	✓		
Plastic used on floor and over equipment	✓		
Area vacuumed	✓		
Employee showered before reapplying street clothes	✓		
Proper clean-up (area housekeeping)	✓		
Barricades down (after clean-up only)		✓	
Employee(s) monitored by Industrial Hygiene		✓	
Type of respirator used:			
Half-face AO R57-A (HEPA)	✓		
Half-face Willson R-12 (HEPA)	✓		
Supplied Air-Full Face - Positive Pressure	✓		
Employee trained for respirator in last 6 months (If not using Supplied Air - Positive Pressure)	✓		
Employee trained for OSHA Asbestos Standard in last 12 months	✓		

COMMENTS: _____

R.D. Dewees Telephone : GS2-3211

(Form Filed By:)

Return filled out form (original) after completion of the job to: M. A. Patel - Bldg. 701/330

1791P

UCC 001965

ASBESTOS INSULATION REMOVAL AND DISPOSAL

CONSTRUCTION/SERVICES DEPARTMENT SUPERVISOR'S REPORT

(LOCATION OF JOB:) PLANT: 380 AREA: -0- ZONE: -0- BLDG: 30 UNIT: -00

JOB SUPERVISOR: _____ DATE JOB PERFORMED: 11-6-87

DESCRIPTION OF JOB: Removeing Tranisite Heads from Lab

LOCATION ASBESTOS INSULATION DISPOSED: 380 Plant Disposeal Site

ESTIMATED FEET REMOVED: _____ LINEAL FEET 2½ SQUARE FEET

EMPLOYEES INVOLVED IN ACTUAL JOB(S): R. L. Hilverding G. Taylor G. Grant

	YES	NO	N/A
Plant 511 Hygienist notified (M. A. Patel - ext. 3750)	✓		
Negative pressure enclosure feasible?	—	✓	—
Negative pressure enclosure installed?	—	✓	—
Use of Glove Bag feasible?	—	✓	—
Glove Bag used?	—	✓	—
Barrier tape used	✓	—	—
Warning signs used	✓	—	—
Protective clothing used - boots, head cover, gloves, coveralls	✓		
Outer coverall vacuumed before removing	✓	—	
Outer coverall removed before leaving barricaded area	✓	—	
Plastic used on floor and over equipment	✓	—	—
Area vacuumed	✓	—	—
Employee showered before reapplying street clothes	✓	—	
Proper clean-up (area housekeeping)	✓	✓	—
Barricades down (after clean-up only)	—	✓	—
Employee(s) monitored by Industrial Hygiene	—	✓	—
Type of respirator used:			
Half-face AO R57-A (HEPA)	✓		
Half-face Willson R-12 (HEPA)	✓		
Supplied Air-Full Face - Positive Pressure	—		
Employee trained for respirator in last 6 months (If not using Supplied Air - Positive Pressure)	✓	—	—
Employee trained for OSHA Asbestos Standard in last 12 months	✓	—	

COMMENTS: _____

P. D. Donovan Telephone: 652-3211

(Form Filed By:)

Return filled out form (original) after completion of the job to: M. A. Patel - Bldg. 701/330

1791P

UCC 001966

ASBESTOS INSULATION REMOVAL AND DISPOSAL

CONSTRUCTION/SERVICES DEPARTMENT SUPERVISOR'S REPORT

(LOCATION OF JOB:) PLANT: 330 AREA: -0- ZONE: -0- BLDG: 330 UNIT: Lab

JOB SUPERVISOR: R.D. Duncan DATE JOB PERFORMED: 11-9-82

DESCRIPTION OF JOB: Removing Transite Heads from Lab

LOCATION ASBESTOS INSULATION DISPOSED: 330 Plant disposal site

ESTIMATED FEET REMOVED: ____ LINEAL FEET 12 SQUARE FEET

EMPLOYEES INVOLVED IN ACTUAL JOB(S): R.L. Hofferding G. Taylor G. Grant W.L. Bird

	YES	NO	N/A
Plant 511 Hygienist notified (M. A. Patel - ext. 3750)	✓		
Negative pressure enclosure feasible?		✓	
Negative pressure enclosure installed?		✓	
Use of Glove Bag feasible?		✓	
Glove Bag used?		✓	
Barrier tape used	✓		
Warning signs used	✓		
Protective clothing used - boots, head cover, gloves, coveralls	✓		
Outer coverall vacuumed before removing	✓		
Outer coverall removed before leaving barricaded area	✓		
Plastic used on floor and over equipment	✓		
Area vacuumed	✓		
Employee showered before reapplying street clothes	✓		
Proper clean-up (area housekeeping)	✓		
Barricades down (after clean-up only)	✓		
Employee(s) monitored by Industrial Hygiene	✓	✓	
Type of respirator used:			
Half-face AO R57-A (HEPA)	✓		
Half-face Willson R-12 (HEPA)	✓		
Supplied Air-Full Face - Positive Pressure			
Employee trained for respirator in last 6 months (If not using Supplied Air - Positive Pressure)	✓		
Employee trained for OSHA Asbestos Standard in last 12 months	✓		

COMMENTS: ____

R.D. Duncan Telephone : 652-3211 ext.

(Form Filed By:)

Return filled out form (original) after completion of the job to: M. A. Patel - Bldg. 701/330

1791P

UCC 001967

ASBESTOS INSULATION REMOVAL AND DISPOSAL

CONSTRUCTION/SERVICES DEPARTMENT SUPERVISOR'S REPORT

(LOCATION OF JOB:) PLANT: 380 AREA: 3 ZONE: -0- BLDG: -0- UNIT: Poly

JOB SUPERVISOR: R.D. Deweese DATE JOB PERFORMED: 11-17-87

DESCRIPTION OF JOB: Remove insulation from Steam Line

LOCATION ASBESTOS INSULATION DISPOSED: _____

ESTIMATED FEET REMOVED: 2 LINEAL FEET _____ SQUARE FEET

EMPLOYEES INVOLVED IN ACTUAL JOB(S): R D Deweese R.L. Hilverding

	YES	NO	N/A
Plant 511 Hygienist notified (M. A. Patel - ext. 3750)	✓		
Negative pressure enclosure feasible?	—	✓	—
Negative pressure enclosure installed?	—	✓	—
Use of Glove Bag feasible?	✓	—	—
Glove Bag used?	✓	—	—
Barrier tape used	✓	—	—
Warning signs used	✓	—	—
Protective clothing used - boots, head cover, gloves, coveralls	✓		
Outer coverall vacuumed before removing	✓	—	
Outer coverall removed before leaving barricaded area	✓	—	
Plastic used on floor and over equipment	✓	—	—
Area vacuumed	✓	—	—
Employee showered before reapplying street clothes	✓	—	
Proper clean-up (area housekeeping)	✓	—	—
Barricades down (after clean-up only)	✓	—	—
Employee(s) monitored by Industrial Hygiene	—	✓	—
Type of respirator used:			
Half-face AO R57-A (HEPA)	✓		
Half-face Willson R-12 (HEPA)	—		
Supplied Air-Full Face - Positive Pressure	—		
Employee trained for respirator in last 6 months (If not using Supplied Air - Positive Pressure)	✓	—	—
Employee trained for OSHA Asbestos Standard in last 12 months	✓	—	

COMMENTS: _____

R D Deweese Telephone: 65-3211 ex 45

(Form Filed By:)

Return filled out form (original) after completion of the job to: M. A. Patel - Bldg. 701/330

1791P

UCC 001968

ASBESTOS INSULATION REMOVAL AND DISPOSAL

CONSTRUCTION/SERVICES DEPARTMENT SUPERVISOR'S REPORT

(LOCATION OF JOB:) PLANT: 770 AREA: II ZONE: _____ BLDG: _____ UNIT: Poly-II

JOB SUPERVISOR: R. D. Deweese DATE JOB PERFORMED: 12-3-82

DESCRIPTION OF JOB: Removing Asbesta form 6" line

LOCATION ASBESTOS INSULATION DISPOSED: _____

ESTIMATED FEET REMOVED: 2 LINEAL FEET _____ SQUARE FEET

EMPLOYEES INVOLVED IN ACTUAL JOB(S): R. Hilvending L. Boddy

	YES	NO	N/A
Plant 511 Hygienist notified (M. A. Patel - ext. 3750)	✓		
Negative pressure enclosure feasible?	—	✓	—
Negative pressure enclosure installed?	—	✓	—
Use of Glove Bag feasible?	✓	—	—
Glove Bag used?	✓	—	—
Barrier tape used	✓	—	—
Warning signs used	✓	—	—
Protective clothing used - boots, head cover, gloves, coveralls	✓		
Outer coverall vacuumed before removing	✓	—	
Outer coverall removed before leaving barricaded area	✓	—	
Plastic used on floor and over equipment	✓	—	—
Area vacuumed	✓	—	—
Employee showered before reapplying street clothes	✓	—	
Proper clean-up (area housekeeping)	✓	—	—
Barricades down (after clean-up only)	✓	—	—
Employee(s) monitored by Industrial Hygiene	✓	—	—
Type of respirator used:			
Half-face AO R57-A (HEPA)	✓		
Half-face Willson R-12 (HEPA)	—		
Supplied Air-Full Face - Positive Pressure	—		
Employee trained for respirator in last 6 months (If not using Supplied Air - Positive Pressure)	✓	—	—
Employee trained for OSHA Asbestos Standard in last 12 months	✓	—	

COMMENTS: _____

R. D. Deweese Telephone: 652-3211 ex. 54

(Form Filed By:)

Return filled out form (original) after completion of the job to: M. A. Patel - Bldg. 701/330

1791P

UCC 001969

WV-0234
#80

CONSTRUCTION/SERVICES DEPARTMENT SUPERVISOR'S REPORT

(LOCATION OF JOB:) PLANT: 380 AREA: ____ ZONE: ____ BLDG: 48 UNIT: B4 II

JOB SUPERVISOR: Ted Alderman DATE JOB PERFORMED: 8-29-87

DESCRIPTION OF JOB: Strip 18 FT. 3" Asbestos Insulation

LOCATION ASBESTOS INSULATION DISPOSED: Plant 380 Asbestos Land Fill

ESTIMATED FEET REMOVED: 18' LINEAL FEET ____ SQUARE FEET

EMPLOYEES INVOLVED IN ACTUAL JOB(S): Deweese

	YES	NO	N/A
Plant 511 Hygienist notified (M. A. Patel - ext. 3750)		✓	
Negative pressure enclosure feasible?		✓	
Negative pressure enclosure installed?		✓	
Use of Glove Bag feasible?	✓		
Glove Bag used?	✓		
Barrier tape used	✓		
Warning signs used	✓		
Protective clothing used - boots, head cover, gloves, coveralls	✓		
Outer coverall vacuumed before removing	✓		
Outer coverall removed before leaving barricaded area	✓		
Plastic used on floor and over equipment			✓
Area vacuumed	✓		
Employee showered before reapplying street clothes	✓		
Proper clean-up (area housekeeping)	✓		
Barricades down (after clean-up only)	✓		
Employee(s) monitored by Industrial Hygiene			NA
Type of respirator used:			
Half-face AO R57-A (HEPA)	✓		
Half-face Willson R-12 (HEPA)			
Supplied Air-Full Face - Positive Pressure			
Employee trained for respirator in last 6 months (If not using Supplied Air - Positive Pressure)	✓		
Employee trained for OSHA Asbestos Standard in last 12 months	✓		

COMMENTS: Mr Deweese done a good Clean Job

Ted Alderman Telephone : 570

(Form Filed By:)

Return filled out form (original) after completion of the job to: M. A. Patel - Bldg. 701/330

1791P

UCC 001970

Published by AsbestosClaims.Law
asbestosclaims.law/library/17894/10

ATTACHMENT A

ASBESTOS INSULATION REMOVAL AND DISPOSAL
SUPERVISOR'S REPORT

1. LOCATION OF JOB: Plant 380 - Poly II
2. DATE(S) JOB PERFORMED: 8-29-86 9⁴⁵ AM to 8-29-86 1130 AM
3. DESCRIPTION OF JOB: Remove asbestos insulation
4. AMOUNT OF ASBESTOS INSULATION INVOLVED: 10 LIN. FT. 3"
5. LOCATION ASBESTOS INSULATION DISPOSED 380 - asb. burial Ground
6. EMPLOYEES INVOLVED: (If more spaces are needed use back of page)

R.L. Hilvending 8-29-86

AO - W RS1 A. Cart. w/R-49A

7. TYPE OF RESPIRATORY EQUIPMENT USED: Filters
8. CHECK IF INSULATION NOT WETTED DOWN: ☐

SUPERVISOR: Ted Alderman

DATE: 8-29-86

UCC 001971

Published by AsbestosClaims.Law
asbestosclaims.law/library/17894/11