WV-0039 #45

PLAINTIFF'S EXHIBIT

UC-3182

UNION CARBIDE

INTERNAL CORRESPONDENCE

UNION CARBIDE CORPORATION TECHNICAL CENTER
P.O. BOX 8361 SOUTH CHARLESTON WV 25303

C. K. Campbell

April 16, 1986

HS&EA

Industrial Hygiene

Asbestos

J. H. Barna
W. L. Browning
C. P. Maxwell
B. R. McMakin

At your request, insulation samples were collected from three lines near the Construction sandblasting shop located at the Institute plant. Your concern was that the protective coating has weathered from the insulation in question, and the insulation is crumbling and could allow it to become airborne. Since these lines are very close to the lunch trailer and close to the sandblasting area, there was concern of asbestos exposure to the employees assigned to this area.

The three samples were analyzed and two of the three (see attached) were determined to contain asbestos.

We feel that the concerns are well founded and we recommend working closely with the Institute plant's Area Maintenance Supervisor in removing the Asbestos, therefore eliminating the possible exposure hazard to our employees.

If you have any questions or need our assistance, please feel free to give us a call on extension 4779 or 3750.

PREPARED BY:

Vance E. Stover

APPROVED BY:

Manhar A. Patel

Attachment

VES:MAP:rab
1204P

UCC 000376

Union Carbide trial exhibit UC-3182: V. E. Stover to C. K. Campbell on Asbestos Testing of Pipe Insulation Near the...
ACL Doc 18009 · Page 2 of 2

INSULATION ASBESTEST RESULTS FORM

No.	Date	Sample Submitted By	Sample Source	Mg Test	Fe Test	By	Remarks
PS-1	4-9-86	Charlie Campbell	Institute - behind paint paint shop - lunch trailer near ground level.	-	+	VES	Very dark red, immediately.
PS-2	4-9-86	Charlie Campbell	Taken behind sandblasting shop near tank no. 1265.	-	+	VES	
PS-3	4-10-86	Charlie Campbell	6" line going overhead - behind trailer - over roadway.	-	-	VES	

UCC 000377

1204P

Published by AsbestosClaims.Law
asbestosclaims.law/library/18009/2