PLAINTIFF'S EXHIBIT

UC-3622

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

June 3, 1987

TO: S. J. Chanley
L. C. Stewart

CC: B. D. Mollohan*
G. F. Painter*
M. J. Shoger*
W. N. Stratton*

Re: SHARE Inspection Results

Dear Sara and Larry:

You will find attached a copy of the findings from the SHARE inspection held June 3, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

Steve Kovach
S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (July 3, 1987)	60 Days (Aug. 3, 1987)	90 Days (Sep. 3, 1987)
% Complete	60 %		
Signature	L.C. Stewart S. J. Chanley for		

Send copy of update to: B. D. Mollohan - Bldg. 82-3
G. F. Painter - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBH/yc
1658A

Attachment

*Copy of letter only

UCC 008448

Union Carbide trial exhibit UC-3622: S. B. Kovach to S. J. Chanley and L. C. Stewart Transmitting South Charleston...
ACL Doc 18348 · Page 2 of 3

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title: Distribution Misc
Dept. No.: 228/068
Location: Upper Island Misc
Date of Inspection: 6/3/87

Inspector Submitting Report: H. H. Price
Phone No.: 2953
Inspection Responsibility: Insulation
Date of Report: 6/3/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Orc Number
IN 1	2 Insulated Lines in #127		Take Samples. Remove if Asbestos Facility out of service.	Complete	
IN 2	Exposed Ins North of 924 Tank & South 925 Tank overhead East #127	✓	Test Remove if Asbestos Facility out of service	Complete	
IN 3	Exposed Insulation in Rack So. Bldg 128	✓	Check Strip		
IN 4	Exposed Ins. East #104 & North		Seal + Strip		
IN 5	3 Rooms Ins. on 1st Floor #1 has Canvas #142; Transite 1st Floor #142	✓	Test & Remove		

UCC 008449

Published by AsbestosClaims.Law
asbestosclaims.law/library/18348/2

Union Carbide trial exhibit UC-3622: S. B. Kovach to S. J. Chanley and L. C. Stewart Transmitting South Charleston...
ACL Doc 18348 · Page 3 of 3

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title: Distribution Misc | Dept. No.: 228/064 | Location: Upper Island Misc | Date of Inspection: 6/3/87

Inspector Submitting Report: H H Price | Phone No.: 3953 | Inspection Responsibility: Insulation | Date of Report: 6/3/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord Number
IN 6	Seal Insulation in RACK 30 West Corner #122				
IN 7	4-3" Pipe Insulated Up in ceiling Painted Blue 15' of Each 3 2" lines in same Area So. of Bldg 1st Floor		Check for Asbestos		

UCC 008450

Published by AsbestosClaims.Law
asbestosclaims.law/library/18348/3