PLAINTIFF'S EXHIBIT

UC-3623

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

June 10, 1987

TO: R. W. Decrease

CC: B. D. Mollohan*
M. J. Shoger*

Re: SHARE Inspection Results

Dear Bob:

You will find attached a copy of the findings from the SHARE inspection held June 10, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

Steve Kovach

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (July 10, 1987)	60 Days (Aug. 10, 1987)	90 Days (Sep. 10, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: B. D. Mollohan - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment *Copy of letter only

UCC 008451

Union Carbide trial exhibit UC-3623: S. B. Kovach to R. W. Decrease transmitting SHARE Inspection Results, Sout...
ACL Doc 18349 · Page 2 of 3

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title SVR | Dept. No. 083 | Location Bldg 189/177 | Date of Inspection 6/10/87

Inspector Submitting Report H.H. Price | Phone No. 2953 | Inspection Responsibility Insulation | Date of Report 6/10/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN1	Exposed Ins. on 1st Floor 177 Perlite A small amount could be Asbestos		Check & Seal		
IN2	Exposed Ins on 3rd Level #177 3A2 Area.		Seal		
IN3	Exposed Ins on west side 4th Floor at Heater 177		Seal		
IN4	Exposed Ins 6th Floor 177 on Left as you Enter from East side Also on west Wall	✓	Strip & Seal		
IN5	Exposed Ins. So. Wall 6th Floor.	✓	Remove		

UCC 008452

Published by AsbestosClaims.Law
asbestosclaims.law/library/18349/2

Union Carbide trial exhibit UC-3623: S. B. Kovach to R. W. Decrease transmitting SHARE Inspection Results, Sout...
ACL Doc 18349 · Page 3 of 3

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title SVR | Dept. No. 083 | Location Bldg 177/189 | Date of Inspection 6/10/87

Inspector Submitting Report H. H Price | Phone No. 2953 | Inspection Responsibility Insulation | Date of Report 6/10/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN6	Exposed Ins in Locker Room 2nd deck Bld 189 over Lockers 287	✓	Seal		
IN7	Exposed ins AT Heaters 189 3rd Floor	✓	Seal		
IN8	Exposed Insulation going N. To Main Rack	✓	Strip.		

UCC 008453

Published by AsbestosClaims.Law
asbestosclaims.law/library/18349/3