PLAINTIFF'S EXHIBIT

UC-3624

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

June 17, 1987

TO: D. H. Ott

CC: B. N. Gliatta*
M. J. Shoger*

Re: SHARE Inspection Results

Dear Dave:

You will find attached a copy of the findings from the SHARE inspection held June 17, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

Steve Kovach

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (July 17, 1987)	60 Days (Aug. 17, 1987)	90 Days (Sep. 17, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: B. N. Gliatta - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment *Copy of letter only

UCC 008454

Union Carbide trial exhibit UC-3624: S. B. Kovach to D. H. Ott Transmitting South Charleston Plant SHARE Inspecti...
ACL Doc 18350 · Page 2 of 4

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title: Polyols | Dept. No.: 106 | Location: Bldg 103 | Date of Inspection: 6/17/87

Inspector Submitting Report: H Price | Phone No.: 3953 | Inspection Responsibility: Insulation | Date of Report: 6/17/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN1	Exposed Ins At Tank 609 c/c West Bldg 103	✓	Strip & Repair. Sample.		
* IN2	Exposed Asbestos ~~Corrugated~~ Paper 1st Floor 103	✓	Strip.		
IN3	Exposed Ins. 1st Floor 103 West Wall. (Platform)		Patch & Seal		
IN4	Exposed Ins. 1st Floor at doorway So.	✓	Sample & Repair		
* IN5	Exposed Asbestos on dead Pipe N. East No 9 Kettle	✓	Strip		

UCC 008455

Published by AsbestosClaims.Law
asbestosclaims.law/library/18350/2

Union Carbide trial exhibit UC-3624: S. B. Kovach to D. H. Ott Transmitting South Charleston Plant SHARE Inspecti...
ACL Doc 18350 · Page 3 of 4

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title: Polyols | Dept. No.: 106 | Location: Bldg 103 | Date of Inspection: 6/17/87

Inspector Submitting Report: H H Price | Phone No.: 2953 | Inspection Responsibility: Insulation | Date of Report: 6/17/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN6	Exposed Insulation overhead So & Kettle	✓	Sample, Strip & Seal		
IN7	Exposed Ins. East Wall 1st Floor at Elevator	✓	Check & Seal		
IN8	Exposed Ins. in Rack North 103 & Against Bldg.	✓	Sample & Strip & Seal		
IN9	Exposed ins in Rack west of 103 ⇐ to Bldg 103	✓	Sample ⇐ Strip		
IN10	Exposed Ins. N. End of 103 3rd Floor	✓	Patch & Seal		

UCC 008456

Published by AsbestosClaims.Law
asbestosclaims.law/library/18350/3

Union Carbide trial exhibit UC-3624: S. B. Kovach to D. H. Ott Transmitting South Charleston Plant SHARE Inspecti...
ACL Doc 18350 · Page 4 of 4

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title: Polyols | Dept. No.: 106 | Location: Bldg 103 | Date of Inspection: 6/17/87

Inspector Submitting Report: H H Price | Phone No.: 2953 | Inspection Responsibility: Insulation | Date of Report: 6/17/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
1N11	Exposed Ins. going from 3rd to Roof on west wall Next ~~Stair~~ Way going To Roof middle of Bldg. ~~East~~	✓	Repair		
1N12	Exposed Ins. So End of 3rd Floor	✓	Patch & Seal		
1N13	Exposed Ins on Roof 103	✓	Patch & Seal & Strip Same		
* 1N14	Exposed Asbestos overhead So End 2nd Floor 103 Paper.	✓	Strip		

UCC 008457
Published by AsbestosClaims.Law
asbestosclaims.law/library/18350/4