PLAINTIFF'S EXHIBIT

UC-3625

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

June 24, 1987

TO: L. C. Stewart

CC: G. F. Painter*
M. J. Shoger*

Re: SHARE Inspection Results

Dear Larry:

You will find attached a copy of the findings from the SHARE inspection held June 24, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (July 24, 1987)	60 Days (Aug. 24, 1987)	90 Days (Sep. 24, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: G. F. Painter - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment *Copy of letter only

UCC 008458

Union Carbide trial exhibit UC-3625: S. B. Kovach to L. C. Stewart Transmitting South Charleston Plant SHARE Ins...
ACL Doc 18351 · Page 2 of 4

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title UCC VME Unit | Dept. No. 064 | Location Bldg 134F | Date of Inspection 6/24/87

Inspector Submitting Report H H Price | Phone No. 3953 | Inspection Responsibility Insulation | Date of Report 6/24/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN 1	Exposed Ins. in Rack East Tank 1197	✓	Sample & Seal		
IN 2	Exposed Ins. on Top Tank Piping & Rack North East #133	✓	Strip.		
IN 3	Exposed ins. West of #134 in Structure	✓	Strip & Seal		
IN 4	Exposed ins S. West #134 in structure	✓	Strip & Patch & Seal - Sample		
IN 5	Exposed Ins at East Wall 1st Floor at 1st door looking N.	✓	Sample & Seal		

UCC 008459

Published by AsbestosClaims.Law
asbestosclaims.law/library/183512

Union Carbide trial exhibit UC-3625: S. B. Kovach to L. C. Stewart Transmitting South Charleston Plant SHARE Ins...
ACL Doc 18351 · Page 3 of 4

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title UCC VME Unit | Dept. No. 06H | Location 134 | Date of Inspection 6/24/87

Inspector Submitting Report H H Price | Phone No. 3953 | Inspection Responsibility Institution | Date of Report 6/24/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN6	Exposed Ins.	✓	Seal		
IN7	Exposed Ins. on 3rd Floor Structure on 3rd Land.	✓	Sample & Repair Strip.		
* IN8	Exposed Asbestos on Roof 134	✓	Strip.		
IN9	Bags of Ins in Rack So. East 133		Remove		
* IN10	Exposed Asbestos So. West Corner 134	✓	Strip & Remove		

UCC 008460

Published by AsbestosClaims.Law
asbestosclaims.law/library/18351/3

Union Carbide trial exhibit UC-3625: S. B. Kovach to L. C. Stewart Transmitting South Charleston Plant SHARE Ins...
ACL Doc 18351 · Page 4 of 4

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title: Vicc VME Unit | Dept. No.: 064 | Location: 134 | Date of Inspection: 6/24/87

Inspector Submitting Report: J H Price | Phone No.: 3953 | Inspection Responsibility: Insulation | Date of Report: 6/24/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN 11	Exposed ins in Rack East 134	✓	Sample & Patch		
IN 10	Exposed Ins in Rack Sec 134	2	Sample & Strip		

UCC 008461

Published by AsbestosClaims.Law
asbestosclaims.law/library/18351/4