PLAINTIFF'S EXHIBIT

UC-3626

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

July 1, 1987

TO: P. R. Desai

CC: G. F. Painter*
H. J. Shoger*

Re: SHARE Inspection Results

Dear Prayful:

You will find attached a copy of the findings from the SHARE inspection held July 1, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

Steve Kovach

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Aug. 1, 1987)	60 Days (Sep. 1, 1987)	90 Days (Oct. 1, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: G. F. Painter - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment *Copy of letter only

UCC 008462

Housekeeping → A-

SOUTH CHARLESTON PLANT MANAGER'S SAFETY AND HEALTH INSPECTION REPORT

Department Title: Mainland Chemicals | Dept. No.: 077 | Location: B-42, B-4, B-5, B-6 East Tnk Farm | Date of Inspection: 7/1/87

Inspector Submitting Report: D. HANSHEW & Cassier, T. Gould II | Phone No.: 3144 | Inspection Responsibility: ENV Prof. | Date of Report: 7/1/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
EP-1	½ Gal of Oil (?) in plastic 1gal container,				
	should be properly labeled (ID, date, etc)	✓			
	Location: ~~west~~ of #19 still under switchbank (B42)				
EP-2	Broken Insulation on line				
	(Asbestos ?) Friable. If Asbestos	✓			
	should be sealed to prevent fiber loss. (B42)				
	South end of #5 still pot near open doorway				
EP-3	Unlabeled Drum -				
	Above #5 still pot on platform B-42				
EP-4	open ended line - (≃ 1¼")				
	stairwell walkway	✓			
	personal hazard from spray				
	south of Tnk 552				
EP-5	Tanks 513, 514, 521, 522				
	No curbs on pumps to prevent oil				
	from entering clean sewer				
	Tag[redacted] on EP-4 on 12/3/86				

513, 514, 521, 522

UCC 008463

Union Carbide trial exhibit UC-3626: S. B. Kovach to P. R. Desai Transmitting South Charleston Plant SHARE Insp...
ACL Doc 18352 · Page 2 of 5
Published by AsbestosClaims.Law
asbestosclaims.law/library/18352/2

Union Carbide trial exhibit UC-3626: S. B. Kovach to P. R. Desai Transmitting South Charleston Plant SHARE Insp...
ACL Doc 18352 · Page 3 of 5

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title P.G. Maint and Chemicals Dept. No. 677 Location Bldg 4 & G 42 Date of Inspection 7/1/87

Inspector Submitting Report H.H. Price Phone No. 2953 Inspection Responsibility Insulation Date of Report 7/1/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN1	Exposed Insulation Bldg 4 1st Floor N. Side	✓	Patch & Seal		
IN2	Exposed Ins. East End No 1 Autoclave 2nd Land. Bldg 4	✓	Patch & Seal		
IN3	Exposed ins (Asbestos in Bldg 5 3rd Land	✓	Strip & Reinsulate Part of Line		
IN4	Exposed ins ~~and~~ Floor Bldg 6 2 places.	✓	Seal & Patch		
IN5	Exposed Ins. Bldg 42 1st Floor S. Wall at door & Stairway	✓	Seal		

UCC 008464

Published by AsbestosClaims.Law
asbestosclaims.law/library/18352/3

Union Carbide trial exhibit UC-3626: S. B. Kovach to P. R. Desai Transmitting South Charleston Plant SHARE Insp...
ACL Doc 18352 · Page 4 of 5

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title Maintenance Chemicals P.G. Dept. No. 077 Location Bldg 4 5 6 42 Date of Inspection 7/1/87

Inspector Submitting Report H H Price Phone No. 2853 Inspection Responsibility Insulation Date of Report 7/1/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN6	Exposed Ins. So. East Corner Bldg 42 1st Floor		Patch & Seal		
IN7	Exposed Insulation Stair Way going To 2nd Floor Both sides stairway Bldg 42	✓	Strip & Reinsulate		
IN8	Exposed Ins 2nd Land East End #42	✓	Patch & Seal		
IN9	Exposed Asbestos 2nd Floor 42 East End	✓	Strip & Reinsulate		
IN10	Exposed Ins at Stair Way Both sides going from 2nd To 3rd East end 42 Under Grating	✓	Strip & Reinsulate		

UCC 00846
Published by AsbestosClaims.Law
asbestosclaims.law/library/18352/4

Union Carbide trial exhibit UC-3626: S. B. Kovach to P. R. Desai Transmitting South Charleston Plant SHARE Insp...
ACL Doc 18352 · Page 5 of 5

SOUTH CHARLESTON PLANT SAFETY/HEALTH AUDIT TEAM'S REPORT

Department Title: Maint'Land Chem (BG) | Dept. No.: 077 | Location: 4,5,6,42 | Date of Inspection: 7/1/87

Inspector Submitting Report: HH Price | Phone No.: 2953 | Inspection Responsibility: Insulation | Date of Report: 7/1/87

Item No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
1N11	Exposed Ins. 3rd Land East End H2	1	Strip & Reinsulate		
1N12	Exposed ins in Rack Tank Farm Piping East West between 2983	2	Strip & Ins.		
1N13	Exposed in Rack	1	Strip		

UCC 008466

Published by AsbestosClaims.Law
asbestosclaims.law/library/18352/5