PLAINTIFF'S EXHIBIT

UC-3631

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

September 3, 1987

TO: S. J. Chanley

CC: B. D. Mollohan*
M. J. Shoger*
W. N. Stratton*

(72)

Re: SHARE Inspection Results

Dear Sara:

You will find attached a copy of the findings from the SHARE inspection held September 3, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Oct. 3, 1987)	60 Days (Nov. 3, 1987)	90 Days (Dec. 3, 1987)
% Complete			
Signature			

Send copy of update to: B. D. Mollohan - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment *Copy of letter only

UCC 008479

Union Carbide trial exhibit UC-3631: S. B. Kovach to S. J. Chanley transmitting South Charleston Plant SHARE Ins...
ACL Doc 18357 · Page 2 of 3

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department Title Distribution | Dept. No. 211 | Location B 80, 75 Oxide RACK | Date of Inspection 9-2-87

Inspector Submitting Report H H Price | Phone No. 3953 | Inspection Responsibility Insulation

	Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN1		Non Asbestos at Pump & Switch Bank So. E. 79 Ground Level.		Seal		
IN2		Exposed Ins. 2nd Level So. E 79 Bldg & As you go up steps at west End Perlite & Kayo		Seal		
IN3		Ins. To Eye bath Needs Weather-Barrier		Seal Waterproof		
IN4		Asbestos on dead Line West 75	✓	Strip & Remove		
IN5		Exposed ins west End 80 outside in RACK.		Needs Weather Barrier.		
		Some Asbestos	✓	Remove.		

UCC 008480

Published by AsbestosClaims.Law
asbestosclaims.law/library/183572

Union Carbide trial exhibit UC-3631: S. B. Kovach to S. J. Chanley transmitting South Charleston Plant SHARE Ins...
ACL Doc 18357 · Page 3 of 3

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department Title Dist. Dept. No. 211 Location Bldg 50,75 oxide RHSH Date of Inspection 9/2/87

Inspector Submitting Report H. H Price Phone No. 2953 Inspection Responsibility Insulation

Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN6	Ins. ja side on 1st & 2nd level Needs Weather Barrier		Seal		

UCC 008481

Published by AsbestosClaims.Law
asbestosclaims.law/library/183573