PLAINTIFF'S EXHIBIT

UC-3632

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

September 23, 1987

TO: D. L. Meadows

CC: B. N. Gliatta*
M. J. Shoger*

Re: SHARE Inspection Results

Dear Dillard:

You will find attached a copy of the findings from the SHARE inspection held September 23, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

Steve Kovach

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Oct. 23, 1987)	60 Days (Nov. 23, 1987)	90 Days (Dec. 23, 1987)
% Complete	30%		
Signature	D L Meadows		

Send copy of update to: G. F. Painter - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment

*Copy of letter only

UCC 008482

Union Carbide trial exhibit UC-3632: S. B. Kovach to D. L. Meadows Transmitting SHARE Inspection Results, South...
ACL Doc 18358 · Page 2 of 4

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department Title Specialty Chemicals Dept. No. 115 Location Truck Rack Drum Fac. West Tank Farm Date of Inspection 9/23/87

Inspector Submitting Report H. H. Price Phone No. 2953 Inspection Responsibility Insulation

	Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Date Correct	Shop Ord. Number
* IN1 MLC		West door overhead So. End Bldg 15b Exposed Asbestos	✓	Seal / This will be included on the 1988 Asburn stripping list Target date for completion end of Oct. 1988		
* IN2 MLC		Exposed Ins on Line going from West Side Bldg to Tank Farm At 5110 Tank. Over Safety shower & Line going to ground on E. side 5110	✓	Strip SAA.		
* IN3 MLC		Exposed Asbestos East 5120 Tank at Pump	✓	Strip. S.A.A.		
* IN4 MLC		Asbestos on tank 40 74	✓	Seal / S. A. A.		
* IN5 MLC		Exposed Ins. N 5171 Tank	✓	Strip. S.A.A.		

* Asbestos

UCC 008483

Published by AsbestosClaims.Law
asbestosclaims.law/library/18358/2

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department Title Specialty Chem & Cat Dept. No. 115 Location West Tank Farm Truck Rack 156 Dunning Date of Inspection 9/23/87

Inspector Submitting Report H.H. Price Phone No. 2953 Inspection Responsibility Insulation

	Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Date Correct	Shop Ord. Number
IN6 MLC		Foamglass Weather Barrier gone on Tank 4077		Repair weather barrier on tank 4077 will be replaced completion date required for Insp		202951
		Ins. in Bags N. West HC IH		Remove Complete	10-15-87	195004
MLC		Exposed Ins 4081 ground	✓	Patch Same as #1		
* IN7 MLC						
* IN4 MLC		Exposed Ins. Leak in Steam Needs Ins after Leak is Fixed West of Bldg.	✓	Repair Same as #1		

UCC 008484

Union Carbide trial exhibit UC-3632: S. B. Kovach to D. L. Meadows Transmitting SHARE Inspection Results, South...
ACL Doc 18358 · Page 3 of 4
Published by AsbestosClaims.Law
asbestosclaims.law/library/18358/3

Union Carbide trial exhibit UC-3632: S. B. Kovach to D. L. Meadows Transmitting SHARE Inspection Results, South...
ACL Doc 18358 · Page 4 of 4

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department Title Spec. Chem/Cat. Dept. No. 115 Location B 15L & Area Date of Inspection 9/23/87

Inspector Submitting Report T.L. Caudill Phone No. X-2299 Inspection Responsibility EP

Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
1 MLC	Asbestos Dumpster - overflowing & contains non-asbestos trash - N/W of Tank Truck Unloading Sta #14		This was a contractors dumpster used for Polyols Dept. while stripping their Phase IV tank farm Out of our work Area	NA	
2 D	Spent Filters lying in NW corner of B-15L 1st Floor Dumping Fac. Fly.		Filters cleaned up.	15 OCT 87	
3 ~~D~~	~~Old buckets - paint - maybe just trash - some paint - at Stop sl road~~				
4 MLC	Elec. control Box - out of service - cover barely on - needs to be removed - West of Drum Conveyor	✓	To be corrected by Area 2 Elec		203295
5 D	2 Sample bottles w/ clear liquid - on drum inside B/15L 1st Floor E-side - no tag identifying contents	✓	Samples Disposed/Emptied From an unkown cat. Blend	23OCT87	

UCC 008485

Published by AsbestosClaims.Law
asbestosclaims.law/library/18358/4