PLAINTIFF'S EXHIBIT

UC-3634

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

September 30, 1987

TO: L. C. Stewart

CC: B. D. Mollohan*
M. J. Shoger*

Re: SHARE Inspection Results

Dear Larry:

You will find attached a copy of the findings from the SHARE inspection held September 30, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Oct. 30, 1987)	60 Days (Nov. 30, 1987)	90 Days (Dec. 30, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: B. D. Mollohan - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment

*Copy of letter only

UCC 008488

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department Title LAB | Dept. No. 355 | Location 106 | Date of Inspection 9/30/87

Inspector Submitting Report H. H. Price | Phone No. 2953 | Inspection Responsibility Insulation

Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Date Correct	Shop Ord. Number
IN1	Exposed Asbestos in Hallway At Room 12 in Basement 106		Seal		
IN2	Exposed Ins. in Room 12 Basement 106		Seal		
IN3	Exposed Asb in Room 115 Basement 106	✓	Patch & Seal		
IN4	Exposed Asbestos in Basement 106	✓	Patch		
IN5	Exposed Ins Asbestos Room 23 II 106 Basement	✓	Strip & Redo.		

UCC 00848

Union Carbide trial exhibit UC-3634: S. B. Kovach to L. C. Stewart Transmitting SHARE Inspection Results, South...
ACL Doc 18360 · Page 2 of 4
Published by AsbestosClaims.Law
asbestosclaims.law/library/18360/2

Union Carbide trial exhibit UC-3634: S. B. Kovach to L. C. Stewart Transmitting SHARE Inspection Results, South...
ACL Doc 18360 · Page 3 of 4

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department Title: Lab | Dept. No.: 3555 | Location: 106 | Date of Inspection: 9/30/87

Inspector Submitting Report: H. H. Price | Phone No.: 2953 | Inspection Responsibility: Insulation

Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
IN6	Exposed Asbestos Room 18 Basement 106	✓	Patch		
IN7	Exposed Ins (Asbestos) Room 19 Basement 106				
IN8	Exposed Ins. Asbestos in hall way Room 32 Basement 106	✓	Patch & Seal		
IN9	Exposed Asbestos in Room Small East Room 32 Basement Lab 106.				
IN10	Exposed Ins Asbestos in Room 106 1st. Fl 106 Room 111		Repair		

UCC 008490

Published by AsbestosClaims.Law
asbestosclaims.law/library/18360/3

Union Carbide trial exhibit UC-3634: S. B. Kovach to L. C. Stewart Transmitting SHARE Inspection Results, South...
ACL Doc 18360 · Page 4 of 4

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department Title Lab | Dept. No. 353 | Location 126 | Date of Inspection 9/30/87

Inspector Submitting Report HHP | Phone No. 2953 | Inspection Responsibility Insulation

Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Shop Ord. Number
-N11	Asbestos in pipe chase No. End Hallway		Remove		
-N10	Asbestos Room 306		Patch		

UCC 008491

Published by AsbestosClaims.Law
asbestosclaims.law/library/18360/4