PLAINTIFF'S EXHIBIT

UC-3635

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

October 21, 1987

TO: P. R. Desai

CC: G. F. Painter*
E. H. Kivett*

Re: SHARE Inspection Results

Dear Praful:

You will find attached a copy of the findings from the SHARE inspection held October 21, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Nov. 21, 1987)	60 Days (Dec. 21, 1987)	90 Days (Jan. 21, 1988)
% Complete			
Signature			

Send copy of update to: G. F. Painter - Bldg. 82-3
S. B. Kovach - Bldg. 109-2

SBK/yc
1658A

Attachment

*Copy of letter only

UCC 008492

Union Carbide trial exhibit UC-3635: S. B. Kovach to P. R. Desai Transmitting SHARE Inspection Results, South Ch...
ACL Doc 18361 · Page 2 of 4

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department Title Maitland Chem. Dept. No. 277 Location H2 Date of Inspection 12/21/77

Inspector Submitting Report HHP HERB PRICE Phone No. 2953 Inspection Responsibility Insulation

Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
* on IN1	Exposed ins. on H.H Reactor Elm East End + Col. setting on Top	✓	Patch / Seal Test for Asbestos		
* IN2	Exposed Ins. on piping 2nd Land East End structure Overhead	✓	Asbestos Remove Reinsulate		
IN3	Exposed ins. N. of Bldg-42 So. Structure on 3rd Landing		Repair		
IN4	Exposed Ins. on Still Top 3rd Land N.E. #2 Structure		Patch		
* IN5	Exposed Ins Top Land N. East Corner #2	✓	Strip & Reinsulate		

* Asbestos

UCC 008493

Published by AsbestosClaims.Law
asbestosclaims.law/library/18361/2

Union Carbide trial exhibit UC-3635: S. B. Kovach to P. R. Desai Transmitting SHARE Inspection Results, South Ch...
ACL Doc 18361 · Page 3 of 4

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department Title Maintenance Chem Dept. No. 077 Location 42 Date of Inspection 10/21/87

Inspector Submitting Report HHP Phone No. 2953 Inspection Responsibility Insulation

Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
* IN6	Exposed ins. on Expansion Loop in steam 3rd Land West End of Bldg 42	✓	Patch		
* IN7	Exposed Asbestos Laying on Grating & on scrap pipe 4th Foot Stairway going to Roof	✓	Remove		
* IN8	Exposed Ins on grating, Piping Overhead 2nd Land. North side Bldg 42	✓	Strip & Replace Check for Asbestos		
IN9	Exposed Ins. on No 1 H Still & Collander 4 Still Col. west 2nd Land 42 Bldg.		Patch		
* IN10	Dead Line West End of Bldg 25' off Floor Exposed Ins.	✓	Remove		

UCC 008494

Published by AsbestosClaims.Law
asbestosclaims.law/library/18361/3

Union Carbide trial exhibit UC-3635: S. B. Kovach to P. R. Desai Transmitting SHARE Inspection Results, South Ch...
ACL Doc 18361 · Page 4 of 4

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department Title Maint Land Chem | Dept. No. 027 | Location 112 | Date of Inspection 10/21/87

Inspector Submitting Report [signature] | Phone No. 2953 | Inspection Responsibility Insulation

Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
* IN 11	Exposed Insc on 1st Floor N East Corner	✓	Strip to Repair		

UCC 008495

Published by AsbestosClaims.Law
asbestosclaims.law/library/18361/4