PLAINTIFF'S EXHIBIT

UC-3817

Initials WV-0195
Audit Report #

# AUDIT REPORT

Filed By: L.W. Thompson

Location: ~~Technical Center~~, South Charleston, West Virginia

Dates at location on task: Nov. 10, 1987 to Nov 17, 1987

Information sources (persons or docs. which led you to files):

Personal interview

Name and title of individual whose files are searched:
~~See Audit Report # WV~~ , Industrial Hygiene Technician

Department of files searched: ~~See Audit Report # WV~~ Industrial Hygiene

Description of files:

Number of file drawers: 5 drawers, Alpha and one in Industrial Hygiene office

Location of file drawers at original site before inspection: ~~See Audit Report # WV~~ Bldg. 106 -10-

Location where file drawers permanently stored after inspection and custodian of the files: ~~See Audit Report # WV~~

Bldg 106- 106

CHIKLES "A"

Special markings on file drawers: ~~See Audit Report # WV~~

Folder Label: ASBESTOS - 671

Approximate total number of documents: Thousands (est)

Range of dates: 1979 to 1987

UCC 0012610

Apparent completeness of files (e.g., any obviously missing dates):

Appears complete _____ Not complete ?V

Explanation: includes much activity 1979,83, 84 - Set none in 1981;

Circle types of documents included in file (e.g. technical, sales records, correspondence, accident reports, health and safety, test results, etc.) If other, describe: _____

Laboratory Notebooks, Minutes of Meetings & from Asbestos Monitoring.

Names which repeatedly appear on documents: _____

Unusual particularly outstanding documents: _____

Comments made by individuals at site: _____

Additional comments: _____

UCC 0012611

Audit Report # WV-0195

DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 1* | ASBESTOS-671 79-83 | 3-7-79 | (AS-3705) WORK PLACE ENVIRONMENT MONITORING - FIELD DATA SHEET - Loc 514, Bldg 320 Sheet Metal Shop, Asbestos |
| 2* | -11- | 9-10-79 | See #1 - Loc 514, Bldg 151 Pipe rack, asbestos insulation |
| 3* | -11- | 9-11-79 | See #1 - Loc 514, Bldg 151, Steam leak insulation |
| 4* | -11- | 9-18-79 | See #1 - Loc 514, Bldg 51 Work unit 2 pipe hanger |
| 5* | -11- | 10-1-79 | See #1 - Loc 514, Bldg 151 Work 7 IPH, insulation |
| 6* | -11- | 10-2-79 | See #1 - Loc 514, bldg 151 Unit I PH |
| 7* | -11- | 4-22-80 | See #1 - Loc 514, Bldg 151 Unit I PH, remove insulation from #15 furnace |
| 8* | -11- | 5-5-80 | See #1 - Loc 514, Bldg 151 Unit I PH, insulation on #15 Boilers |
| 9* | -11- | 5-6-80 | See #1 - Loc 514, Bldg 151 Unit I PH, remove insulation from #15 boiler |
| 10* | -11- | 5-7-80 | See #1 - Loc 514 Bldg 151 Unit I PH, remove insulation from #15 boiler |
| 11* | -11- | 5-8-80 | See #1 - Loc 514, Bldg 151 Unit I PH, Ductwork #15 Boilers |
| 12* | -11- | 5-22-80 | See #1 - Loc 514, Bldg 151 Unit I PH, steam insulation from #11 boiler |
| 13* | -11- | 5-23-80 | See #1 - Loc 514, Bldg 151 Unit I PH, steam insulation #11 boiler |



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fil... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 3 of 19 asbestosclaims.law/library/18472/3

Audit Report # WV-0195

DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 14* | ASBESTOS-671 79-83 | 5-27-80 | See #1-Loc 514, Bldg 151 Unit IP#, Remove insul. #11 boiler |
| 15* | -11- | 5-28-80 | See #1-Loc 514, Bldg 151, Unit-IP#, Remove insulation from #11 boiler |
| 16* | -11- | 5-29-80 | See #1-Loc 514, Bldg 157 unit= IP#, Remove #1 P#5 boiler |
| 17* | -11- | 5-29-80 | See #1-Loc 514 Bldg 36, Unit= Oxide adducts, Remove insulation from steam line |
| 18* | -11- | 5-30-80 | See #1-Loc 514 Bldg 36 unit= oxide adducts, remove insulation from steam line. |
| 19* | -11- | 6-4-80 | See #1-Loc 514, Bldg 151 Unit= IP#, Remove insulation #11 boiler |
| 20* | -11- | 6-5-80 | See #1-Loc 514, Bldg 36, 71 Unit= Oxide adducts, Remove insulation from steam line. |
| 21* | -11- | 6-10-80 | See #1-Loc 514, Bldg 151 Unit=IP#, Remove insulation #11 boiler |
| 22* | -11- | 6-23-80 | See #1-Loc 514, Bldg 323 Unit= plant mixtures, Remove insulation |
| 23* | -11- | 7-1-80 | See #1-Loc 514, Bldg 323 Unit=plant mixtures, Remove insulation from steam line. |
| 24* | -11- | 7-16-80 | See #1- Loc 514, Bldg 303 Unit=Oilyard, Remove insulation from steam line |
| 25* | -11- | 9-2-80 | See #1- Loc 514, Bldg 305 Unit= maintenance - bag insulation |
| 26* | -11- | 10-23-80 | See #1- Loc 514, Bldg 202 Unit= maint., Remove asbestos to plastic bags |
| 27* | -11- | 10-24-80 | See #1- Loc 514, Bldg 202 Unit= maint., Remove insulation from [illegible] |

UCC 0012613

Audit Report # WV-0195

DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 28* | Asbestos-671 79-83 | 10-27-80 | See #1- Loc 514, Bldg 202 Unit= Maintenance, Removal asbestos on steam line in Tunnel |
| 29* | -11- | 10-28-80 | See #1- Loc 514, Bldg 202 Unit= maintenance, Removal insulation from steam line in Tunnel. |
| 30* | -11- | 6-23-82 | See #1 Loc 514 Bldg 151 Unit= IPH, Remove asbestos from steam Valve |
| 31* | -11- | 6-29-82 | See #1- Loc 514, Bldg 151 Unit= IPH. Insulation removal & |
| 32* | -11- | 12-15-82 | See #1 - Loc 514, Bldg 152 Unit= UCAR Solution Vessels, strip insulation from compressor Low line |
| 33* | -11- | 12-16-82 | See #1- Loc 514, Bldg 152 Unit= UCAR Solution - Vessels, Strip insulation in compressor room |
| 34* | -11- | 4-5-83 | See #1- Loc 514, Bldg 428 Unit= garage, Relining brake on vehicle |
| 35* | -11- | 4-26-83 | See #1- Loc 514, Bldg 151 Unit= IPH, Repair insulation under grating |
| 36* | -11- | 10-11-83 | See #1- Loc 514, Loc 97 & Septum Unit= IPH - pulverize asbestos, Less asbestos Clutch |
| 37* | -11- | 10-17-83 | See #1- Loc 514, Bldg 36 Unit= Oxide Adducts, strip insulation |
| 38* | -11- | 10-24-83 | See #1- Loc 514, Bldg 303, 327 Unit= Oilyard, Strip asbestos from Tanks under hood. |
| 39* | -11- | 11-2-83 | See #1- Loc 514, Bldg 303 Unit= Oilyard - Strip asbestos insul. from 40 ft pipe |
| 40* | -11- | 11-4-83 | See #1- Loc 514, Bldg 151-1 Unit= IPH Strip insul from Steam Valves. |

UCC 0012614

Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fil... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 5 of 19 asbestosclaims.law/library/18472/5

Audit Report # WV-0195

DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 41* | Asbestos-671 79-83 | 12-9-83 | See #1- Loc 514, Bldg 436 Unit= Maintenance, remove insul. from steam line. |
| 42* | -11- | 12-12-83 | See #1- Loc 514, Bldg 103 Unit=Polymer-Polypro, Strip/pack insulation from pipe |
| 43* | -11- | 12-14-83 | See #1- Loc 514, Bldg 216 Unit=Polymer-Polypro, Strip insulation from tanks |
| 44* | -11- | 12-30-83 | See #1- Loc 514 Bldg 308 Unit=Maintenance, Strip/pack insulation from 4" line |
| 45* | ASBESTOS 1984 | 1-6-84 | See #1- Loc 514 Bldg 144 Unit= UCC, Strip insulation from calandria |
| 46* | -11- | 1-11-84 | See #1- Loc 514, Bldg 151-1 Unit= IPP - Remove insulation from steam system |
| 47* | -11- | 1-13-84 | See #1- Loc 514 Bldg 151-1 Unit=IPP - Strip insulation from 12 ft + line. |
| 48* | -11- | 1-20-84 | See #1- Loc 514, Bldg 151 Unit IPH, remove insulation from pump head |
| 49* | -11- | 2-9-84 | See #1- Loc 514, Bldg 302 Unit= Oil yard, remove insulation from small tanks. |
| 50* | -11- | 2-10-84 | See #1- Loc 514 Bldg 36 Unit= Oxide Addnct, Strip ~ 40 ft 4" pipe. |
| 51* | -11- | 2-16-84 | See #1- Loc 514, Bldg 152 Unit= Ucon Solution Bldg, Remove insulation from 3" steam line. |
| 52* | -11- | 2-17-84 | See #1- Loc 514, Bldg 36 Unit= oxide additives - Remove insulation from acid tank. |
| 53* | -11- | 2-23-84 | See #1- Loc 514 Bldg 36 Unit oxide Addncts - Remove insulation from 4" line. |



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fil... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 6 of 19 asbestosclaims.law/library/18472/6

Audit Report # WV-0195

DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 54* | AGC 5705-1954 | 3-2-84 | See #1 - Loc 514, Bldg 151, unit = IPH Strip insulation bottom #2 furnace |
| 55* | — " — | 3-3-84 | See #1 - Loc 514, Bldg 47 unit = Maintenance, Remove insulation from precipitator |
| 56* | — " — | 3-3-84 | See #1 - Loc 514, Bldg 106 unit = Maintenance, remove insulation from Truck |
| 57* | — " — | 5-1-84 | See #1 - Loc 514 Bldg 106 Strip asbestos - Tar from pipe [illegible] |
| 58* | — " — | 4-6-84 | See #1 - Loc 514, Bldg 151 Unit = IPH, Strip asbestos fr 600 # steam - |
| 59* | — " — | 4-17-84 | See #1 - Loc 514, Bldg 151, Unit = IPH, Stripping insulation from line & valves. |
| 60* | — " — | 3-17-84 | See #1 - Loc 514 Unit = Loc 514, Bldg 4, Strip asbestos from 8" line in pit |
| 61* | — " — | 4-30-84 | See #1 - Loc 514, Bldg 151, Unit = IPH, Strip insul. from ~~steam~~ Feeder |
| 62* | — " — | 5-18-84 | See #1 - Loc 514, Bldg 36 Unit = OVIS, asbestos Strip 1" line |
| 63* | — " — | 5-21-84 | See #1 - Loc 514, Bldg 151-2 unit = IPH, Project asbestos |
| 64* | — " — | 5-23-84 | See #1 - Loc 514, Bldg 174 unit = MCC, Roof - Strip in for 3" line. |
| 65* | — " — | 5-31-84 | See #1 - Loc 514 Bldg 174 Unit = MCC, Strip insulation from flanges, (HOAC charge) |
| 66* | — " — | 6-1-84 | See #1 - Loc 514, Bldg 174 unit = MCC, strip insulation from flanges, HOAC charge |
| 67* | — " — | 6-6-84 | See #1 Loc 514 Bldg 174, Unit = MCC, Strip insulation [illegible] |



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fil... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 7 of 19 asbestosclaims.law/library/18472/7

Audit Report # WV-0195

DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 68* | ASBESTOS-1984 | 7-9-84 | See #1 Loc 514, Bldg 151-2 unit = I #4, strips insulation from #14 boiler |
| 69* | -4- | 6-14-84 | See #1 - Loc 514, Bldg 151- unit = I #4, strips asbestos from #7 generator |
| 70* | -11- | 6-19-84 | See #1 - Loc 514, Bldg 174, unit = MCC, strips asbestos from 4" line |
| 71* | -4- | 7-30-84 | See #1 - Loc 514 Bldg S-27 unit = UCAR Solutes Vessels Strips asbestos from 2" line, |
| 72* | -11- | 7-3-84 | See #1 - Loc 514 Bldg 151 unit = I #4, Strips asbestos from #14 boiler |
| 73* | -11- | 7-5-84 | See #1 - Loc 514 Bldg 151, unit = Polymer, MCC, Strips asbestos from 10" line |
| 74* | -4- | 7-11-84 | See #1 Loc 514, Bldg 151 unit = I #4, strips insulation from 8" generator |
| 75* | -11 | 7-10-84 | See #1 Loc 514, Bldg 151 Unit = I #4, strips insulation from #7 generator |
| 76* | -4- | 8-15-84 | See #1 Loc 514, Bldg 315 unit = UCAR Solutes Vessels, Strips insul. from #10 steam line |
| 77* | -11- | 8-28-84 | See #1, Loc 514, Bldg 77, unit = UCAR Solutes Vessels Strips asbestos from 4" line |
| 78* | -11- | 9-6-84 | See #1 Loc 514, Bldg 304 Unit = Main Entrance, Strips asbestos from 1" air conditioning |
| 79* | -11- | 9-11-84 | See #1, Loc 514, Bldg 42 unit = Main Change Room Strips insul. from boiler room |
| 80* | -11- | 9-17-84 | See #1 Loc 514, Bldg 189 Unit = Main Entrance, strips insulation off steam line in ceiling |
| 81* | -11- | 9-28-84 | See #1 Loc 514, Bldg 303 Unit = Bilyard, Strips asbestos from 2" steam line |



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fil... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 8 of 19 asbestosclaims.law/library/18472/8

Audit Report # WV-0195

DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 82* | ASBESTOS - 1984 | 10-26-84 | See #1 - Loc 514, Bldg 177 unit = Service Building Strip Asbestos from 2" line |
| 83* | -11- | 11-18-84 | See #1 - Loc 514, Bldg #'s 406 unit = maintenance Stripping insulation |
| 84* | -11- | 10-27-84 | See #1 - Loc 514, Bldg 146 unit = Lower Bridge, Check for Asbestos when demolishing |
| 85* | -11- | 11-29-84 | See #1 - Loc 514, Bldg 146 unit = Maintenance, Checking area around Bldg 146 |
| 86* | -11- | 12-20-84 | See #1 - Loc 514, Bldg 47, unit = Maintenance asbestos dust monitoring |
| 87* | -11- | 12-21-84 | See #1 - Loc 514, Bldg 47 unit = maintenance Asbestos dust monitoring |
| 88* | -11- | 12-26-84 | See #1 - Loc 514, Bldg 107, unit = maintenance Strip asbestos from steam line |
| 89* | -11- | 12-28-84 | See #1 - Loc 514, Bldg 151 unit = Maintenance, Strip insul. from valve Hoses pulverizer |
| 90* | ASBESTOS, 1985 | 2-4-85 | See #1 - Loc 514 Bldg 152 unit = Maintenance - Strip insulation from line Comp. Room. |
| 91* | -11- | 2-20-85 | See #1 - Loc 514, Bldg 152 unit = Maintenance, Strip asbestos from - 2" line |
| 92* | -11- | 2-19-85 | See #1 - Loc 514, Bldg 151, unit = Maintenance, Strip asbestos from 150 ft 2" line |
| 93* | -11- | 2-26-85 | See #1, Loc 514, unit = Maintenance Strip asbestos from 100 ft 2 1/2" line, |
| 94* | -11- | 3-12-85 | See #1 - Loc 514, Bldg 135 unit = Maintenance, Remove insulation from 20 ft. section of 8" line. |
| 95* | -11- | 3-15-85 | See #1 - Loc 514, Bldg 151 unit = Maint. Strip asbestos from 1 and 6" line. |

UCC 0012618

Audit Report # WV-0195

## DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 96* | ASBESTOS-1985 | 3-20-85 | See #1 - Loc 514, Bldg 135 UNIT = UICC, Remove insulation from #2 Still |
| 97* | -11- | 3-29-85 | See #1 - Loc 514, Bldg 144 UNIT = UICC, Strip Asbestos from #24 Still Enformers |
| 98* | -11- | 4-2-85 | See #1 - Loc 514, UNIT = MAINTENANCE Background Checks |
| 99* | -11- | 4-3-85 | See #1 - Loc 514, UNIT = Maintenance MAINLAND Power house background Check for asbestos |
| 100* | -11- | 4-3-85 | See #1 - Loc 514 UNIT = Maintenance Remove insulation from Mainland Powerhouse |
| 101* | -11- | 4-4-85 | See #1 - Loc 514, UNIT = Maintenance Remove insulation inside Mainland Powerhouse |
| 102* | -11- | 4-4-85 | See #1 - Loc 514 UNIT = Maintenance Remove insulation inside Mainland Powerhouse |
| 103* | -11- | 4-8-85 | See #1 - Loc 514, UNIT = Maintenance Remove insulation inside Mainland Powerhouse |
| 104* | -11- | 4-9-85 | See #1 - Loc 514, UNIT = Maintenance Removing insulation inside Mainland Powerhouse |
| 105* | -11- | 4-16-85 | See #1 - Loc 514 UNIT = Maintenance Removing insulation Mainland Powerhouse |
| 106* | -11- | 4-17-85 | See #1 - Loc 514, Bldg 49 UNIT = Maintenance, Removing insulation Mainland Powerhouse |
| 107* | -11- | 4-19-85 | See #1, Loc 514, Bldg 47, UNIT = maintenance, Removing insulation Mainland Power house |
| 108* | -11- | 4-22-85 | See #1, Loc 514, Bldg 151, UNIT = Pipe Strip asbestos from 10' level |
| 109* | -11- | 4-23-85 | See #1, Loc 514 - Bldg 47 UNIT = Maintenance. Strip asbestos from Powerhouse. |



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fi... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 10 of 19 asbestosclaims.law/library/18472/10

Audit Report # WV-0195

## DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 110 * | ASBESTOS-1985 | 4-25-85 | See #1 - Loc 514, Bldg 47, unit = maintenance, remove insulation, manhead powerhouse |
| 111 * | -11- | 5-1-85 | See #1 - Loc 514, Bldg 47, unit = maintenance, strip insulation from manhead powerhouse |
| 112 * | -11- | 5-6-85 | See #1 - Loc 514, Bldg 47, unit = maintenance, strip insulation from manhead powerhouse |
| 113 * | -11- | 5-9-85 | See #1 - Loc 514, Bldg 47, unit = maintenance, remove insulation from precipitator in MP #1, |
| 114 * | -11- | 5-15-85 | See #1 - Loc 514 Bldg 307 unit = maintenance, cutting gaskets from asbestos, |
| 115 * | -11- | 5-16-85 | See #1 - Loc 514, Bldg 320, unit = maintenance, cutting gaskets from asbestos |
| 116 * | -11- | 5-20-85 | See #1 - Loc 514 Bldg 47 unit = maintenance, strip asbestos from manhead powerhouse |
| 117 * | -11- | 5-21-85 | See #1 - Loc 514 Bldg 107 unit = laboratory, strip insulation from 1" line |
| 118 * | -11- | 5-21-85 | See #1 - Loc 514, Bldg 36, unit = Oxide products, strip asbestos from tanks 961, 962 |
| 119 * | -11- | 5-22-85 | See #1 - Loc 514, Bldg 36 unit = oxide products, strip asbestos from tanks 961, 962 |
| 120 * | -11- | 5-30-85 | See #1 - Loc 514, Bldg 47, unit = maintenance, contractor removing asbestos manhead powerhouse |
| 121 * | -11- | 6-3-85 | See #1 - Loc 514, Bldg 320 unit = maintenance, cutting gaskets |
| 122 * | -11- | 7-15-85 | See #1 - Loc 514, Bldg 156 unit = specialty catalyst, stripping asbestos from line. |
| 123 * | -11- | 8-29-85 | See #1 - Loc 514, Bldg 307, unit = fabrication shop - removing asbestos pad |



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fi... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 11 of 19 asbestosclaims.law/library/18472/11

Audit Report # WV-0195

## DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 124* | ASBESTOS - 1985 | 9-23-85 | See #1, Loc 514, Bldg 151 unit = IHP Strip insul. # 12 Boiler. |
| 125* | -11- | 10-3-85 | See #1, Loc 514, Bldg 307 unit = fabrication Shop, Strip asbestos from 4" line. |
| 126* | -11- | 10-10-85 | See #1, Loc 514, Bldg 208, unit = MICC, Remove insulation from 3" line. |
| 127* | -11- | 10-11-85 | See #1, Loc 514, Bldg 208 unit = MICC, Strip asbestos from #7 evaporator. |
| 128* | -11- | 10-22-85 | See #1, Loc 514, Bldg 157 unit = Union Chem Solutions, Remove insulation from 4" line. |
| 129* | -11- | 10-23-85 | See #1, Loc 514, unit = UICC Bldg 134, remove insulation from Steam line. |
| 130* | -11- | 11-12-85 | See #1, Loc 514, unit = Fabrication Shop, Change filters in air purifier. |
| 131* | -11- | 11-20-85 | See #1, Loc 514, Bldg 42, unit = Main Chem complex, Strip insulation from 2" steam line. |
| 132* | -11- | 11-25-85 | See #1 Loc 514, Bldg 106, unit = Laboratory, Suspected asbestos Contamination in area 15 |
| 133* | -11- | 12-13-85 | See #1, Loc 514, Bldg 42, unit = MAIN Chem. Complex, Remove insulation from 10" line. |
| 134* | ASBESTOS - 1986 | 1-9-86 | See #1 Loc 514, Bldg 151, unit = IPH = ISLAND Power House Remove insulation #12, 14 boilers |
| 135* | -11- | 1-6-86 | See #1, Loc 514, Bldg 151, unit = IPH - ISLAND Power House, Remove insulation by Contractors |
| 136* | -11- | 1-4-86 | See #1, Loc 514, Bldg 151 unit = IPH - ISLAND Power house, Contractor removal insulation #12, 14 boilers |
| 137* | -11- | 1-15-86 | See #1, Loc 514, Bldg 151, unit = IPH - ISLAND Power house - Contractor remove insulation #12, 14 boilers |



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fi... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 12 of 19 asbestosclaims.law/library/18472/12

Audit Report # WV-0195

DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 138* | Asbestos 5-1986 | 1-27-85?) 1-27-86 | See #1, Loc 514, B Bldg 151, Unit = IAP - SCADA power house, Sample for Asbestos After Contractors Finished |
| 139* | -u- | 2-5-86 | See #1, Loc 514, B Bldg 82 Unit = Maintenance, Monitor for Asbestos in basement |
| 140* | -u- | 2-13-86 | See #1, Loc 514, B Bldg 134, Unit = UICC Remove insulation from 1st floor, north |
| 141* | -u- | 4-30-86 | Employee Notification of occupational exposure monitoring results |
| 142* | -u- | 3-7-86 | Industrial Hygiene Survey Report - So. Charleston Plant |
| 143* | -u- | 4-17-86 | Employee notification of occupational exposure monitoring results |
| 144* | -u- | 4-17-86 | Industrial Hygiene Survey Report - So. Charleston Plant |
| 145* | -u- | 4-22-86 | See #1, Loc 514 - B Bldg 151, Unit = IAP Remove insulation from pipes between #14, 15 boilers |
| 146* | -u- | 4-30-86 | See #1, Loc 514 - Bldg 80, Unit = main Chem Complex, Remove insulation from pipes and employee monitoring results |
| 147* | -u- | 5-15-86 | See #1, Loc 514, B Bldg 174, 2FT, Unit = maintenance, Remove insulation from pipe rack, employee monitoring |
| 148* | -u- | 5-19-(85)? 5-19-86 | See #1, Loc 514, Bldg 154, Unit = UCC, Solution UIP, CS, Monitoring while contractor removes asbestos |
| 149* | -u- | 5-21-85 | See #1, Loc 514, B Bldg 154, Unit = UCC Solution UIP, CS - Monitor Condition while Contractor removes insulation |

UCC 0012622

Audit Report # WV-0195

## DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 150* | ASBESTOS - 1986 | 6-2-86 | See #1, Loc 514, Bldg 154, unit = UCAR Solutions - Vinyls - Measure asbestos under normal conditions |
| 151* | - " - | 6-4-86 | See #1, Loc 514, Bldg 51, unit = IPH Remove insulation from pipes in basement |
| 152* | - " - | 4-15-86 | See #1, Loc 514, Bldg 151, unit = IPH Remove insulation from a steam condensate line |
| 153* | - " - | 4-22-86 | See #1, Loc 514, Bldg 151, unit = IPH Remove insulation between #14, 15 boilers |
| 154* | - " - | 6-26-86 | See #1, Loc 514, Bldg 195, unit = Specialty Chemicals, Contractor remove insulation, monitor results |
| 155* | - " - | 6-27-86 | See #1, Loc 514, Bldg 195, unit = Specialty Chemicals, Monitor asbestos fibers |
| 156* | - " - | 7-30-86 | See #1, Loc 514, Bldg 151, unit = IPH Contractor removed insulation from pipes |
| 157* | - " - | 4-11-86 | See #1, Loc 514, Logan Pump Station |
| 158* | - " - | 8-1-86 | See #1, Loc 514 Bldg 151 unit = IPH Contractor removed insulation from pipes |
| 159* | - " - | 9-16-86 | See #1, Loc 514, Bldg 320, unit = FABRICATION SHOP - Removal cutting + Garlock 500 |
| 160* | - " - | 9-24-86 | See #1, Loc 514, Bldg 177, unit = UCAR Solutions Vinyls, Removal ABS from 4 levels on 5th floor. |
| 161* | - " - | 11-10-86 | See #1, Loc 514, unit = TRUCKING, Project = ABS |
| 162* | - " - | 11-1-86 | See #1, Loc 514, Bldg 701, unit = Maintenance, Remove insulation from #10 pumps |
| 163* | - " - | 11/4/86 | See #1, Loc 514, unit = TRUCKING Remove insulation to Landfill |



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fi... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 14 of 19 asbestosclaims.law/library/18472/14

Audit Report # WV-0195

## DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 164* | ASBESTOS-1986 | 11/5/86 | See #1, Loc 514, Unit=Truck... Moving insulation to landfill |
| 165* | -u- | 11-6-86 | See #1, Loc 514, Unit=TRUCKING, MOVING INSULATION to landfill |
| 166* | -u- | 11/11/86 | See #1, Loc 514, unit=TRUCKING, MOVING INSULATION to Landfill |
| 167* | -u- | 11-12-86 | See #1, Loc 514, unit=TRUCKING MOVING INSULATION TO LANDFILL |
| 168* | -u- | 11-13-86 | See #1, Loc 514, Bldg 307 unit= Maintenance, cutting Gaskets from Durlon 900 |
| 169* | -u- | 11-13-86 | See #1, Loc 514, Unit=Garage Relining Boilers |
| 170* | -u- | 11-17-86 | See #1, Loc 514, unit=TRUCKING, Moving Materials to landfill |
| 171* | -u- | 11-14-86 | See #1, Loc 514, Bldg 151, unit= IP#. Removing insulation from Lines. |
| 172* | -u- | 11-18-86 | See #1, Loc 514, unit=trucking Monitoring reports, moving Materials to landfill. |
| 173* | -u- | 12-5-86 | See #1, Loc 514, Bldg 151, unit= IP#. Removing ABS from #8 generation area Monitoring reports, |
| 174* | ASBESTOS-671 1987 | 1-15-87 | See #1, Loc 514, Bldg 106 Check for Asbestos in Bldg 106, Inside 105/106 |
| 175* | -u- | 1-20-87 | See #1, Loc 514 Bldg 174, unit=UICC Strip Asbestos from pipe... |
| 176* | -u- | 1-20-87 | See #1, Loc 514, Bldg 135, unit=UICC Contractor remove insulation |
| 177* | -u- | 1-21-87 | See #1, Loc 514, Bldg 36 unit= OXIDE ADDUCTS, remove insulation from pipe in dump... |



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fi... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 15 of 19 asbestosclaims.law/library/18472/15

Audit Report # WV-0195

## DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 178* | ASBESTOS-GW 1987 | 2-11-87 | See #1, Loc 514 Bldg 128, Unit = GARAGE. BRAKE JOB, Monitor Asbestos. |
| | | 3-18 to 23-87 | Hand written table, Bldg 303 asbestos survey |
| 179* | -11- | | |
| 180* | -11- | 3-19-87 | See #1, Loc 514, Bldg 303 Unit = airyard, Sample for asbestos, employee monitoring. |
| 181* | -11- | 3-18-87 | See #1, Loc 514, Bldg 303, Unit = airyards, employee monitoring |
| 182* | -11- | 3-11-87 | See #1, Loc 514, Bldg 106, Contractor removing insulation from pipe |
| 183* | -11- | [illegible] | See #1, Loc 514, Bldg 303, Unit = airyards, employee monitoring. |
| 184* | -11- | 5-22-87 | See #, Loc 514, Bldg 75, Sampling after asbestos removal |
| 185* | -11- | 6-22-87 | See #1, Loc 514, Bldg 82, Unit = office bldg. Employee monitoring. |
| 186* | -11- | 7-29-87 | See #1, Loc 514, Bldg 151, Unit = Maintenance, asbestos sampling. |
| 187* | -11- | 7-30 87 | See #1, Loc 514, Bldg 151 Unit = maintenance, employee monitoring. |
| 188* | -11- | 7-31-87 | See #1, Loc 514, Bldg 151, Unit = Maintenance, employee monitoring |
| 189* | -11- | 8-3 87 | See #1 Loc 514, Bldg 151, Unit = Maintenance, Monitor for asbestos in bldg. |
| 190* | -11- | 8-4 87 | See #1, Loc 514, Bldg 151, Unit = maintenance, monitor for asbestos in bldg. |
| 191* | -11- | 10-28-87 | See #1, Loc 514, Bldg 82, Unit = Maintenance, Sample for asbestos in Steam Chase [illegible] |



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fi... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 16 of 19 asbestosclaims.law/library/18472/16

Audit Report # WV-0195

## DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 192* | ASBESTOS-671 1987 | 8-21-87 | See #1, Lac 514, Bldg 8V, Unit = maintenance, Sample for asbestos in steam chase liner |
| 193* | -11- | Various | a Collection of letters/analytical results from Asbestos Testing, Inc. re work a Contractor Firm did at the So Charleston Plant. Employees were not Occ. |
| 194 Note(1) | Lab Notebook 1-KMS Industrial Hygiene measurements, CP plant 514 See doc 194, | 6-6-86 to - 5187 | Author KM Stevenson Relevant pages are: 8, 9, 70, 71, 72, 78, 79, 81, 82, 111, 133, |
| 195 Note(1) | 2-KMS See doc 194, | 2-4-87 to - (Current typing) | Author KM Stevenson, Relevant Pages are: 58, 59, 60, 64, 68, 70, |
| 196 Note(1) | 1-LEM | 4-10-86 to- 3-18-87 | Author LEMILLER III Relevant pages are: 2, 6, 11, 21, 23, 24, 26, 65, 66, 89, 97, 104, 118, 119, 120, 122, 133, 136, |
| 197 Note(1) | See doc 194, 2-LEM | 3-20-87 to 9-28-87 | Author L.E. Miller III Relevant Pages are: 1, 3, 5, 25, 30, 37, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64 65, 66, 67 68, 73, 74, 98, 99, 103, 104, 109, 110, 111, 119, 120, 121, 122, 123, 129, 130, 131, |
| 198 Note(1) | See doc 194 3-LEM See doc 194. | 10-29-87 to current typing 9-10-86 to | Author L.E. Miller III No relevant Pages to Page 50. |
| 199 Note(1) | 1-CLS-X See doc 194 | 4-28-87 4-9-87 to - | Author C.L. Staley II relevant pages are: 15, 39, 45, 46, |
| 200 Note(1) | 2-CLS-X | 10-31-87 | Author C.L. Staley II relevant pages are: 39, |
| | (Also received 3 WCY and 3 CLS-X but from No Asbestos data), | | |

Note (1) Laboratory Notebooks, the Custodian Plaintiff's Counsel to Explain the WV-0195 documents. In addition in many cases the lab Tech made Comments, Titles, Names etc. Page Notations. Core Docs: documents with J. Thomas who, Deposition to not [illegible] but were a Record of Lab Sys



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fi... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 17 of 19 asbestosclaims.law/library/18472/17

Note (1) Copy so it can be [illegible] These notebooks are part of the Industrial Hygiene Technician's Asbestos Fiber Notebooks WV-0017. The relevant pages are tested so that they could be easily located without browsing the entire [illegible] unit could be found.

UCC 0012627


Published by AsbestosClaims.Law
asbestosclaims.law/library/18472/18

Audit Report # WV-0195

DOCUMENT LIST

(Note: * indicates a core document)

| Doc. # | Folder Title | Doc. Date | Doc. Description |
|---|---|---|---|
| 201* | OSHREC MANUAL | 2/3/1/87 | NIOSH Course 582 Sampling and evaluating Airborne Asbestos Dust, The Univ. of N.C. at Chapel Hill. |
| | | | |
| 202 | ASBESTOS (DESK DRAWER) | 10/6/87 | Letter from S.W. Drake outlining the asbestos document search |
| | | | |
| 203 | — 4 — | May 1979 | Formulas for asbestos determinations, info from an asbestos course |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |



Union Carbide trial exhibit UC-3817: Audit Report WV-0195: Search of Industrial Hygiene Technician's Asbestos Fi... Published by AsbestosClaims.Law
ACL Doc 18472 · Page 19 of 19 asbestosclaims.law/library/18472/19