UNION CARBIDE

PLAINTIFF'S EXHIBIT

UC-4145

Mr. S. E Hine
Linde Division
Speedway Factory
4801 West 16th Street
Indianapolis Indiana 46224

November 21 1975

Medical Department

Mr P. J. Burtis
Mr. H. L. Phillips
Mr. R. M. Neary/Mr. B. Higdon
Dr. J. J. Welsh/Dr. K. S. Lane
Mr L. J. Suelter

Dear Mr Hine:

The air samples for asbestos taken at various factory locations during October have been evaluated with the following results:

Locations	Asbestos Fibers per ml 5 microns	Remarks
Machine shop: cutting cylinder open	< 1	Personnel Sample
Machine shop: cutting filler samples	< 1	Personnel Sample
Lance out Room	2	Normal operation· Door open
Shredder Room	12	Personnel Sample
Shredder Room· General	6	Blower on· 4M28 Asbestos
Top of asbestos mix tank	< 1	Asbestos visible on surfaces
Valve well drilling	< 1	Personnel Sample
Top Clearance inspection station	1	Personnel Sample
General Area· Dep t. 511	0	Considerable dust noted
General Area· Top of power cabinet	0	Considerable dust noted

A21868

X415696

Published by AsbestosClaims.Law
asbestosclaims.law/library/18750/1

UNION CARBIDE

Mr. S. E. Hine (2) November 21, 1975

Warehouse: Asbestos Storage Area	<1	Considerable dust noted
Small Metal Blast Room	1	Blasting WQ Cylinders

As can be seen from these results, the Shredder Room is still the location with levels of asbestos in excess of limits. Further work will be necessary at this operation to reduce the level of air borne asbestos fibers.

Very truly yours,

L. J. LaFrance
Industrial Hygienist

LJL/eg

A21669

X415697

Published by AsbestosClaims.Law
asbestosclaims.law/library/18750/3