PLAINTIFF'S EXHIBIT

UC-1909

9-7-89

Called EPA Hotline Number 1-800-424-9346

Re: Asbestos Containing Material

Dismantling of the Process area -

We are removing ~~the~~ and disposing of the asbestos insulation per the requirements

a question ~~has~~ ~~as~~ we need some guidance from you:

When a piece of equipment was insulated with asbestos - let's say a steam pipe these are the steps used to insulate the pipe:

1. a form of asbestos insulation was made and put around the ~~pipe~~ pipe
2. Another piece of insulation was wrapped around the pipe screen
3. Then a piece of cloth was wrapped around the pipe
4. A stainless piece of stainless steel ~~wire~~ band was wrapped around the insulation to

BRA 2954

5. Thin SS Sheeting to was wrapped around and secured to with SS bands to ~~secure the insulation~~ protect insulation from mechanical damage.

Classified — Sheeting

1-800-Asbestos-Number-
1-800-368-5888

BRA 2955

$ 10 /w transp. /per. equip.

30 + Transp. 5-10

40

2500

$6,000

$6,00 - Total = $250,000
(165,000)

Anticipated problems / hurdles

Community opposition

Legal issues