PLAINTIFF'S EXHIBIT

UC-1927

UNION CARBIDE CORPORATION
COATINGS MATERIALS DIVISION
P.O. BOX 3370, BROWNSVILLE, TEXAS 78520

October 24, 1990

Nus Laboratories
900 Gemini Ave.
Houston, Texas 77058

Re: Samples Taken from the Union Carbide Brownsville, Texas Plant to be analyzed for Asbestos Fibers.

Enclosed are 131 bags containing samples taken from various parts of the Union Carbide Brownsville, Texas Facility. The samples are to be analyzed for asbestos fibers. There are an additional 2 personnel samples included.

Per Ms. Christy Stewart, the cost of the analysis is $14 per sample. I gave Ms. Stewart our Purchase Order No. of 0526-133415 for the cost of the samples. I understand the results should be ready no later than October 26, 1990.

Please call me at (512) 831-4501 when the results are ready.

Thank you,

Belia Cortez
Site Manager

BRD 1402

UNION CARBIDE CORPORATION
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78520
(512) 831-4501

BULK SAMPLES:

SAMPLE NO.	DESCRIPTION
108A, 108B, 108C, AND 108D	PIPERACK AT BARGE DOCK
1	BLDG. 124 - CEILING TILE
200	BLDG. 166 - PIPE INSULATION
201	BLDG. 166 - PIPE INSULATION
202	BLDG. 166 - FLOOR TILE - 4TH FLOOR
203	BLDG. 166 - CONDUIT INSULATION - 4TH ROOM
204	BLDG. 166 - PIPE INSULATION - SOUTH ROOM
205	#511 - INSULATION ROOM
206	#511 - PIPE INSULATION
207	#511 - FLOOR TILE
208	BLDG. 166- PIPE OUTER WEST WALL
209	BLDG. 166- PIPERACK WEST
210	BLDG.168 - 1ST ROOM RH PIPE
211	BLDG. 168 - FLOOR TILE 1ST ROOM RH
212	CEILING TILE BY STAIRS
213	PIPERACK EAST OF SUB 4
214	PIPE UNLOADING AREA ACROSS ES
215	PIPE UNLOADING AREA ACRISS ES
216	PIPE
217	PIPE ON PIPERACK 1ST PIPE SOUTH SIDE

BRD 1403

BULK SAMPLES - UCC BROWNSVILLE, TEXAS CONTINUED: PAGE 2

SAMPLE NO.	DESCRIPTION
218 neg.	PIPE ON PIPERACK 3RD PIPE ON SOUTH SIDE
219 neg.	PIPE ON PIPERACK 4TH PIPE ON SOUTH SIDE
220 neg.	PIPE ON PIPERACK 5TH PIPE ON SOUTH SIDE
221 neg.	PIPE ON PIPERACK 6TH PIPE ON SOUTH SIDE
222 neg.	PIPE ON PIPERACK 7TH PIPE ON SOUTH SIDE
224 pos	PIPERACK FRONT OXYGEN PLANT - 1ST PIPE TOP
225 neg.	PIPERACK IN FRONT O2 2ND PIPE - BOTTOM
226 pos.	PIPERACK - O2, 3RD PIPE
227 pos.	PIPERACK - O2, 4TH PIPE
229 pos.	PIPERACK - O2, 5TH PIPE
230 pos.	PIPE WEST OF SUB 2, BY CONCRETE WALL
231 pos.	PIPE WEST OF SUB 2, BY FLANGE
232 pos.	PIPE WEST OF SUB 2, ELBOW
233 neg.	200# STEAM LINE ACROSS SALVAGE
234 neg.	CONDENSATE LINE ACROSS FROM SALVAGE
235 pos.	2ND 200# STEAM LINE ACROSS SALVAGE
236 pos.	CITY WATER LINE ACROSS SALVAGE
237 pos	PIPE - INCINERATOR
238 neg.	LINE BY ROADWAY ACROSS SALVAGE CORNER 7TH AVE.
239 pos	ACROSS TANK 3321 MIDDLE PIPE
240 neg.	PIPE ON PIPERACK 2ND PIPE SOUTH SIDE
100A pos	PIPE RACK WEST OF BLK 52
100B pos	PIPE RACK WEST OF BLK 52

BRD 1404

BULK SAMPLES - UCC BROWNSVILLE, TEXAS CONTINUED

SAMPLE NO.	DESCRIPTION
100D pos.	PIPE RACK WEST OF BLK 52
100E neg.	PIPE RACK WEST OF BLK 52
100F neg.	PIPE RACK WEST OF BLK 52
101A neg.	PIPE RACK WEST OF F STREET
101B pos.	PIPE RACK WEST OF F STREET
101C pos.	PIPE RACK WEST OF F STREET
102A pos.	PIPE RACK WEST OF BLK 22
102B neg.	PIPE RACK WEST OF BLK 22
102C neg.	PIPE RACK WEST OF BLK 22
103A pos.	PIPE RACK WEST OF D STREET
103B neg.	PIPE RACK WEST OF D STREET
103C neg.	PIPE RACK WEST OF D STREET
104A pos.	PIPE RACK WEST OF BLDG 123
104B pos.	PIPE RACK WEST OF BLDG. 123
104C neg.	PIPE RACK WEST OF BLDG. 123
105A neg.	PIPE RACK WEST OF A STREET
105B neg.	PIPE RACK WEST OF A STREET
105C pos.	PIPE RACK WEST OF A STREET
105D neg.	PIPE RACK WEST OF A STREET
105E pos.	PIPE RACK WEST OF A STREET
106A neg.	PIPE RACK WEST OF BLK 12
106B pos.	PIPE RACK WEST OF BLK 12
106C neg.	PIPE RACK WEST OF BLK 12
107A neg.	PIPE RACK BETWEEN 1ST & 2ND AVE

BRD 1405

BULK SAMPLES - UCC BROWNSVILLE, TEXAS PAGE 4

SAMPLE NO.	DESCRIPTION
107B neg.	PIPE RACK BETWEEN 1ST & 2ND AVE.
107C neg.	PIPE RACK BETWEEN 1ST & 2ND AVE.
109A neg.	PIPE RACK WEST OF TK 1216
109B neg.	PIPE RACK WEST OF TK 1216
110A neg.	TANK 1216
110B neg.	TANK 1216
110C neg.	TANK 1216
111A pos.	PIPE RACK WEST OF 1ST ST.
111B pos.	PIPE RACK WEST OF 1ST ST.
111C pos.	PIPE RACK WEST OF 1ST ST.
111D pos.	PIPE RACK WEST OF 1ST ST.
111E pos.	PIPE RACK WEST OF 1ST ST.
112A pos.	TK FM AREA 12
112B neg.	TK FM AREA 12
112C neg.	TK FM AREA 12
113A pos.	TK FM AREA 13
113B pos.	TK FM AREA 13
113C pos.	TK FM AREA 13
114A neg.	PIPE RACK WEST OF BLK 14
114B neg.	PIPE RACK WEST OF BLK 14
115A neg.	PIPE RACK BLK 24 BETWEEN OIL TANKS
115B neg.	PIPE RACK BLK 24 BETWEEN OIL TANKS
115C negative	PIPE RACK BLK 24 BETWEEN OIL TANKS

BRD 1406

BULK SAMPLES - UCC BROWNSVILLE, TEXAS PAGE 5

SAMPLE NO.	DESCRIPTION
115D Negative	PIPE RACK BLK 24 BETWEEN OIL TANKS
115E Negative	PIPE RACK BLK 24 BETWEEN OIL TANKS
115F Negative	PIPE RACK BLK 24 BETWEEN OIL TANKS
115G Negative	PIPE RACK BLK 24 BETWEEN OIL TANKS
116A Negative	ABSORBER COL. BLK 94
116B Negative	ABSORBER COL. BLK 94
116C Negative	ABSORBER COL. BLK 94
116D Negative	ABSORBER COL. BLK 94
117A Negative	BATCH STILL
117B Negative	BATCH STILL
117C Negative	BATCH STILL
117D Negative	BATCH STILL
2 Positive	OXYGEN PLANT TURBINE
241 Negative	SOUTH SIDE 48
242 Positive	BLDG. 168 - NORTHWEST CORNER OUTSIDE
243 Positive	BLDG. 168 - NORTHWEST CORNER OUTSIDE
244 Negative	BLDG. 168 - NORTHWEST CORNER OUTSIDE
245 Positive	BLDG. 168 - NORTHWEST CORNER OUTSIDE
246 Negative	BLDG. 221 FLOOR TILE
247 Negative	BLDG. 124 CEILING TILE
248 Positive	BLDG. 124 FURNACE ROOM
249 Positive	BLDG. 124 FLOOR

BRD 1407

BULK SAMPLES - UCC BROWNSVILLE, TEXAS CONTINUED PAGE 6

SAMPLE NO.	DESCRIPTION
250 positive	BLDG. 224 FLOOR
251 positive	300' NORTH OF OXYGEN PIPERACK
252 negative	BLDG. 422 FURNACE ROOM
253 positive	BLDG. 422 FLOOR
254 negative	BLDG. 425 CEILING BY ALB'S OFFICE
255 positive	BLDG. 425 FLOOR
256 negative	INSULATED PIPE IN QUONSET
257 positive	BLDG. 259 BOILER ROOM
258 positive	BLDG. 259 INSULATED PIPES
259 negative	BLDG. 259 FLOOR TILE
260 positive	BLDG. 364 #1 COC
261 positive	BLDG. 364 #2 COC
262 positive	BLDG. 221 INSULATED PIPE
263 positive	BLDG. 221 INSULATED PIPE
264 positive	BLDG. 163 INSULATED PIPE
265 14.0 F/mm2	PERSONNEL SAMPLE
266 <0.64 F/mm2	PERSONNEL SAMPLE - BLANK

BRD 1408

Union Carbide trial exhibit UC-1927: Bella Cortez to NUS Laboratories Transmitting Brownsville Plant Samples for...
ACL Doc 16986 · Page 8 of 17

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2796
713-488-1610

REPORT TO:		INVOICE TO:		☑ CHECK BOX
COMPANY	UNION CARBIDE CORP	COMPANY		IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS	STAR ROUT, BOX 90	ADDRESS		
CITY / STATE / ZIP	BROWNSVILLE / TX / 78521	CITY / STATE / ZIP		P.O. #
ATT. / PHONE	B. CORTEZ / (512)831-4501	ATT. / PHONE #		RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPELS FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1									
2	103 C				✓	PIPERACK WEST OF "D" ST.	1	✓	
3	104 A					" " " BLDG. 123			
4	104 B					" " " "			
5	104 C					" " " "			
6	105 A					" " " "A" ST.			
7	105 B					" " " "			
8	105 C					" " " "			
9	105 D					" " " "			
10	105 E					" " " "			
11	106 A					" " " BLK. 12			
12	106 B					" " " "			
13	106 C					" " " "			
14	107 A					" BETWEEN 1ST & 2ND AVE			
15	107 B					" " " "			

RELINQUISHED BY: SIGN — Bella Cortez 10/24/90 4:30pm	DATE/TIME	RECEIVED BY: SIGN	
RELINQUISHED BY: SIGN	DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN	DATE/TIME
CARRIER CO		AIR BILL NO	
RELINQUISHED BY: SIGN	DATE/TIME	RECEIVED BY: SIGN	
SAMPLE CONDITION			
CARRIER PHONE #		DATE RESULTS REPORTED BY: SIGN	DATE/TIME

BRD 1409

Published by AsbestosClaims.Law
asbestosclaims.law/library/16986/8

Union Carbide trial exhibit UC-1927: Belia Cortez to NUS Laboratories Transmitting Brownsville Plant Samples for...
ACL Doc 16986 · Page 9 of 17

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2796
713-488-1810

REPORT TO:		INVOICE TO:		☑ CHECK BOX
COMPANY	UNION CARBIDE CORP	COMPANY		IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS	STAR ROUT, BOX 90	ADDRESS		
CITY	BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP		P.O. #
ATT.	B. CORTEZ PHONE (512)831-4501	ATT. PHONE #		RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPELS FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1	10/24/90	4 PM							
2	240				✓	PIPE ON PIPERACK, 2ND PIPE-S. SIDE	1	✓	
3	100 A					PIPERACK WEST OF BLK 52			
4	100 B					" " " "			
5	100 D					" " " "			
6	100 E					" " " "			
7	100 F					" " " "			
8	101 A					" " " "F" ST			
9	101 B					" " " " "			
10	101 C					" " " " "			
11	102 A					" " " BLK 22			
12	102 B					" " " "			
13	102 C					" " " "			
14	103 A					" " " "D" ST.			
15	103 B					" " " " "			

RELINQUISHED BY: SIGN Belia Cortez 10/24/90 4:30 pm DATE/TIME	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME	SAMPLE CONDITION	
CARRIER CO	AIR BILL NO	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1410

Published by AsbestosClaims.Law
asbestosclaims.law/library/16986/9

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1510

REPORT TO:		INVOICE TO:		☑ CHECK BOX
COMPANY	UNION CARBIDE CORP	COMPANY		IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS	STAR ROUT, BOX 90	ADDRESS		
CITY	BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP		P.O. #
ATT.	B. CORTEZ PHONE (512)831-4501	ATT. PHONE #		RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPELS FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1		10/24/90	4 PM				1		
2	225				✓	PIPERACK FRONT O2, 2ND PIPE BTM		✓	
3	226					" " " 3RD PIPE			
4	227					" " " 4TH "			
5	229					" " " 5TH "			
6	230					PIPE WEST SUB2, BY CONCRETE WALL			
7	231					" " " , BY FLANGE			
8	232					" " " , ELBOW			
9	233					200# STM. LINE ACROSS SALVAGE			
10	234					CONDENSATE " " "			
11	235					2ND. 200# STM. LINE " "			
12	236					CITY WATER " " "			
13	237					PIPE - INCINERATOR			
14	238					LINE BY ROAD, ACROSS SALVAGE, 7TH AVE			
15	239					ACROSS TANK 3321 2ND PIPE S. SIDE			

RELINQUISHED BY: SIGN Belia Cortez DATE/TIME 10/24/90 4:30pm	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME	SAMPLE CONDITION	
CARRIER CO	AIR BILL NO.	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1411

Union Carbide trial exhibit UC-1927: Belia Cortez to NUS Laboratories Transmitting Brownsville Plant Samples for...
ACL Doc 16986 · Page 10 of 17
Published by AsbestosClaims.Law
asbestosclaims.law/library/16986/10

Union Carbide trial exhibit UC-1927: Belia Cortez to NUS Laboratories Transmitting Brownsville Plant Samples for...
ACL Doc 16986 · Page 11 of 17

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
500 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1610

REPORT TO:		INVOICE TO:		☑ CHECK BOX
COMPANY	UNION CARBIDE CORP	COMPANY		IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS	STAR ROUT, BOX 90	ADDRESS		
CITY	BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP		P.O. #
ATT.	B. CORTEZ PHONE (512)831-4501	ATT. PHONE #		RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPELS FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1	19	10/24/90	4pm						
2	210				✓	BLDG. 168 - 1ST. ROOM RH PIPE	1	✓	
3	211					" " - FLOOR TILE, 1ST ROOM RH			
4	212					CEILING TILE BY STAIRS			
5	213					PIPERACK EAST OF SUB 4			
6	214					PIPE UNLOADING AREA ACROSS ES			
	215					" " " " "			
	216					PIPE			
	217					PIPE ON PIPERACK, 1ST PIPE S. SIDE			
	218					" " " 3RD. " " "			
	219					" " " 4TH " " "			
	220					" " " 5TH " " "			
	221					" " " 6TH " " "			
	222					" " " 7TH " " "			
	224				↓	PIPERACK FRONT O2 PLANT, 1ST. PIPE TOP	↓		

RELINQUISHED BY: SIGN Belia Cortez 10/24/90 4:30pm. DATE/TIME	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME	SAMPLE CONDITION	
CARRIER CO.	AIR BILL NO.	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1412

Published by AsbestosClaims.Law
asbestosclaims.law/library/16986/11

Union Carbide trial exhibit UC-1927: Bella Cortez to NUS Laboratories Transmitting Brownsville Plant Samples for...
ACL Doc 16986 · Page 12 of 17

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2796
713-488-1810

REPORT TO:	INVOICE TO:	☑ CHECK BOX
COMPANY UNION CARBIDE CORP	COMPANY	IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUT, BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE (512)831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPELS FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1	10/24/90 4PM								
2	108A				✓	PIPE RACK AT BARGE DOCK	1	✓	
3	108B					" "	1	✓	
4	108C					" "	1	✓	
5	108D					" "	1	✓	
6	200					BLDG. 166 - PIPE INSULATION	1	✓	
7	201					" " " "	1	✓	
8	202					" " FLOOR TILE, 4TH FLOOR	1	✓	
9	203					" " CONDUIT INSUL. 4TH ROOM	1	✓	
10	204					" " PIPE INSUL. - SOUTH ROOM	1	✓	
11	205					#511 - INSULATION ROOM	1	✓	
12	206					" - PIPE INSULATION	1	✓	
13	207					" - FLOOR TILE	1	✓	
14	208					BLDG. 166 - PIPE OUTER WEST WALL	1	✓	
15	209				✓	" " - PIPERACK WEST	1	✓	

RELINQUISHED BY: SIGN Bella Cortez DATE/TIME 10/24/90 4:30pm	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME	SAMPLE CONDITION	
CARRIER CO	AIR BILL NO.	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1413

Published by AsbestosClaims.Law
asbestosclaims.law/library/16986/12

Union Carbide trial exhibit UC-1927: Bella Cortez to NUS Laboratories Transmitting Brownsville Plant Samples for...
ACL Doc 16986 · Page 13 of 17

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2796
713-488-1810

REPORT TO:	INVOICE TO:	☑ CHECK BOX
COMPANY UNION CARBIDE CORP	COMPANY	IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUT, BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE (512)831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPELS FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1									
2	107 C				✓	PIPERACK BETWEEN 1ST & 2ND AVE	1	✓	
3	109 A					" WEST OF TK 1216			
4	109 B					" " " "			
5	110 A					TANK 1216			
6	110 B					" "			
7	110 C					" "			
8	111 A					PIPERACK WESTOF 1ST. ST.			
9	111 B					" " "			
10	111 C					" " "			
11	111 D					" " "			
12	111 E					" " "			
13	112 A					TK FM AREA 12			
14	112 B					" " "			
15	112 C					" " "			

RELINQUISHED BY: SIGN Bella Cortez DATE/TIME 10/24/90 4:30pm	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME	SAMPLE CONDITION	
CARRIER CO	AIR BILL NO	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1414

Published by AsbestosClaims.Law
asbestosclaims.law/library/16986/13

Union Carbide trial exhibit UC-1927: Bella Cortez to NUS Laboratories Transmitting Brownsville Plant Samples for...
ACL Doc 16986 · Page 14 of 17

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2796
713-488-1810

REPORT TO:		INVOICE TO:	
COMPANY	UNION CARBIDE CORP	COMPANY	☑ CHECK BOX IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS	STAR ROUT, BOX 90	ADDRESS	
CITY	BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT.	B. CORTEZ PHONE (512)831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPELS FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1	10/29/90 4PM								
2	113 A				✓	TK FM AREA 13	1	✓	
3	113 B					" " " "			
4	113 C					" " " "			
5	114 A					PIPERACK WEST OF BLK 14			
6	114 B					" " " "			
7	115 A					" BLK 24 BETWEEN OIL TANKS			
8	" B					" " " "			
9	" C					" " " "			
10	" D					" " " "			
11	" E					" " " "			
12	" F					" " " "			
13	" G					" " " "			
14	116 A					ABSORBER COL BLK 94			
15	116 B					" " " "			

RELINQUISHED BY: SIGN Bella Cortez DATE/TIME 10/29/90 4:30 pm	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME	SAMPLE CONDITION	
CARRIER CO	AIR BILL NO.	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1415

Published by AsbestosClaims.Law
asbestosclaims.law/library/16986/14

Union Carbide trial exhibit UC-1927: Belia Cortez to NUS Laboratories Transmitting Brownsville Plant Samples for...
ACL Doc 16986 · Page 15 of 17
Published by AsbestosClaims.Law
asbestosclaims.law/library/16986/15

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
500 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1810

REPORT TO:	INVOICE TO:	☑ CHECK BOX
COMPANY UNION CARBIDE CORP	COMPANY	IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUT, BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE (512)831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPELS FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1		10/24/90	4P						
2	116	D			✓	ABSORBER COL. BLK 9 4	1	✓	
3	117	A				BATCH STILL			
4	"	B				" "			
5	"	C				" "			
6	"	D				" "			
7	2					OL PLANT TURBINE			
8	241					S. SIDE 48			
9	242					BLDG. 168 N.W. CORNER OUTSIDE			
10	243					" " " "			
11	244					" " " "			
12	245					" " " "			
13	246					" 221 FLOOR TILE			
14	247					" 124 CEILING TILE			
15	248					" " FURNACE ROOM			

RELINQUISHED BY: SIGN Belia Cortez 10/24/90 4:30pm DATE/TIME	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME	SAMPLE CONDITION	
CARRIER CO	AIR BILL NO.	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1416

Union Carbide trial exhibit UC-1927: Belia Cortez to NUS Laboratories Transmitting Brownsville Plant Samples for...
ACL Doc 16986 · Page 16 of 17

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
500 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1610

REPORT TO:		INVOICE TO:		☑ CHECK BOX
COMPANY	UNION CARBIDE CORP	COMPANY		IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS	STAR ROUT, BOX 90	ADDRESS		
CITY	BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP		P.O. #
ATT.	B. CORTEZ PHONE (512)831-4501	ATT. PHONE #		RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPELS		
FOR ASBESTOS		
ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1									
2	249				✓	BLDG. 124 FLOOR	1		
3	250					" 224 "			
4	251					300' N. OF O2 PIPERACK			
5	252					BLDG 422 FURNACE ROOM			
6	253					" " FLOOR			
7	254					" 425 CEILING BY ALB's OFFICE			
8	255					" " FLOOR			
9	256					INSULATED PIPE IN QUONSET			
10	257					BLDG. 259 BOILER ROOM			
11	258					" " INSULATED PIPES			
12	259					" " FLOOR TILE			
13	260					" 36# #1 COC			
14	261					" " #2 "			
15	262					BLDG. 221 INSULATED PIPE			

RELINQUISHED BY: SIGN Belia Cortez 10/24/90 4:30 pm DATE/TIME	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME	SAMPLE CONDITION	
CARRIER CO	AIR BILL NO	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1417

Published by AsbestosClaims.Law
asbestosclaims.law/library/16986/16

Union Carbide trial exhibit UC-1927: Bella Cortez to NUS Laboratories Transmitting Brownsville Plant Samples for...
ACL Doc 16986 · Page 17 of 17

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2796
713-488-1810

REPORT TO:		INVOICE TO:		☑ CHECK BOX
COMPANY	UNION CARBIDE CORP	COMPANY		IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS	STAR ROUT, BOX 90	ADDRESS		
CITY	BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP		P.O. #
ATT.	B. CORTEZ PHONE (512)831-4501	ATT. PHONE #		RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPELS FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1		10/24/90	4pm		•		1		
2	263				✓	BLDG 221 INSULATED PIPE		✓	
3	264					" 163 " "			
4	265					PERSONNEL SAMPLE			
5	266					" " -BLANK			
6									

RELINQUISHED BY: SIGN Bella Cortez DATE/TIME 10/24/90 4:30pm	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME	SAMPLE CONDITION	
CARRIER CO	AIR BILL NO	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1418

Published by AsbestosClaims.Law
asbestosclaims.law/library/16986/17