PLAINTIFF'S EXHIBIT

UC-1928

UNION CARBIDE CORPORATION
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78520
(512) 831-4501

BULK SAMPLES:

SAMPLE NO.		DESCRIPTION
267	Negative	BLDG. 166 ROOF TAR S END CENTER
268	Negative	BLDG. 166 ROOF FIBER S END CENTER
269	Negative	BLDG. 167 ROOF LAYER UNDER TAR
270	Negative	BLDG. 167 ROOF TAR N END CENTER
300	Positive	BLDG. 168 PIPE
301	Positive	BLDG. 168 PIPE
302	Negative	BLDG. 161 CEILING
303	Positive	BLDG. 161 PIPING
304	Positive	BLDG. 161 FLOOR
305	Positive	BLDG. 162 PIPE
306	Positive	BLDG. 164 PIPE
307	Negative	BLDG. 167 CEILING
308	Negative	BLDG. 166 CEILING
309	Negative	BLDG. 221 CEILING
310	Negative	BLDG. 123 CEILING
311	Negative	BLDG. 123 FLOOR
312	Positive	BLDG. 123 PIPE
313	Negative	BLDG. 230 CEILING
314	Negative	BLDG. 224 CEILING
315	Negative	BLDG. 224 A/C DUCT
316	Negative	BLDG. 230 FLOOR

BRD 1419

SAMPLE NO.		DESCRIPTION
317	positive	BLDG. 420 FLOOR
318	Negative	BLDG. 420 CEILING
319	Negative	BLDG. 422 CEILING
320	Negative	BLDG. 424 PIPE
321	Negative	BLDG. 425 FLOOR
322	Negative	BLDG. 424 CEILING
323	positive	BLDG. 424A PIPE
324	positive	BLDG. 425 PIPE
325	positive	BLDG. 425 A/C DUCT
326	Negative	BLDG. 428 FLOOR
327	Negative	BLDG. 428 CEILING
328	Negative	BLDG. 428 CEILING
329	Negative	BLDG. 525 CEILING
330	Negative	BLDG. 525 PIPE
331	Negative	BLDG. 523 FLOOR
332	Negative	BLDG. 523 CEILING
333	Negative	BLDG. 522 FLOOR
334	Negative	BLDG. 522 CEILING
335	Negative	BLDG. 821 FLOOR
336	Negative	BLDG. 821 CEILING
337	Negative	BLDG. 489 FLOOR
338	Negative	BLDG. 489 CEILING
339	Negative	BLDG. 625 FLOOR
340	Negative	BLDG. 625 CEILING

BRD 1420

BULK SAMPLES - UNION CARBIDE BROWNSVILLE, TEXAS PAGE 3

SAMPLE NO.	DESCRIPTION	
341 Negative	BLDG. 625	A/C DUCT
341A Negative	BLDG. 731	FLOOR
342 Negative	BLDG. 731	CEILING
343 Negative	BLDG. 731	A/C DUCT
344 Negative	BLDG. 731	PIPE
345 Negative	BLDG. 168	ROOF CENTER
346 Negative	BLDG. 168	ROOF B TAR
347 Negative	BLDG. 168	ROOF TOP LAYER
348 Negative	BLDG. 259	CEILING HALL
349 Positive	BLDG. 259	R. ROOM PIPE
371 Positive	BLDG. 731	ROOF (TOP)
372 Positive	BLDG. 422	PIPE IN CEILING
373 Negative	BLDG. 422	PIPE IN CEILING
374 Negative	BLDG. 731	ROOF (BOTTOM)
375 Negative	BLDG. 731	ROOF MIDDLE LAYER

Union Carbide trial exhibit UC-1928: Union Carbide Brownsville, Texas Plant Bulk Sample Results and Belia Cortez… Published by AsbestosClaims.Law
ACL Doc 16987 · Page 3 of 11 asbestosclaims.law/library/16987/3

UNION CARBIDE CORPORATION
COATINGS MATERIALS DIVISION
STAR ROUTE BOX 90 BROWNSVILLE, TEXAS 78521

November 7, 1990

NUS Laboratories
900 Gemini
Houston, Texas 77058

Re: Additional Samples Taken from the Union Carbide Brownsville, Texas Plant to be Analyzed for Asbestos Fibers.

Enclosed are 60 bags containing additional samples taken from various parts of the Union Carbide Brownsville, Texas Facility. The samples are to be analyzed for asbestos fibers. These are in adddition to the 136 previously sent in.

The cost of the analysis will be against the existing Purchase Order No. of 0526-133415. Please call me at (512) 831-4501 as soon as the results are available. You can fax the results to us at (512) 831-5278.

Thank you,

Belia Cortez
Site Manager

BRD 1422

Union Carbide trial exhibit UC-1928: Union Carbide Brownsville, Texas Plant Bulk Sample Results and Belia Cortez...
ACL Doc 16987 · Page 5 of 11
Published by AsbestosClaims.Law
asbestosclaims.law/library/169875

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
800 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2799
713-486-1010

REPORT TO:	INVOICE TO:	☑ CHECK BOX
COMPANY UNION CARBIDE, CORP.	COMPANY	IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUTE BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT B. CORTEZ PHONE # (512)831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
	11-7-90		10AM						
1	326				✓	BLDG. 428 FLOOR	1	✓	
2	327					" " CEILING			
3	328					" " "			
4	329					" 525 "			
5	330					" 525 PIPE			
6	331					" 523 FLOOR			
7	332					" " CEILING			
8	333					" 522 FLOOR			
						" " CEILING			
						" 821 FLOOR			
						" " CEILING			
						" 489 FLOOR			
						" " CEILING			
						" 625 FLOOR			
					✓	" 625 CEILING	↓	↓	

BRD 1423

RELINQUISHED BY: SIGN	DATE/TIME	RECEIVED BY: SIGN
Belia Cortez	5 P.M. 11/7/90	
RELINQUISHED BY: SIGN	DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN / DATE/TIME
SAMPLE CONDITION		
AIR BILL NO		CARRIER PHONE #
DATE RESULTS REPORTED BY: SIGN / DATE/TIME		

Union Carbide trial exhibit UC-1928: Union Carbide Brownsville, Texas Plant Bulk Sample Results and Belia Cortez...
ACL Doc 16987 · Page 6 of 11
Published by AsbestosClaims.Law
asbestosclaims.law/library/1698716

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
800 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1810

REPORT TO:		INVOICE TO:		☑ CHECK BOX
COMPANY	UNION CARBIDE, CORP.	COMPANY		IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS	STAR ROUTE BOX 90	ADDRESS		
CITY / STATE / ZIP	BROWNSVILLE TX 78521	CITY / STATE / ZIP		P.O. #
ATT / PHONE	B. CORTEZ (512)831-4501	ATT. / PHONE #		RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
	11-7-90		10AM						
1	311				✓	BLDG. 123 FLOOR	1	X	
2	312					" " PIPE			
3	313					" 230 CEILING			
4	314					" 224 "			
5	315					" " A/C DUCT			
6	316					" 230 FLOOR			
7	317					" 420 "			
						" " CEILING			
						" 422 "			
						" 424 PIPE			
						" 425 FLOOR			
						" 424 CEILING			
						" 424A PIPE			
						" 425 "			
					✓	" " A/C DUCT			

BRD 1424

RELINQUISHED BY SIGN	DATE/TIME	RECEIVED BY SIGN	RELINQUISHED BY SIGN	DATE/TIME	RECEIVED BY SIGN
Belia Cortez	5PM. 11/7/90				
RELINQUISHED BY SIGN	DATE/TIME	RECEIVED FOR LABORATORY BY SIGN / DATE/TIME	SAMPLE CONDITION		
P.O.		AIR BILL NO	CARRIER PHONE #		DATE RESULTS REPORTED BY SIGN / DATE/TIME

Union Carbide trial exhibit UC-1928: Union Carbide Brownsville, Texas Plant Bulk Sample Results and Belia Cortez...
ACL Doc 16987 · Page 7 of 11
Published by AsbestosClaims.Law
asbestosclaims.law/library/1698717

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
800 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1810

REPORT TO:	INVOICE TO:	
COMPANY UNION CARBIDE, CORP.	COMPANY	☑ CHECK BOX IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUTE BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE (512)831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS	PLEASE FAX RESULTS WHEN FINISHED. FAX NO. (512) 831-5278	

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1	267	11-7-90	10AM		✓	BLDG. 166 ROOF TAR S. END CENTER	1		
2	268					" " " FIBER " " "			
3	269					" 167 " LAYER UNDER TAR			
4	270					" " " TAR N. END CENTER			
5	300					" 168 PIPE			
6	301					" " "			
7	302					" 161 CEILING			
8	303					" " PIPING			
						" " FLOOR			
						" 162 PIPE			
						" 164 "			
						" 167 CEILING			
						" 166 "			
						" 221 "			
		↓	↓		↓	" 123 "	↓	↓	

RELINQUISHED BY: SIGN	DATE/TIME	RECEIVED BY: SIGN
[signature]	5 P.M. 11/7/90	
RELINQUISHED BY: SIGN	DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME
		SAMPLE CONDITION
AIR BILL NO		CARRIER PHONE #
		DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1425

Union Carbide trial exhibit UC-1928: Union Carbide Brownsville, Texas Plant Bulk Sample Results and Belia Cortez...
ACL Doc 16987 · Page 8 of 11
Published by AsbestosClaims.Law
asbestosclaims.law/library/1698718

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1810

REPORT TO:	INVOICE TO:	
COMPANY UNION CARBIDE, CORP.	COMPANY	☑ CHECK BOX IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUTE BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE # (512) 831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
		11-7-90	10AM						
1	341				✓	BLDG. 625 A/C DUCT	1	✓	
2	341-A					" 731 FLOOR			
3	342					" " CEILING			
4	343					" " A/C DUCT			
5	344					" " PIPE			
6	345					" 168 ROOF CENTER			
7	346					" " ROOF B TAR			
8						" " " TOP LAYER			
9						" 259 CEILING HALL			
10						" 259 R. Room PIPE			
11						" 731 ROOF (TOP)			
12						" 422 PIPE IN CEILING			
13						" " " " "			
14						" 731 ROOF (BOTTOM)			
15						" " " MIDDLE LAYER			

RELINQUISHED BY: SIGN [signature] DATE/TIME 5 P.M. 11/7/90	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME	SAMPLE CONDITION	
CARRIER CO	AIR BILL NO	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1426

UNION CARBIDE CORPORATION
STAR ROUTE BOX 90
BROWNSVILLE, TEXAS 78520
(512) 831-4501

BULK SAMPLES:

SAMPLE NO.	DESCRIPTION
267	BLDG. 166 ROOF TAR S END CENTER
268	BLDG. 166 ROOF FIBER S END CENTER
269	BLDG. 167 ROOF LAYER UNDER TAR
270	BLDG. 167 ROOF TAR N END CENTER
300	BLDG. 168 PIPE
301	BLDG. 168 PIPE
302	BLDG. 161 CEILING
303	BLDG. 161 PIPING
304	BLDG. 161 FLOOR
305	BLDG. 162 PIPE
306	BLDG. 164 PIPE
307	BLDG. 167 CEILING
308	BLDG. 166 CEILING
309	BLDG. 221 CEILING
310	BLDG. 123 CEILING
311	BLDG. 123 FLOOR
312	BLDG. 123 PIPE
313	BLDG. 230 CEILING
314	BLDG. 224 CEILING
315	BLDG. 224 A/C DUCT
316	BLDG. 230 FLOOR

Union Carbide trial exhibit UC-1928: Union Carbide Brownsville, Texas Plant Bulk Sample Results and Belia Cortez… Published by AsbestosClaims.Law
ACL Doc 16987 · Page 9 of 11 asbestosclaims.law/library/16987/9

SAMPLE NO.	DESCRIPTION
317	BLDG. 420 FLOOR
318	BLDG. 420 CEILING
319	BLDG. 422 CEILING
320	BLDG. 424 PIPE
321	BLDG. 425 FLOOR
322	BLDG. 424 CEILING
323	BLDG. 424A PIPE
324	BLDG. 425 PIPE
325	BLDG. 425 A/C DUCT
326	BLDG. 428 FLOOR
327	BLDG. 428 CEILING
328	BLDG. 428 CEILING
329	BLDG. 525 CEILING
330	BLDG. 525 PIPE
331	BLDG. 523 FLOOR
332	BLDG. 523 CEILING
333	BLDG. 522 FLOOR
334	BLDG. 522 CEILING
335	BLDG. 821 FLOOR
336	BLDG. 821 CEILING
337	BLDG. 489 FLOOR
338	BLDG. 489 CEILING
339	BLDG. 625 FLOOR
340	BLDG. 625 CEILING

Union Carbide trial exhibit UC-1928: Union Carbide Brownsville, Texas Plant Bulk Sample Results and Belia Corte… Published by AsbestosClaims.Law
ACL Doc 16987 · Page 10 of 11 asbestosclaims.law/library/16987/10

BULK SAMPLES - UNION CARBIDE BROWNSVILLE, TEXAS PAGE 3

SAMPLE NO.	DESCRIPTION
341	BLDG. 625 A/C DUCT
341A	BLDG. 731 FLOOR
342	BLDG. 731 CEILING
343	BLDG. 731 A/C DUCT
344	BLDG. 731 PIPE
345	BLDG. 168 ROOF CENTER
346	BLDG. 168 ROOF B TAR
347	BLDG. 168 ROOF TOP LAYER
348	BLDG. 259 CEILING HALL
349	BLDG. 259 R. ROOM PIPE
371	BlDG. 731 ROOF (TOP)
372	BLDG. 422 PIPE IN CEILING
373	BLDG. 422 PIPE IN CEILING
374	BLDG. 731 ROOF (BOTTOM)
375	BLDG. 731 ROOF MIDDLE LAYER

Union Carbide trial exhibit UC-1928: Union Carbide Brownsville, Texas Plant Bulk Sample Results and Belia Corte… Published by AsbestosClaims.Law
ACL Doc 16987 · Page 11 of 11 asbestosclaims.law/library/16987/11