PLAINTIFF'S EXHIBIT
UC-1931

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2796
713-488-1810

REPORT TO:	INVOICE TO:	☑ CHECK BOX
COMPANY UNION CARBIDE, CORP.	COMPANY	IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUTE BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE # (512)831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS	PLEASE FAX RESULTS WHEN FINISHED. FAX NO. (512) 831-5278	

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
		11-7-90	10AM						
1	267	↓	↓		✓	BLDG. 166 ROOF TAR S. END CENTER	1	↓	
2	268					" " " FIBER " " "			
3	269					" 167 " LAYER UNDER TAR			
4	270					" " " TAR N. END CENTER			
5	300					" 168 PIPE			
6	301					" " "			
7	302					" 161 CEILING			
8	303					" " PIPING			
9	304					" " FLOOR			
10	305					" 162 PIPE			
11	306					" 164 "			
12	307					" 167 CEILING			
13	308					" 166 "			
14	309					" 221 "			
15	310	↓	↓	↓		" 123 "	↓	↓	

RELINQUISHED BY: SIGN Barbara Cortez DATE/TIME 5 P.M. 11/7/90	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME (illegible) 11-8-90 0930	SAMPLE CONDITION #H145678-5737	
CARRIER CO.	AIR BILL NO	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1452

Union Carbide trial exhibit UC-1931: NUS Corporation Chain of Custody Forms for Union Carbide Insulation Sampl...
ACL Doc 16990 · Page 1 of 8
Published by AsbestosClaims.Law
asbestosclaims.law/library/16990/1

Union Carbide trial exhibit UC-1931: NUS Corporation Chain of Custody Forms for Union Carbide Insulation Sampl...
ACL Doc 16990 · Page 2 of 8

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2788
713-488-1810

REPORT TO:	INVOICE TO:	☑ CHECK BOX
COMPANY UNION CARBIDE, CORP.	COMPANY	IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUTE BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE # (512) 831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
	11-7-90		10AM						
1	311				✓	BLDG. 123 FLOOR	1		
2	312					" " PIPE			
3	313					" 230 CEILING			
4	314					" 224 "			
5	315					" " A/C DUCT			
6	316					" 230 FLOOR			
7	317					" 420 "			
8	318					" " CEILING			
9	319					" 422 "			
10	320					" 424 PIPE			
11	321					" 425 FLOOR			
12	322					" 424 CEILING			
13	323					" 424A PIPE			
14	324					" 425 "			
15	325				✓	" " A/C DUCT			

RELINQUISHED BY: SIGN Dilia Cortez DATE/TIME 5 P.M. 11/7/90	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN CNunnam 11/8/90 0930 DATE/TIME	SAMPLE CONDITION #H145678-5737	
CARRIER CO	AIR BILL NO.	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1453

Published by AsbestosClaims.Law
asbestosclaims.law/library/16990/2

Union Carbide trial exhibit UC-1931: NUS Corporation Chain of Custody Forms for Union Carbide Insulation Sampl...
ACL Doc 16990 · Page 3 of 8

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2788
713-488-1610

REPORT TO:	INVOICE TO:	☑ CHECK BOX
COMPANY UNION CARBIDE, CORP.	COMPANY	IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUTE BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE # (512) 831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1	326	11-7-90	10AM		✓	BLDG. 428 FLOOR	1	✓	
2	327					" " CEILING			
3	328					" " "			
4	329					" 525 "			
5	330					" 525 PIPE			
6	331					" 523 FLOOR			
7	332					" " CEILING			
8	333					" 522 FLOOR			
9	334					" " CEILING			
10	335					" 821 FLOOR			
11	336					" " CEILING			
12	337					" 489 FLOOR			
13	338					" " CEILING			
14	339					" 625 FLOOR			
15	340				↓	" 625 CEILING	↓	↓	

RELINQUISHED BY: SIGN	DATE/TIME	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN	DATE/TIME	RECEIVED BY: SIGN
Debi Cortez	5 P.M. 11/7/90				
RELINQUISHED BY: SIGN	DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN	DATE/TIME	SAMPLE CONDITION	
		CNiuman	11.8.90/0930	# H145678-5737	
CARRIER CO		AIR BILL NO.	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN	DATE/TIME

BRD 1454

Published by AsbestosClaims.Law
asbestosclaims.law/library/16990/3

Union Carbide trial exhibit UC-1931: NUS Corporation Chain of Custody Forms for Union Carbide Insulation Sampl...
ACL Doc 16990 · Page 4 of 8
BRD 1455
Published by AsbestosClaims.Law
asbestosclaims.law/library/16990/4

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1810

REPORT TO:	INVOICE TO:	☑ CHECK BOX
COMPANY UNION CARBIDE, CORP.	COMPANY	IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUTE BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE (512)831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
	11-7-90		10AM						
1	341				✓	BLDG. 625 A/C DUCT	1	✓	
2	341-A					" 731 FLOOR			
3	342					" " CEILING			
4	343					" " A/C DUCT			
5	344					" " PIPE			
6	345					" 168 ROOF CENTER			
7	346					" " ROOF B TAR			
8	347					" " " TOP LAYER			
9	348					" 259 CEILING HALL			
10	349	↓	↓		↓	" 259 R. Room PIPE	↓	↓	
11	371					" 731 ROOF (TOP)			
12	372					" 422 PIPE IN CEILING			
13	373					" " " " "			
14	374					" 731 ROOF (BOTTOM)			
15	375	↓	↓		↓	" " " MIDDLE LAYER	↓	↓	

RELINQUISHED BY SIGN: Helen Cortez DATE/TIME: 5P.M. 11/7/90	RECEIVED BY SIGN	RELINQUISHED BY SIGN DATE/TIME	RECEIVED BY SIGN
RELINQUISHED BY SIGN DATE/TIME	RECEIVED FOR LABORATORY BY SIGN: A Newman 11/8/90 0930 DATE/TIME	SAMPLE CONDITION: #N145678-5737	
CARRIER CO	AIR BILL NO	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

Union Carbide trial exhibit UC-1931: NUS Corporation Chain of Custody Forms for Union Carbide Insulation Sampl...
ACL Doc 16990 · Page 5 of 8
Published by AsbestosClaims.Law
asbestosclaims.law/library/16990/5

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1810

REPORT TO:	INVOICE TO:	☑ CHECK BOX
COMPANY UNION CARBIDE, CORP.	COMPANY	IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUTE BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE (512)831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
	11-7-90		10AM						
1	311				✓	BLDG 123 FLOOR	1	✓	
2	312					" " PIPE			
3	313					" 230 CEILING			
4	314					" 224 "			
5	315					" " A/C DUCT			
6	316					" 230 FLOOR			
7	317					" 420 "			
8	318					" " CEILING			
9	319					" 422 "			
10	320					" 424 PIPE			
11	321					" 425 FLOOR			
12	322					" 424 CEILING			
13	323					" 424A PIPE			
14	324					" 425 "			
15	325	↓	↓		✓	" " A/C DUCT	↓	↓	

RELINQUISHED BY: SIGN [signature] DATE/TIME 5PM 11/7/90	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN [signature] DATE/TIME 11-8-90 0930	SAMPLE CONDITION #H145678-5737	
CARRIER CO	AIR BILL NO.	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1456

Union Carbide trial exhibit UC-1931: NUS Corporation Chain of Custody Forms for Union Carbide Insulation Sampl...
ACL Doc 16990 · Page 6 of 8

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1810

REPORT TO:		INVOICE TO:		☑ CHECK BOX
COMPANY	UNION CARBIDE, CORP.	COMPANY		IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS	STAR ROUTE BOX 90	ADDRESS		
CITY	BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP		P.O. #
ATT.	B. CORTEZ PHONE (512)831-4501	ATT. PHONE #		RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1	326	11-7-90	10AM		✓	BLDG. 428 FLOOR	1	✓	
2	327					" " CEILING			
3	328					" " "			
4	329					" 525 "			
5	330					" 525 PIPE			
6	331					" 523 FLOOR			
7	332					" " CEILING			
8	333					" 522 FLOOR			
9	334					" " CEILING			
10	336					" 821 FLOOR			
11	336					" " CEILING			
12	337					" 489 FLOOR			
13	338					" " CEILING			
14	339					" 625 FLOOR			
15	340				✓	" 625 CEILING	↓	↓	

RELINQUISHED BY: SIGN Bob Cortez DATE/TIME 5P.M. 11/7/90	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN Newman DATE/TIME 11.8.90/0930	SAMPLE CONDITION #H145678-5737	
CARRIER CO.	AIR BILL NO.	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1457

Published by AsbestosClaims.Law
asbestosclaims.law/library/16990/6

Union Carbide trial exhibit UC-1931: NUS Corporation Chain of Custody Forms for Union Carbide Insulation Sampl...
ACL Doc 16990 · Page 7 of 8

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1610

REPORT TO:	INVOICE TO:	☑ CHECK BOX
COMPANY UNION CARBIDE, CORP.	COMPANY	IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUTE BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE (512)831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS		

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
	11-7-90		10AM						
1	341				✓	BLDG. 625 A/C DUCT	1	✓	
2	341-A					" 731 FLOOR			
3	342					" " CEILING			
4	343					" " A/C DUCT			
5	344					" " PIPE			
6	345					" 168 ROOF CENTER			
7	346					" " ROOF B TAR			
8	347					" " " TOP LAYER			
9	348					" 259 CEILING HALL			
10	349	↓	↓		↓	" 259 R. Room PIPE	↓	↓	
11	371					" 731 ROOF (TOP)			
12	372					" 422 PIPE IN CEILING			
13	373					" " " " "			
14	374					" 731 ROOF (BOTTOM)			
15	375	↓	↓		↓	" " " MIDDLE LAYER	↓	↓	

RELINQUISHED BY: SIGN Delia Cortez DATE/TIME 5 P.M. 11/7/90	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN DATE/TIME J. Wilmer 11/8/90 0930	SAMPLE CONDITION #H145678-5737	
CARRIER CO.	AIR BILL NO	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1458

Published by AsbestosClaims.Law
asbestosclaims.law/library/16990/7

Union Carbide trial exhibit UC-1931: NUS Corporation Chain of Custody Forms for Union Carbide Insulation Sampl...
ACL Doc 16990 · Page 8 of 8

CHAIN OF CUSTODY

NUS CORPORATION
HOUSTON ANALYTICAL LABORATORY
900 GEMINI AVENUE, CLEAR LAKE CITY
HOUSTON, TEXAS 77058-2798
713-488-1810

REPORT TO:	INVOICE TO:	☑ CHECK BOX
COMPANY UNION CARBIDE, CORP.	COMPANY	IF INVOICE TO ADDRESS AND REPORT TO ADDRESS ARE SAME
ADDRESS STAR ROUTE BOX 90	ADDRESS	
CITY BROWNSVILLE STATE TX ZIP 78521	CITY STATE ZIP	P.O. #
ATT. B. CORTEZ PHONE (512)831-4501	ATT. PHONE #	RELEASE #

PROJECT NAME/SITE NAME	CLIENT COMMENTS	NUS COMMENTS & SAMPLE #'S
INSULATION SAMPLES FOR ASBESTOS ANALYSIS	PLEASE FAX RESULTS WHEN FINISHED. FAX NO. (512) 831-5278	

WARRANTY AND LIMITATION OF LIABILITY

Any service or work performed by NUS Laboratory Services Group is expressly subject to the following provision and NUS does not agree to any provision that is in conflict.

NUS Corporation (NUS) warrants that work will be performed in accordance with sound laboratory practice and accepted analytical procedures, but makes no other warranty, express or implied. NUS is solely responsible for performance of this contract, and no affiliated company, director, officer, employee, agent or subcontractor of NUS shall have any legal responsibility hereunder, whether in contract or tort, or otherwise. Liability for injury or damage to persons or property arising out of this work (other than for professional errors, omissions, or other professional negligence, which are covered by the next sentence) shall be limited to the amount covered by the general comprehensive insurance carried by NUS. In the event of error, omission, or other professional negligence or any breach of the above warranty, the sole and exclusive responsibility of NUS shall be to reperform the deficient work at its own expense, and NUS shall have no other liability whatsoever. In no event shall NUS be liable, whether in contract or tort, or otherwise for any incidental consequential or special damages including but not limited to, damages in any way connected with the use or interpretation of information or analysis provided by NUS or with action related to such use of interpretation.

	SAMPLE NUMBER	DATE	TIME	COMPOSITE	GRAB	SAMPLE SOURCE & DESCRIPTION	NUMBER CONTAINERS	REQUESTED ANALYSIS: ASBESTOS	REMARKS
1	11-7-90 267		10AM		✓	BLDG. 166 ROOF TAR S. END CENTER	1		
2	268					" " " FIBER " " "			
3	269					" 167 " LAYER UNDER TAR			
4	270					" " " TAR N. END CENTER			
5	300					" 168 PIPE			
6	301					" " "			
7	302					" 161 CEILING			
8	303					" " PIPING			
9	304					" " FLOOR			
10	305					" 162 PIPE			
11	306					" 164 "			
12	307					" 167 CEILING			
13	308					" 166 "			
14	309					" 221 "			
15	310	✓	✓		✓	" 123 "	✓	✓	

RELINQUISHED BY: SIGN Colin Cotty DATE/TIME 5PM. 11/7/90	RECEIVED BY: SIGN	RELINQUISHED BY: SIGN DATE/TIME	RECEIVED BY: SIGN
RELINQUISHED BY: SIGN DATE/TIME	RECEIVED FOR LABORATORY BY: SIGN (Illegible) 11-8-90 0930 DATE/TIME	SAMPLE CONDITION #H145678-5737	
CARRIER CO.	AIR BILL NO.	CARRIER PHONE #	DATE RESULTS REPORTED BY: SIGN DATE/TIME

BRD 1459

Published by AsbestosClaims.Law
asbestosclaims.law/library/16990/8