PLAINTIFF'S EXHIBIT

UC-2496

INDUSTRIAL HYGIENE - ENVIRONMENTAL PROTECTION

ENVIRONMENTAL HAZARD REPORT

DATE 3-17-77 TIME 1300 Hrs

PERSON REQUESTING ASSISTANCE Monin

LOCATION Bldg 770-237 DEPARTMENT R+D

IH DEPARTMENT CONTACT Bill Bott

REQUEST Assist in the dismantling of Insulated Water Lines. Insulating material thought to be Asbestos.

ACTION TAKEN Pipe clamps loosened, unions broken and pipe and insulation taken out in one piece. Material wet down to control dust and stored in plastic bags for disposal in land fill. Personnel involved - Monin and Raines

IH FILE Asbestos

ATN: Wilson Shelton
704 Shop

(IH #1 2/77)

UCC 024314

Union Carbide trial exhibit UC-2496: Industrial Hygiene Environmental Hazard Report on Dismantling Suspected As... Published by AsbestosClaims.Law
ACL Doc 17475 · Page 1 of 1 asbestosclaims.law/library/17475/1