PLAINTIFF'S EXHIBIT

UC-3633

UNION CARBIDE CORPORATION
SOUTH CHARLESTON PLANT
Safety and Health Department
South Charleston, West Virginia 25303

October 26, 1987

TO: P. R. Desai
J. C. Ketcham
D. B. Howard
D. H. Ott
D. R. Stokely
T. G. Swanson

CC: J. R. Dement*
S. W. Drake*
B. N. Gliatta*
G. F. Painter*
E. H. Kivett, Jr.*

Re: SHARE Inspection Results

Gentlepeople:

You will find attached a copy of the findings from the SHARE inspection held October 14, 1987. Thank you for the cooperation of your staff and hourly folke in making the audit meaningful.

The program goals are that the following items be satisfied by your department:

1. All deficiencies must be addressed within ninety (90) days of the inspection; and

2. An update is sent to the SHARE coordinator and your APM each thirty (30) days after the inspection until completion. You can use a copy of this report and the spaces below in summarizing your completion progress.

I trust that you will find this program worth supporting to continue to maintain and improve our plant facilities and safety. If you have any questions or need help in understanding the requirements/specifications contained within, please contact me at your earliest convenience.

S. B. Kovach
SHARE Coordinator

PROGRESS UPDATE

	30 Days (Nov 26, 1987)	60 Days (Dec 26, 1987)	90 Days (Jan 26, 1987)
% Complete	_____	_____	_____
Signature	_____	_____	_____

Send copy of update to: S. B. Kovach - Bldg. 109-2
S. W. Drake - Bldg. 82-3
B. N. Gliatta - Bldg. 82-3
G. F. Painter - Bldg. 82-3

[redacted]
1658A

Attachment

*Copy of letter only

UCC 008486

Union Carbide trial exhibit UC-3633: S. B. Kovach to P. R. Desai and Others Transmitting SHARE Inspection Result...
ACL Doc 18359 · Page 2 of 2

SOUTH CHARLESTON PLANT SHARE AUDIT TEAM'S REPORT

Department, Title: Lower Island | Dept. No. | Location: Lower Island | Date of Inspection: 10/24/87

Inspector Submitting Report: HHP | Phone No.: 3953 | Inspection Responsibility: Insulation

Tag No.	Description of Substandard Condition	Item Tagged (✓)	Corrective Action Plan: Action Steps or Explanation	Corrective Action Plan: Date Correct	Corrective Action Plan: Shop Ord. Number
N1	Exposed I... North East Painted Tank		Weather Proof		
* N2	Exposed ins. (Non Asbestos) North Dike Wall at Sphere Tanks		Patch		
N3	Exposed Asbestos on Steam S. TK 538	✓	Seal Strip ½" Dead Line		
N4	Exposed Ins. Outside Fence Lower End of Island	✓	Test & Strip		
N5	Exposed Ins. (Perlite) Eth Line		Shop Order - Written Waiting on A decision on Paint		

* Asbestos

UCC 008487

Published by AsbestosClaims.Law
asbestosclaims.law/library/18359/2