2089

LUU-0195 # 112

WORKPLACE ENVIRONMENT MONITORING - FIELD DATA SHEET

Page ____ of ____

Date 5-6-85 Project ASBESTOS Department 327000 BLDG 47

General Operating Conditions: SCRAPING ASBESTOS FROM MAINLAND POWER HOUSE

Sampling Method and Equipment: Personal ____ : Area ✓ : Portable Sampler Pump ✓ : Charcoal Tube ____ : Bag ____ : Other FILTER CASETTE

Remarks:

Shift: Day ____ Eve. ____ Mid. ____ No. Employees ____ Sampled By HCJ

Employee Name, Job Title, Payroll No., Soc. Sec. No., Bldg. No. - Monitoring Loc. Smoke - Chew?	Sample No.	Pump Ser. Number	Pump Kv	Pump Flow Control Set	Initial Pump Reading	Final Pump Reading	Net Pump Reading	Start (Time)	Stop (Time)	Net Sample Time, Min.	Volume, Liters.	Conc., f/cc
NORTH EAST CORNER BLDG 50	1	9365		~~500~~ 5	~~500~~ 5			0645	1115	450	900	.002
EAST SIDE AREA 1 EXCEL SHOP	2	9371										
NORTH OF BLDG 47 AT TK FARM	3	9376										
EAST BLDG 47 at CORNER	4	9146										
South of BLDG 47	5	9254										
South of BLDG 47	6	9671										

.01 X 855 / 5.8 X 900 = .002


Remarks: (See Reverse Side) NO FIBERS FOUND ON ANY OF THE SAMPLES

2089

UCC 0012247

PLAINTIFF'S EXHIBIT UC-3778

Union Carbide trial exhibit UC-3778: Workplace Environment Monitoring Field Data Sheet and Industrial Hygiene S...
ACL Doc 18457 · Page 1 of 6
Published by AsbestosClaims.Law
asbestosclaims.law/library/184571



Union Carbide trial exhibit UC-3778: Workplace Environment Monitoring Field Data Sheet and Industrial Hygiene S... Published by AsbestosClaims.Law
ACL Doc 18457 · Page 2 of 6 **asbestosclaims.law/library/18457/2**

INDUSTRIAL HYGIENE WORKPLACE SAMPLING SUPPLEMENTAL COMMENTS

W20189 | CSTD | 05 08 85

REMOVING INSULATION FROM THE MAINLAND POWER HOUSE INSIDE AND OUTSIDE AREA NEAR NORTHWEST CORNER OF ELECTRICAL SHOP BLDG. 50 AT SOUTHWEST CORNER OF BLDG. 47 AT JANE FARM HALF WAY BETWEEN BLDG. 47 AND BLDG. 300

LINE NO. 1002 2011 2211 2341 2511

UPDATE

DATE

SIGNATURE

UCC 0012249

2086

WV-0195 4/11

WORKPLACE ENVIRONMENT MONITORING - FIELD DATA SHEET

Page ____ of ____

Date 5-1-85 Project ASBESTOS Department

General Operating Conditions: SCRIPPING ASBESTOS FROM MAINLAND POWER HOUSE (Co

Sampling Method and Equipment: Personal ____ : Area ✓ : Portable Sampler Pump ____ : Charcoal Tube ____ : Bag ____ : Other FILTER CASSETTE

Remarks:

Shift: Day ✓ Eve. ____ Mid. ____ No. Employees ____ Sampled By HCS

Employee Name, Job Title, Payroll No., Soc. Sec. No., Bldg. No. - Monitoring Loc. Smoke - Chew?	Sample No.	Pump Ser. Number	Pump Kv	Pump Flow Control Set	Initial Pump Reading	Final Pump Reading	Net Pump Reading	Start (Time)	Stop (Time)	Net Sample Time, Min.	Volume, Liters.	Conc. f/cc
NORTH EAST CORNER OF BLDG 47	1	9371			500/15	100/15		0645	1145	480	960	.002
AREA 1 ELECT SHOP WEST OF BLDG 47	2	9671 ✓										.008
NORTH OF BLDG 47 AT TK FARM	3	9253 ✓										.002
SOUTH EAST BLDG 47	4	9365 ✓										.002
South BLDG 47	5	9254 ✓										.002
South BLDG 47	6	9146 ✓										.002

2086

Remarks: (See Reverse Side)

#2 HAD 2FC/100 FIELDS

#1, 3, 4, 5, 6 HAD ØFC/100 FIELDS

UCC 0012250

Union Carbide trial exhibit UC-3778: Workplace Environment Monitoring Field Data Sheet and Industrial Hygiene S...
ACL Doc 18457 · Page 4 of 6
Published by AsbestosClaims.Law
asbestosclaims.law/library/184574

INDUSTRIAL HYGIENE WORKPLACE SAMPLING
MAINTENANCE
ASBESTOS
KEYPUNCH DATA SHEET NO. IN COLS. 1 - 5 OF EACH CARD

UCC 0012251

INDUSTRIAL HYGIENE WORKPLACE SAMPLING SUPPLEMENTAL COMMENTS

WZ0184 | PLANT 6 CSTM | JOB NO 03021 | DAY YR 15 85

RE MOVING INSULATION FROM THE MAINLAND POWER HOUSE INSIDE AND OUTSIDE CORNER OF ELECTRICAL SHOP WEST OF MAIN ENTRANCE TO POWER HOUSE AT LOADING DOCK OF BLDG 47 AT TARA FARM

WE WILL BE WORKING OUTSIDE OF BLDG 47 AT LOADING DOCK AREA AND INSIDE BLDG 47 AT TARA FARM HALF WAY BETWEEN BLDG 47 AND BLDG 300

LINE NO.	UPDATE
1012	
2011	
2211	
2311	
2411	
2511	

DATE

SIGNATURE

UCC 0012252