WJ-0195 #784

WORKPLACE ENVIRONMENT MONITORING - FIELD DATA SHEET Page ___ of ___

Date 5-22-87 Project ASBESTOS Department 22050 BLDG 75

General Operating Conditions: ~~ROOFS~~ AGRESSIVE SAMPLING INSIDE BLDG 75 AFTER ASBESTOS REMOVAL

Sampling Method and Equipment: Personal ___ : Area ✓ : Portable Sampler Pump ✓ : Charcoal Tube ___ : Bag ___ : Other FILTER CASSETTE

Remarks: ___

Shift: Day ___ Eve. ✓ Mid. ___ No. Employees ___ Sampled By CLS/LEM

Employee Name, Job Title, Payroll No., Soc. Sec. No., Bldg. No. - Monitoring Loc. Smoke - Chew?	Sample No.	Pump Ser. Number	Pump Kv	Pump Flow Control Set	Initial Pump Reading	Final Pump Reading	Net Pump Reading	Start (Time)	Stop (Time)	Net Sample Time, Min.	Volume, Liters.
ON DRUM IN FRONT of DRUMING STATION	1	6307			2LPM	2LPM	2LPM	1615	0015	480	960
ON DRUM UNDER LINE THAT WAS STRIPPED SOUTH WALL MIDDLE OF 75.	2	6308			2LPM	2LPM	2LPM	1615	0015	480	960
ON LABEL CABINET UNDER LINE where STRIPPED WEST END BLDG 75	3	6309			2LPM	2LPM	2LPM	1615	0015	480	960
NOTE: NO DECTABLE FIBERS											


Remarks: (See Reverse Side)

UCC 0012509

PLAINTIFF'S EXHIBIT UC-3811

Union Carbide trial exhibit UC-3811: Workplace Environment Monitoring Field Data Sheet and Sketch for Aggressiv...
ACL Doc 18471 · Page 1 of 2
Published by AsbestosClaims.Law
asbestosclaims.law/library/18471/1

lines along south side of 6309 75 more than only ones stripped & reinstalled



UCC 0012510